

ASS. REC. BY:

REF: CF/MS419014587/Cq d307 Special Instruction:

Signature: Simon

ASSIGNMENT (Office)

Meimien

From (Person): Fiewel POO

of

MSIG

Date/Time: 14/8/19 @ 447pm

Estimated Cost:

Bill to:

OD / TI / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT6901M

Insured:

SLV 2299J

at Workshop in/s

Hui Yeng Motor

Tel:

64515732

of

176 Sin Ming Drive # 04-02

Policy No:

29112616

Claim No:

599252

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

3/7/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Bel

Vehicle: IN/OUT

Date/Time

Action/Instruction

Shen/19 ✓

SLT6901M - X

SLV2299J - X.

09/9/19 @ 11.56am confirmed with Bel LS \$3200, 4 days. (cost + labour = LS
 ched \$ 3970.35, 55%.)

RECEIVED 09 SEP 2019



MSIG Insurance (Singapore Pte. Ltd) (Co. Reg. No 200412212G)
4 Shenton Way. #27-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg

Executive
Claims Services

Inspection Report

Type of Survey:

OD - Excess	
TP Without Prejudice	☒

Vehicle Data:

Odometer reading	230409 km
Engine No	
VIN No	
Engine capacity	
Engine modification	

Vehicle Details:

Vehicle Reg No
Make
Model
Passenger capacity
Paint colour & code
Paint type

SLT 6901 M
Toyota
CH-R
05
Yellow

Vehicle Extras:

In-built camera
Modification

Yes / No
Yes / No

Vehicle Condition:

Seviceable Yes / No

Handbrake	
Footbrake	
Steering	
Body	
Paint	

Tyre Condition:

Tread mm Hanking Size Condition

Front right	4	Headling	235 / 50 / 18	
Front left	4		"	
Rear left	4		"	
Rear right	4		"	

General Data:

Date of accident
Date of inspection
Date of assignment
Inspection location

03-07-19
05-07-19
04-07-19
Hui Yang

Painting Process:

Prepare off vehicle	
Painting off vehicle	
Neither (default)	

Cost Details:

Parts
Supplementary
Miscellaneous
Body Labour
Paint labour
Paint material
TOTAL
Towing
Excess
Total less excess
Estimated days for repair

Repaierer Adjuster

Body Panel Repair:

Panel repair calculator used	
Yes / No	

Remarks:

Lump / Global Sum

Reason(s) Margin Repair / Fast-line

Others:

Repair Authorised

Date:

--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jul 2019 15:15		14 Aug 2019 16:47 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	BLUECAR EAST ASIA PTE LTD, Co. Reg. No.: 201617259H		
Main Claimant:	LE MOTOR CAR RENTAL PTE LTD, Co. Reg. No.: 201401553D		
Vehicle Reg. No.:	SLT6901M	Date of Loss:	03/07/2019 12:00 - :59 [19 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 599252	Policy/Cover Note No.:	29112616 (Comprehensive) Coverage: 01/01/2019 - 31/12/2019
Vehicle Reg. No. (Insured):	SLV2299J	Policy No. (Claimant):	
		Excess:	
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2019]		
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. Liab: Dispute (NR). Assign: IHS. Contact: Bel @ 6451 5752		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Hui Yang Motor <hui_yang_motor@hotmail.com>
Sent: Monday, 9 September 2019 11:56 AM
To: Shiau Chan (LKKAUTO)
Subject: Re: KINDLY ADVISE THE STATUS OF SLT 6901M (DOA: 03/07/2019) SLT6901M (? photos & after repair photos) and marked estimate

Importance: High

Hi Shiau Chan,

We accept Lump sum repair \$3200.00 and 4 days repair.

The LOD I post to LKK or post to MSIG Ins?

Thank you & Regards,
Bel
Tel: 64515752

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Monday, September 9, 2019 11:47 AM
To: Hui Yang Motor <hui_yang_motor@hotmail.com>
Subject: RE: KINDLY ADVISE THE STATUS OF SLT 6901M (DOA: 03/07/2019) SLT6901M (? photos & after repair photos) and marked estimate

Dear Bel,

WITHOUT PREJUDICE

My calculation error, the repair cost should be at Lump Sum \$3,200.00 and 4 repair days.

Kindly check and confirm.

Please note that the finalisation subject to insurer's approval.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 6 September 2019 2:25 PM
To: Hui Yang Motor <hui_yang_motor@hotmail.com>
Subject: RE: KINDLY ADVISE THE STATUS OF SLT 6901M (DOA: 03/07/2019) SLT6901M (? photos & after repair photos) and marked estimate



PRELIMINARY ADVICE

OD Claim / TP Claim

Attn : _____
Date : _____

Policy No : _____
Claim No : _____



Insured Vehicle No : SLV 2299J Date of Accident : 03-07-19
TP Vehicle No : SLT 6901M Place of Survey : Hui Yang
Make & Model : Toyota CH-R 1.8A Date of Survey : 05-07-19

Point of Impact / Damages :

Rear

Recommended Reserve :

Repairer's Estimate : \$ 7170.35
Interim Adjustment : \$ 2702.00
Check Items : \$ 970.00



Proposed : Part by Part / Lump Sum Repair \$2900/- Excess : \$ -

Estimate Repair Period : 04 days

Pre-accident Market Value (for total loss consideration) : \$ -

COE / PARF to owner : \$ -

Vehicle within / not within limit of economical repair.

Others :

Surveyed By :

MSIG Insurance (Singapore) Pte. Ltd.

☐

OD Claim
Excess : \$ _____
(Authorised / Revert)

☒

TP Claim
(Without Prejudice)

Vehicle No. SLT 6901M

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 04

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 05-07-19


MSIG

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200412212G)
 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581
 Tel 6220 9644, Fax 6225 6371
 www.msig.com.sg

To: MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

From: MSIG Insurance (Singapore) Pte. Ltd.
 16 Raffles Quay
 #24-01 Hong Leong Building
 Singapore 048581

Attn: Fievel Foo Wenyaoy

Date: 08 Jul 2019

Preliminary Advice

Insured Vehicle No	: SLV2299J	Accident Date	: 03/07/2019
TP Vehicle No	: SLT6901M	Assignment Date	: 05/07/2019
Make	: TOYOTA C-HR HYBRID	Est. Duration of Repair	: 4.00
Date of Inspection	: 05/07/2019		
Inspection At	: HUI YANG MOTOR PTE LTD (HQ) 176 SIN MING DRIVE #04-02, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the rear portion.

Repairer's Estimate (Gross)	:S\$	7,170.35
Revised Amount	:S\$	2,702.00
Check Items (Estimated)	:S\$	970.00
Total	:S\$	
 Lump Sum Repair	:S\$	 2,900

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- (X) The vehicle is economical/~~not economical~~ for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

A Member of MS & AD INSURANCE GROUP



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	553D
Vehicle Details	
Vehicle No.:	SLT6901M
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.8G CVT
Primary Colour:	Yellow
Manufacturing Year:	2017
Engine No.:	2ZR8198336
Chassis No.:	ZYX102076524
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$30,694.00
Original Registration Date:	07 Nov 2017
First Registration Date:	07 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Nov 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	06 Nov 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$49,000.00
COE Rebate Amount:	\$39,252.00
Total Rebate Amount:	\$43,002.00

The information contained herein is correct as at 09 Sep 2019

OK

Enquire Transfer Fee

Enquire Transfer Fee

Vehicle Details			
Vehicle No.:	SLT6901M		
Vehicle Type:	Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme:	Normal		
Vehicle Make:	TOYOTA		
Vehicle Model:	C-HR HYBRID 1.8G CVT		
Chassis No.:	ZYX102076524		
Propellant:	Petrol-Electric		
Engine No.:	2ZR8198336		
Motor No.:	20A317707494		
Engine Capacity:	1797 cc		
Power Rating:	53.0 kW		
Maximum Power Output:	90.0 kW (120 bhp)		
Maximum Laden Weight:	1715 kg		
Unladen Weight:	1440 kg		
Year Of Manufacture:	2017		
Original Registration Date:	07 Nov 2017		
Lifespan Expiry Date:	-		
COE Category:	E - Open - all except motorcycle		
Quota Premium:	\$49,000.00		
COE Expiry Date:	06 Nov 2027		
Road Tax Expiry Date:	06 Nov 2019		
PARF Eligibility Expiry Date:	06 Nov 2027		
Inspection Due Date:	06 Nov 2020		
Intended Transfer Date:	09 Sep 2019		
CO2 Emission:	88.00 (g/km)		
CEV/VES Rebate Utilised Amount:	\$29,972.00		
CO Emission:	-		
HC Emission:	-		
NOx Emission:	-		
PM Emission:	-		
The current road tax expiry is 06 Nov 2019. You may renew the road tax from 07 Aug 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 06 Nov 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 07 Nov 2019 to 06 May 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	487.00	-	487.00
Total Amount Payable:			512.00
Amount Payable (From 07 Nov 2019 to 06 Nov 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	974.00	-	974.00
Total Amount Payable:			999.00

You may print this page for reference.

OK

Print

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

MSIG
Vehicle in
2/7/19
4/7/19

03/07/2019

2X X 10

Owner: LE MOTOR CAR RENTAL PTE LTD

ESTIMATE TO REPAIR TOYOTA CHR 1.8 - SLT6901M

1pc	rear tailgate X repair	\$ 680.00 X
1pc	rear RH taillamp ? NN	\$ 360.00 X
1pc	rear RH taillamp lower bracket ? NN	\$ 35.00 X
1pc	rear bumper / Deformed	\$ 320.00
1pc	rear bumper towing cover / grazed	\$ 50.00
1pc	rear bumper inner RH cover / cracked	\$ 55.00
1pc	rear bumper RH side retainer / cracked	\$ 45.00
1pc	rear bumper RH reflector garnish / Deformed	\$ 65.00
1pc	rear bumper diffuser / Deformed	\$ 280.00
6pcs	rear bumper diffuser clip @\$2.00 / new	\$ 12.00
1pc	rear bumper reinforcement ? DD	\$ 195.00 ✓
1pc	rear end panel ? DD	\$ 380.00 ✓
1pc	rear RH fender protector / cracked	\$ 165.00
1pc	rear windscreen moulding X NN	\$ 100.00 X
1pc	rear exhaust box X repair.	\$ 1,500.00 X
		\$ 4,242.00
cost + 15%		\$ 268.35
		\$ 4,510.35
1pc	rear exhaust extension X NN	s.nett \$ 380.00
1set	rear bumper reflector / cracked LED	s.nett \$ 280.00
	remove & refit rear windscreen glass	\$ 120.00 X
	sealant	\$ 80.00 X
	tuffkote	\$ 120.00 80 50
	wiring	\$ 80.00 30 30
	spray painting	\$ 800.00 600
	labour charges Exhaust & Tailgate.	\$ 800.00 700
	Total	
		\$ 7,170.35

04 days.

05/07/19 @ 1330 hrs

Victor_Seng @ sg-msig-asia.com

87747011

L 15 pfter paint.



6907.00

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

MSIG
Vehicle in
2/7/19
4/7/19

03/07/2019

Owner: LE MOTOR CAR RENTAL PTE LTD

ESTIMATE TO REPAIR TOYOTA CHR 1.8 - SLT6901M

1pc	rear tailgate X repair	\$ 680.00 X
1pc	rear RH taillamp ?	\$ 360.00 X
1pc	rear RH taillamp lower bracket ?	\$ 35.00 X
1pc	rear bumper / Deformed	\$ 320.00 ✓
1pc	rear bumper towing cover / grazed	\$ 50.00 ✓
1pc	rear bumper inner RH cover / cracked	\$ 55.00 ✓
1pc	rear bumper RH side retainer / cracked	\$ 45.00 ✓
1pc	rear bumper RH reflector garnish / Deformed	\$ 65.00 ✓
1pc	rear bumper diffuser / Deformed	\$ 280.00 ✓
6pcs	rear bumper diffuser clip @\$2.00 / rec	\$ 12.00 ✓
1pc	* rear bumper reinforcement ?	\$ 195.00 ✓
1pc	* rear end panel ?	\$ 380.00 ✓
1pc	rear RH fender protector / cracked	\$ 165.00 ✓
1pc	rear windscreen moulding X	\$ 100.00 X
1pc	rear exhaust box X repair.	\$ 1,500.00 X

12/7/19
? photo &
after for
photo and
to victor
6/8 - remain

cost + 15%

\$ 4,242.00
\$ 268.35
\$ 4,510.35

1567
1710
153277

1pc	rear exhaust extension X	s.nett \$ 380.00
1set	rear bumper reflector / cracked LED	s.nett \$ 280.00

remove & refit rear windscreen glass	\$ 120.00 X
sealant	\$ 80.00 X
tuffkote	\$ 120.00 80
wiring	\$ 80.00 50
spray painting	\$ 800.00 600
labour charges Exhaust & tailgate.	\$ 800.00 700
Total	\$ 7,170.35

5 or 6 days

04 days.

05/07/19 @ 1330 hrs

Victor_Seng @ sg.msig-asia.com

87747011

L15 After paint.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Jul 2019 15:15		14 Aug 2019 16:47 Edit Adj Rpt	S\$3,200.00 Edit Estimates	S\$3,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: BLUECAR EAST ASIA PTE LTD , Co. Reg. No.: 201617259H									
Main Claimant: LE MOTOR CAR RENTAL PTE LTD , Co. Reg. No.: 201401553D									
Vehicle Reg. No.: SLT6901M		Date of Loss: 03/07/2019 12:00 - :59 [19 Months and 26 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 599252		Policy/Cover Note No.: 29112616 (Comprehensive) Coverage: 01/01/2019 - 31/12/2019							
Vehicle Reg. No. (Insured): SLV2299J		Policy No. (Claimant):							
		Excess:							
Repairer: Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by SIMON HO LEONG CHUAN] ... [Imm.Advice due 15/08/2019]									
Adj Asg. Remarks: As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. Liab: Dispute (NR). Assign: IHS. Contact: Bel @ 6451 5752									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT6901M (599252)
[SLV2299J]
TP
LE MOTOR CAR RENTAL PTE LTD
Jul 3 2019 12:00PM
[BLUECAR EAST ASIA PTE LTD]
Hui Yang Motor Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	08/07/19 10:33	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
2	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
3	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
4	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
5	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
6	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
7	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
8	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
9	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
10	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
11	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
12	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
13	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
14	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
15	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
16	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
17	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
18	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
19	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
20	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
21	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
22	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
23	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
24	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
25	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
26	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
27	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
28	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
29	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
30	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
31	06/07/19 14:56	SURVEY PHOTO	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/07/19 15:17	Email - PRI	 Load PDF	
2	05/07/19 15:19	Estimate	 Load PDF	
3	05/07/19 15:20	TP GIA Rpt	 Load PDF	
4	05/07/19 15:37	Acknowledge PRI	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	08/07/19 11:54	Preliminary Loss Advise	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CF/MSG19014587/CQD3E2

Date: 16/09/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29112616

Claimant

Vehicle No : SLT6901M

Insured Vehicle No : SLV2299J

Date of Loss: 03/07/2019

Nature of Claim:

TP

Claim No: 599252

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT6901M

Make & Model: TOYOTA C-HR HYBRID, 1.8 E G CVT (A)

Engine No: 2ZR8198336

Reg. Date: 07/11/2017 (Man. Year: 2017)

Chassis No: ZYX102076524

Colour: Yellow

Odometer: 230409 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18

Rear Tyre Size:

235/50 R18

Front Left Side: Hanking 4 mm

Rear Left Side:

Hanking 4 mm

Front Right Side: Hanking 4 mm

Rear Right Side:

Hanking 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,982.00	1,847.00	3,135.00	62.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,920.00	1,380.00	540.00	28.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,902.00	3,227.00	3,675.00	53.25
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	6,902.00	3,200.00	3,702.00	53.64
+ GST 7.00/7.00% (S\$)	483.14	224.00	259.14	53.64
Nett Amount (S\$)	7,385.14	3,424.00	3,961.14	53.64

INSPECTION

Date of Assignment: 14/08/2019

Date Inspected: 05/07/2019 Inspected At:

Hui Yang Motor Pte Ltd (HQ)
176 Sin Ming Drive #04-02, Sin Ming
AutoCare
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: SIMON HO LEONG CHUAN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Sep 2019)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 E G CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT6901M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	680.00 F	*- F
2	1		*REAR RH TAILLAMP	Not Necessary	360.00 F	*- F
3	1		*REAR RH TAILLAMP LOWER BRACKET	Not Necessary	35.00 F	*- F
4	1		*REAR BUMPER	Deformed	320.00 F	*320.00 F
5	1		*REAR BUMPER TOWING COVER	Grazed	50.00 F	*50.00 F
6	1		*REAR BUMPER INNER RH COVER	Cracked	55.00 F	*55.00 F
7	1		*REAR BUMPER RH SIDE RETAINER	Cracked	45.00 F	*45.00 F
8	1		*REAR BUMPER RH REFLECTOR GARNISH	Deformed	65.00 F	*65.00 F
9	1		*REAR BUMPER DIFFUSER	Deformed	280.00 F	*280.00 F
10	6		*REAR BUMPER DIFFUSER CLIP	Necessary	12.00 F	*12.00 F
11	1		*REAR BUMPER REINFORCEMENT	Dented	195.00 F	*195.00 F
12	1		*REAR END PANEL	Dented	380.00 F	*380.00 F
13	1		*REAR RH FENDER PROTECTOR	Cracked	165.00 F	*165.00 F
14	1		*REAR WINDSCREEN MOULDING	Not Necessary	100.00 F	*- F
15	1		*REAR EXHAUST BOX	Repair	1,500.00 F	*- F
16	1		*REAR EXHAUST EXTENSION	Not Necessary	380.00 FS	*- FS
17	1		*SET REAR BUMPER REFLECTOR	Cracked	280.00 FS	*280.00 FS
18	1		*SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **4,982.00** **1,847.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIT REAR WINDSCREEN GLASS	New	120.00	0.00
2	TUFFKOTE	New	120.00	50.00
3	WIRING	New	80.00	30.00
4	SPRAY PAINTING	New	800.00	600.00
5	LABOUR CHARGES	New	800.00	700.00
Gross Labour Cost (S\$)			1,920.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >