

ASS. REC. D76

REF: CF/MSG/19014589/Cqd3ⁿ²

Special Instruction:

Surveyor: SIMON

ASSIGNMENT (Office)

Menmen

From (Person): peng xu shi

of MSLG

Date/Time: 14/8/2019 @ 4:44pm

Estimated Cost: Bill to:

DI / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLA 6395Z

Insured:

at Workshop n/s Green & fur spray

Tel: 6546 3092

of BIK 2011 Bedok north Ave # #01-2004

Policy No: 1000909460

Claim No: 228816

Sum Insured:

Excess: \$500.00

Make of Veh: (Client's Record)

D.O.A. 26/06/2019

CA (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle: IN/OUT

| Date/Time | Action/Instruction |
|------------------|--------------------------------------------------------------------------------------------------------------------------------|
| | SLA 6395Z - X |
| 05/9/19 @ 4.54pm | confirmed with Janice final fee \$ 5940.20, 7 days. (Red to 3382.80, 37%) MV. \$ 75k (est); LTR: \$ 40787; NV: \$ 34213. |
| | |
| | |

RECEIVED 0 0 SEP 2019

150
11
161



MSIG Insurance (Singapore Pte. Ltd) (Co. Reg. No 200412212G)
 4 Shenton Way, #27-01, SGX Centre 2, Singapore 068807
 Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg

Executive
Claims Services

Green Star

Inspection Report

Type of Survey:

| | |
|----------------------|-----------|
| OD - Excess | / \$500 - |
| TP Without Prejudice | |

Vehicle Data:

| | |
|---------------------|----------|
| Odometer reading | 93166 km |
| Engine No | |
| VIN No | |
| Engine capacity | |
| Engine modification | |

Vehicle Details:

| | |
|---------------------|-----------|
| Vehicle Reg No | SLA 6395Z |
| Make | Toyota |
| Model | Wish 1.8A |
| Passenger capacity | 07 |
| Paint colour & code | Red |
| Paint type | |

Vehicle Condition:

| Seviceable | Yes / No |
|------------|----------|
| Handbrake | |
| Footbrake | |
| Steering | |
| Body | |
| Paint | |

Vehicle Extras:

| | |
|-----------------|-----------------|
| In-built camera | Yes / <u>No</u> |
| Modification | Yes / <u>No</u> |

| Tyre Condition: | Tread mm | Size | Condition |
|-----------------|----------|---------------------|-----------|
| Front right | 5 | Dunlop 195 / 65 R15 | |
| Front left | 5 | " | |
| Rear left | 4 | " | |
| Rear right | 4 | " | |

General Data:

| | |
|---------------------|-----------|
| Date of accident | 26-06-19 |
| Date of inspection | 03-07-19 |
| Date of assignment | 02-07-19 |
| Inspection location | Greenstar |

Painting Process:

| | |
|----------------------|--|
| Prepare off vehicle | |
| Painting off vehicle | |
| Neither (default) | |

| Cost Details: | Repairer | Adjuster |
|---------------------------|----------|----------|
| Parts | | |
| Supplementary | | |
| Miscellaneous | | |
| Body Labour | | |
| Paint labour | | |
| Paint material | | |
| TOTAL | | |
| Towing | | |
| Excess | | |
| Total less excess | | |
| Estimated days for repair | | |

Body Panel Repair:

| | |
|------------------------------|--|
| Panel repair calculator used | |
| Yes / No | |

Remarks:

| | |
|-------------------|---------------------------|
| Lump / Global Sum | |
| Reason(s) | Margin Repair / Fast-line |

Others:

| |
|--|
| |
| |
| |

Repair Authorised
Date:

| |
|--|
| |
|--|



MSIG

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200412212G)
 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581
 Tel 6220 9644, Fax 6225 6371
 www.msig.com.sg

To: MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

From: MSIG Insurance (Singapore) Pte. Ltd.
 16 Raffles Quay
 #24-01 Hong Leong Building
 Singapore 048581

Attn: Pang Xiu Shi

Date: 04 Jul 2019

Preliminary Advice

| | | | |
|--------------------|------------------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Vehicle No | : SLA6395Z | Accident Date | : 26/06/2019 |
| Make | : TOYOTA WISH | Policy No. | : 1000909460 |
| Assignment Date | : 02/07/2019 | Excess | : S\$500.00 |
| Date of Inspection | : 03/07/2019 | Est. Duration of Repair | : 7.00 |
| Inspection At | : GREEN STAR SPRAY PAINTING (HQ) BLK 3011 BEDOK NORTH AVENUE 4 #01-2004 BEDOK INDUSTRIAL PARK E SINGAPORE 489977 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front right portion.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 9,123.00 |
| Revised Amount | :S\$ | 5,740.20 |
| Check Items (Estimated) | :S\$ | 1,749.00 |
| Total | :S\$ | |
| Lump Sum Repair | :S\$ | |

Total Loss Consideration

| | | |
|--------------------|------|-----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 75,000.00 |
| COE / PARF Rebate | :S\$ | 40,745.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | |

Remarks

- (x) The vehicle is economical/~~not economical~~ for repair.
- () The above survey was conducted on a 'without prejudice' basis.

A Member of MS & AD INSURANCE GROUP



...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|------------------------------------------------|---------|---------------|-------------|------------------------------------------------------|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 26 Jun 2019 | | 14 Aug 2019 16:44 Assign | | | | New Assignment Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|-----------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------|------------------------|------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: Sharin bin Mohamad Sani , ID: S1800971D, Tel: +6598573531, Email: sharin.mdsani@gmail.com | | | | | | | | | |
| Vehicle Reg. No.: | SLA6395Z | Date of Loss: | 26/06/2019 09:00 - :59 [39 Months and 17 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | OD / 228816 | Policy/Cover Note No.: | 1000909460 (Comprehensive) Coverage: 08/03/2019 - 08/03/2020 | | | | | | |
| | | Excess: | S\$500.00 | | | | | | |
| Repairer: | GREEN STAR SPRAY PAINTING (HQ) BLK 3011 BEDOK NORTH AVENUE 4 #01-2004 BEDOK INDUSTRIAL PARK E, 489977 Bedok - Tel: | | | | | | | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pang Xiu Shi - 6594 2586] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2019] | | | | | | | | |
| Driver/Custodian: | Sharin bin Mohamad Sani (51 / Male) , NRIC: S1800971D, Tel: +6598573531 Email: sharin.mdsani@gmail.com | | | | | | | | |
| Adj Asg. Remarks: | As per Jason instruction, re-assigned to LKK to follow-up this case. | | | | | | | | |
| ASSOCIATED MAIL RECEIVED | | | | View All Compose Case Mail | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS <input type="checkbox"/> | | | | View All Search Tasks Create New Task Complete | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Shiau Chan (LKKAuto)

From: Sales-GreenStarSP <sales@greenstarsp.com>
Sent: Thursday, 5 September 2019 4:54 PM
To: Shiau Chan (LKKAuto)
Subject: RE: OWN DAMAGE CLAIM : REPAIR COSTS FOR SLA 6395Z (Finalisation)

Dear Mr. Shiau,

We accepted the said offered (\$5,740.20 before GST and excess \$500.00 and 7 repair days.)

Thanks & Best Regards,
Janice

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Thursday, September 05, 2019 4:20 PM
To: sales@greenstarsp.com
Cc: admin@greenstarsp.com
Subject: RE: OWN DAMAGE CLAIM : REPAIR COSTS FOR SLA 6395Z (Finalisation)

Dear Jane,

WITHOUT PREJUDICE

Offer final fig \$5,740.20 before GST and excess \$500.00 and 7 repair days.

Kindly check and confirm.

Please note that the finalisation subject to insurer's approval.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sales-GreenStarSP <sales@greenstarsp.com>
Sent: Monday, 2 September 2019 10:57 AM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Cc: admin@greenstarsp.com
Subject: RE: OWN DAMAGE CLAIM : REPAIR COSTS FOR SLA 6395Z (Finalisation)
Importance: High

Dear Shiau,

Please see attached photos for your reference..

Kind Regards,

Jane



MSIG

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
www.msia.com.sg

PRELIMINARY ADVICE

OD Claim / TP Claim

Attn : _____ Policy No : _____
Date : _____ Claim No : _____

Insured Vehicle No : SLA 6395A Date of Accident : 26-06-19
TP Vehicle No : - Place of Survey : Greenstar
Make & Model : Toyota Wish 1.8A Date of Survey : 03-07-19

Point of Impact / Damages :
Front Right

| | | |
|-----------------------|--------------------|--|
| Recommended Reserve : | | |
| Repairer's Estimate | <u>:\$ 9123.00</u> | |
| Interim Adjustment | <u>:\$ 5740.20</u> | |
| Check Items | <u>:\$ 1749.00</u> | |

Proposed : Part by Part / Lump Sum Repair Excess : \$ 500/-

Estimate Repair Period : 07 days

Pre-accident Market Value (for total loss consideration) : \$ 75000/-

COE / PARF to owner : \$ 140745.00

Vehicle within / not within limit of economical repair.

Others :

Surveyed By :

Celine Fong (LKKAuto)

From: Winnie Chua <pingping_chua@sg.msig-asia.com>
Sent: Wednesday, 14 August 2019 10:02 AM
To: assignments
Subject: FW: REPAIR COSTS FOR SLA6395Z (Victor's case)

Dear Denise,

As spoken, please help to finalise this case. Tks.

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey)

Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Sales-GreenStarSP [<mailto:sales@greenstarsp.com>]
Sent: Tuesday, 13 August, 2019 4:10 PM
To: Jason Sim <Jason_Sim@sg.msig-asia.com>
Cc: admin@greenstarsp.com; Pang Xiu Shi <xiushi_pang@sg.msig-asia.com>
Subject: RE: REPAIR COSTS FOR SLA 6395Z
Importance: High

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Hi Mr. Jason,

As spoken to you a while ago, please send the details of the new person in charge to the case mentioned above.

Thank you..

Kind Regards,

Jane

GREEN STAR SPRAY PAINTING

Blk 3011 Bedok North Ave 4

#01-2004 Bedok Ind Park E Singapore 489977

Tel: +6546 3092 | Fax: 6545 2066 | Website: www.greenstarsp.com

CONFIDENTIALITY NOTE:

The information and/or files attached to this email message may contain information which is confidential or privileged. The information is intended for the use of the individual or entity to whom it is addressed. If you are not the intended recipient, be aware that any disclosure, copying, distribution, or other use of the contents of the information contained within the email message and/or any attachments is prohibited. If you have received this email message in error, please contact the above named sender immediately to notify him of the error, and delete the email message.

From: Sales-GreenStarSP [mailto:sales@greenstarsp.com]
Sent: Friday, July 19, 2019 12:51 PM
To: 'Pang Xiu Shi' <xiushi_pang@sg.msig-asia.com>; 'Victor_Seng@sg.msig-asia.com' <Victor_Seng@sg.msig-asia.com>
Cc: 'admin@greenstarsp.com' <admin@greenstarsp.com>
Subject: RE: REPAIR COSTS FOR SLA 6395Z
Importance: High

Dear Sirs,

Any update on the above vehicle claim.

Kind Regards,

Jane

GREEN STAR SPRAY PAINTING

Blk 3011 Bedok North Ave 4

#01-2004 Bedok Ind Park E Singapore 489977

Tel: +6546 3092 | Fax: 6545 2066 | Website: www.greenstarsp.com

CONFIDENTIALITY NOTE:

The information and/or files attached to this email message may contain information which is confidential or privileged. The information is intended for the use of the individual or entity to whom it is addressed. If you are not the intended recipient, be aware that any disclosure, copying, distribution, or other use of the contents of the information contained within the email message and/or any attachments is prohibited. If you have received this email message in error, please contact the above named sender immediately to notify him of the error, and delete the email message.

From: Sales-GreenStarSP [mailto:sales@greenstarsp.com]
Sent: Tuesday, July 16, 2019 6:25 PM
To: 'Pang Xiu Shi' <xiushi_pang@sg.msig-asia.com>; 'Victor_Seng@sg.msig-asia.com' <Victor_Seng@sg.msig-asia.com>
Cc: 'admin@greenstarsp.com' <admin@greenstarsp.com>
Subject: FW: REPAIR COSTS FOR SLA 6395Z
Importance: High

Hi Mr. Victor,

Please see attached revised estimate repair cost for the above vehicle.

Thank you..

Kind Regards,

Jane

GREEN STAR SPRAY PAINTING

Blk 3011 Bedok North Ave 4

#01-2004 Bedok Ind Park E Singapore 489977

Tel: +6546 3092 | Fax: 6545 2066 | Website: www.greenstarsp.com

From: Sales-GreenStarSP [<mailto:sales@greenstarsp.com>]

Sent: Saturday, July 13, 2019 6:09 PM

To: 'Victor_Seng@sg.msg-asia.com' <Victor_Seng@sg.msg-asia.com>

Cc: 'admin@greenstarsp.com' <admin@greenstarsp.com>; 'admin@greenstarsp.com' <admin@greenstarsp.com>

Subject: REPAIR COSTS FOR SLA 6395Z

Importance: High

Hi Mr. Victor,

Please see attached estimate repair cost for the above vehicle.

Thank you..

Kind Regards,

Jane

GREEN STAR SPRAY PAINTING

Blk 3011 Bedok North Ave 4

#01-2004 Bedok Ind Park E Singapore 489977

Tel: +6546 3092 | Fax: 6545 2066 | Website: www.greenstarsp.com

CONFIDENTIALITY NOTE:

The information and/or files attached to this email message may contain information which is confidential or privileged. The information is intended for the use of the individual or entity to whom it is addressed. If you are not the intended recipient, be aware that any disclosure, copying, distribution, or other use of the contents of the information contained within the email message and/or any attachments is prohibited. If you have received this email message in error, please contact the above named sender immediately to notify him of the error, and delete the email message.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person

Other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------|---------------------------------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 0971D |
| Vehicle Details | |
| Vehicle No.: | SLA6395Z |
| Vehicle to be Exported: | Yes |
| Intended Deregistration Date: | 28 Jun 2019 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | WISH 1.8 CVT |
| Primary Colour: | Red |
| Manufacturing Year: | 2015 |
| Engine No.: | 2ZR1712372 |
| Chassis No.: | JTDGG20W40J003598 |
| Maximum Power Output: | 105.0 kW (140 bhp) |
| Open Market Value: | \$19,953.00 |
| Original Registration Date: | 09 Mar 2016 |
| First Registration Date: | 09 Mar 2016 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$19,953.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 08 Mar 2026 |
| PARF Rebate Amount: | \$14,964.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 08 Mar 2026 |
| COE Category: | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$38,610.00 |
| COE Rebate Amount: | \$25,823.00 |
| Total Rebate Amount: | \$40,787.00 |

The information contained herein is correct as at 28 Jun 2019

OK

> Back to OneMotoring

Enquire Transfer Fee

| Vehicle Details | | | |
|------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------|---------------------|---------------------------|
| Vehicle No. : | SLA6395Z | | |
| Vehicle Type : | P11 - Passenger Station Wagon/Jeep/Land Rover | | |
| Vehicle Attachment 1 : | No Attachment | | |
| Vehicle Scheme : | Normal | | |
| Vehicle Make : | TOYOTA | | |
| Vehicle Model : | WISH 1.8 CVT | | |
| Chassis No. : | JTDGG20W40J003598 | | |
| Propellant : | Petrol | | |
| Engine No. : | 2ZR1712372 | | |
| Engine Capacity : | 1798 cc | | |
| Maximum Power Output : | 105.0 kW (140 bhp) | | |
| Maximum Laden Weight : | 1935 kg | | |
| Unladen Weight : | 1360 kg | | |
| Year Of Manufacture : | 2015 | | |
| Original Registration Date : | 09 Mar 2016 | | |
| Lifespan Expiry Date : | - | | |
| COE Category : | B - Car above 1600cc or 97kW (130bhp) | | |
| Quota Premium : | \$38,610.00 | | |
| COE Expiry Date : | 08 Mar 2026 | | |
| Road Tax Expiry Date : | 08 Mar 2020 | | |
| PARF Eligibility Expiry Date : | 08 Mar 2026 | | |
| Inspection Due Date : | 08 Mar 2021 | | |
| Intended Transfer Date : | 05 Sep 2019 | | |
| CO2 Emission : | 159.00 (g/km) | | |
| CEV/VES Rebate Utilised Amount : | - | | |
| CO Emission : | - | | |
| HC Emission : | - | | |
| NOx Emission : | - | | |
| PM Emission : | - | | |
| Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable. | | | |
| Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred. | | | |
| Amount Payable | | | |
| | Amount Before GST (S\$) | GST Amount (S\$) | Amount After GST (S\$) |
| Transfer Fee : | 25.00 | - | 25.00 |
| Total Amount Payable : | | | 25.00 |

You may print this page for reference.

OK

Print

MSIG Insurance (Singapore) Pte. Ltd.



OD Claim
Excess: \$ 500/-
(Authorized / Revert)



TP Claim
(Without Prejudice)

Vehicle No. SLA 6395 Z

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 07

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 03/07/19.

Victor_Seng@sg.msig-asia-com



GREEN STAR SPRAY PAINTING

Workshop: Blk 3011 Bedok North Ave 4 #01-2004 Bedok Industrial Park E (S) 469977
 Tel: 8546 3092 Fax: 8545 2066

REPAIR COST & REPLACEMENT OF PARTS

Registratio SLA6395Z TOYOTA WISH

CHASSIS NO: JTDGG20W40J003598

| Repairs Estimate | | Price | 10% | Amount |
|-------------------------------------------------------|-------------------------------------------------------------------------------------------------------|--------------------|-----------|--------------------------|
| Replacement of Damaged Panels/Parts and Labour Charge | | | | |
| 1 | Replacement of Damaged Panels/Parts RH FRONT FENDER / Deformed | \$ 855.00 | \$ 85.50 | \$ 940.50 |
| 2 | FRONT BUMPER / Deformed | \$ 584.00 | \$ 58.40 | \$ 642.40 |
| 3 | HEADLAMP RH / cracked | \$ 1,239.00 | \$ 123.90 | \$ 1,362.90 |
| 4 | BANANA LEAF RH / Torn | \$ 165.00 | \$ 16.50 | \$ 181.50 |
| 5 | FOG COVER RH / cracked | \$ 75.00 | \$ 7.50 | \$ 82.50 |
| 6 | BUMPER RETAINER RH / cracked | \$ 59.00 | \$ 5.90 | \$ 64.90 |
| 7 | FRONT BONNET / Deformed | \$ 710.00 | \$ 71.00 | \$ 781.00 |
| 8 | REINFORCEMENT PANEL ? X R | \$ 301.00 | \$ 30.10 | \$ 331.10 |
| 9 | WATER TANK / Deformed | \$ 95.00 | \$ 9.50 | \$ 104.50 |
| 10 | FRONT GRILLE X NN | \$ 398.00 | \$ 39.80 | \$ 437.80 |
| 11 | SUPPORT PANEL ? X R | \$ 1,289.00 | \$ 128.90 | \$ 1,417.90 |
| 12 | WINDSCREEN X NN | \$ 605.00 | \$ 60.50 | \$ 665.50 |
| 13 | WINDSCREEN MOULDING X NN | \$ 55.00 | \$ 5.50 | \$ 60.50 |
| Labour Charges | | | | |
| 1 | Dismantling damaged parts and attachments, repair & reshape dented panels, align & refit attachments. | \$ 580.00 | | \$ 580.00 500 |
| 2 | Respraying special colour for the front bumper, front bonnet, other affected areas | \$ 900.00 | | \$ 900.00 800 |
| 3 | Spray anti rust proofing, check wiring, lighting system & focus front headlamps | \$ 450.00 | | \$ 450.00 200 |
| 4 | Wheel alignment & balancing | \$ 120.00 | | \$ 120.00 80 |
| SUB TOTAL | | \$ 8,480.00 | | \$ 9,123.00 |
| GST 7% | | \$ 593.60 | | \$ 638.61 |
| TOTAL | | \$ 9,073.60 | | \$ 9,761.61 |



GREEN STAR SPRAY PAINTING

Windsor, ON N7L 5B9 (North York) 487-0894 (South York) 496-1087
 Tel: 416-291-2222 Fax: 416-291-2222

REPAIR COST & REPLACEMENT OF PARTS

Registration: SLA6395Z TOYOTA WISH

CHASSIS NO: JT03520W4J0603291

| Repairs Estimate | | | | |
|--------------------------------------------------------|-------------------------------------------------------------------------------------------------------|-------------|-----------|--------------------------|
| Replacement of Damaged Panels/Parts and Labour Charges | | Price | 10% | Amount |
| 1 | Replacement of Damaged Panels/Parts RH FRONT FENDER <i>Deformed</i> | \$ 555.00 | \$ 55.50 | \$ 940.50 |
| 2 | FRONT BUMPER <i>Deformed</i> | \$ 531.00 | \$ 53.10 | \$ 642.40 |
| 3 | HEADLAMP RH <i>cracked</i> | \$ 1,139.00 | \$ 113.90 | \$ 1,362.90 |
| 4 | BANANA LEAF RH <i>Torn</i> | \$ 165.00 | \$ 16.50 | \$ 181.50 |
| 5 | FOG COVER RH <i>cracked</i> | \$ 75.00 | \$ 7.50 | \$ 82.50 |
| 6 | BUMPER RETAINER RH <i>cracked</i> | \$ 59.00 | \$ 5.90 | \$ 64.90 |
| 7 | FRONT BONNET <i>Deformed</i> | \$ 710.00 | \$ 71.00 | \$ 781.00 |
| 8 | REINFORCEMENT PANEL <i>X</i> | \$ 301.00 | \$ 30.10 | \$ 331.10 |
| 9 | WATER TANK <i>Deformed</i> | \$ 95.00 | \$ 9.50 | \$ 104.50 |
| 10 | FRONT GRILLE <i>X</i> | \$ 398.00 | \$ 39.80 | \$ 437.80 |
| 11 | SUPPORT PANEL <i>Deformed X R</i> | \$ 1,289.00 | \$ 128.90 | \$ 1,417.90 |
| 12 | WINDSCREEN <i>X</i> | \$ 605.00 | \$ 60.50 | \$ 665.50 |
| 13 | WINDSCREEN MOULDING <i>X</i> | \$ 55.00 | \$ 5.50 | \$ 60.50 |
| Labour Charges | | | | |
| 1 | Dismantling damaged parts and attachments, repair & reshape dented panels, align & refit attachments. | \$ 530.00 | | \$ 530.00 500 |
| 2 | Respraying special colour for the front bumper, front bonnet, other affected areas | \$ 900.00 | | \$ 900.00 800 |
| 3 | Spray anti-rust proofing, check wiring, lighting system & focus front headlamps | \$ 450.00 | | \$ 450.00 200 |
| 4 | Wheel alignment & balancing | \$ 120.00 | | \$ 120.00 80 |
| SUB TOTAL | | \$ 8,480.00 | | \$ 9,123.00 |
| GST 7% | | \$ 593.60 | | \$ 638.61 |
| TOTAL | | \$ 9,073.60 | | \$ 9,761.61 |

* Supplementary

- 1) Front absorber / cracked *replaced 500 above item (2)*
- 2) Front Right inner shield / cracked
- 3) Front Right panel cover / cracked

re-survey
 04-07-2019 @ 1330 hrs
 Victor.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CF/MSG19014589/CQD3N2

Date: 16/09/2019

REFERENCE

Insured/Claimant: Sharin bin Mohamad Sani Policy No: 1000909460
Date of Loss: 26/06/2019 Nature of Claim: OD Claim No: 228816

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA6395Z Engine No: 2ZR1712372
Make & Model: TOYOTA WISH, 1.8 (A) Chassis No: JTDGG20W40J003598
Reg. Date: 09/03/2016 (Man. Year: 2015) Odometer: 93166 km
Colour: Red
Engine Capacity: 1798 cc
Market Value/New Car Price: S\$75,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 4 mm
Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

| | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts | 7,073.00 | 4,160.20 | 2,912.80 | 41.18 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,050.00 | 1,580.00 | 470.00 | 22.93 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 9,123.00 | 5,740.20 | 3,382.80 | 37.08 |
| - Excess (S\$) | 500.00 | 500.00 | 0.00 | 0.00 |
| (S\$) | 8,623.00 | 5,240.20 | 3,382.80 | 39.23 |
| + GST 7.00/7.00% (S\$) | 603.61 | 366.81 | 236.80 | 39.23 |
| Nett Amount (S\$) | 9,226.61 | 5,607.01 | 3,619.60 | 39.23 |

INSPECTION

Date of Assignment: 14/08/2019

Date Inspected: 03/07/2019 Inspected At:

GREEN STAR SPRAY PAINTING (HQ)
BLK 3011 BEDOK NORTH AVENUE 4
#01-2004 BEDOK INDUSTRIAL PARK
E
Singapore 489977

Estimated Period of Repair: 7.0 days

Adjuster: SIMON HO LEONG CHUAN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 16 Sep 2019) |
| Parts: M1-MPV | TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SLA6395Z) | |
| Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount | |
|-----|-----|----------|----------------------------|---------------|--------------------------------------------------|-----------------|-----------------|
| 1 | 1 | | *RH FRONT FENDER (WCP) | Deformed | 855.00 F | *855.00 F | |
| 2 | 1 | | *FRONT BUMPER (WCP) | Deformed | 584.00 F | *584.00 F | |
| 3 | 1 | | *HEADLAMP RH (WCP) | Cracked | 1,239.00 F | *1,239.00 F | |
| 4 | 1 | | *BANANA LEAF RH (WCP) | Torn | 165.00 F | *165.00 F | |
| 5 | 1 | | *FOG COVER RH (WCP) | Cracked | 75.00 F | *75.00 F | |
| 6 | 1 | | *BUMPER RETAINER RH (WCP) | Cracked | 59.00 F | *59.00 F | |
| 7 | 1 | | *FRONT BONNET (WCP) | Deformed | 710.00 F | *710.00 F | |
| 8 | 1 | | *REINFORCEMENT PANEL (WCP) | Repair | 301.00 F | *-F | |
| 9 | 1 | | *WATER TANK (WCP) | Deformed | 95.00 F | *95.00 F | |
| 10 | 1 | | *FRONT GRILLE (WCP) | Repair | 398.00 F | *-F | |
| 11 | 1 | | *SUPPORT PANEL (WCP) | Repair | 1,289.00 F | *-F | |
| 12 | 1 | | *WINDSCREEN (WCP) | Not Necessary | 605.00 F | *-F | |
| 13 | 1 | | *WINDSCREEN MOULDING (WCP) | Not Necessary | 55.00 F | *-F | |
| | | | | | Sub Total (\$\$) | 6,430.00 | 3,782.00 |
| | | | | | + Margin on L,N Items 10.00/10.00% (\$\$) | 643.00 | 378.20 |
| | | | | | Total Parts (\$\$) | 7,073.00 | 4,160.20 |

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|----------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | DISMANTLING DAMAGED PARTS AND ATTACHMENTS,REPAIR & RESHAPE DENTED PANELS,ALIGN & REFIT ATTACHMENTS | New | 580.00 | 500.00 |
| 2 | RESPRAYING SPECIAL COLOUR FOR THE FRONT BUMPER,FRONT BONNET,OTHER AFFECTED AREAS | New | 900.00 | 800.00 |
| 3 | SPRAY ANTI RUST PROOFING,CHECK WIRING,LIGHTING SYSTEM & FOCUS FRONT HEADLAMPS | New | 450.00 | 200.00 |
| 4 | WHEEL ALIGNMENT & BALANCING | New | 120.00 | 80.00 |
| Gross Labour Cost (S\$) | | | 2,050.00 | 1,580.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >