

Surveyor:

Rasm.

DOI:

ASSIGNMENT

26/8/19.

Date / Time:

20/08/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SLM 4491D

Claim No. : S9M01XMO

Name of Insured : XI CHEN

Policy No. :

Insured Tel No. : HP:

Make / Model :

Excess Sec II : \$5 D.O.A : 18/08/2019 16:50

Place of Accident : TAMAN WARNA

Is driver the owner? (YES / ☒ NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: ☒ YES / NO)

OI GIA REPORT: ☒ YES / NO : TP GIA REPORT: ☒ YES / NO

Insured Liability : % Final ? Yes / No

SMG 8510B



INSRS:
WSP: KAH MOTOR
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	SMG 8510B - X	SLM 4491D - X	STAGE	DATE / PIC
20/08/19	OINR. To send out first letter. File pass to Su Li.		Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	
			After call ltr to OI:	
			Documentation Check List:	Handler Typist
			Notification ltr (if non-pickup)	☒
			After call ltr to OI:	☒
			Authorisation To Act:	☒
			Release Voucher:	☒
			Final Repair Bill:	☒
			Car Rental Invoice:	☒
			Towing Invoice:	☒
			LTA / GIA :	☒
			Medical Bill:	☒
			PIR:	☒
			Mandate/Reject Instruction:	☒
			LOD	☒
			Payment Breakdown Form:	☒
			Post-Repair Photos:	☒
			Others:	☒

PRELIMINARY ADVICE	Date/Time:	Sent By:
--------------------	------------	----------

FINALIZATION	Date/Time:	Confirm with:	Confirm by: Rasm.
Repair Cost:	\$5 4644.11	(6 days) Reduction:	\$3403.62 @ 42

FINAL SETTLEMENT	Date/Time: 18/11/2020	Confirm with: Diamond	Email ☐ Call ☐
------------------	-----------------------	-----------------------	--

Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	9.
Repair Cost:	\$5 5022.70		

Loss of Rental (LOR):	\$5 -	(days)	
Loss of Use (LOU):	\$5 480.00	(560) x 8 days)	
Loss of Income (LOI):	\$5 -	(5 x days)	

LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search	\$5 -		

Medical:	\$5 -		
Disbursement:	\$5 -	(e.g. Tow/ Independent)	
Legal Cost	\$5 -		

Total:	\$5 5022.70	Global Sum \$5:	
--------	-------------	-----------------	--

FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	\$5 5502.70	Name 1:	Kan Motor Co. Sdn. Bhd.
Payee 2: (Strike if N.A.)	\$5	Name 2:	
Payee 3: (Strike if N.A.)	\$5	Name 3:	

✓ GIA.

ASL REC BY: Pam

REF:

ASM(CAXA)

14595/1113

741H

ASSIGNMENT

From:

Date:

26/8/2019

Veh No:

SMG 8510B

Yr Regn:

2019 Jan

Estimated Cost:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

SMG 8510B

Make:

Honda Civic 1.6 VT

cc 1597

at Workshop m/s

Kah Motor

Colour:

Grey

A/C:

Insured / Std / NI / NA

of

No. 255 Alexandra Road

Sp. Reading

010279

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

MRHFC 5650 JT 001973

Policy No:

C/No:

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Mowing
Ng sin HaiModi: Nil / SRim / STD A/Rim or


(Policy Condition)

Tyre Size:

F:

215/55R16

R:

Remark: The veh had commenced its
repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Bal. or Market Value:

89K

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

6

days

Res.:

Yes or No

D.O.A.

18/08/19

D.O.I.

26/08/19

Lum Sum:

1-3-1 %

3 Val:

Yes or No

'Survey held at

KAH MOTOR

CA / REV / REP. / 24 HRS ^{1up}

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	P/P \$4694.11 (Red- \$3403.62 / 42.1)
	18/08/2019
	6 repair days + 1 PRS + 1 sat + 1 sun = 9 days.

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Wheel end (\$

Survey Fee:

Transportation:

S + PS \$

Parked

Other

Total

Report Format:

Lump Sum / L&B: (\$



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 20/12/2019

Survey Details:

Date of loss	18-Aug-19
Date of appointment	20-Aug-19
Date of survey	26-Aug-19
Location of survey	KAH MOTOR CO SDN BERHAD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SMG8510B
Make and Model	HONDA CIVIC 1.6 VTI CVT
Date of registration	2-Jan-19
Parf Rebate	
Market Value	\$ 89,000.00
Parf Rebate	\$ 35,417.00
Nett Loss	\$ 53,583.00

Repair details:

Initial Estimate	\$ 8,070.21
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 694.11
Check items (estimate)	\$ -
Labour	\$ 4,000.00
Total	\$ 4,694.11
Lump Sum(if applicable)	\$ -

Number of days for repair	6
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

06 RECOMMENDED REPAIR DAYS + 1PRS + 1SAT + 1SUN = 9DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 5,022.70	W/GST
Loss of use	\$ 540.00	9days x \$60.00
Loss of rental	\$ -	
Loss of income	\$ -	
LTA search fees	\$ -	
Others	\$ -	
Proposed Total	\$ 5,562.70	



<MANDATE IA> - S9M01XMO {ACCIDENT INVOLVING SLM 4491D & SMG 8510B ON 18/08/2019}

Type

🔔 Question

Message

LIABILITY: 100% BOLA S9 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$5562.70 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL 20/12/2019

Reply



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE PTE LTD	Document No.	: SQT19003733	Page	1
	: 8 SHENTON WAY	Date	: 26. Aug 2019		
	: #27-01 AXA TOWER	Customer No.	: WZA006		
	: SINGAPORE 068811	Svc Advisor	:		
Registration No	: SMG8510B	Engine No	: R16B25502262		
Chassis No	: MRHFC5650JT001973	Date Time	: 26. Aug 2019 8:37:35 AM		
Model	: CIVIC 1.6 VTI YM2018	Surveyor Name	:		
Owner's Name	: NG TECK KHIM	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 18/8/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (JND:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
67510-TEA-T002Z	PANEL RR.DOOR <i>bt</i>	1	717.50	25	538.12	37.67	575.79
72810-TEA-T01	WEATHERSTRIP R.RR.DOOR <i>7.5m</i>	1	96.40	25	72.30	5.06	77.36
04646-TEA-T002Z	PANEL SETL.RR.OUTSIDE <i>repair</i>	1	711.60	25	533.70	37.36	571.06
71800-TEA-T012B	GARNISH ASSY.R.SIDE SILL <i>scr</i>	1	117.80	25	88.35	6.18	94.53
72721-TEA-T01	GARNISH RR.DOOR QUARTER OUT <i>7.5m</i>	1	23.50	25	17.62	1.23	18.85
72930-TEA-T01	GARNISH ASSY.RR.DOOR SASH <i>7. cut</i>	1	28.30	25	21.22	1.49	22.71
72910-TEA-T01	MOLDING ASSY.RR.DOOR <i>7. cut</i>	1	25.20	25	18.90	1.32	20.22
	Sum Item				1290.21	90.31	1,380.52
BOSUN	SUNDRIES <i>Nu</i>	1	100.00 <i>30</i>		100.00	7.00	107.00
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	560.00		560.00	39.20	599.20
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	380.00		380.00	26.60	406.60
BMI03D	REMOVE & INSTALL RHS COMPARTMENT LININGS	1	560.00 <i>250</i>		560.00	39.20	599.20
BKFE22K	STRAIGHTEN ALIGN RR R FENDER AND RENEW ALL DAMAGE	1	3000.00 <i>1400</i>		3000.00	210.00	3210.00
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (4P)	1	2000.00 <i>1350</i>		2000.00	140.00	2140.00
	Sum Labor				6600.00	462.00	7,062.00
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00 <i>X^n</i>		180.00	12.60	192.60

Printed on 26/8/2019 8:51:20 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

An amount of \$52.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

Registration No : SMG8510B

Chassis No : MRHFC5650JT001973

Model : CIVIC 1.6 VTI YM2018

Owner's Name : NG TECK KHIM

Ins Policy No. :

Date of Accident : 18/8/2019

Document No. : SQT19003733 Page 2

Date : 26. Aug 2019

Customer No. : WZA006

Svc Advisor :

Engine No : R16825502262

Date | Time : 26. Aug 2019 8:37:35 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
Sum Ext. Service					180.00	12.60	192.60

Survey By

Date & Time

Excess

Status

Signature

Repair - Hp 900/10568

26/08/19 @ 1535

6 days

Signature

Repair before paint

Total Amount 8,070.21 564.91 8,635.12

Total (Inclusive of GST) 8,635.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurer

Acknowledged by Repairer

Signature:

Date:

Printed on 26/8/2019 8:51:20 AM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages

GST Amount is calculated from individual line(s)

An amount of \$50.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0047553 / AXA INSURANCE
 Chassis No: MRHFC5650JT001973
 License No: SMG8510B
 Mileage: 8849
 Engine No: R16B25502262

Document No: SVO19054759
 Printed By: SHNG
 Order Date: 26. August 2019
 Order Time: 4:56:42 PM
 Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:NG TECK KHIM						
	OWNER INSURER:TOKIO						
	ACC DATE:18/08/2019						
	SURVEYED BY:RASUL						
	DATE:26/08/2019						
	REF NO:						
	TP INSURER:AXA						
	TP VEH:SLM491D						
	SUPPLEMENTARY						
67510-TEA-T00ZZ	PANEL,R.R.DOOR	1	717.50	25	538.12 ✓	37.67	575.79
71800-TEA-T01ZB	GARNISH ASSY,R.SIDE SILL	1	117.80	25	88.35 ✓	6.18	94.53
72930-TEA-T01	GARNISH ASSY,R.R.DOOR SASH	1	26.30	25	21.22 ✓	1.49	22.71
72910-TEA-T01	MOLDING ASSY,R.R.DOOR	1	25.20	25	18.90 ✓	1.32	20.22
72925-TEA-T01	MOLDING ASSY,R.R.DRINNER	1	29.20	25	21.90(✓)	1.53	23.43
72956-TEA-T01	GARNISH,R.R.CENTER CORNER	1	1.30	25	0.97(✓)	0.07	1.04
72828-TEA-T01	SEAL,R.R.DOOR LOWER	1	6.20	25	4.65(✓)	0.33	4.98
	SUM PARTS:				694.11	48.59	742.70
BOSUN	0701	1	30.00 ✓		30.00	2.10	32.10
	SUNDRIES						
BKDR22R	0671	1	560.00 ✓		560.00	39.20	599.20
	REMOVE & TRANSFER ITEMS TO NEW						
	RR R DR. ADJUST						
	& ALIGN INCLUDING FITTINGS ON						
	ATTACHMENT ITEMS.(N)						
BC012R	0701	1	380.00 ✓		380.00	26.60	406.60
	RESET VEHICLE SMART ENTRY						
	SYSTEM						
BMI03D	1757	1	280.00 ✓		280.00	19.60	299.60
	REMOVE & INSTALL RHS						
	COMPARTMENT LININGS						
	GARNISHES.(N)						
BKFE22K	0671	1	1,400.00 ✓		1,400.00	98.00	1,498.00
	STRAIGHTEN ALIGN RR R FENDER AND						
	RENEW ALL DAMAGE.						
	PARTS						
BP04R	1610	1	1,350.00 ✓		1,350.00	94.50	1,444.50
	SPRAY PAINTING ON REPAIRED OR						
	REPLACED AREAS.(4P)						
	SUM LABOUR:				4,000.00	280.00	4,280.00
	TOTAL SGD				4,894.11	328.59	5,022.70

Total Payable (SGD)

5,022.70

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0047553 / NG TECK KHIM
Chassis No: MRHFC5650JT001973
License No: SMG8510B
Mileage: 8849
Engine No: R16B25502262

Document No: SVO19054759
Printed By: SHNG
Order Date: 26. August 2019
Order Time: 4:56:42 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incl GST
	SUPPLEMENTARY						
72925-TEA-T01	MOLDING ASSY,R.RR.DRINNER <i>cut</i>	1	29.20	25	21.90 ✓	1.53	23.43
72956-TEA-T01	GARNISHR.RR.CENTER CORNER <i>cut</i>	1	1.30	25	0.97 ✓	0.07	1.04
72826-TEA-T01	SEALRR.DOOR LOWER <i>per</i>	1	6.20	25	4.65 ✓	0.33	4.98
	SUM PARTS:				27.52	1.93	29.45
	TOTAL SGD				27.52	1.93	29.45

Total Payable (SGD)

29.45

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SMG8510B
Chassis No : MRHFC5650JT001973
Model : CIVIC 1.6 VTI YM2018
Owner's Name : NG TECK KHIM
Ins Policy No. :
Date of Accident : 18/8/2019

Document No. : SQT19003733
Date : 26. Aug 2019
Customer No. : WZA006
Svc Advisor :
Engine No : R16B25502262
Date | Time : 26. Aug 2019 8:37:35 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
67510-TEA-T00ZZ	PANEL,R.R.DOOR <i>bl ✓</i>	1	717.50	25	538.12	37.67	575.79
72810-TEA-T01	WEATHERSTRIP,R.RR.DOOR <i>?</i>	1	96.40	25	72.30	5.06	77.36
04646-TEA-T00ZZ	PANEL SETL,RR.OUTSIDE <i>repair</i>	1	711.60	25	533.70	37.36	571.06
71800-TEA-T01ZB	GARNISH ASSY,R.SIDE SILL <i>scr -</i>	1	117.80	25	88.35	6.18	94.53
72721-TEA-T01	GARNISHR,RR.DOOR QUARTER OUT <i>?</i>	1	23.50	25	17.62	1.23	18.85
72930-TEA-T01	GARNISH ASSYR,RR.DOOR SASH <i>?</i>	1	28.30	25	21.22	1.49	22.71
72910-TEA-T01	MOLDING ASSYR,RR.DOOR <i>?</i>	1	25.20	25	18.90	1.32	20.22
	Sum Item				1290.21	90.31	1,380.52
BOSUN	SUNDRIES	1	100.00 <i>30</i>		100.00	7.00	107.00
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	560.00		560.00	39.20	599.20
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	380.00		380.00	26.60	406.60
BMI03D	REMOVE & INSTALL RHS COMPARTMENT LININGS	1	560.00 <i>250</i>		560.00	39.20	599.20
BKFE22K	STRAIGHTEN ALIGN RR R FENDER AND RENEW ALL DAMAGE.	1	3000.00 <i>1400</i>		3000.00	210.00	3210.00
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	2000.00 <i>1350</i>		2000.00	140.00	2140.00
	Sum Labor				6600.00	462.00	7,062.00
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00 <i>X</i>		180.00	12.60	192.60

Printed on 26/8/2019 8:51:20 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above-estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.

28097.73



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SMG8510B
Chassis No : MRHFC5650JT001973
Model : CIVIC 1.6 VTI YM2018
Owner's Name : NG TECK KHIM
Ins Policy No. :
Date of Accident : 18/8/2019

Document No. : SQT19003733 **Page** 2
Date : 26. Aug 2019
Customer No. : WZA006
Svc Advisor :
Engine No : R16B25502262
Date | Time : 26. Aug 2019 8:37:35 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Sum Ext. Service					180.00	12.60	192.60

Survey By : Person - Hp 90010568
Date & Time : 26/08/19 @ 1535
Excess : _____
Status : _____
Signature : [Signature]

Total Amount 8,070.21 564.91 8,635.12
Total (Inclusive of GST) 8,635.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insulation Company

Acknowledged by Repairer:
Signature:
Date:

Printed on 26/8/2019 8:51:20 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.



Service Request Details

Claim

S9M01XMO

Reference

None 

P: Sin Hai

Loss Date

August 18, 2019

T: 10-03 9.m

Report Date

Aug 20, 2019 9:23:11 AM

V: Out

Request Date

August 20, 2019

E: ✓

Due Date

August 27, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SMG8510B

Model

CIVIC-1.6 (A)

Service Address

...

Primary Contact/Insured

XI CHEN

11A SOMMERVILLE ROAD, 358311, Singapore

CELENECHEN@PRUDADVISER.COM.SG

Claim Handler

KHONG Lynn

68804892

lynn.khong@axa.com.sg

Additional Instructions

NON-REPORTED

1

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>
Sent: Monday, 19 August, 2019 7:13 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: [EXTERNAL] RE: 3rd party direct settlement SMG8510B/ & your insured SLM4491D/DOA:18/08/2019/Est \$
Attachments: MRM43444566.PDF
Categories: Santosh

Dear Motor Claims,

Please refer to the attached pdf, we are assisting our insured vehicle **SMG8510B** to file a 3rd party claim against your insured vehicle **SLM4491D** and to request for direct settlement.

Please assist and expedite to check the claim liability soonest.

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai
Kah Motor Co. Sdn. Bhd
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937
DID: 6471 5419
HP: 9072 1769
E-mail: shng@honda.com.sg



Visit our
Facebook page

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

**Kah Motor Co. Sdn. Bhd.**

(A Member of Oriental Holdings Berhad)

6A Mandai Estate, SINGAPORE 729903

Mandai Parts Centre

Phone No. : +65 6841 3838 Fax No. :

AXA INSURANCE PTE LTD

MOTOR CLAIMS DEPT

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE, 068811

Customer Code : CU0129734

Payment Term : 30 Days

Service Tax Invoice

GST Reg No. M200050223

Company Ref. No. S60FC13803

Invoice No.	:	SINV-BM19002040
Invoice Date	:	26/11/19
Order No.	:	SVO19054759
Reference	:	
Job Card No.	:	10925
Date/Time Received	:	26/08/19 / 8:37:35 AM
Licence No.	:	SMG8510B
Model	:	CIVIC 1.6 VTI YM2018
Car Chassis No.	:	MRHFC5650JT001973
Car Engine No.	:	R16B25502262
Mileage	:	8849
Service Advisor	:	NG SIN HAI 1596
Served By	:	SHNG
Page	:	1

No.	Description	Qty.	UoM	U. Price	Disc %	Amount	7% GST Amount	Incid GST
	TP DIRECT SETTLEMENT (J/NO:)							
	OWNER:NG TECK KHIM							
	OWNER INSURER:TOKIO							
	ACC DATE:18/08/2019							
	SURVEYED BY:RASUL							
	DATE:26/08/2019							
	REF NO:							
	TP INSURER:AXA							
	TP VEH:SLM4491D							
BOSUN	0701 SUNDRIES	1	Hours	30.00		30.00	2.10	32.10
BKDR22R	0671 REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST & ALIGN INCLUDING FITTINGS ON ATTACHMENT ITEMS.(N)	1	Hours	560.00		560.00	39.20	599.20
BC012R	0701 RESET VEHICLE SMART ENTRY SYSTEM	1	Hours	380.00		380.00	26.60	406.60
BMI03D	1757 REMOVE & INSTALL RHS COMPARTMENT LININGS GARNISHES.(N)	1	Hours	260.00		260.00	19.60	299.60
BKFE22K	0671 STRAIGHTEN ALIGN RR R FENDER AND RENEW ALL DAMAGE. PARTS	1	Hours	1,400.00		1,400.00	98.00	1,498.00
BP04R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (4P) SUPPLEMENTARY	1	Hours	1,350.00		1,350.00	94.50	1,444.50
67510-TEA-T00ZZ	PANELR.RR.DOOR	1	Each	717.50	25	538.12	37.67	575.79
71800-TEA-T01ZB	GARNISH ASSY,R.SIDE SILL	1	Each	117.80	25	88.35	6.18	94.53
72930-TEA-T01	GARNISH ASSYR.RR.DOOR SASH	1	Each	28.30	25	21.22	1.49	22.71
72910-TEA-T01	MOLDING ASSYR.RR.DOOR	1	Each	25.20	25	18.90	1.32	20.22
72925-TEA-T01	MOLDING ASSY,R.RR.DRINNER	1	Each	29.20	25	21.90	1.53	23.43
72956-TEA-T01	GARNISHR.RR.CENTER CORNER	1	Each	1.30	25	0.97	0.07	1.04
72828-TEA-T01	SEALRR.DOOR LOWER	1	Each	6.20	25	4.65	0.33	4.98

Sum Labor	4,000.00	280.00	4,280.00
-----------	----------	--------	----------

Sum Item	694.11	48.59	742.70
----------	--------	-------	--------

Total SGD	4,694.11	328.59	5,022.70
-----------	----------	--------	----------

Total Payable (SGD)	5,022.70
---------------------	----------

Printed by: SHNG on 26 Nov 2019 at 1:28:17 PM

This is a computer generated invoice. No signature is required. Please review your bill and advise us of any errors or omissions.
Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s).

Payment due upon Payment Terms as stated above. Please make payment strictly in accordance with payment terms.
Interest will be charged at 2% per month on overdue amounts.

Please give us your
feedback by scanning
the QR Code using
mobile device.



 Re:<MANDATE IA> - S9M01XMO {ACCIDENT INVOLVING SLM 4491D & SMG 8510B ON 18/08/2019}

Type

 Question

Message

Dear CCL, COR to proceed, LOU to offer up to 8 days. Thanks

[Reply](#)



Kah Motor Co. Sdn. Bhd.
A Member of Oriental Holdings Berhad
Body Repair & Paint Centre
6A Mendal Estate
Singapore 729903
Tel : +65 6841 3838
Fax : +65 6362 5015
www.honda.com.sg

M/s: **AXA Insurance Singapore Pte Ltd**
8 Shenton Way
#27-01
Singapore 068811
Attn: **Motor Claims Department**

Date : 9/12/2019

Your ref : SLM4491D

Dear Sir / Madam,

Our ref : SMG8510B

THIRD PARTY DIRECT SETTLEMENT

ACCIDENT INVOLVING SMG8510B & SLM4491D ON 18/08/2019

We refer to the item(s) marked ☒ below:

☒ We refer to your email dated 02/09/2019.

☒ We enclosed herewith the repair invoice / Third Party Direct Settlement Agreement.

☒ Kindly forward the discharge voucher for our client's signature within **2 weeks** via email to **desmondtoh@honda.com.sg**.

☐ We return your discharge voucher duly completed.

☒ Kindly expedite settlement of the following :-

Repair Cost	S\$5,022.70 payable to Kah Motor Co. Sdn. Bhd.
Loss of use	S\$60.00 x 9 days : S\$540.00 payable to NG TECK KHIM.
	[Inclusive of 1 PRI, 1 Saturday, 1 Sunday.]

☒ Kindly let us have your cheque made in favour of the above mentioned name(s) for our transmission as soon as possible.

☒ Enclosures

☒ Repair/Excess Bill
☐ Rental Invoice
☐ Others: _____

☒ Letter of Authority
☐ GIA Search

☐ LTA Search

Thank you.

Yours faithfully,

Ng Sin Hai



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19014595/R1ga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:LYNN

Date : 20-01-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLM 4491D	Veh. Inspected	SMG 8510B
Policy No.	CN819966	Coverage (\$)	0.00
Claim No.	S9M01XMO	Excess (\$)	0.00
Assign From		Assign Date	20/08/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC 1.6 VTI	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MRHFC5650JT001973	Colour	GREY
Odometer	010279	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R16	HANKOOK	6 mm
L/H Front Tyre	215/55 R16	HANKOOK	6 mm
R/H Rear Tyre	215/55 R16	HANKOOK	6 mm
L/H Rear Tyre	215/55 R16	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/08/2019	Inspection Date	26/08/2019
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 8510B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	100.00	30.00
1	PANELR.RR.DOOR (SN) (CONSISTENT)	BENT	538.12	538.12
1	WEATHERSTRIP,R.RR.DOOR (SN) (CONSISTENT)	SERVICEABLE	72.30	-
1	PANEL SETL.RR.OUTSIDE (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	533.70	-
1	GARNISH ASSY,R.SIDE SILL (SN) (CONSISTENT)	SCRATCHED	88.35	88.35
1	GARNISHR.RR.DOOR QUARTER OUT (SN) (CONSISTENT)	SERVICEABLE	17.62	-
1	GARNISH ASSYR.RR.DOOR SASH (SN) (CONSISTENT)	CUT	21.22	21.22
1	MOLDING ASSYR.RR. DOOR (SN) (CONSISTENT)	CUT	18.90	18.90
1	MOLDING ASSY,R.RR.DRINNER (SN) (CONSISTENT) (ADDITIONAL)	CUT	21.90	21.90
1	GARNISHR.RR.CENTER CORNER (SN) (CONSISTENT) (ADDITIONAL)	CUT	0.97	0.97
1	SEALRR.DOOR LOWER (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	4.65	4.65
			1,417.73	724.11
	LABOUR			
	REMOVE & TRANSFER ITEMS TO NEW RR R DR ADJUST .		560.00	560.00
	RESET VEHICLE SMART ENTRY SYSTEM.		380.00	380.00
	REMOVE & INSTALL RHS COMPARTMENT LININGS.		560.00	280.00
	STRAIGHTEN ALIGN RR R FENDER AND RENEW ALL DAMAGE.INCLUSIVE OF THE REPAIR OF PANEL SETL.RR.OUTSIDE.		3,000.00	1,400.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		2,000.00	1,350.00
			6,500.00	3,970.00
	GRAND TOTAL		7,917.73	4,694.11
	RECOMMENDED COST OF REPAIRS			4,694.11

Report Ref No. CC4/ASM19014595/R1ga3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on this Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	S9M0DXMO
Reference	CC4/ASM19014595/R1.g3a2 
Loss Date	18 August 2019
Report Date	20 Aug 2019 9:23:11 AM
Request Date	7 October 2019
Due Date	

Actions

Next Step

Wait for: Approve Invoice

Approve Invoice

Vehicle Information	
Incident Vehicle Registration #	SMC2810B
Make	TMVD HONDA
Model	CIVIC-1.6 (A)
Service Address	

...

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TPH)

Type of Loss
Third Party Vehicle Damage

Services
Pending verification - Direct Settlement

Primary Contact/Insured

Xi CHEN
11A SOMMERVILLE ROAD, 358311, Singapore
CELENECHEN@PRUDADVISER.COM.SG

Claim Handler

KHONG Lynn
68804892
lynn.khong@axa.com.sg

Additional Instructions

NON-REPORTED

Messages Invoices History Documents Assessment Metrics Notes

Document Type

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Accident Statement	Reports & Statement	GIA Report	Merimen	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UNLOADED
LKKInvoicet1 (1).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
LKKInspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
TP FINAL EST LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
PAIRF COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
MANDATE IA DO 2012019.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
TP - IA.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	2 September 2019
TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	2 September 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 EMAIL FROM WORKSHOP FOR TP REG.mng	Letters and Correspondence	Others	NIKAM Santosh Pandurang	20 August 2019
 P1918374_RN_00002_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	NIKAM Santosh Pandurang	20 August 2019