

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SMG8510B

Chassis No : MRHFC5650JT001973

Model : CIVIC 1.6 VTI YM2018

Owner's Name : NG TECK KHIM

Ins Policy No. :

Date of Accident : 18/8/2019

Document No. : SQT19003733

Date : 26. Aug 2019

Customer No. : WZA006

Svc Advisor :

Engine No : R16B25502262

Date | Time : 26. Aug 2019 8:37:35 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
67510-TEA-T00ZZ	PANELL.RR.DOOR <i>bl ✓</i>	1	717.50	25	538.12	37.67	575.79
72810-TEA-T01	WEATHERSTRIP,R.RR.DOOR <i>?</i>	1	96.40	25	72.30	5.06	77.36
04646-TEA-T00ZZ	PANEL SETL.RR.OUTSIDE <i>repair</i>	1	711.60	25	533.70	37.36	571.06
71800-TEA-T01ZB	GARNISH ASSY,R.SIDE SILL <i>sla -</i>	1	117.80	25	88.35	6.18	94.53
72721-TEA-T01	GARNISHR.RR.DOOR QUARTER OUT <i>?</i>	1	23.50	25	17.62	1.23	18.85
72930-TEA-T01	GARNISH ASSYR.RR.DOOR SASH <i>?</i>	1	28.30	25	21.22	1.49	22.71
72910-TEA-T01	MOLDING ASSYR.RR.DOOR <i>?</i>	1	25.20	25	18.90	1.32	20.22
	Sum Item				1290.21	90.31	1,380.52
BOSUN	SUNDRIES	1	100.00 <i>30</i>		100.00	7.00	107.00
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	560.00		560.00	39.20	599.20
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	380.00		380.00	26.60	406.60
BMI03D	REMOVE & INSTALL RHS COMPARTMENT LININGS	1	560.00 <i>250</i>		560.00	39.20	599.20
BKFE22K	STRAIGHTEN ALIGN RR R FENDER AND RENEW ALL DAMAGE.	1	3000.00 <i>1400</i>		3000.00	210.00	3210.00
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	2000.00 <i>1350</i>		2000.00	140.00	2140.00
	Sum Labor				6600.00	462.00	7,062.00
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00 <i>X</i>		180.00	12.60	192.60

Printed on 26/8/2019 8:51:20 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SMG8510B
Chassis No : MRHFC5650JT001973
Model : CIVIC 1.6 VTI YM2018
Owner's Name : NG TECK KHIM
Ins Policy No. :
Date of Accident : 18/8/2019

Document No. : SQT19003733 Page 2
Date : 26. Aug 2019
Customer No. : WZA006
Svc Advisor :
Engine No : R16B25502262
Date | Time : 26. Aug 2019 8:37:35 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Sum Ext. Service					180.00	12.60	192.60

Survey By

Date & Time

Excess

Status

Signature

Resur - 4p 90010568
26/08/19 @ 1535

6 days

Signature

Repur before paint

Total Amount 8,070.21 564.91 8,635.12
Total (Inclusive of GST) 8,635.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 26/8/2019 8:51:20 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.