

1kg
Not Authorized
Repairing B4 painting
4 days



ESTIMATE TO REPAIR

VEHICLE NO. : SMK 4192 R
MAKE : HONDA
MODEL : FIT 1.3 GF CVT
YEAR : 2019
CHASSIS NO : GK31343914

SURVEYOR NAME :
DATE OF SURVEY : 26-Aug-19
TIME OF SURVEY :

DATE : 20-Aug-19
DATE OF ACCIDENT : 18-Aug-19
THIRD-PARTY REF : SLV 935 U / AXA

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ 580.00
2 pcs	Rear Bumper Retainer		\$ 13.50	0150.1	\$ 27.00
1 pc	Rear End Panel				\$ 390.00
1 pc	Rear End Panel Garnish				\$ 60.80
1 pc	Tailgate				\$ 814.20
1 pc	Tailgate Emblem				\$ 35.10
1 set	Rear Windscreen Moulding				\$ 120.00
					\$ 2,027.10
	Less 20%				\$ 405.42
					\$ 1,621.68
1 set	Rear Bumper Sensor	S.Nett			\$ 200.00
1 pc	Rear Number Plate	S.Nett			\$ 40.00
1 tube	Rear Windscreen Sealant	S.Nett			\$ 40.00
	To putty and spray painting				\$ 550.00
	To transfer tailgate fittings				\$ 80.00
	To remove & refix rear windscreen				\$ 120.00
	To send vehicle for no. plate seal				\$ 60.00
	To anti-rust				\$ 50.00
	Labour charges				\$ 600.00
	Paint \$1576.30				
	-20%				\$315.26
					\$1261.04
	S/N \$80.00				
	Labour \$1270.00				
	PPR \$2611.04				
TG/RA-	Total				\$ 3,461.68
	04 days				

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd