

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 23.08.2019

Time: 09:07:29

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305325775
REGN NO : SHC2817L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 01.03.2019
DATE/TIME IN : 19.08.2019 11:35
ACCIDENT DATE : 18.08.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0576-G	IONIQVC PANEL ASSY-QUARTE	1 L	1,788.30 ^{1,462.30}	20.00	1,430.64
0002 04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52
0003 28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1 N	80.00	2.00-	80.00
0004 03-01-0104-2061-G	IONIQV1/3 CAP ASSY-WHEEL	1 L	346.40	20.00	277.12

SUB-TOTAL : 2,155.28

JOB NATURE

0000 L	MERIMEN	11.00
0001 PB	PANEL BEATING	600.00
0002 SP	SPRAYPAINT CHARGE	800.00
0003 20-204	REMOVE/REFIX UPHOLSTERY ASST REPAIR	200.00

SUB-TOTAL : 1,611.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 23.08.2019

REPAIR ESTIMATE

Time: 09:00:55

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305325775
REGN NO : SHC2817L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 01.03.2019
DATE/TIME IN : 19.08.2019 11:3
ACCIDENT DATE : 18.08.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,766.28

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Aug 2019 11:02 Sendback Est	20 Aug 2019 11:13 S\$6,351.36	21 Aug 2019 09:03 Edit Adj Rpt	S\$3,600.28 Edit Estimates	S\$3,600.28 View Rpt		Pending for Survey Report Cancel Case
Supp #1	22 Aug 2019 10:28	22 Aug 2019 10:32 S\$277.12	22 Aug 2019 10:32			(Combined)	Combined with Main Uncombine Suppl.
Supp #2	23 Aug 2019 09:02	23 Aug 2019 09:04 S\$367.52	23 Aug 2019 09:04			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	LION CITY RENTALS PTE LTD, Co. Reg. No.: 201504621K		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SHC2817L	Date of Loss:	18/08/2019 09:00 - :59 [5 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1906399	Policy/Cover Note No.:	MK000573 (Third Party Only) Coverage: 25/06/2019 - 24/02/2020
Vehicle Reg. No. (Insured):	SLK2069P	Policy No. (Claimant):	
		Excess:	S\$1,600.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Telma Gomez - 65926402]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 30/08/2019]		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHC2817L (M1906399)
[SLK2069P]
TP
CTPL
Aug 18 2019 9:00AM
[LION CITY RENTALS PTE LTD]
ComfortDelGro Engineering Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports

No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	1 per page	Thumbnail	Print
1	20/08/19 11:14	Repairer Estimates	1	Load HTM	
2	22/08/19 10:32	Repairer Estimates Suppl. #1	1	Load HTM	
3	23/08/19 09:04	Repairer Estimates Suppl. #2	1	Load HTM	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	20/08/19 19:08	Accident Statement From: SC - Reg. No: SLK2069P, Claimant: LION CITY RENTALS PTE LTD	1	Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page	Thumbnail	Print
1	22/08/19 09:12	General View	1	Load JPG	✓
2	22/08/19 09:12	General View	1	Load JPG	✓
3	22/08/19 09:12	General View	1	Load JPG	✓
4	22/08/19 09:12	General View	1	Load JPG	✓
5	22/08/19 09:12	General View	1	Load JPG	✓
6	22/08/19 09:12	General View	1	Load JPG	✓
7	22/08/19 09:12	General View	1	Load JPG	✓
8	22/08/19 09:12	General View	1	Load JPG	✓
9	22/08/19 09:12	General View	1	Load JPG	✓
10	22/08/19 09:12	General View	1	Load JPG	✓
11	22/08/19 09:12	General View	1	Load JPG	✓
12	22/08/19 09:12	General View	1	Load JPG	✓
13	22/08/19 09:12	General View	1	Load JPG	✓
14	22/08/19 09:12	General View	1	Load JPG	✓
15	22/08/19 09:12	General View	1	Load JPG	✓
16	22/08/19 09:12	General View	1	Load JPG	✓
17	22/08/19 09:12	General View	1	Load JPG	✓
18	22/08/19 09:12	General View	1	Load JPG	✓
19	22/08/19 09:12	General View	1	Load JPG	✓
20	22/08/19 09:12	General View	1	Load JPG	✓
21	22/08/19 09:12	General View	1	Load JPG	✓
22	22/08/19 09:12	General View	1	Load JPG	✓
23	22/08/19 09:12	General View	1	Load JPG	✓
24	22/08/19 09:12	General View	1	Load JPG	✓
25	22/08/19 09:12	General View	1	Load JPG	✓
26	22/08/19 09:12	General View	1	Load JPG	✓
27	22/08/19 09:12	General View	1	Load JPG	✓
28	22/08/19 09:12	General View	1	Load JPG	✓

Assessment Reports			1 per page	☒	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
29	22/08/19 09:12	General View		Load JPG	☒
30	22/08/19 09:12	General View		Load JPG	☒
31	22/08/19 09:12	General View		Load JPG	☒
32	22/08/19 09:12	General View		Load JPG	☒
33	22/08/19 09:12	General View		Load JPG	☒
34	22/08/19 09:12	General View		Load JPG	☒
35	22/08/19 09:12	General View		Load JPG	☒
36	22/08/19 09:12	General View		Load JPG	☒
37	23/08/19 09:28	Reinspection Photo		Load JPG	☒
38	23/08/19 09:28	Reinspection Photo		Load JPG	☒
39	23/08/19 09:28	Reinspection Photo		Load JPG	☒
40	23/08/19 09:28	Reinspection Photo		Load JPG	☒
41	23/08/19 09:28	Reinspection Photo		Load JPG	☒
42	23/08/19 09:28	Reinspection Photo		Load JPG	☒
43	23/08/19 09:28	Reinspection Photo		Load JPG	☒
44	23/08/19 09:28	Reinspection Photo		Load JPG	☒
45	23/08/19 09:28	Reinspection Photo		Load JPG	☒
46	23/08/19 09:28	Reinspection Photo		Load JPG	☒

Documentation				1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Print
1	27/08/19 14:39	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee		Load PDF	
2	27/08/19 14:44	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee		Load PDF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	20/08/19 13:02	E-filed GIA report		Load PDF	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	05/09/19 13:00	Letter of Demand from Third Party		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#)
[Save](#)
[Print](#)

There are no document checklists configured.

Show Remarks To: ☐ Repairer ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI19014602/K1YF3S2
Date: 06/09/2019

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MK000573
Claimant Vehicle No: SHC2817L Insured Vehicle No: SLK2069P
Date of Loss: 18/08/2019 Nature of Claim: TP Claim No: M1906399

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC2817L Engine No: G4LEJU191245
Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Chassis No: KMHC851CVKU141237
Reg. Date: 01/03/2019 (Man. Year: 2018) Odometer: 51977 km
Colour: Blue
Engine Capacity: 1580 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: Michelin 9 mm Rear Left Side: Michelin 9 mm
Front Right Side: Michelin 9 mm Rear Right Side: Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,575.00	2,139.28	2,435.72	53.24
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,410.00	1,450.00	960.00	39.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,996.00	3,600.28	3,395.72	48.54
+ GST 7.00/7.00% (S\$)	489.73	252.02	237.71	48.54
Nett Amount (S\$)	7,485.73	3,852.30	3,633.43	48.54

INSPECTION

Date of Assignment: 21/08/2019 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected: 20/08/2019 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969
Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 06 Sep 2019)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC2817L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER LH	Buckled	1,768.30 FL	*1,768.30 FL
2	1		*REAR FENDER INNER LINING LH	Serviceable	73.60 FL	*- FL
3	1		*REAR WINDSCREEN MOULDING	Not Necessary	28.20 FL	*- FL
4	1		*REAR DOOR LH	Repair	1,789.90 FL	*- FL
5	1		*REAR TYRE RIM LH	Serviceable	1,124.20 FL	*- FL
6	1		*SEALANT REAR WINDSCREEN	Not Necessary	23.00 F	*- F
7	1		*REAR DOOR COMFORT DELGRO AND APPS STICKER	Necessary	80.00 F	*80.00 F
8	1		*ROCKER PANEL GARISH (LH) (NPA)	Repair	-	*- FL
Supplementary #1						
9	1		*REAR WHEEL RIM CAP	Grazed	346.40 FL	*346.40 FL
Supplementary #2						
10	1		*REAR BUMPER ASSY	Cracked	459.40 FL	*459.40 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,693.00	2,654.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,118.00	514.82
Total Parts (\$\$)	4,575.00	2,139.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	600.00
2	SPRAYPAINT	New	900.00	800.00
3	WIRING	New	50.00	0.00
4	TUFF KOTE	New	50.00	0.00
5	REMOVE/REFIX CUSHION & REAR UPHOLSTERY	New	150.00	50.00
6	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	0.00
7	REMOVE/REFIX REVERSE SENSOR	New	100.00	0.00
8	TRANSFER DOOR PARTS	New	120.00	0.00
9	REAR WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (S\$)			2,410.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >