

ASS. REC. BY:

REF: CS/MSG 19014603/EGF 302

Special Instruction:

Survivor: Steve

ASSIGNMENT (Office)From (Person): Kenny Ong Thiam Beng of MSG Date/Time: 21.8.19 9.48 p.m

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SHB 1632P Insured: SLL 70500at Workshop m/s SMRT Tel: 64662622of 60 woodland Industrial Park E4Policy No: 29114756 MCF Claim No: 603300

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 12.8.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 21.8.19 9.53 a.m Person Contacted: shanti H.O.D. Endorsement: _____Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 1632P-X
	SLL 70500 - (C6/A3G130108121) RIW9352
	D.O.A - 07/06/2018
<u>21/8/19 @ 5.01 PM</u>	<u>noted to Kenny Ong via Messenger.</u>

ASS. REC. BY:

Steve

REF:

MS19

ASSIGNMENT

From:

Date:

21/8/19

Veh No:

SHB 1632 P

Yr Regn:

16/5/14

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover /

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SHB 1632 P

Make:

Toyota Prius

C.C

1798

at Workshop m/s

SMRT

Colour

N/A

A/C:

Insured / Std / NI / NA

of

Woodlands Depot

Sp. Reading

353574

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

J70KN364605742427

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:


195/50R15

R:

11

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Veh Make

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

5

mm

R/Bal.

5

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

5

mm

L/Bal.

5

mm

Est. Repairs:

8

days

Res.:

Yes or No

D.O.A.

18/8/19

D.O.I.

21/8/19

Lum Sum:

%

3 Val.:

Yes or No

Survey held at

SMRT

CA / REV / REP. / 24 HRS^{up}

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

9/9/19

Findia Conf. \$5400, 8 days (Per Juan) (Red \$ 21428.15, 80%)

08/19/2019

SLL 79500

9/9/2019

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

8

1)

☐

Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Week end (\$

Survey Fee:

250

Transportation:

S + RS, SI

Photos

Others

11

Report Format:

MER-TP

Lump Sum / LPA: (\$

5400

TOTAL

261

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Aug 2019		21 Aug 2019 09:48 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS		[Created by insurer]																						
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G																							
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K																							
Vehicle Reg. No.:	SHB1632P	Date of Loss:	18/08/2019 23:00 - :59 [63 Months and 2 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	TP	Policy/Cover Note No.:	29114756MKF (Comprehensive) Coverage: 01/02/2019 - 31/01/2020																					
Vehicle Reg. No. (Insured):	SLL7050D	Policy No. (Claimant):																						
		Excess:																						
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628																							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Keny Ong Thiam Beng - 6643 1309]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/08/2019]																							
Driver/Custodian (Insured):	YUE WAI KIT (), NRIC: S12287871 Email:																							
Adj Asg. Remarks:	MANUAL ASSIGNED CAR IN. OI:Grab. Liab: Dispute. Assign: LKK Auto Consultants Pte Ltd. Contact: Shanti @ 6866 2671/2.																							
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail																						
There are no mail for this case.																								
<div> ALL ASSOCIATED TASKS </div> <div> View All Search Tasks Create New Task Complete </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Keny Ong Thiam Beng

Date: 22 Aug 2019

Preliminary Advice

Insured Vehicle No	: SLL7050D		
TP Vehicle No	: SHB1632P	Accident Date	: 18/08/2019
Make	: TOYOTA PRIUS	Assignment Date	: 21/08/2019
Date of Inspection	: 21/08/2019	Est. Duration of Repair	: 8.00
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS) 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body & o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,898.15
Revised Amount	:S\$	5,885.36
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,885.36

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB1632P
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR6027190
Chassis No.:	JTDKN36U605742427
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	16 May 2014
First Registration Date:	16 May 2014
Transfer Count:	0
Actual ARF Paid:	\$8,368.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 May 2022
PARF Rebate Amount:	\$5,857.00
Intended COE Rebate Details	
COE Expiry Date:	15 May 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$60,414.00
COE Rebate Amount:	\$20,631.00
Total Rebate Amount:	\$26,488.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 21 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/08/2019 15:24
Date Of Accident	18/08/2019 23:00
Exact Location Of Accident	SUNTEC CITY TOWER THREE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1632P
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	CHIN YONG SHENG JOHNSON
NRIC No	S7905347C
Date Of Birth	06/02/1979
Occupation	OUTDOOR
Date Of Driving Pass	03/02/2009
Driving Experience	10 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20190819/7037 MY VEHICLE WAS ON THE LEFT LANE PROCEEDING STRAIGHT. THE OTHER VEHICLE ON MY RIGHT LANE TURNED LEFT AND HIT ME. I ENDED UP ON THE CURB. THE SIDE OF MY VEHICLE HIT THE SIGNBOARD.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL7050D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YUE WAI KIT
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	CHIN YONG SHENG JOHNSON
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHB1632P
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.DECLARATION ~~MR.~~

I/We declare the foregoing particulars are true in every respect.



Driver's Signature _____ 19/8/19.
(If driver is not the policyholder)
Date & Time:

19/8/2019

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(If driver is not the policyholder)

Date & Time:

19/8/19.

[Signature]
19/8/2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190819/7037

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20190819/7037

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/08/2019 22:32		Vide Report No.: A/20190818/0161		Station Diary No.:
Informant's Particulars				
Name of Informant: CHIN YONG SHENG JONSON		Address: 333D YISHUN STREET 31 #04-139 SINGAPORE 764333		
ID Type / ID No.: NRIC NO / S7905347C		Contact No.: Home/Office: Mobile: 86877861		
Nationality: SINGAPORE CITIZEN		Email: jonsonchinys@yahoo.com		
Sex: Male	Age: 40	Date of Birth: 06/02/1979	Type of Informant: Driver	
Race: Chinese		Language: English	Institution / School Name:	
Occupation:		Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 18/08/2019 22:58	Type of Location:
Location: TEMASEK BOULEVARD				
Weather:		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHB1632P	Car	TOYOTA	Prius	Brown	Slightly Damaged	0
SLL7050D	Car	MAZDA	3	Blue	Slightly Damaged	2

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190819/7037

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20190819/7037

CONTINUATION OF REPORT

Driver			
Name	CHIN YONG SHENG JONSON	ID No.	S7905347C
Related Vehicle	SHB1632P (Car)	Contact No.	86877861
Hospital/Clinic	338 FAMILY CLINIC	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	19/08/2019	Date Discharge	19/08/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Passenger			
Name	Unknown Passenger	ID No.	NIL
Related Vehicle	SLL7050D (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	Unknown Passenger	ID No.	NIL
Related Vehicle	SLL7050D (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

My vehicle was on the left lane proceeding straight. The other vehicle on my right lane turned left and hit me. I ended up on the curb. The side of my vehicle hit the signboard.



**SINGAPORE
POLICE FORCE**



T/20190819/7037

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20190819/7037

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
ONG CHEE HIEN
Contact No.: 65476437

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
19/08/2019 22:32

Classification Of Case:



Case Details

Case Reference Number : TAX/08/19/2060
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1632P

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-8129-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : MSIG Insurance (S) Pte Ltd
 Accident Date and Time : 18/08/2019 03:00 PM
 Vehicle Age(In Months) : 63

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main		6505517	BUMPER FRT	1	482.00	482.00	30.00	337.40	Replace	1	0	Repair	X R
Standard	Main		6505515	BUMPER SUPPORT F/RH	1	76.40	76.40	30.00	53.48	Replace	0	0	Not Given	X NN
Standard	Main		6505516	BUMPER SUPPORT F/LH	1	76.40	76.40	30.00	53.48	Replace	0	0	Not Given	X NN
Standard	Main		6505541	BUMPER GRILLE SUB-ASSY,LOWER	1	311.10	311.10	30.00	217.77	Replace	0	0	Not Given	X NN
Standard	Main		6505616	BUMPER LIP FRT	1	139.60	139.60	30.00	97.72	Replace	0	0	Check	X NN
Standard	Main		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	127.70	30.00	89.39	Replace	0	0	Not Given	X NN
Standard	Main		6505304	RADIATOR HOSE LOWER	1	42.40	42.40	30.00	29.68	Replace	0	0	Not Given	X NN
Standard	Main		6505303	RADIATOR TOP HOSE NO 1	1	42.40	42.40	30.00	29.68	Replace	0	0	Not Given	X NN
Standard	Main		6505557	FENDER FRT/RH	1	723.40	723.40	30.00	506.38	Replace	1	506.38	Replace	X / 00
Standard	Main		6505640	NAME PLATE (HYBRID)	1	51.90	51.90	30.00	36.33	Replace	1	36.33	Replace	/ REC
Standard	Main		6505553	FENDER LINER FRT/RH	1	171.70	171.70	30.00	120.19	Replace	1	120.19	Replace	/ CR4
Standard	Main		6505658	WHEEL DISC. FRONT	1	1,484.20	1,484.20	30.00	1,038.94	Replace	1	0	Repair	X R
Standard	Main		6503707	TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Given	X NN
Total Spare Part Cost									17,674.16	Surveyor Total			2,629.44	
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)			20	
Final Spare Part Cost									14,139.33	Final Sur Total			2,103.55	

3845.94

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main		6505606	MOULDING BODY, RH	1	673.60	673.60	30.00	471.52	Replace	1	471.52	Replace	✓ CR4
Standard	Main		6505524	QUARTER GLASS FRT/RH	1	234.90	234.90	30.00	164.43	Replace	0	0	Not Giv	✓ X N/A
Standard	Main		6505528	DOOR FRT/RH	1	894.40	894.40	30.00	626.08	Replace	1	626.08	Replace	✓ 00
Standard	Main		6505482	DOOR HINGE UPPER FRT/RH	1	80.50	80.50	30.00	56.35	Replace	0	0	Not Giv	✓ X N/A
Standard	Main		6505484	DOOR HINGE UPPER RR/RH	1	90.10	90.10	30.00	63.07	Replace	0	0	Not Giv	✓ X N/A
Standard	Main		6506195	CHECK ASSY, FR DOOR,	1	150.30	150.30	30.00	105.21	Replace	0	0	Not Giv	✓ X N/A
Standard	Main		6505600	MIRROR ASSY, RH	1	1,307.10	1,307.10	10.00	1,176.39	Replace	0	0	Not Giv	✓ X N/A
Standard	Main		6505466	MIRROR LAMP RH	1	65.30	65.30	10.00	58.77	Replace	0	0	Not Giv	✓ X N/A
Standard	Main		6505486	DOOR RR/RH	1	954.50	954.50	30.00	668.15	Replace	1	0	Repair	✓ X R
Standard	Main		6505526	QUARTER GLASS RR/RH	1	846.50	846.50	30.00	592.55	Replace	0	0	Not Giv	✓ X N/A
Standard	Main		6505558	FENDER FRT/LH	1	723.40	723.40	30.00	506.38	Replace	1	0	Repair	✓ X R
Standard	Main		6505640	NAME PLATE (HYBRID)	1	51.90	51.90	30.00	36.33	Replace	1	36.33	Replace	✓ APC
Standard	Main		6505658	WHEEL DISC. FRONT	1	1,484.20	1,484.20	30.00	1,038.94	Replace	1	0	Repair	✓ X R
Standard	Main		6503707	TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Giv	✓ X N/A
Standard	Main		6505529	DOOR FRT/LH	1	894.40	894.40	30.00	626.08	Replace	1	0	Repair	✓ X R
Standard	Main		6505599	MIRROR ASSY,LH	1	1,224.90	1,224.90	10.00	1,102.41	Replace	0	0	Not Giv	✓ X N/A
Standard	Main		6505465	MIRROR LAMP LH	1	65.30	65.30	10.00	58.77	Replace	0	0	Not Giv	✓ X N/A
Standard	Main		6505597	MIRROR GLASS LH	1	142.50	142.50	30.00	99.75	Replace	0	0	Not Giv	✓ X N/A
Standard	Main		6505607	MOULDING BODY, LH	1	673.60	673.60	30.00	471.52	Replace	1	0	Repair	✓ X R
Standard	Main		6505487	DOOR RR/LH	1	954.50	954.50	30.00	668.15	Replace	1	0	Repair	✓ X R
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	30.00	11.27	Replace	10	11.27	Replace	✓ APC

1165474

Total Spare Part Cost 17,674.16

Surveyor Total 2,629.44

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 14,139.33

Final Sur Total 2,103.55

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BRACKET, FR BUMPER	1	110.40	110.40	30.00	77.28	Replace	0	0	Not Givr	X N/A
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	0	0	Not Givr	X N/A
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	0	0	Not Givr	X N/A
One Time Key In	Main		6505508	UNDER COVER CENTER	1	448.30	448.30	30.00	313.81	Replace	0	0	Not Givr	X N/A
One Time Key In	Main			SUPPORT SUB-ASSY	1	1,460.40	1,460.40	30.00	1,022.28	Replace	0	0	Not Givr	X N/A
One Time Key In	Main		6505302	RADIATOR ASSY	1	1,496.90	1,496.90	30.00	1,047.83	Replace	0	0	Not Givr	X N/A
One Time Key In	Main			SUPPORT, RADIATOR	2	18.50	37.00	30.00	25.90	Replace	0	0	Not Givr	X N/A
One Time Key In	Main		6505507	RADIATOR LOWER SUPPORT	1	876.30	876.30	30.00	613.41	Replace	0	0	Not Givr	X N/A
One Time Key In	Main			COOLANT	1	12.32	12.32	0.00	12.32	Replace	0	0	Not Givr	X N/A
One Time Key In	Main		6505552	FENDER SEAL TO COWL SIDE RH	1	15.20	15.20	30.00	10.64	Replace	0	0	Not Givr	X N/A
One Time Key In	Main		6505560	FENDER PROTECTOR FRT/RH SIDE	1	113.90	113.90	30.00	79.73	Replace	0	0	Not Givr	X N/A
One Time Key In	Main			FENDER LINER PAD, FR WHEEL, RH	1	49.30	49.30	30.00	34.51	Replace	0	0	Not Givr	X N/A
One Time Key In	Main			WHEEL HUB FRT	1	549.70	549.70	30.00	384.79	Replace	0	0	Not Givr	X N/A
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Givr	X N/A
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	✓ N/A
One Time Key In	Main		6505598	COVER, OUTER MIRROR, RH	1	107.40	107.40	30.00	75.18	Replace	0	0	Not Givr	X N/A
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	✓ N/A
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	30.00	536.76	Replace	1	536.76	Replace	✓ DP
Total Spare Part Cost									17,674.16	Surveyor Total 2,629.44				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									14,139.33	Final Sur Total 2,103.55				

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			STICKER DECAL SMRT	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	✓ / N/A
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	✓ / N/A
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	✓ / N/A
One Time Key In	Main			SHOCK ABSORBER FRT/LH	1	394.20	394.20	30.00	275.94	Replace	0	0	Check	✓ / N/A
One Time Key In	Main		6505339	SHOCK ABSORBER MOUNTNG FRT, RH/LH	1	193.80	193.80	30.00	135.66	Replace	0	0	Not Give	✓ / N/A
One Time Key In	Main		6506611	SHOCK ABSORBER BEARING, FRT LH/RH	1	34.00	34.00	30.00	23.80	Replace	0	0	Not Give	✓ / N/A
One Time Key In	Main		6505336	STABILIZER BAR LINK FRT/RH/LH	1	195.00	195.00	30.00	136.50	Replace	0	0	Not Give	✓ / N/A
One Time Key In	Main		6505730	STEERING KNUCKLE LH FRT	1	580.80	580.80	30.00	406.56	Replace	0	0	Check	✓ / N/A
One Time Key In	Main		6505355	TIE ROD END LH	1	159.30	159.30	30.00	111.51	Replace	0	0	Not Give	✓ / N/A
One Time Key In	Main		6505732	LOWER ARM FRT/LH	1	625.90	625.90	30.00	438.13	Replace	0	0	Check	✓ / N/A
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	✓ / N/A
One Time Key In	Main		6505597	COVER, OUTER MIRROR, LH	1	107.40	107.40	30.00	75.18	Replace	1	75.18	Replace	✓ / N/A
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	0.00	Replace	✓ / N/A
Total Spare Part Cost									17,674.16	Surveyor Total 2,629.44				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									14,139.33	Final Sur Total 2,103.55				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	1,014.00	500	
2	Main	TO REPAIR LH PORTION	1,014.00	300	
Total:			2,028.00	800.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
3	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
4	Main	TO RESPRAY FRONT DOOR LH	378.00	200	
5	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
6	Main	TO RESPRAY REAR DOOR LH	378.00	200	
7	Main	TO RESPRAY REAR DOOR RH	378.00	200	
8	Main	TO RESPRAY RIM	360.00	50	
9	Main	TO RESPRAY SILL MEMBER PANEL LH	180.00	150	
10	Main	TO RESPRAY SILL MEMBER PANEL RH	0.00	150	
11	Main	RESPRAY MIRROR COVER LH	180.00	50	
12	Main	RESPRAY MIRROR COVER RH	180.00	0	
13	Main	TO RESPRAY REAR FENDER RH	378.00	200	
14	Main	TO RESPRAY REAR BUMPER	378.00	200	
15	Main	TO RESPRAY RADIATOR LOWER SUPPORT	180.00	0	
Total:			4,482.00	2,200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	56.00	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	240.00	60	
4	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	20	
Total:			2,681.00	256.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
5	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	375.00	0	NN
6	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	240.00	30	MC
7	Main	TO TRANSFER DOOR MECHANISM	480.00	30	MC
8	Main	TO REMOVE AND REFIX WING MIRROR	240.00	20	MC
9	Main	TO REMOVE / REFIT SEAT	120.00	0	
10	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	
11	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
12	Main	TO REMOVE AND REFIX UNDERCARRIAGE	250.00	0	
13	Main	TO REPLACE SUNDRY PARTS	100.00	20	MC
14	Main	TO WASH AND VACUUM	60.00	0	
Total:			2,681.00	256.00	

33406-40

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	14,139.33	2,103.55
Total Labour Cost	0.00	800.00
Total Spray Painting	0.00	2,200.00
Other	0.00	256.00
Overall Total	14,139.33	5,359.55
Lump Sum Repair Option		✓
Lump Sum Total	14,150.00	5,350.00
Surveyor Approved Amount		5,350.00
No of Repair Days*	14	8
Remarks	-	L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com
Surveyor Name		STEVE CHEN

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
5	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	375.00	0	
6	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	240.00	30	
7	Main	TO TRANSFER DOOR MECHANISM	480.00	30	
8	Main	TO REMOVE AND REFIX WING MIRROR	240.00	20	
9	Main	TO REMOVE / REFIT SEAT	120.00	0	
10	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	
11	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
12	Main	TO REMOVE AND REFIX UNDERCARRIAGE	250.00	0	
13	Main	TO REPLACE SUNDRY PARTS	100.00	20	
14	Main	TO WASH AND VACUUM	60.00	0	
Total:			2,681.00	256.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	14,139.33	2,103.55
Total Labour Cost	0.00	800.00
Total Spray Painting	0.00	2,200.00
Other	0.00	256.00
Overall Total	14,139.33	5,359.55
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	14,150.00	5,350.00
Surveyor Approved Amount		5,350.00
No of Repair Days*	14	8
Remarks	-	L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com
Surveyor Name		STEVE CHEN

Estimator Assessment(\$)

Surveyor Assessment(\$)

Signature


23/8/2019

Save

Clear

Survey Date

21/08/2019

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



file

Section A - Accident Details

Registration Number	SHB1632P
Case Reference Number	TAX/08/19/2060
Registration Date	16/5/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHIN YONG SHENG JOHNSON
Type of Accident	Head To Side
Accident Date and Time	18/8/2019 11:00 PM
Accident Reported Date and Time	19/8/2019 3:06 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	18/8/2019 11:01 PM
Replacement Vehicle issued?	No
Job Card Number	24102915
Special Instruction to ARC, if any	TOWED \$40 / TP / MSIG
Prepared Date and Time	20/8/2019 10:38 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,028.00	\$800.00
Total Spray Cost	\$4,662.00	\$2,200.00
Total Spare Part Cost	\$14,139.33	\$2,151.55
Total Other Cost	\$2,681.00	\$256.00
TOTAL COST	\$23,510.33	\$5,407.55
Lump Sum Total	\$23,500.00	\$5,400.00 (L/S)
Number of Repair Days	14.0	8.0
Prepared / Adjusted By	Kim Ming Chin	STEVE CHEN (LKK) / MSIG
ARC / Surveyor Sign Off Date	21/08/2019 4:52 PM	21/08/2019 2:53 PM
Signature		
Remarks	L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1909-0043	Invoice Number	
Quotation Date	04.09.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$1,014.00	\$500.00
TO REPAIR LH PORTION	\$1,014.00	\$300.00
Total Labour	\$2,028.00	\$800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY REAR DOOR RH	\$378.00	\$200.00
TO RESPRAY RIM	\$360.00	\$50.00
TO RESPRAY SILL MEMBER PANEL LH	\$180.00	\$150.00
TO RESPRAY SILL MEMBER PANEL RH	\$180.00	\$150.00
RESPRAY MIRROR COVER LH	\$180.00	\$50.00
RESPRAY MIRROR COVER RH	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY RADIATOR LOWER SUPPORT	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$4,662.00	\$2,200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$56.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$240.00	\$60.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$20.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$375.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$240.00	\$30.00
TO TRANSFER DOOR MECHANISM	\$480.00	\$30.00
TO REMOVE AND REFIX WING MIRROR	\$240.00	\$20.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$0.00



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 80 Woodlands Industrial Park E4, Singapore 757706
 FAX Number : 63655592
 Estimator Telephone Number : 65651023
 Accident Reporting Number : 88602672

Date Generated : 06/09/2019

User ID : PohSuan

TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO REMOVE AND REFIX UNDERCARRIAGE	\$250.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$2,681.00	\$256.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair R
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given X
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given X
		53102-47020	BUMPER GRILLE SUB-ASSY LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given X
		76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Check X
		52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Not Given X
		16572-37120	RADIATOR HOSE LOWER	0.00	\$42.40	0.00	\$0.00	Replace	Not Given X
		16571-37140	RADIATOR TOP HOSE NO 1	0.00	\$42.40	0.00	\$0.00	Replace	Not Given X
		53801-47050	FENDER FRT/RH	1.00	\$723.40	30.00	\$506.38	Replace	Replace ✓
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	30.00	\$36.33	Replace	Replace ✓
		53875-47030	FENDER LINER FRT/RH	1.00	\$171.70	30.00	\$120.19	Replace	Replace ✓
		42611-47140 (Frt)	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair R
6503707			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X
		75851-47900	MOULDING BODY, RH	1.00	\$673.60	30.00	\$471.52	Replace	Replace ✓
		62110-47021	QUARTER GLASS FRT/RH	0.00	\$234.90	0.00	\$0.00	Replace	Not Given X
		67001-47070	DOOR FRT/RH	1.00	\$894.40	30.00	\$626.08	Replace	Replace ✓
		68710-12151	DOOR HINGE UPPER FRT/RH	0.00	\$80.50	0.00	\$0.00	Replace	Not Given X
		68730-12120	DOOR HINGE UPPER RR/RH	0.00	\$90.10	0.00	\$0.00	Replace	Not Given X
		68610-47021	CHECK ASSY, FR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given X
		87910-47330	MIRROR ASSY, RH	0.00	\$1,307.10	0.00	\$0.00	Replace	Not Given X
		81730-52090	MIRROR LAMP RH	0.00	\$65.30	0.00	\$0.00	Replace	Not Given X
		67003-47080	DOOR RR/RH	1.00	\$954.50	100.00	\$0.00	Replace	Repair R
		62710-47130	QUARTER GLASS RR/RH	0.00	\$846.50	0.00	\$0.00	Replace	Not Given X
		53802-47050	FENDER FRT/LH	1.00	\$723.40	100.00	\$0.00	Replace	Repair R
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	30.00	\$36.33	Replace	Replace ✓
		42611-47140 (Frt)	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair R
6503707			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X
		67002-47070	DOOR FRT/LH	1.00	\$894.40	100.00	\$0.00	Replace	Repair R
6505599		87940-47310	MIRROR ASSY, LH	0.00	\$1,224.90	0.00	\$0.00	Replace	Not Given X
6505465		81740-52040	MIRROR LAMP LH	0.00	\$65.30	0.00	\$0.00	Replace	Not Given X
			MIRROR GLASS LH	0.00	\$142.50	0.00	\$0.00	Replace	Not Given X
		75852-47900	MOULDING BODY, LH	1.00	\$673.60	100.00	\$0.00	Replace	Repair R
		67004-47080	DOOR RR/LH	1.00	\$954.50	100.00	\$0.00	Replace	Repair R

	52161-16010	BUMPER CLIPS	10.00	\$1.61	30.00	\$11.27	Replace	Replace	✓
	52114-47140	BRACKET, FR BUMPER	0.00	\$110.40	0.00	\$0.00	Replace	Not Given	X
		NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given	X
		NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given	X
6505508	51410-12105	UNDER COVER CENTER	0.00	\$448.30	0.00	\$0.00	Replace	Not Given	X
	53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Not Given	X
6505302	16400-37230	RADIATOR ASSY	0.00	\$1,496.90	0.00	\$0.00	Replace	Not Given	X
	16535-20030	SUPPORT, RADIATOR	0.00	\$18.50	0.00	\$0.00	Replace	Not Given	X
6505507	57104-47020	RADIATOR LOWER SUPPORT	0.00	\$876.30	0.00	\$0.00	Replace	Not Given	X
		COOLANT	0.00	\$12.32	0.00	\$0.00	Replace	Not Given	X
6505552	53866-47020	FENDER SEAL TO COWL SIDE RH	0.00	\$15.20	0.00	\$0.00	Replace	Not Given	X
6505560	53827-47030	FENDER PROTECTOR FRT/RH SIDE	0.00	\$113.90	0.00	\$0.00	Replace	Not Given	X
	53851-47040	FENDER LINER PAD, FR WHEEL RH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X
	43550-47011	WHEEL HUB FRT	0.00	\$549.70	0.00	\$0.00	Replace	Not Given	X
		SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
		STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	✓
6505598	879157-4010	COVER, OUTER MIRROR, RH	0.00	\$107.40	0.00	\$0.00	Replace	Not Given	X
		PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	✓
	61604-47090	FENDER RR/RH	1.00	\$766.80	30.00	\$536.76	Replace	Replace	✓
		STICKER DECAL SMRT	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓
		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓
		SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
	48520-80294	SHOCK ABSORBER FRT/LH	0.00	\$394.20	0.00	\$0.00	Replace	Check	X
6505339	48609-47040	SHOCK ABSORBER MOUNTNG FRT, RH/LH	0.00	\$193.80	0.00	\$0.00	Replace	Not Given	X
6506611	48619-28010	SHOCK ABSORBER BEARING, FRT LH/RH	0.00	\$34.00	0.00	\$0.00	Replace	Not Given	X
6505336	48820-47020	STABILIZER BAR LINK FRT/RH/LH	0.00	\$195.00	0.00	\$0.00	Replace	Not Given	X
6505730	43202-47030	STEERING KNUCKLE LH FRT	0.00	\$580.80	0.00	\$0.00	Replace	Check	X
6505355	45047-49165	TIE ROD END LH	0.00	\$159.30	0.00	\$0.00	Replace	Not Given	X
6505732	48069-47050	LOWER ARM FRT/LH	0.00	\$625.90	0.00	\$0.00	Replace	Check	X
		STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	✓
6505597	87945-74010	COVER, OUTER MIRROR, LH	1.00	\$107.40	30.00	\$75.18	Replace	Replace	✓
		PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	✓
Total				\$24,182.41		\$2,689.44			

2689.44
 -20%
 2151.55
 + 800.00
 + 2956.00
 5407.55
 4s \$5400/-

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Aug 2019		21 Aug 2019 09:48 Edit Adj Rpt	S\$5,400.00 Edit Estimates	S\$5,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHB1632P	Date of Loss: 18/08/2019 23:00 - :59 [63 Months and 2 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 603300	Policy/Cover Note No.: 29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020							
Vehicle Reg. No. (Insured):	SLL7050D	Policy No. (Claimant):							
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Keny Ong Thiam Beng - 6643 1309]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 20/09/2019]								
Driver/Customer (Insured):	YUE WAI KIT (), NRIC: S1228787I Email:								
Adj Asg. Remarks:	MANUAL ASSIGNED CAR IN. OI:Grab. Liab: Dispute. Assign: LKK Auto Consultants Pte Ltd. Contact: Shanti @ 6866 2671/2.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHB1632P (603300)
[SLL7050D]
TP
SMRT TAXIS PTE LTD
Aug 18 2019 11:00PM
[GRAB RENTALS PTE LTD]
SMRT Automotive Services Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports











































1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/08/19 17:00	Adjuster Immediate Advice	1	Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/08/19 19:21	General View	1	Load JPG	
2	21/08/19 19:21	General View	1	Load JPG	
3	21/08/19 19:21	General View	1	Load JPG	
4	21/08/19 19:21	General View	1	Load JPG	
5	21/08/19 19:21	General View	1	Load JPG	
6	21/08/19 19:21	General View	1	Load JPG	
7	21/08/19 19:21	General View	1	Load JPG	
8	21/08/19 19:21	General View	1	Load JPG	
9	21/08/19 19:21	General View	1	Load JPG	
10	21/08/19 19:21	General View	1	Load JPG	
11	21/08/19 19:21	General View	1	Load JPG	
12	21/08/19 19:21	General View	1	Load JPG	
13	21/08/19 19:21	General View	1	Load JPG	
14	21/08/19 19:21	General View	1	Load JPG	
15	21/08/19 19:21	General View	1	Load JPG	
16	21/08/19 19:21	General View	1	Load JPG	
17	21/08/19 19:21	General View	1	Load JPG	
18	21/08/19 19:21	General View	1	Load JPG	
19	21/08/19 19:21	General View	1	Load JPG	
20	21/08/19 19:21	General View	1	Load JPG	
21	21/08/19 19:21	General View	1	Load JPG	
22	21/08/19 19:21	General View	1	Load JPG	
23	21/08/19 19:21	General View	1	Load JPG	
24	21/08/19 19:21	General View	1	Load JPG	
25	21/08/19 19:21	General View	1	Load JPG	
26	21/08/19 19:21	General View	1	Load JPG	
27	21/08/19 19:21	General View	1	Load JPG	
28	21/08/19 19:21	General View	1	Load JPG	
29	21/08/19 19:21	General View	1	Load JPG	
30	21/08/19 19:21	General View	1	Load JPG	
31	21/08/19 19:21	General View	1	Load JPG	
32	21/08/19 19:21	General View	1	Load JPG	
33	21/08/19 19:21	General View	1	Load JPG	
34	21/08/19 19:21	General View	1	Load JPG	
35	21/08/19 19:21	General View	1	Load JPG	
36	21/08/19 19:21	General View	1	Load JPG	
37	21/08/19 19:21	General View	1	Load JPG	
38	21/08/19 19:21	General View	1	Load JPG	
39	21/08/19 19:21	General View	1	Load JPG	
40	21/08/19 19:21	General View	1	Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
42	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
43	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
44	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
45	21/08/19 19:21	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
46	21/08/19 19:21	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
47	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
48	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
49	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
50	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
51	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
52	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
53	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
54	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
55	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
56	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
57	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
58	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
59	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
60	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
61	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
62	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
63	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
64	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
65	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
66	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
67	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
68	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
69	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
70	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
71	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
72	21/08/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
73	09/09/19 18:28	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
74	09/09/19 18:28	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
75	09/09/19 18:28	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
76	09/09/19 18:28	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
77	09/09/19 18:28	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
78	09/09/19 18:28	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/08/19 17:01	PRI	 Load PDF	
2	20/08/19 17:01	OI Accident Report	 Load PDF	
3	20/08/19 17:01	TP SHB1632P E-REPORT	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	21/08/19 09:44	email - manual assign	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014603/EQF3E2

Date: 16/09/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29114756

Claimant SHB1632P

Insured Vehicle No: SLL7050D

Vehicle No: SHB1632P

Date of Loss: 18/08/2019

Nature of Claim: TP

Claim No: 603300

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB1632P

Make & Model: TOYOTA PRIUS, 1.8 (A)

Engine No: 2ZR6027190

Reg. Date: 16/05/2014 (Man. Year: 2014)

Chassis No: JTDKN36U605742427

Colour: Maroon

Odometer: 353574 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R15

Rear Tyre Size: 195/50 R15

Front Left Side: West Lake 5 mm

Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,590.40	2,689.44	21,900.96	89.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,816.00	3,256.00	5,560.00	63.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,406.40	5,945.44	27,460.96	82.20
Approved Total (Overridden) (S\$)		5,400.00		
Nett Amount (S\$)	33,406.40	5,400.00	28,006.40	83.84

INSPECTION

Date of Assignment: 21/08/2019

Date Inspected: 21/08/2019 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Sep 2019)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB1632P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER FRT / RH (DISC 30%)	Dented	723.40 F	*506.38 F
2	1		*NAME PLATE (HYBRID) (DISC 30%)	Necessary	51.90 F	*36.33 F
3	1		*FENDER LINER FRT / RH (DISC 30%)	Crushed	171.70 F	*120.19 F
4	1		*MOULDING BODY, RH (DISC 30%)	Crushed	673.60 F	*471.52 F
5	1		*DOOR FRT / RH (DISC 30%)	Dented	894.40 F	*626.08 F
6	1		*NAME PLATE (HYBRID) (DISC 30%)	Necessary	51.90 F	*36.33 F
7	1		*BUMPER CLIPS (DISC 30%) (10PCS)	Necessary	16.10 F	*11.27 F
8	1		*FENDER RR/RH (DISC 30%)	Dented	766.80 F	*536.76 F
9	1		*COVER, OUTER MIRROR, LH (DISC 30%)	Missing	107.40 F	*75.18 F
10	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
11	1		*PIXEL STICKER (SN)	Necessary	60.00 F	*60.00 F
12	1		*STICKER DECAL SMRT (SN)	Necessary	7.80 F	*7.80 F
13	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
14	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
15	1		*PIXEL STICKER (SN)	Necessary	60.00 F	*60.00 F
16	1		*BUMPER SUPPORT F/RH	Not Necessary	76.40 F	*- F
17	1		*BUMPER SUPPORT F/LH	Not Necessary	76.40 F	*- F
18	1		*BUMPER GRILLE SUB-ASSY, LOWER	Not Necessary	311.10 F	*- F
19	1		*BUMPER LIP FRT	Not Necessary	139.60 F	*- F
20	1		*BUMPER FRT ABSORBER LOWER	Not Necessary	127.70 F	*- F
21	1		*RADIATOR HOSE LOWER	Not Necessary	42.40 F	*- F
22	1		*RADIATOR TOP HOSE NO 1	Not Necessary	42.40 F	*- F
23	1		*TYRE	Not Necessary	126.74 F	*- F
24	1		*QUARTER GLASS FRT / RH	Not Necessary	234.90 F	*- F
25	1		*DOOR HINGE UPPER FRT / RH	Not Necessary	80.50 F	*- F
26	1		*DOOR HINGE UPPER RR / RH	Not Necessary	90.10 F	*- F
27	1		*CHECK ASSY, FR DOOR,	Not Necessary	150.30 F	*- F
28	1		*MIRROR ASSY, RH	Not Necessary	1,307.10 F	*- F
29	1		*MIRROR LAMP RH	Not Necessary	65.30 F	*- F
30	1		*QUARTER GLASS RR / RH	Not Necessary	846.50 F	*- F
31	1		*TYRE	Not Necessary	126.74 F	*- F
32	1		*MIRROR ASSY, LH	Not Necessary	1,224.90 F	*- F
33	1		*MIRROR LAMP LH	Not Necessary	65.30 F	*- F
34	1		*MIRROR GLASS LH	Not Necessary	142.50 F	*- F
35	1		*BRACKET, FR BUMPER	Not Necessary	110.40 F	*- F
36	1		*NUMBER PLATE FRAME	Not Necessary	12.00 F	*- F
37	1		*NUMBER PLATE	Not Necessary	15.00 F	*- F
38	1		*UNDER COVER CENTER	Not Necessary	448.30 F	*- F
39	1		*SUPPORT SUB-ASSY	Not Necessary	1,460.40 F	*- F
40	1		*RADIATOR ASSY	Not Necessary	1,496.90 F	*- F
41	2		*SUPPORT, RADIATOR	Not Necessary	37.00 F	*- F
42	1		*RADIATOR LOWER SUPPORT	Not Necessary	876.30 F	*- F
43	1		*COOLANT	Not Necessary	12.32 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*FENDER SEAL TO COWL SIDE RH	Not Necessary	15.20 F	*- F
45	1		*FENDER PROTECTOR FRT / RH SIDE	Not Necessary	113.90 F	*- F
46	1		*FENDER LINER PAD, FR WHEEL, RH	Not Necessary	49.30 F	*- F
47	1		*WHEEL HUB FRT	Not Necessary	549.70 F	*- F
48	1		*SEALANT W/SCREEN	Not Necessary	37.00 F	*- F
49	1		*COVER, OUTER MIRROR, RH	Not Necessary	107.40 F	*- F
50	1		*SEALANT W/SCREEN	Not Necessary	37.00 F	*- F
51	1		*SHOCK ABSORBER FRT / LH	Not Necessary	394.20 F	*- F
52	2		*SHOCK ABSORBER MOUNTING FRT, RH / LH	Not Necessary	193.80 F	*- F
53	2		*SHOCK ABSORBER BEARING, FRT LH / RH	Not Necessary	34.00 F	*- F
54	2		*STABILIZER BAR LINK FRT / RH / LH	Not Necessary	195.00 F	*- F
55	1		*STEERING KNUCKLE LH FRT	Not Necessary	580.80 F	*- F
56	1		*TIE ROD END LH	Not Necessary	159.30 F	*- F
57	1		*LOWER ARM FRT / LH	Not Necessary	625.90 F	*- F
58	1		*BUMPER FRT	Repair	482.00 F	*- F
59	1		*WHEEL DISC. FRONT	Repair	1,484.20 F	*- F
60	1		*DOOR RR/RH	Repair	954.50 F	*- F
61	1		*FENDER FRT / LH	Repair	723.40 F	*- F
62	1		*WHEEL DISC. FRONT	Repair	1,484.20 F	*- F
63	1		*DOOR FRT / LH	Repair	894.40 F	*- F
64	1		*MOULDING BODY, LH	Repair	673.60 F	*- F
65	1		*DOOR RR / LH	Repair	954.50 F	*- F
66	1		*SOLAR FILM	Not Necessary	375.00 F	*- F

F=Franchise part.

Total Parts (S\$)	24,590.40	2,689.44
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	2,028.00	800.00
2	SPRAY PAINT	New	4,482.00	2,200.00
3	TOWING CHARGE	New	56.00	56.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
5	TO DO WHEEL ALIGNMENT / TYRE BALANCING	New	240.00	60.00
6	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	200.00	20.00
7	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	240.00	30.00
8	TO TRANSFER DOOR MECHANISM	New	480.00	30.00
9	TO REMOVE AND REFIX WING MIRROR	New	240.00	20.00
10	TO REMOVE / REFIT SEAT	New	120.00	0.00
11	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	0.00
12	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	New	120.00	0.00
13	TO REMOVE AND REFIX UNDERCARRIAGE	New	250.00	0.00
14	TO REPLACE SUNDRY PARTS	New	100.00	20.00
15	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			8,816.00	3,256.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >