

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0983/2019/TNS  
**Date** : 19-Aug-19

**Vehicle IN workshop. Kindly arrange for survey.**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : MS. MICHELLE KUAH  
**Address** : BLK 103 JALAN RAJAH  
#05-50  
Singapore 321103  
**Telephone** : (HP) +65 98008896  
**Type of Claim** : Own Damage Claims  
**Policy No.** : 1900067636  
**Vehicle No** : **SMK 8698 Y**  
**Model Code** : Audi Q2 1.0 TFSI S Tronic  
**Model / Year** : 28/3/2019  
**Engine No** : CHZ C26392  
**Chassis No** : WAUZZZGA5KA027348  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 15-Aug-19  
**Place of Accident** : RIVER VALLEY ROAD

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SMK 8698 Y

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Reccomendation</u>
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper, both front fenders, bonnet and both headlights. Re-organise rear crash management components. Reinstall all parts removed. ✓	\$ <del>4,800.00</del> 1000	
3	To respray front bumper, both front fenders and bonnet. ✓	\$ <del>4,500.00</del> 1100	
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ <u>9,852.00</u></b>	

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

**Telefax**

**Material List for Accident Vehicle Regn No. SMK 8698 Y**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER - LH / RH <i>reband</i>	2 \$ 1,572.00	✓
2	FRONT BUMPER CONNECTING PIECE - CENTRE ?	\$ 134.00	?
3	BUMPER FIXING PARTS <i>seen</i>	\$ 314.00	x
4	FRONT BUMPER GRILLE - CENTRE ?	2 \$ 179.00	?
5	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>seen</i>	2 \$ 308.00	x.
6	FRONT BUMPER END CAP - LH / RH <i>seen</i>	2 \$ 62.00	+
7	FRONT BUMPER SPOILER ?	\$ 273.00	?
8	FRONT BUMPER CLOSING ELEMENT <i>seen</i>	2 \$ 142.00	x.
9	WHEEL SPOILER - LH / RH <i>seen</i>	2 \$ 62.00	+
10	FRONT BUMPER ADAPTER - LH / RH <i>seen</i>	2 \$ 70.00	+
11	RADIATOR GRILLE <i>reband</i>	\$ 1,301.00	✓
12	RADIATOR GRILLE STRIKER PLATE ?	\$ 114.00	?
13	FRONT BUMPER CARRIER ?	\$ 625.00	?
14	FRONT BUMPER FOAM FILLER PIECE ?	2 \$ 71.00	?
15	FRONT BUMPER COVER <i>seen</i>	\$ 91.00	x.
16	FRONT BUMPER GUIDE SECTION - LH / RH <i>seen</i>	2 \$ 64.00	+
17	CAUTION SIGN <i>seen</i>	NEC \$ 13.00	+
18	AIRCON STICKER <i>seen</i>	NEC \$ 7.00	+
19	HORN - LH LOW TONE <i>seen</i>	\$ 262.00	+
<b>SUB TOTAL SPARE PARTS</b>		<b>\$ 5,664.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

**Telefax****Material List for Accident Vehicle Regn No.SMK 8698 Y**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
20	SIGNAL HORN - RH HIGH TONE	\$ 180.00	+ ✓
21	HORN SPRING SHACKLE - LH / RH	\$ 58.00	+ ✓
22	FENDER - LH / RH	2 \$ 2,094.00	+ ✓
23	FENDER ATTACHMENT PARTS	2 \$ 72.00	+ ✓
24	FENDER BRACKET - LH / RH	2 \$ 86.00	+ ✓
25	FENDER BRACE - LH / RH	2 \$ 58.00	+ ✓
26	WHEEL HOUSING LINER - LH / RH	2 \$ 366.00	+ ✓
27	WHEEL HOUSING LINER ATTACHMENT PARTS	2 \$ 103.00	+ ✓
28	BONNET LID HINGE - LH / RH	\$ 2,549.00	✓
29	BONNET ATTACHMENT PARTS	\$ 149.00	?
30	IMPACT PROTECTION - LH / RH / CENTRE	3 \$ 82.00	✓
31	BONNET BOWDEN CABLE - CENTRE	\$ 53.00	+ ✓
32	BONNET LID LOCK CABLE	\$ 67.00	+ ✓
33	BONNET BOWDEN CABLE - LH / RH	2 \$ 106.00	+ ✓
34	BONNET RELEASE LEVER	\$ 12.00	+ ✓
35	BONNET RELEASE ELEMENT	\$ 53.00	+ ✓
36	BONNET LID LOCK	2 \$ 367.00	+ ✓
37	BONNET STRIKER - LH / RH	2 \$ 200.00	+ ✓
38	MAIN BEAM HEADLIGHT MOUNTING - LH / RH	2 \$ 214.00	+ ✓
39	LED HEADLIGHT - LH / RH	2 \$ 8,982.00	+ ✓
40	LIFT CYLINDER - LH / RH	2 \$ 256.00	+ ✓
<b>SUB TOTAL SPARE PARTS</b>		<b>\$ 16,107.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

**Telefax**

**Material List for Accident Vehicle Regn No. SMK 8698 Y**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	HEADLIGHT HOSE - RH	5 \$	850.00 ✕
42	WHEEL COVER - LH / RH	2 \$	588.00 ✓
43	RADIATOR AIR GUIDE - LH / RH	2 \$	54.00 ✕
44	RADIATOR AIR GUIDE - UPPER CENTRE	\$	19.00 ✕
45	FRONT NO. PLATE <i>Best</i>	S/N \$	40.00 ✓
46	SUNDRIES ?	\$	300.00 ?
<b>TOTAL SPARE PARTS</b>		<b>\$</b>	<b>23,622.00</b>
<b>TOTAL LABOUR CHARGES</b>		<b>\$</b>	<b>9,852.00</b>
<b>GRAND TOTAL</b>		<b>\$</b>	<b>33,474.00</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : *Adrian Lij*  
Surveyed Date : *20/08/19.*  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : *Not Authorised, 25 days*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant