

INS. CASE OWNER:

LOH CHEE HENG

CC6/AIG19014627/Uha3

LKK:

IDAC:

Surveyor:

MARCUS

DOI: 21/08/2019

Date / Time: 21/08/2019

Registered in Merimen: 21/08/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SLX 7364K

Claim No. : 3044513385SG

Name of Insured : GOLDBELL CAR RENTAL PTE LTD

Policy No. : 0999994314

Insured Tel No. : HP:

Make / Model :

Excess Sec II :SS D.O.A : 21/08/2019

Place of Accident :

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SMK 2502T

INSRS:
WSP: FASTECH
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	SMK 2502T - X	SLX 7364K - X	STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	
21/08/19			After call ltr to OI:	21/08/19 - VIC
			Documentation Check List:	Handler Typist
			Notification ltr (if non-pickup)	
			After call ltr to OI:	
			Authorisation To Act:	
			Release Voucher:	
			Final Repair Bill:	
			Car Rental Invoice:	
			Towing Invoice	
			LTA / GIA :	
			Medical Bill:	
			PIR:	
			Mandate/Reject Instruction:	
			LOD	
			Payment Breakdown Form:	
			Post-Repair Photos:	
			Others:	

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	L10	SS 4,800.00 (5 days) Reduction: 82 %	Confirm by:
FINAL SETTLEMENT		Date/Time: 16/12/19	Confirm with: 2460N
Final Liability:	% 100 (Agreed / Assessed)	BOLA S/N No. : 27	Email ☒ Call ☐
Repair Cost: (w/1895)	SS 4,601.00		If NO or B 28, Ass. Lia :
Loss of Rental (LOR):	SS 200.00 (2 days) X \$100		COLD RATE - ENDED TP)
Loss of Use (LOU):	SS - (\$ x days)		
Loss of Income (LOI):	SS - (\$ x days)		
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐ (Tick only one)		
GIA/LTA Search	SS 7.45		
Medical:	SS -		
Disbursement:	SS - (e.g. Tow/ Independent)		
Legal Cost	SS -		
Total:	SS 4,808.45	Global Sum SS: 4,800.00	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	SS 4,800.00	Name 1:	FASTECH AUTO PTE LTD
Payee 2: (Strike if N.A.)	SS -	Name 2:	-
Payee 3: (Strike if N.A.)	SS -	Name 3:	-

(08/11/13) wel
ASS. REC. BY: MARUS

REF:

ALL

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMK 25027
at Workshop m/s SL
of SLV 7364K
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

CBP
Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMK 25027 Yr Regn: 41 19
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or SA

Make: Honda Fit c.c. 1317

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 1774 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GK 3 1342802

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/70R14

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear
R/Bal. <u>8</u> mm		R/Bal. <u>8</u> mm
L/Bal. <u>8</u> mm		L/Bal. <u>8</u> mm
D.O.A. <u>21/8/19</u>		D.O.I. <u>21/8/19</u>

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LIA 29 484 have hit

30/8/19 4/5 @ 4300 confirmed with AAR.
(CRK: \$20,105.40/82.1.)

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)) S+RS, SI
☐ : Interview (\$ _____)) Photos
☐ : Tech. Invs (\$ _____)) Others
☐ : Weekend (\$ _____)

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

TOTAL

(08/11/13) wel

ASS-REC. BY: MARCUS

REF:

ALL**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

CBPZ

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LIA 29 484

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format:

Lump Sum / I.B.I: (\$

TOTAL

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

the Repairer of the following:
• To resurvey before/after spray painting
• To describe damaged part(s) during resurvey
• Part(s) price are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No rework/modification(s) is allowed
• Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repeller

Signature:
Date:

Not Authorised
N/A
21/8/19
4/s = 4300/
5kg

VEHICLE NO: **SMK 250LT**

QTY	PARTICULAR
1 PCS	REAR WINDSCREEN
1 PCS	REAR WINDSCREEN MOULDING
1 PCS	REAR WINDSCREEN INNER SEAL
1 PCS	REAR WINDSCREEN WIPER ARM
1 PCS	REAR WIPER BLADE
1 PCS	REAR WIPER MOTOR
1 PCS	TAILGATE
1 PCS	TAILGATE 'H' LOGO
1 PCS	TAILGATE OUTER GARNISH
1 PCS	TAILGATE 'FIT' EMBLEM
1 PCS	TAILGATE INNER LOCK
1 PCS	TAILGATE WEATHERSTRIP
1 PCS	TAILGATE INNER TRIM BOARD
1 SET	TAILGATE INNER TRIM BOARD CLIPS
2 PCS	TAILGATE INNER TOP SIDE GARNISHS @\$195.20
2 PCS	TAILGATE REAR LICENCE LAMPS @\$50.50
1 PCS	REAR BUMPER
1 PCS	REAR BUMPER <i>centre moulding</i>
1 SET	REAR BUMPER CLIPS
1 PCS	REAR END PANEL
1 PCS	REAR END PANEL TOP GARNISH
2 PCS	REAR FENDERS @\$971.00
2 PCS	REAR FENDER INNER TRIM BOARDS @\$385.00
1 SET	REAR FENDER INNER TRIM BOARD CLIPS
1 PCS	REAR FENDER INNER TOP SIDE GARNISH N/S
1 PCS	REAR WHEEL HOUSING PANELS N/S
1 PCS	REAR TAILLAMP PANEL N/S
2 PCS	TAILLAMPS @\$305.00
1 PCS	REAR AIR VENT
2 PCS	REAR BUMPER SPLASH SHIELDS @\$45.00
1 PCS	REAR DOOR N/S
1 PCS	REAR FENDER GLASS N/S
1 PCS	ROOF MOULDING N/S
1 PCS	REAR SHOCK ABSORBER N/S
1 PCS	REAR WHEEL HUB BEARING N/S
1 PCS	REAR FLOOR PANEL
1 PCS	REAR FLOOR PANEL TOP BOARD
1 PCS	REAR FLOOR PANEL TOOLS SPONGE
1 PCS	ROOF LINING
S.NETT	
1 PCS	REAR WINDSCREEN SEALANT
1 PCS	REAR WINDSCREEN SOLAR FILM
1 PCS	REAR LICENCE PLATE W/HOLDER
1 SET	REAR REVERSE CAMERA
1 SET	REAR REVERSE SENSOR

11	\$1,105.30	X
rec	\$68.50	/
rec	\$35.00	/
11	\$121.00	X
11	\$68.50	X
11	\$335.10	X
body	\$803.20	/
11	\$45.00	X
11	\$245.50	X
rec	\$42.50	/
20/shell	\$266.20	/
twi	\$148.20	/
Be/cra	\$341.80	/
rec	\$50.00	/
11	\$390.40	X
11	\$101.00	X
10/me	\$545.30	/
cra	\$73.00	/
rec	\$30.00	/
11	\$306.30	/
twi	\$166.50	/
R	\$1,942.00	X
11	\$770.00	X
11	\$39.00	X
11	\$248.00	X
R	\$795.20	X
R	\$288.50	X
o/scre	\$610.00	IPC
11	\$86.20	X
11	\$90.00	X
11	\$971.10	X
11	\$350.00	X
11	\$122.30	X
11	\$322.20	X
11	\$380.00	X
R	\$911.40	X
11	\$315.00	X
11	\$485.00	/
11	\$866.20	X
	\$14,880.40	

rec	\$50.00	40
11	\$200.00	X
11	\$50.00	X
11	\$380.00	X
shell	\$280.00	200

3666.50
202
2933.20

1 PCS
1 PCS
1 PCS
1 PCS
1 SET

TAILGATE TOP SPOILER
TAILGATE THIRD LAMP
REAR FENDER GLASS SEALANT N/S
REAR BUMPER LOWER SKIRTING
REAR FLOOR PANEL INSULATOR

11 \$880.00 X
11 \$185.00 X
11 \$50.00 X
Nf \$820.00 X
re \$200.00 ✓

LABOUR CHARGES:

TO CHECK WIRING
TO DISMANTLE & REPLACING REVERSE SENSOR
TO DISMANTLE & REPLACING REAR WINDSCREEN
TO DISMANTLE & REPLACING REAR FENDER GLASS N/S
TO DISMANTLE & REFIX ROOF LINING
TO CONDUCT WHEEL ALIGNMENT
TO DISMANTLE & REFIX REAR UNDERCARRIAGE
TO DISMANTLE & REFIX FUEL TANK
TO SPRAY RUST PROOFING
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY
TO MOUNT VEHICLE ON CAR O-LINER
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$80.00 30
\$80.00 50
\$150.00 120
11 \$100.00 X
11 \$280.00 X
11 \$120.00 X
11 \$280.00 X
11 \$100.00 X
\$180.00 80
\$180.00 80
11 \$380.00 X
\$2,500.00 800
\$2,000.00 1100
TOTAL \$24,405.40

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	568F

Vehicle Details

Vehicle No.:	SMK2502T
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3GF CVT
Primary Colour:	Black
Manufacturing Year:	2019
Engine No.:	L13B1450946
Chassis No.:	GK31342802
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$15,154.00
Original Registration Date:	01 Apr 2019
First Registration Date:	01 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$5,154.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Mar 2029
PARF Rebate Amount:	\$3,865.00

Intended COE Rebate Details

COE Expiry Date:	31 Mar 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,659.00
COE Rebate Amount:	\$25,619.00
Total Rebate Amount:	\$29,484.00

The information contained herein is correct as at 21 Aug 2019

OK

View Received Message

This mail is associated with :

***SMK2502T (3044513385SG)**
[SLX7364K]

TP

HUI KONG HENG, ADRIAN

Aug 21 2019 12:00AM

[GOLDBELL CAR RENTAL PTE LTD]

Fastech Auto Pte Ltd

Reply	Reply All	Mark as Unread	Print Message	Delete Message	Forward
-------	-----------	----------------	---------------	----------------	---------

From AIG Asia Pacific Insurance Pte. Ltd, (AIG_SG), sent on **22/08/2019 08:10 AM.**
To LKK_HQ
Subject No OI GIA Report

Hi,

Please be informed that no OI GIA report received till date.
Please find OI details below for your further action.

OI name: Goldbell Car Rental Pte Ltd

Address:

10 Raeburn Park

#02-01

Singapore 088702

Contact No: 6838 6300

Regards,

Wah Xin

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG19014627/Uha3

23 August, 2019

Goldbell Car Rental Pte Ltd

10 Raeburn Park
#02-01
Singapore 088702

Dear Sirs,

**ACCIDENT INVOLVING SLX 7364K AND SMK 2502T ON 21/08/2019 ALONG/
AT COMPASSVALE DR TOWARDS COMPASSVALE WALK**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Vic Alpeh Sanghilan
Claims
Tel : 6841 2096
Fax: 6741 4108
Email : vicalpeh@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Print Received Message

This mail is associated with :

***SMK2502T (3044513385SG)
[SLX7364K]**

TP

HUI KONG HENG, ADRIAN
Aug 21 2019 7:00AM
[GOLDBELL CAR RENTAL PTE LTD]
Fastech Auto Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 08/11/2019 09:07 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4808.45) - SMK2502T - Claim Handler: Loh, Chee-Heng

Approved:4808.45.

MSIG

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
 Individual Ownership

MOTOR MAX
 Comprehensive

Certificate No. A 25120799 QMX

Excess : SGD500

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
SMK2502T
2. Name of Policyholder
Hui Kong Heng Adrian (Xu Guangxing)
3. Effective Date of the Commencement of Insurance for the purposes of the Act
01/04/2019
4. Date of Expiry of Insurance
31/03/2020
5. Persons or Classes of Persons entitled to drive*
Hui Kong Heng Adrian (Xu Guangxing)
Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to use*
Use only for social domestic and pleasure purposes and for the Policyholder's business.
The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT ANY MSIG
 AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved Insurers



for Chief Executive Officer

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 568F

Vehicle Details

Vehicle No.: SMK2502T
Vehicle to be Exported: Yes
Intended Deregistration Date: 22 Aug 2019
Vehicle Make: HONDA
Vehicle Model: FIT 1.3GF CVT
Primary Colour: Black
Manufacturing Year: 2019
Engine No.: L13B1450946
Chassis No.: GK31342802
Maximum Power Output: 73.0 kW (97 bhp)
Open Market Value: \$15,154.00
Original Registration Date: 01 Apr 2019
First Registration Date: 01 Apr 2019
Transfer Count: 0
Actual ARF Paid: \$5,154.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 31 Mar 2029
PARF Rebate Amount: \$3,865.00

Intended COE Rebate Details

COE Expiry Date: 31 Mar 2029
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$26,659.00
COE Rebate Amount: \$21,327.00
Total Rebate Amount: \$25,192.00

The information contained herein is correct as at 22 Aug 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Aug 2019 Edit Reg		21 Aug 2019 00:00 Edit Adj Rpt	S\$4,300.00 Edit Estimates	S\$4,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	GOLDBELL CAR RENTAL PTE LTD, Co. Reg. No.: 200710651D								
Main Claimant:	HUI KONG HENG, ADRIAN, ID: S7829568F								
Vehicle Reg. No.:	SMK2502T	Date of Loss:	21/08/2019 07:00 - :59 [4 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3044513385SG	Policy/Cover Note No.:	0999994314 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLX7364K	Policy No. (Claimant):	A29120799QMX						
		Excess:							
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 30/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (08/11/2019): Alert - Adj Mandate Approved (S\$4808.45) - SMK2502T - Claim Handler: Loh, Chee-H... - AIG_SG (22/08/2019): No OI GIA Report - AIG_SG (22/08/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMK2502T (3044513385SG)
[SLX7364K]
TP
HUI KONG HENG, ADRIAN
Aug 21 2019 7:00AM
[GOLDBELL CAR RENTAL PTE LTD]
Fastech Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser v 	
Letters/Correspondences										1 per page v ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown								Edit	
Assessment Reports										1 per page v ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	06/11/19 13:30	Adjuster Immediate Advice								Load HTM	
Photos/Images										3 per page v ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	21/08/19 17:15	Odometer Reading								Load JPG ☒	
2	21/08/19 17:15	Chassis Number								Load JPG ☒	
3	21/08/19 17:16	General View								Load JPG ☒	
4	21/08/19 17:16	General View								Load JPG ☒	
5	21/08/19 17:16	General View								Load JPG ☒	
6	21/08/19 17:16	General View								Load JPG ☒	
7	21/08/19 17:16	General View								Load JPG ☒	
8	21/08/19 17:16	General View								Load JPG ☒	
9	21/08/19 17:16	General View								Load JPG ☒	
10	21/08/19 17:16	General View								Load JPG ☒	
11	21/08/19 17:16	General View								Load JPG ☒	
12	21/08/19 17:16	General View								Load JPG ☒	
13	21/08/19 17:16	General View								Load JPG ☒	
14	21/08/19 17:16	General View								Load JPG ☒	
15	21/08/19 17:16	General View								Load JPG ☒	
16	21/08/19 17:16	General View								Load JPG ☒	
17	21/08/19 17:16	General View								Load JPG ☒	
18	21/08/19 17:16	General View								Load JPG ☒	
19	21/08/19 17:16	General View								Load JPG ☒	
20	21/08/19 17:16	General View								Load JPG ☒	
21	21/08/19 17:16	General View								Load JPG ☒	
22	21/08/19 17:16	General View								Load JPG ☒	
23	21/08/19 17:16	General View								Load JPG ☒	
24	21/08/19 17:16	General View								Load JPG ☒	
25	21/08/19 17:16	General View								Load JPG ☒	
26	21/08/19 17:16	General View								Load JPG ☒	
27	21/08/19 17:16	General View								Load JPG ☒	
28	21/08/19 17:16	General View								Load JPG ☒	
29	21/08/19 17:16	General View								Load JPG ☒	
30	21/08/19 17:16	General View								Load JPG ☒	
31	21/08/19 17:16	General View								Load JPG ☒	
32	21/08/19 17:16	General View								Load JPG ☒	
33	21/08/19 17:16	General View								Load JPG ☒	
34	21/08/19 17:16	General View								Load JPG ☒	
35	21/08/19 17:16	General View								Load JPG ☒	
36	21/08/19 17:17	Reinspection Photo								Load JPG ☒	

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
37	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
38	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
39	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
40	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
41	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
42	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
43	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
44	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
45	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
46	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
47	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
48	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
49	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
50	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
51	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
52	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
53	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
54	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
55	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
56	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
57	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
58	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
59	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
60	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
61	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
62	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
63	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
64	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
65	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
66	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
67	21/08/19 17:17	Reinspection Photo	 Load JPG	☒	
68	21/08/19 17:17	Reinspection Photo	Load JPG	☒	
69	21/08/19 17:17	Reinspection Photo	Load JPG	☒	
70	21/08/19 17:17	Reinspection Photo	Load JPG	☒	
71	21/08/19 17:17	Reinspection Photo	Load JPG	☒	
72	21/08/19 17:17	Reinspection Photo	Load JPG	☒	
73	21/08/19 17:17	Reinspection Photo	Load JPG	☒	
74	21/08/19 17:17	Reinspection Photo	Load JPG	☒	
75	21/08/19 17:17	Reinspection Photo	Load JPG	☒	
76	21/08/19 17:17	Reinspection Photo	Load JPG	☒	
77	21/08/19 17:17	Reinspection Photo	Load JPG	☒	
78	21/08/19 17:17	Reinspection Photo	Load JPG	☒	
79	21/08/19 17:17	Reinspection Photo	Load JPG	☒	
80	21/08/19 17:17	Reinspection Photo	Load JPG	☒	
81	21/08/19 17:17	Reinspection Photo	Load JPG	☒	
82	21/08/19 17:17	Reinspection Photo	Load JPG	☒	
83	21/08/19 17:17	Reinspection Photo	Load JPG	☒	
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	22/08/19 19:24	TP GIA REPORT	 Load PDF		
2	27/08/19 14:33	LETTER TO OI	 Load PDF		
3	06/11/19 10:25	TP ESTIMATE-MARKED	 Load PDF		
4	06/11/19 13:07	TP LOD	 Load PDF		
5	20/12/19 08:28	WORKSHOP INVOICE	 Load PDF		
6	20/12/19 08:28	AUTHORISATION TO ACT FORM	 Load PDF		
7	20/12/19 08:28	Release Voucher	Load PDF		
8	20/12/19 08:28	RENTAL RECEIPT	Load PDF		

Letters/Correspondences			1 per page	☒
No	Finalized On			Thumbnail Print
9	20/12/19 08:28	LKK Auto Consultants Pte Ltd (HQ)	1	Load PDF
10	20/12/19 08:28	LTA SEARCH	1	Load PDF
		LOD		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	23/08/19 10:32	OI GIA REPORT	1	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLX7364K (Insd veh)	Model:	HONDA FIT 1.3 GF CVT (A)
	SMK2502T (TP veh)		
Date of Accident:	21/08/2019		

Global Sum Settlement	:	☒ [X] Yes	☐ [] No
Repair Estimate	:	\$	26,113.78
Final Repair Cost	:	\$	4,800.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	2 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	4,800.00
Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ____ 100 ____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	:	\$ 4,800.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

20 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC8/AIG19014627/UHA3Q2

Date: 20/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994314
 Claimant: SMK2502T Insured Vehicle No: SLX7364K
 Vehicle No: SMK2502T
 Date of Loss: 21/08/2019 Nature of Claim: TP Claim No: 3044513385SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMK2502T
 Make & Model: HONDA FIT, 1.3 GF CVT (A) Engine No: L13B1450946
 Reg. Date: 01/04/2019 (Man. Year: 2019) Chassis No: GK31342802
 Colour: Black Odometer: 17741 km
 Engine Capacity: 1317 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,975.40	3,373.20	14,602.20	81.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,430.00	2,260.00	4,170.00	64.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,405.40	5,633.20	18,772.20	76.92
Approved Total (Overridden) (S\$)		4,300.00		
(S\$)	24,405.40	4,300.00	20,105.40	82.38
+ GST 7.00/7.00% (S\$)	1,708.38	301.00	1,407.38	82.38
Nett Amount (S\$)	26,113.78	4,601.00	21,512.78	82.38
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,808.45		
Global Sum Settlement (S\$)		4,800.00		

INSPECTION

Date of Assignment: 21/08/2019
 Date Inspected: 21/08/2019 Inspected At: Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50
 Autobay
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR WINDSCREEN	Not Necessary	1,105.30 F	*- FL
2	1	*REAR WINDSCREEN MOULDING	Necessary	68.50 F	*68.50 FL
3	1	*REAR WINDSCREEN INNER SEAL	Necessary	35.00 F	*35.00 FL
4	1	*REAR WINDSCREEN WIPER ARM	Not Necessary	121.00 F	*- FL
5	1	*REAR WIPER BLADE	Not Necessary	68.50 F	*- FL
6	1	*REAR WIPER MOTOR	Not Necessary	335.10 F	*- FL
7	1	*TAILGATE	Badly Dented	803.20 F	*803.20 FL
8	1	*TAILGATE H LOGO	Not Necessary	45.00 F	*- FL
9	1	*TAILGATE OUTER GARNISH	Not Necessary	245.50 F	*- FL
10	1	*TAILGATE FIT EMBLEM	Necessary	42.50 F	*42.50 FL
11	1	*TAILGATE INNER LOCK	Dented / Shorted	266.20 F	*266.20 FL
12	1	*TAILGATE WEATHERSTRIP	Twisted	148.20 F	*148.20 FL
13	1	*TAILGATE INNER TRIM BOARD	Deformed / Cracked	341.80 F	*341.80 FL
14	1	*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
15	2	*TAILGATE INNER TOP SIDE GARNISHS	Not Necessary	390.40 F	*- FL
16	2	*TAILGATE REAR LICENCE LAMPS	Not Necessary	101.00 F	*- FL
17	1	*REAR BUMPER	Dented / Deformed	545.30 F	*545.30 FL
18	1	*REAR BUMPER CENTRE MOULDING	Cracked	73.00 F	*73.00 FL
19	1	*SET REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
20	1	*REAR END PANEL	Dented	306.30 F	*306.30 FL
21	1	*REAR END PANEL TOP GARNISH	Twisted	166.50 F	*166.50 FL
22	2	*REAR FENDERS	Repair	1,942.00 F	*- FL
23	2	*REAR FENDER INNER TRIM BOARDS	Not Necessary	770.00 F	*- FL
24	1	*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	39.00 F	*- FL
25	1	*REAR FENDER INNER TOP SIDE GARNISH N/S	Not Necessary	248.00 F	*- FL
26	1	*REAR WHEEL HOUSING PANELS N/S	Repair	795.20 F	*- FL
27	1	*REAR TAILLAMP PANEL N/S	Repair	288.50 F	*- FL
28	1	*TAILLAMPS	O/S Cracked	610.00 F	*305.00 FL
29	1	*REAR AIR VENT	Not Necessary	86.20 F	*- FL
30	2	*REAR BUMPER SPLASH SHIELDS	Not Necessary	90.00 F	*- FL
31	1	*REAR DOOR N/S	Not Necessary	971.10 F	*- FL
32	1	*REAR FENDER GLASS N/S	Not Necessary	350.00 F	*- FL
33	1	*ROOF MOULDING N/S	Not Necessary	122.30 F	*- FL
34	1	*REAR SHOCK ABSORBER N/S	Not Necessary	322.20 F	*- FL
35	1	*REAR WHEEL HUB BEARING N/S	Not Necessary	380.00 F	*- FL
36	1	*REAR FLOOR PANEL	Repair	911.40 F	*- FL
37	1	*REAR FLOOR PANEL TOP BOARD	Not Necessary	315.00 F	*- FL
38	1	*REAR FLOOR PANEL TOOLS SPONGE	Torn	485.00 F	*485.00 FL
39	1	*ROOF LINING	Not Necessary	866.20 F	*- FL
40	1	*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
41	1	*REAR WINDSCREEN SOLAR FILM	Not Necessary	200.00 FS	*- FS
42	1	*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
43	1	*SET REAR REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
44	1	*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
45	1	*TAILGATE TOP SPOILER	Not Necessary	880.00 FS	*- FS
46	1	*TAILGATE THIRD LAMP	Not Necessary	185.00 FS	*- FS
47	1	*REAR FENDER GLASS SEALANT N/S	Not Necessary	50.00 FS	*- FS
48	1	*REAR BUMPER LOWER SKIRTING	Not fitted	820.00 FS	*- FS
49	1	*SET REAR FLOOR PANEL INSULATOR	Necessary	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **17,975.40** **4,106.50**

- List Item Discount on L Items 0.00/20.00% (\$\$) **0.00** **733.30**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					17,975.40	3,373.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REPLACING REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REPLACING REAR FENDER GLASS N/S	New	100.00	0.00
5	TO DISMANTLE & REFIX ROOF LINING	New	280.00	0.00
6	TO CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
7	TO DISMANTLE & REFIX REAR UNDERCARRIAGE	New	280.00	0.00
8	TO DISMANTLE & REFIX FUEL TANK	New	100.00	0.00
9	TO SPRAY RUST PROOFING	New	180.00	80.00
10	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	180.00	80.00
11	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
12	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	2,500.00	800.00
13	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,100.00
Gross Labour Cost (S\$)			6,430.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >