FASTECH AUTO PTE LTD **BLK1 KAKI BUKIT AVE 6** #01-46,48,50 AUTOBAY SINGAPORE 417883

VEHICLE NO:SGQ 116C

Maria Committee Committee

QTY	PARTICULAR
1 PCS	FRONT BUMPER (650,00
1 PCS	FRONT BUMPER SIDE RETAINER O/S /05.00
1 SET	FRONT BUMPER CLIPS
1 PCS	FRONT BUMPER REINFORCEMENT
1 PCS	FRONT BUMPER SPONGE
1 PCS	FRONT FENDER O/S
1 PCS	FRONT FENDER OUTER PROTECTOR O/S
1 SET	FRONT FENDER INNER SHIELD CLIPS O/S
1 PCS	HEADLAMP ASSY O/S 2280.03
1 PCS	FRONT SUPPORT PANEL (050.0)

LABOUR CHARGES TO CHECK WIRING TO DISMANTLE & REFIX FRONT PDC SENSOR TO CONDUCT WHEEL ALIGNMENT TO REFILL AIRCON GAS TO SPRAY RUST PROOFING LABOUR FOR PANEL BEATING & REPLACING PARTS TO PUTTY & SPRAY PAINTING

Not Allord
1/5 = 4500

P/De	\$2,100.00
Sel	\$150.00
u	\$60.00
11	\$820.00 X
11	\$285.00 🔾
altan	\$988.00,
al/ton	\$385.00
17	\$50.00 🗙
Che	\$3,200.00
cre	\$1,650.00
	\$0.699.00

\$80.00 20 \$80.00 40 \$100.00 🗙 11 \$150.00 X \$50.00 X \$980.00 600 \$900.00 600 TOTAL

\$12,028.00

LKK Auto Consultants hence notify the Repairer of the following:

- . To reservey belote/after spray painting
- . To display famaged part(s) during resurvey
- Parts prices are subject to confirmation
- * Third entry survey is on a "Without Prejudice" basis
- * No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

55301