



樹發汽車修理廠 SHU FATT AUTO WORKS

9-11

BLOCK 1008 BUKIT MERAH LANE 3 #01-80 SINGAPORE 153723 TEL: 6273 0119 FAX: 6270 7065

Waiting for 2nd pass of paint (approx 20/5/11)

Our Ref: WSK, by Special
20th August 2011
1133

Receipt

1984 14K

AKS 8188 V1 110514116 V

Speed/maintenance

Qty	Description	Unit	Price	Total
	Rear boot	bt	1108.90	
	Rear boot logo	re	21.70	
	Rear boot "VTH" emblem	re	21.70	
	Rear boot "HR-V" emblem	re	43.20	
	Rear boot lock	X	182.20	
	Rear boot rubber	X	98.60	
	Rear boot rubber	re	140.20	
	Rear windscreen moulding	re	224.20	
	Rear boot inner garnish	X	240.20	
	Rt rear boot reflector	ca	482.70	
1pc	Rear tail lights	ca - RH	482.70	
	Rear tail light holders	X	583.40	
	Rear support panel	bt	63.20	
	Rear panel inner garnish	de	884.20	
	Rt rear fender	repa + su	584.10	
	Rt rear fender inner garnish	de	261.40	
	Rt rear fender inner cowling	nt	48.00	
	Set rt rear fender inner cowling clips	re	528.10	
	Rear bumper	70cm	300.80	195.40
1pc	Rear bumper sides	@ \$105.40	48.00	
	Set rear bumper clips	re	48.20	24.10
1pc	Rear bumper side retainers	@ \$24.10	312.40	156.20
1pc	Rear bumper reflectors	@ \$156.20	182.40	
	Rt rear fender arch garnish	sc	182.40	
	Rt rear door	repa + su	113.10	
	Rt rear door rubber	X		
			8590.70	
			p.t.o	

Paints: 5724.70

10%: (1144.94)

4579.76

Subst: 307.60

4886.76

Labour: -440.00

7826.76

Supp: 2151.26

9978.52

10%: (1995.70)

7982.82

HS: 7950



樹發汽車修理廠

SHU FATT AUTO WORKS

5KS 845517

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

B.F.

- 1 Rear windscreen inner seal *ne* ✓
- 1 Rear windscreen sealant *ne* ✓
- 1 Rear number plate *X*
- 1 Set rear reverse sensors *ne* ✓

8590.70

42.00 Snet

45.00 Snet

~~55.00~~ Snet

220 ~~280.00~~ Snet

9012.70

Less 20% 1718.14

Labour

- To knock, straighten rear inner panel, rear lower panel, rear side panel, left rear chassis, rt rear chassis, rt rear arch inner panel, rt rear door pillar, rear floor board, rear member, renew rear boot, rear support panel, rear lights, rt rear fender, rear bumper and assembly
- To respray damaged parts.
- To remove, replace rear windscreen
- To remove rear seats, upholstery, root lining, garnishes carpets to facilitate repairs and assembly
- To remove rt rear under carriage to facilitate repairs and assembly
- To check and adjust wheel alignment
- To check and reset ECU.

7294.30

~~1800.00~~

1260 1300

~~1050.00~~

~~180.00~~

~~280.00~~

180.00

~~150.00~~

~~150.00~~

11084.30

Dunlop 215-55R17
MRHRU1830FP000080
84023

Supplementary.

- 1) Spare wheel *base* *bt* ✓
- 2) Rear exhaust pipe (Rt) *bt* ✓
- 3) Exhaust *nut* *bt* ✓
- 4) Rear exhaust holders x2 *ne* ✓
- 5) Rear exhaust heat shield (Rt) *bt* ✓
- 6) Front catalytic gaslet *ne* ✓
- 7) Front exhaust seal *ne* ✓
- 8) R/Spare wheel lower hook *ca* ✓

Pass

Hy 900/0068

11 days

4/5

23/08/19 @ 1200

Reg after repair



樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo
20th August 2019

Supplementary
India International Insurance Pte Ltd
TP33

SKS 8455 M HONDA HR-V

		S\$
Spare parts	1 Spare wheel base <i>bt</i> ✓	685.10
	1 Rear exhaust silencer <i>bt</i> ✓	704.90
	1 Rear centre exhaust <i>bt</i> ✓	762.90
	2 Rear exhaust holders @S\$20.50 <i>neu</i> ✓	41.00
	1 Rear exhaust heat shield <i>bt</i> ✓	75.00
	1 Rear exhaust seal <i>neu</i> ✓	45.00
	1 Centre exhaust seal <i>neu</i> ✓	28.10
	1 Rear spare wheel cover hook <i>neu</i> ✓	50.20
	1 Right rear spring shock mounting <i>neu</i> ✓	65.00
	1 Right rear reversed sensor bracket <i>neu</i> ✓	45.00

		2502.20
Less 20%		(500.44)

Labour	To remove, replace rear exhaust & assembly	2001.76
		450.00 <i>150</i>

		2451.76 <i>2151.76</i>