



樹發汽車修理廠 SHU FATT AUTO WORKS

0-19

BLOCK 1008 BUKIT MERAH LANE 3 #01-00 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Waiting for 2nd page of Police Report 22/8/19

Our Ref: WSK/jw/SF-quo
20th August 2019
TP33

SKS 8455 M HONDA HR-V

Spare Parts			SS
1	Rear boot.	bt /	1108.90
1	Rear boot logo.	re /	21.70
1	Rear boot 'i-VTEC' emblem.	re /	21.70
1	Rear boot 'HR-V' emblem.	re /	43.20
1	Rear boot lock.	X	157.20
1	Rear boot rubber.	re /	98.60
1	Rear windscreen moulding.	re /	149.20
1	Rear boot inner garnish.	X	224.20
1	Rt rear-boot reflector.	ca /	240.20
1 pc /	Rear tail lights.	ca - RH	482.70
4	Rear tail light holders.	X	965.40
1	Rear support panel.	bt /	583.40
1	Rear panel inner garnish.	de /	63.20
1	Rt rear fender.	re - bu /	884.20
1	Rt rear fender inner garnish.	de /	584.10
1	Rt rear fender inner cowl.	at /	261.40
1	Set rt rear fender inner cowl clips.	re /	48.00
1	Rear bumper.	1000 /	528.10
1 pc /	Rear bumper sides.	@\$195.40 cut - RH	390.80
1	Set rear bumper clips.	re /	48.00
1 pc /	Rear bumper side retainers.	@\$24.10 re - RH	48.20
1 pc /	Rear bumper reflectors.	@\$156.20 RH, ca /	312.40
1	Rt rear fender arch garnish.	sc /	182.40
1	Rt rear door.	re - bu /	930.40
1	Rt rear door rubber.	X	213.10
			8590.70

-1-

p.t.o.



樹發汽車修理廠

SHU FATT AUTO WORKS

5125 8455117

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

B/F

1	Rear windscreen inner seal. <i>m</i> ✓	8590.70	
1	Rear windscreen sealant. <i>m</i> ✓	42.00	Snet
1	Rear number plate. <i>X</i>	45.00	Snet
1	Set rear reverse sensors. <i>m</i> ✓	55.00	Snet
		220 280.00	Snet

9012.70
Less 20% 1718.14

Labour

To knock, straighten rear inner panel, rear lower panel, rear side panel, left rear chassis, rt rear chassis, rt rear arch inner panel, rt rear door pillar, rear floor board, rear member, renew rear boot, rear support panel, rear lights, rt rear fender, rear bumper and assembly.
To respray damaged parts.
To remove, replace rear windscreen.
To remove rear seats, upholstery, roof lining, garnishes, carpets to facilitate repairs and assembly.
To remove rt rear under carriage to facilitate repairs and assembly.
To check and adjust wheel alignment.
To check and reset ECU.

7294.56
~~1800.00~~ *1200 1300*

~~1650.00~~ *1600 1400 1200*
~~180.00~~ *120*
~~280.00~~ *100*

180.00 *X 80*

~~150.00~~ *60*
~~150.00~~ *80*

11684.56

-2-

Dunlop 215/55R17
MRHRU1830FP000089
84023

Supplementary.

Pass
Hg 900/100/68
11 days
45
23/08/19 @ 1200
Reg after repair

