

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

G671080931

CELESTE WONG

BLK 165 HOUGANG AVE 1

#10-1602

S 530165

TP ALG.

Jiale

Date

:24.08.2019

Vehicle No

:SMK 8207 G

Make/Model

:HONDA FREED

Accident date

:20.07.2019

No	DESCRIPTION	Qty	Amount (\$)
List Items			
1	Rear windscreen rubber <i>NEAR</i>	1	\$ 88 ✓
2	Rear tailgate <i>Dented</i>	1	\$ 1320 ✓ <i>1208</i>
3	Rear tailgate hinges @ \$ 82.50 <i>NEAR</i>	2	\$ 165 X
4	Rear tailgate upper lock <i>NEAR</i>	1	\$ 231 X
5	Rear tailgate lower lock <i>NEAR</i>	1	\$ 57.2 X
6	Rear tailgate weather strip <i>cut</i>	1	\$ 143 ✓
7	Rear tailgate inner board <i>NEAR</i>	1	\$ 418 X
8	Rear tailgate shock absorber @ \$ 165.00 <i>NEAR</i>	2	\$ 330 X
9	Rear tailgate H emblem <i>NEAR</i>	1	\$ 68.2 ✓
10	Rear tailgate Freed emblem	1	\$ 68.2 ✓
11	Rear tailgate Hybrid emblem <i>NEAR</i>	1	\$ 64.9 ✓
12	Rear tailgate reflector @ \$ 748.00 <i>NEAR</i>	2	\$ 1496 X
13	Rear tailgate handle <i>NEAR</i>	1	\$ 198 X
14	Rear bumper <i>Deformed</i>	1	\$ 1155 ✓ <i>1157</i>
15	Rear bumper side holder @ \$ 60.50 <i>NEAR</i>	2	\$ 121 ✓
16	Rear bumper reverse sensor (1 set) <i>Dented</i>	1	\$ 418 <i>200 (SN)</i>
17	Rear bumper clips (1 set) <i>NEAR</i>	1	\$ 66.30
18	Rear end panel <i>Dented</i>	1	\$ 528 ✓
19	Rear end panel top garnish <i>NEAR</i>	1	\$ 198 X
20	Rear bumper LH inner side garnish <i>Deformed</i>	1	\$ 418 <i>95</i>
			\$ 7551.5
Less 20% Disc			\$ 1510.3
Total			\$ 6041.2

Labour Cost

1	To supply rear windscreen sealant <i>NEAR</i>	\$ 50 ✓
2	Remove & reinstall rear windscreen	\$ 150 <i>120</i>
3	Remove & reinstall reverse sensor	\$ 150 <i>50</i>
4	Remove & reinstall bootlid inner garnish	\$ 200 <i>60</i>
5	Remove, replace & repair consistent to the accident	\$ 1300 <i>900</i>
6	Respray painting	\$ 1200 <i>900</i>
7	Tuff-kote	\$ 100 <i>80</i>
Total		\$ 3150

Grand Total

\$ 9191.2

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Total: 5234.64
H/S: A2K 06 Days