

15/5/2010

INS. CASE OWNER:

CC 6 /AIG1901

66h6, Aebk

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

20/8/10


Date / Time:

20/8/10

Registered in Merimen:

21/8/10

Pre-assign / CCU / FTE



Insured Vehicle No.:

SDT 8080M

Claim No.:

08604777056

Name of Insured:

Gou Lee Tiong

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

11/8/10

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:


(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SML 804AP



INSRS:

WSP:

Tel:

Liability:

RMKS:

Green

Forest




INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
	SML 804AP - X		
	SDT 8080M - X		
	NO of Gm, sent out 1st letter.	Non-Reporting ltr (1st):	
	PENDING TO REQUEST TP FOR VIDEO.	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	EMAIL 1.11.19
		After call ltr to OI:	
	RED TP VIDEO SAVE (Y: ASHER: 301) VIDEO SHOW A ROLL BACK AND HIT TP VEH.	Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☐
		Towing Invoice	☐
		LTA / GIA :	☒
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☒
		LOD	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	45 SS 1,400	(2 days) Reduction:	76 %
FINAL SETTLEMENT		Date/Time: 30.03.20	Confirm with: CHRIS
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	NIL
Repair Cost:	21/10/1 SS 1,498.00	01. ROLL BK AND HIT TP VEH.	
Loss of Rental (LOR):	SS - (days)		
Loss of Use (LOU):	SS 180.00 (S 60 x 3 days)		
Loss of Income (LOI):	SS - (S x days)		
LOR only ☐	LOU only ☒	LOR + LOU ☐	LOR + LO ☐ [Tick only one]
GIA/LTA Search	SS 7.45		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/ Independent)	
Legal Cost	SS -		
Total:	SS 1,685.45	Global Sum SS:	
FINAL PAYMENT		Date/Time: 30.03.20	Confirm with: CHRIS
Payee 1:	SS 1,685.45	Name 1:	GREEN FOREST AUTOMOBILE PTE LTD
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SML8549P Yr Regn: 2019 JuneType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Freed Hybrid c.c. 1486Colour: Red A/C: Insured / Std / NI / NASp. Reading: 22016 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GB71087182Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/65 R15R: 185/65 R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 20/08/19Survey held at Green ForestDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ALG.1/2: +1,400 (RED: +4,396 76%)MV:PV:Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

1)

2)

3)

4)

5)

6)

Pref. Report

Final Report

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

CARRO LEASING PTE LTD
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

TPA 16.

Asher

15th August 2019

Accident date: 13th AUGUST 2019

Estimated repair cost for vehicle no: SML8549P HONDA FREED 1.5 '2019

S/n	Qty	Items	U/price	Amount
1	2	Front head lamp <i>new</i>	\$951.00	\$1,902.00 X
2	2	Front head lamp lower bracket <i>new</i>	\$78.20	\$156.40 X
3	1	Front bumper <i>delivered</i>		\$950.00 ✓
4	2	Front bumper side bracket <i>new</i>	\$68.20	\$136.40 X
5	10	Front bumper clips <i>new</i>	\$5.00	\$50.00 30
6	1	Front bumper number plate <i>new</i>		\$50.00 +
7	1	Front bumper reinforcement <i>new</i>		\$380.00 +
8	1	Front bumper center garnish <i>new</i>		\$220.10 ✓
9	1	Front bumper center lower cover <i>new</i>		\$295.10 +
10	1	Front bumper lower grille <i>new</i>		\$285.00 +
11	1	Front Grille <i>new</i>		\$385.00 ✓
12	1	Front Grille emble logo <i>new</i>		\$56.00 -
13	10	Front Grille clips <i>new</i>	\$5.00	\$50.00 20

166/10

Subtotal :- \$4,916.00

132888

Labour charges

To Check Wiring System

~~\$80.00~~ 30

Panel beating

430

~~\$400.00~~ 200

Spray painting

~~\$400.00~~ 200

Subtotal :- \$880.00

Total :- \$5,796.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 1758.88

h/s: 1.41c.

02 Days