

ASS. REC. BY:

REF:

083/INC19014640/RISD3

Special Instruction:

Surveyor: Raisul

ASSIGNMENT (Office)

From (Person): Daniel Koh

of

INC

Date/Time: 00/8/19 @ 4.34pm

Estimated Cost:

Bill to:

OD ☒ WS/TP RES / OD RES ☒ EVA / INV / MV / CS

To Inspect Vehicle No:

SFW 113R

Insured:

FBF 7533C

at Workshop in/s

MTM Performance

Tel:

922 16409.

of 1st Chuan Rd East # 01-78

Policy No:

Claim No:

MT/1056623-002

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

5/8/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.13am @ 00/8/19

Person Contacted:

ERWIN

Vehicle ☒ IN/OUT

Date/Time	Action/Instruction
	Tobacco? ☒ Kindly Refer to the memo.
	SFW 113R -X
	FBF 7533 C -X

ASS. REQ. BY:

REF:

INC

ASSIGNMENT

From:

Date:

20/8/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SFW 113R

at Workshop m/s

MTM Performance

of

18 Tch Chen Rd East #01-78

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Erwing 9221 0404
After 1pm

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SFW 113R

Yr Regn: 2017 /

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MERCEDES BENZ GLE 43 AMG c.c 3000 c

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

9013

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDC2923642A086004

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

325/352R22

R:

1 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

20/08/19

Survey held at

MTM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear A/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range / days - 2k-3k / 3 days

Submit HS \$ 4,900/- @ 4 days, checked by Simon.
(\$ 3,400/- Red - 41%)

RECEIVED 23 SEP 2019

Date/Time, File Pass to?

23/09/19
TYP4

Preli. Report



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Week-end (\$)

Survey Fee:

Transportation:

3 + RS, SI

Photos

Others

TOTAL

Report Format:

Lump Sum / L.B.B. (\$)

4,900/- 45

Nivitha (LKK Auto)

From: Daniel Koh <daniel.koh@income.com.sg>
Sent: Tuesday, 20 August 2019 6:22 PM
To: 'assignments@lkkauto.com'
Cc: admin-d@lkkauto.com
Subject: FW: TP CASES FARMED OUT TO LKK ON 20/8/2019

R E S E N D with claim number & OIC

From: Daniel Koh
Sent: Tuesday, 20 August 2019 9:39 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: FW: TP CASES FARMED OUT TO LKK ON 20/8/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OIV	DOA	Additional Remarks
1	CHRYLLIS QUAH	MT/1057350- 002	SGX2788M	AUTO WHEELS MOTOR WORKS	No.1 BUKIT BATOK CRESCENT #02-40	Louis Ong / 91928963	10:00- 12:00	SMF9355G	10/8/2019	Customer waiting

2		Claim no and OIC will revert later	SFW113R	MTM PERFORMANCE AUTO PTE LTD	48 TOH GUAN ROAD EAST #01-78 ENTERPRISE HUB SINGAPORE 608583	Erwin Ho / 92210404				
3	CHRYLLIS QUAH	MT/1058341-001	SLL427Y	SK AUTOMOBILE PTE LTD	48 TOH GUAN ROAD EAST #01-121 ENTERPRISE HUB SINGAPORE 608586	Yvette Zhao / 6266 0555	SIP7455Y	15/8/2019		
4	AZHARI	MT/1058476-001	SKJ5161C	VAG SINGAPORE PTE. LTD.	48 TOH GUAN ROAD EAST #04-123 ENTERPRISE HUB SINGAPORE 608586	Jie Ren / 6267 9916	GBD8624C	17/8/2019		
5	MUHAMMAD AIRWAN	MT/1058234-002	SKK2543Z	VAG SINGAPORE PTE. LTD.	48 TOH GUAN ROAD EAST #05-155 ENTERPRISE HUB SINGAPORE 608586	Jie Ren / 94316186	SKE3933G	18/8/2019	Owner waiting	
6	MUHAMMAD AIRWAN	MT/1058310-002	SMJ888Z	WILLIAM'S AUTO PTE LTD	391B WOODLANDS ROAD BLK 3 YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965	Ang Ngoh Tee / 67636811	SFQ3637H	15/8/2019		

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Daniel Koh
Senior Admin Assistant
Motor Insurance
T +65 6430 7901
www.income.com.sg

income
made efficient



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Nivitha (LKK Auto)

From: Fiona Shen <fiona.shen@income.com.sg>
Sent: Thursday, 5 September 2019 9:08 AM
To: Admin-D (LKKAuto)
Subject: RE: TP CASES FARMED OUT TO LKK ON 20/8/2019 - MT/1056623-002

Hi

We have assigned the case to LKK on 20 Aug 2019.

Now, workshop has submitted the survey report and photos to us.

Please assist to do a paper survey for the case.

Thank you

Best Regards

Fiona Shen
Senior Claims Executive
Motor Insurance
T +65 6430 7923
www.income.com.sg



At Income, we are "In with You" on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at Income.com.sg/careers



From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 5 September 2019 7:50 AM
To: Fiona Shen <fiona.shen@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 20/8/2019 - MT/1056623-002

Dear Fiona,

Do we need to conduct Paper survey for this case?

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 4 September 2019 12:05 PM
To: 'Fiona Shen' <fiona.shen@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 20/8/2019 - MT/1056623-002

Nivitha (LKK Auto)

From: Fiona Shen <fiona.shen@income.com.sg>
Sent: Monday, 2 September 2019 10:57 AM
To: 'assignments@lkkauto.com'
Cc: admin-d@lkkauto.com
Subject: RE: TP CASES FARMED OUT TO LKK ON 20/8/2019 - MT/1056623-002
Attachments: Survey+Report+(for+Tablet)+2019-8-28.pdf.pdf; LOD2+ survey photos .pdf

Dear LKK

We refer to the above case.

As attached is the survey report and photos submitted by the third party for vehicle SFW113R.

Thank you

Best Regards

Fiona Shen
Senior Claims Executive
Motor Insurance
T +65 6430 7923
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers



From: Daniel Koh
Sent: Wednesday, 21 August 2019 3:09 PM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: FW: TP CASES FARMED OUT TO LKK ON 20/8/2019

Dear LKK

R E S E N D with claim number & OIC

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OIV	DOA
2	FIONA SHEN	MT/1056623-002	SFW113R	MTM PERFORMANCE AUTO PTE LTD	48 TOH GUAN ROAD EAST #01-78 ENTERPRISE HUB SINGAPORE 608583	Erwin Ho / 92210404		FBF7533C	5/8/2019

From: Daniel Koh

Sent: Tuesday, 20 August 2019 9:39 AM

To: 'assignments@lkkauto.com' <assignments@lkkauto.com>

Cc: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>

Subject: FW: TP CASES FARMED OUT TO LKK ON 20/8/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OIV	DOA
1	CHRYLLIS QUAH	MT/1057350-002	SGX2788M	AUTO WHEELS MOTOR WORKS	No.1 BUKIT BATOK CRESCENT #02-40	Louis Ong / 91928963	10:00- 12:00	SMF9355G	10/8/20:
2		Claim no and OIC will revert later	SFW113R	MTM PERFORMANCE AUTO PTE LTD	48 TOH GUAN ROAD EAST #01-78 ENTERPRISE HUB SINGAPORE 608583	Erwin Ho / 92210404			
3	CHRYLLIS QUAH	MT/1058341-001	SLL427Y	SK AUTOMOBILE PTE LTD	48 TOH GUAN ROAD EAST #01- 121 ENTERPRISE HUB SINGAPORE 608586	Yvette Zhao / 6266 0555		SJP7455Y	15/8/20:
4	AZHARI	MT/1058476-001	SKJ5161C	VAG SINGAPORE PTE. LTD.	48 TOH GUAN ROAD EAST #04- 123 ENTERPRISE HUB SINGAPORE 608586	Jie Ren / 6267 9916		GBD8624C	17/8/20:
5	MUHAMMAD AIRWAN	MT/1058234-002	SKK2543Z	VAG SINGAPORE PTE. LTD.	48 TOH GUAN ROAD EAST #05- 155 ENTERPRISE HUB SINGAPORE 608586	Jie Ren / 94316186	10:00- 13:00	SKE3933G	18/8/20:
6	MUHAMMAD AIRWAN	MT/1058310-002	SMJ888Z	WILLIAM'S AUTO PTE LTD	391B WOODLANDS ROAD BLK 3 YEY TEE	Ang Ngoh Tee / 67636811		SFQ3637H	15/8/20:

					INDUSTRIAL ESTATE SINGAPORE 677965			
--	--	--	--	--	---	--	--	--

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Daniel Koh
Senior Admin Assistant
Motor Insurance
T +65 6430 7901
www.income.com.sg

 income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

RE: TP CASES FARMED OUT TO LKK ON 20/8/2019 - MT/1056623-002


Fiona Shen <fiona.shen@income.com.sg>

Fri 6/9/2019 9:09 AM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Hi,


FBF7533C Report as below:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling behind vehicle B. As I did not notice that vehicle B had slowed down and came to a complete stop, thus I hit into the rear left area of vehicle B.

SFW113R Report as below:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Turning into Paterson Road on 5th Aug 2019 approx. 1845 at a speed of 25km/hr and when I stopped, FBF7533C knocked into the rear of my car SFW113R. Weather was fine & Mr Chen, rider of FBF7533C admitted he ran into my car and provided me with his insurance NTUC Income policy number 5066535850-04 for claims purpose.

Thank you

Best Regards

Precise Appraiser Pte Ltd

Reg no. 201924041Z

Invoice

To: Neo Kai Kiat Clifford

Invoice No: 2019/INV/0008

CC: MTM PERFORMANCE AUTO PTE. LTD.

Your Reference: SFW113R

42 Toh Guan Road East #01-78

Our Reference: 2019/0009

Enterprise hub

Date : 26/8/2019

Singapore 608583

Decription	Amount S\$
<u>Particular</u>	
Vehicle No: SFW113R	
Accident Date : 5/8/2019	
Date of Inspection: 15/8/2019	
<u>Service:</u>	
Assesment with report (inclusive of photographs and transport charges etc)	\$479
Total Amount:	\$479

We would appreciate your cheque to be crossed and make payable to:

Precise Appraiser Pte Ltd

or bank transfer to details below:

Maybank account no: 041-9107653-9



Precise Appraiser Pte Ltd

Address: 53 Hume Avenue, #05-08, Singapore 598751,
Email: Preciseappraiser@gmail.com, Mobile: +65 9103 5000

To: Neo Kai Kiat Clifford

CC: MTM PERFORMANCE AUTO PTE. LTD.
42 Toh Guan Road East #01-78
Enterprise hub
Singapore 608583

REFERENCES

Ref No	: 2019/0009	Date of Report	: 19/8/2019
Claim Type	: Third Party	Date of Request	: 15/8/2019
Third party vehicle	: SFW113R	Date of Accident	: 5/8/2019
Insured Vehicle	:	Date of Inspection	: 15/8/2019
Your Reference No	:		

DAMAGED VEHICAL PARTICULARS

Registration Plate No	: SFW113R	Engine Modification	: NIL
Model / Make	: Mercedes GLE43 AMG	Pre-accident damage	: NIL
Colour	: Black	General Condition	: Good
Manufacturing Year	: 2017	General Paint Work	: Good
Engine No	: 27682130642079	Steering	: Serviceable
Engine Capacity	: 3000cc	Handbrake	: Serviceable
Chassis No	: WDC2923642A086004	Footbrake	: Serviceable
Odometer No	: 8937		
Transmission	: Auto		

TYRES CONDITION

Front Right		Rear Left	
Make	: Continental	Make	: Bridgestone
Size	: 285/40 R22 7	Size	: 325/35 R22 7
Front Left		Rear Right	
Make	: Continental	Make	: Bridgestone
Size	: 285/40 R22 7	Size	: 325/35 R22 7

The above millimetres represent the remaining life of tyre treads


VEHICAL REPAIR COST

Descriptions	Repairer (\$\$)	Difference (\$\$)	Adjuster (\$\$)
Parts	10,619.04		7,195.44
Labour	4,400.00		3,200.00
Calculated Cost (\$\$):	15,019.04	4,623.60	10,395.44

Recommended Lump Sum Repair Cost (\$\$) : 8,300.00
 Estimate Repair Duration : 6
 Survey Inspection At : MTM PERFORMANCE AUTO PTE. LTD.
 Survey Inspection Address : 42 Toh Guan Road East #01-78
 Enterprise Hub
 Singapore 608583

DESCRIPTION OF DAMAGE

At the time of inspection, this vehicle sustained damages to the **Rear portion**. Please see attached scheduled details.



SPECIAL REMARKS

We have not authorised repair. Under normal circumstances, estimated 6 working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



Automotive Appraiser
MSAAA

Disclaimer:

This survey was conducted by Precise Appraiser Pte Ltd without prejudice basis and we do not authorized repair. Report by Precise Appraiser Pte Ltd is deemed as confidential and provided for the use of clients and appointed agent. We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle. All findings and recommendations are listed accordingly and final decision of settlement to your good selves parts thereof accordingly and final. No liability shall be attached to Precise Appraiser Pte Ltd therefore.

Our Reference : 2019/0009

Your Reference:

Vehicle Number : SFW113R

S/N	Qty	Description	Condition	Repairer Estimate (\$\$)	Our Assessment (\$\$)
		Parts			
1	1pcs	Rear bumper	Dented / Deformed	2235.33	2235.33
2	1pcs	Rear bumper LH vent	Scarp	82.14	82.14
3	2pcs	Rear bumper Sensor (LH)	Malfunction	280	280
4	1pcs	Rear bumper lower spoiler	Cut	1920.02	1920.02
5	1pcs	Tailgate	Repair	3288	-
6	2pcs	Emblem "GLE 63"	Necessary	132.42	132.42
7	1pcs	Emblem "AMG"	Necessary	82.14	82.14

Total 8020.05 4732.05
Less 5% 401.0025 236.6025
Parts Sub Total 7619.0475 4495.4475

4732.05
10%
4258.84

Special Nett

7	1pcs	Rear Bumper protective sticker	Necessary	1200	1100 300
8	1pcs	Rear Bumper spoiler protective sticker	Necessary	800	700 200
9	1pcs	Tailgate protective sticker	Necessary	1000	900 200
		Total		3000	2700

700

Labour			
1	To check wiring system	200	100 X
2	To R&R Rear Sensor and transfer attachment	300	250 60
6	To reset and programme and accident repair	600	450 100
8	To panel beat on rear end panel, tailgate. To R&R rear bumper and lower spoiler and others attachments.	1500	1200 400
9	To respray on rear bumper, rear bumper lower spoiler, rear end panel, tailgate and accident affected area.	1800	1200 600
	Labour Total	4400	3200
	Sub Total (labour and parts)	15019.0475	10395.4475

1160

4258.84
700.00
1160.00
6118.84
20%
4895.07

14618.04

Adjustment / Recommendations

Note: For Lump Sum Repair

The workshop has agreed to undertake the repair on a Lump Sum Basis, and/or use of ex-stock/reconditioned parts whichever is possible (having taken into consideration to repair instead of replacements).

The final adjusted Lump Sum contract amount is **\$58300**

Under normal circumstances, the repair period would be about 6 working days.

Address: 53 Hume Avenue, #05-08, Singapore 598751,
Email: Preciseappraiser@gmail.com, Mobile: +65 9103 5000

4 days
23/9/2019

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS3/INC19014640/R1sd3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date : 23-09-2019

189556



Code : INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBF 7533C	Veh. Inspected	SFW 113R
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1056623-002	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	20/08/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ GLE43 AMG	c.c	3000
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WDC2923642A086004	Colour	BLACK
Odometer	9013	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	325/35 ZR22	CONTINENTAL	6 mm
L/H Front Tyre	325/35 ZR22	CONTINENTAL	6 mm
R/H Rear Tyre	325/35 ZR22	CONTINENTAL	6 mm
L/H Rear Tyre	325/35 ZR22	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SYSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	05/08/2019	Inspection Date	20/08/2019
Survey held at	MTM PERFORMANCE AUTO PTE. LTD. 48 TOH GUAN ROAD EAST #01-115 ENTERPRISE HUB SINGAPORE 608586		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFW 113R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED / DEFORMED	2,235.33	2,235.33
1	REAR BUMPER LH VENT	SCARP	82.14	82.14
2	REAR BUMPER SENSOR (LH)	MALFUNCTION	280.00	280.00
1	REAR BUMPER LOWER SPOILER	CUT	1,920.02	1,920.02
1	TAILGATE	TO REPAIR SEE LABOUR	3,288.00	-
2	EMBLEM "GLE 63"	NECESSARY	132.42	132.42
1	EMBLEM "AMG"	NECESSARY	82.14	82.14
	LESS 10% DISCOUNT		-802.01	-473.21
			7,218.04	4,258.84
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER PROTECTIVE STICKER (SN)	NECESSARY	1,200.00	300.00
1	REAR BUMPER SPOILER PROTECTIVE STICKER (SN)	NECESSARY	800.00	200.00
1	TAILGATE PROTECTIVE STICKER (SN)	NECESSARY	1,000.00	200.00
			3,000.00	700.00
	<u>LABOUR</u>			
	TO CHECK WIRING SYSTEM.	NOT NECESSARY	200.00	-
	TO R&R REAR SENSOR AND TRANSFER ATTACHMENT.		300.00	60.00
	TO RESET AND PROGRAME AND ACCIDENT REPAIR.		600.00	100.00
	TO PANEL BEAT ON REAR END PANEL, TAILGATE, TO R&R REAR BUMPER AND LOWER SPOILER AND OTHERS ATTACHMENTS. INCLUSIVE OF THE REPAIR OF TAILGATE.		1,500.00	400.00
	TO RESPRAY ON REAR BUMPER, REAR BUMPER LOWER SPOILER, REAR END PANEL, TAILGATE AND ACCIDENT AFFECTED AREA.		1,800.00	600.00
			4,400.00	1,160.00
	GRAND TOTAL		14,618.04	6,118.84
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,900.00

Report Ref No. CS3/INC19014640/R1sd3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.