

ASS. REC. BY:

REF: CS/INC/19014647/R/ld3

Special Instruction:

Surge: Rasu

ASSIGNMENT (Office)

From (Person): Daniel Koh

of INC

Date/Time: 20/8/19 @ 6.22pm

Estimated Cost:

Bill to:

OD (P) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

S4x 2788M

Insured:

SME 93554

at Workshop in/

Auto wheel

Tel:

9192 8963

of

No 1 Bukit Batok Crescent #02-40

Policy No:

Claim No:

MT/1057356-002

Sum Insured:

Process:

Make of Veh:

(Client's Record)

D.O.A.

10/2/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

20/8/19 @ 10.03am

Person Contacted:

Louis

Vehicle:

IN/OUT

Date/Time

Action/Instruction

10/08/19 ✓

S4x 2788 M - X

SME 93554 - X.

3/9/19

@242pm Louis said parts just arrived.

6/9/19

LS \$7200 confirmed by email (Ref 22,344,66, 769)

ISS. REC. BY

REF:

INC

8082

ASSIGNMENT

From:

Date:

2018/19

Veh No:

SGX 2788M

Tr Regn: 2016 / SEP

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SGX 2788M

Make:

MERCEDES Benz GLA 200

c.c 1595

at Workshop m/s

Auto wheel

Colour:

Red

A/C: Insured / Std / NI / NA

of

No 1 Bukit Batok Crescent #02-40

Sp. Reading

83087

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

WDC1569432J 245761

Claims No.

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Louis @ 9/9/2018

Modi: Nil / S/Rim / STD A/Rim or

10am - 12pm

Tyre Size:

F: 235/50R18

R: 1 ^

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CONTINENTAL

Bel. or Market Value:

112K

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen.

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

10/08/19

D.O.I.

20/08/19

Lum Sum:

%

3 Val: Yes or No

Survey held at

Auto wheel

11:27am

CA / REV / REP. / 24 HRS

(up)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 09 SEP 2019

Date/Time, File Pass to?

☐

: Prel. Report

If

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

6

Resurvey No. of Trip:

2

9/9 - typst

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Wheel end (\$

Report Format:

TP

Lump Sum / H.B. / \$

7200/-

Survey Fee:

Transportation:

\$ + PS \$

Phone:

Other:

TOTAL

250

Nivitha (LKK Auto)

From: Daniel Koh <daniel.koh@income.com.sg>
Sent: Tuesday, 20 August 2019 6:22 PM
To: 'assignments@lkkauto.com'
Cc: admin-d@lkkauto.com
Subject: FW: TP CASES FARMED OUT TO LKK ON 20/8/2019

R E S E N D with claim number & OIC

From: Daniel Koh
Sent: Tuesday, 20 August 2019 9:39 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: FW: TP CASES FARMED OUT TO LKK ON 20/8/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OIV	DOA	Additional Remarks
1	CHRYLLIS QUAH	MT/1057350- 002	SGX2788M	AUTO WHEELS MOTOR WORKS	No.1 BUKIT BATOK CRESCENT #02-40	Louis Ong / 91928963	10:00- 12:00	SMF9355G	10/8/2019	Customer waiting

2		Claim no and OIC will revert later	SFW113R	MTM PERFORMANCE AUTO PTE LTD	48 TOH GUAN ROAD EAST #01-78 ENTERPRISE HUB SINGAPORE 608583	Erwin Ho / 92210404				
3	CHRYLLIS QUAH	MT/1058341- 001	SLL427Y	SK AUTOMOBILE PTE LTD	48 TOH GUAN ROAD EAST #01- 121 ENTERPRISE HUB SINGAPORE 608586	Yvette Zhao / 6266 0555	SJP745SY	15/8/2019		
4	AZHARI	MT/1058476- 001	SKJ5161C	VAG SINGAPORE PTE. LTD.	48 TOH GUAN ROAD EAST #04- 123 ENTERPRISE HUB SINGAPORE 608586	Jie Ren / 6267 9916	GBD8624C	17/8/2019		
5	MUHAMMAD AIRWAN	MT/1058234- 002	SKK2543Z	VAG SINGAPORE PTE. LTD.	48 TOH GUAN ROAD EAST #05- 155 ENTERPRISE HUB SINGAPORE 608586	Jie Ren / 94316186	SKE3933G	18/8/2019	Owner waiting	
6	MUHAMMAD AIRWAN	MT/1058310- 002	SMJ888Z	WILLIAM'S AUTO PTE LTD	391B WOODLANDS ROAD BLK 3 YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965	Ang Nghoh Tee / 67636811	SFQ3637H	15/8/2019		

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Daniel Koh
Senior Admin Assistant
Motor Insurance
T +65 6430 7901
www.income.com.sg

income
made different



in with
you

At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 9 September 2019 9:14 AM
To: Louis Ong; Rasul (LKKAUTO); SUR
Subject: RE: Finalize for vehicle SGX2788M Lumpsum \$10,000/- with 6 repair days

Dear Louis,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Louis Ong <louisongautowheels@yahoo.com>
Sent: Friday, 6 September 2019 8:18 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: Re: Finalize for vehicle SGX2788M Lumpsum \$10,000/- with 6 repair days

Hi Veron,

Amount confirmed.

We will submit our LOD to NTUC 1 weeks later for your side to prepare the report.

Thanks

Auto Wheels Motorworks PTE LTD

Louis Ong

91928963

On Friday, 6 September 2019 10:06:48 AM +08, Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Louis,

WITHOUT PREJUDICE

Offer Lump Sum \$7200/- @ 6 working days

PARTS-\$7961.90 (less 10%)=7165.71

LABOUR-\$1820

TOTAL-\$8985.71 (less 20%)=7188.57

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Louis Ong <louisongautowheels@yahoo.com>
Sent: Wednesday, 4 September 2019 8:04 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Finalize for vehicle SGX2788M Lumpsum \$10,000/- with 6 repair days

Hi Rasul,

The above attachment is the finalize and after paint photo.

Can help to Finalize for vehicle SGX2788M Lumpsum \$10,000/- with 6 repair days.

No Supplementary.

Please check and revert.

Thanks

Auto Wheels Motorworks PTE LTD

Louis Ong

91928963

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Details	
Owner ID Type:	Singapore NRIC
Owner ID:	8041
Vehicle Details	
Vehicle No.:	SGX2788M
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Aug 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	GLA200 URBAN (R18 BI)
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	27091030938273
Chassis No.:	WDC1569432J245761
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$29,142.00
Original Registration Date:	02 Sep 2016
First Registration Date:	02 Sep 2016
Transfer Count:	1
Actual ARF Paid:	\$27,799.00
Intended PARF/COE Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Sep 2026
PARF Rebate Amount:	\$20,849.00
Intended COE Rebate Details	
COE Expiry Date:	01 Sep 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,089.00
COE Rebate Amount:	\$39,428.00
Total Rebate Amount:	\$60,277.00

The information contained herein is correct as at 21 Aug 2019

OK

112,000
60,277

51,723

50k

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/08/2019 13:24
Date Of Accident	10/08/2019 18:45
Exact Location Of Accident	JALAN DATO SULAIMAN- JOHOR BAHRU
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGX2788M
Insured/Policyholder	
Name Of Registered Owner	SOO YONG SERN
NRIC No	S8671804I
Email Address	JOSEPHSOO1603@GMAIL.COM
Mobile Phone No	(LOCAL) +65-83215675
Alternative Phone No	OFFICE-83215675

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	GLA200 URBAN (R18 BI)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA452607/1
Cover Note Number	16/03/2019-15/03/2020

Driver

Name of Driver	SOO YONG SERN
NRIC No	S8671804I
Date Of Birth	16/03/1986
Occupation	INDOOR
Date Of Driving Pass	07/05/2019
Driving Experience	0 YEAR AND 3 MONTH
Gender	MALE
Mobile Number	+65-83215675
Fax Number	
Contact Number	OFFICE-83215675
Email Address	JOSEPHSOO1603@GMAIL.COM

Address	818B CHOA CHU KANG AVE 1 13-128
Postcode	682818
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : SONIA CHEW WEI LIN GENDER: : FEMALE
Passenger 2	NAME: : SEAN JACOB SOO GENDER: : MALE
Passenger 3	NAME: : CEZEIL NAMOCA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMF9355G
Vehicle Make/Model/Colour	BMW X1
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	BASANTA KUMAR DASH
NRIC/Passport Number	S2661146F

Contact Number

81127202

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

E. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name: _____
NRIC/FIN No.: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a **FOURTEEN (14) DAYS CLAUSE** WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.

- | | |
|-------------------------------------|---------------------------------|
| ☐ | - Reporting Only |
| ☐ | - Claim OD |
| ☐ | - Claim TP |
| ☒ | - Claim OD/TP at other workshop |

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

Policyholder's signature
Date & Time

Driver's Signature
(If driver not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
Nric/Fin No.

AXA FORM



POLICYHOLDER ACKNOWLEDGEMENT FORM

Date: 12/01/2017

To: Owner of Vehicle Number: SGYD 705M

The following has been advised to you via your workshop, ETHOZ PROTECT PTE LTD through their staff, rehab

Please tick the applicable box if you had been advised on any of the following

- ☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence
- ☒ You had been advised by the workshop on the liability and merits of the case accordingly
- ☒ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident
- ☐ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to import it from overseas
- ☐ There will be no cancellation/withdrawal of the Own Damage claim once the order of spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- ☐ The estimated waiting time for the spare parts to arrive is _____ The estimated arrival time does not include the repair period.
- ☐ You will be driving the vehicle out despite being advised by the workshop mechanic/ personnel that the vehicle may not be road worthy.
- ☐ For vehicles below three (3) years old or under warranty with a local distributor, your insurance company will use only original parts to repair your vehicle.
For vehicles above three (3) years old and no longer under warranty with a local distributor, your insurance company will be carrying out repairs where any damaged part that can be repaired will be repaired and any part that needs to be replaced will be replaced using **any combination** of original parts and/or original equipment manufacturer (OEM) parts and/or second-hand parts.
- ☐ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- ☐ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.

Others: Claim 3rd party

Signed and acknowledged by

Name and signature of policyholder/ authorized driver* and company stamp (where applicable)

*authorized driver is either the named drivers as per motor insurance policy or in the case of commercial vehicles, permitted drivers who are permitted to drive the insured Vehicle.

Name and signature of workshop personnel including company stamp



TRAFFIC POLICE
AMENDMENT

Traffic Police Department
Charge Office
10 Ubi Avenue 3
Singapore 408865


NP 168 No: T/20190813/2060 Name: SON YONG SEEN
Accident Date/Time: 10/08/2019 - 1846HRS Address: BLK 818B CHEN CHU KAHN APT
Vehicle(s) involved: QGX 2786 #1 1 #13-128 S(682818)
SME 9355 G1 NRIC No: S86718041
Tel No: 8321 5645
Date: 13/08/2019

Dear Sir / Madam

I wish to amend as follows:

ON THE ABOVE DATE AND TIME 10/08/2019 - 1846HRS, I WAS DRIVING
JALAN DATO SULAIMAN- TRAFFIC LIGHT TURN GREEN, I MAKE A LEFT TURN
SUDDENLY VEHICLE SME 9355G HIT ONTO MY VEHICLE. I HAVE VIDEO
TO PROVE THE TRAFFIC IS ON MY FAVOUR.

Yours faithfully





**SINGAPORE
POLICE FORCE**



T/20190813/2060

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

1 of 4

Report No. T/20190813/2060

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/08/2019 13:02		Vide Report No.:		Station Diary No.: 24	
Informant's Particulars					
Name of Informant: SOO YONG SERN			Address: APT BLK 818B CHOA CHU KANG AVENUE 1 #13-128 SINGAPORE 682818		
ID Type / ID No.: NRIC NO / S86718041			Contact No.: Home/Office: Mobile: 83215675		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 33	Date of Birth: 16/03/1986	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: MANAGER			Driving Licence Information: Class: 3A Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 10/08/2019 18:45	Type of Location: T-Junction
Location: Along Road 1 CAUSEWAY Jalan Dato Sulaiman - Johor Bahru				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SGX2788M	Car	MERCEDES BENZ	GLA200 URBAN (R18 BI)	Red	Slightly Damaged	4
SMF9355G	Car				Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
-------------	-------------------	---------------	-----------	-------------



**SINGAPORE
POLICE FORCE**



T/20190813/2060

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

2 of 4
Report No. T/20190813/2060

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SGX2788M	AXA INSURANCE SINGAPORE PTE LTD	GA452607	16/03/2019	15/03/2020

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	SOO YONG SERN		ID No.	S8671804I
Related Vehicle	SGX2788M (Car)		Contact No.	83215675
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL
Driver				
Name	basantha kumar dash		ID No.	S2661146F
Related Vehicle	SMF9355G (Car)		Contact No.	81127202
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL

Brief Details.

On the 10th of August 2019, at around 1846hrs, I was driving my Car bearing the registration plate number SGX2788M along Jalan Dato Sulaiman in Johor Bahru. As I was reaching the junction of the said location, the traffic light was red. My intention was to turn left after the traffic light had turn green. As soon as the traffic light turned green, I moved forward. Suddenly a car bearing the registration plate SMF9355G drove in front of me from my right. I could not stop in time and thus, the front of my car bumped into the left rear of his car.

No one was injured. I made a check and there were damages to the front right bumper of my car. On the other party's vehicle, the damages were dents above the rear left wheel and also scratches along its left rear side. I wish to state that there are in car camera's in my car and I have the footage of which shows that the traffic light was in my favor.

I am lodging this report for insurance claims purposes.



**SINGAPORE
POLICE FORCE**



T/20190813/2060

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

3 of 4

Report No. T/20190813/2060

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20190813/2060

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

4 of 4

Report No. T/20190813/2060

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: D / Sgt 2 NABIL FIKRI BIN ADNAN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 13/08/2019 13:02
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:
Authentication Stamp NP188	

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: NTUC INCOME INSURANCE

DATE: 13/08/2019

VEHICLE NO: SGX2788M

MODEL: MERCEDES GLA 200

YEAR: 2016

ACCIDENT DATE: 10/8/2019

TYPE OF CLAIM: TP

CLAIM ADVISOR: LOUIS (91928963)

EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
BONNET	1	REPAIR
BONNET LOCK X 500	1	\$ 453.10
FRONT GRILLE ASSY ? X 500	1	\$ 987.40
FRONT GRILLE CENTRE BRACKET ? X 300	1	\$ 194.30
FRONT GRILLE EMBLEM ? X 500	1	\$ 366.80
FRONT GRILLE CLIPS new /	10	\$ 30.00
FRONT EMBLEM new /	1	\$ 78.50
FRONT BUMPER new /	1	\$ 2,310.90 1645
FRONT BUMPER CLIPS new /	10	\$ 50.00
RH FRONT BUMPER RETAINER new /	1	\$ 188.60
FRONT BUMPER LOWER SPOILER new /	1	\$ 1,167.50 280
FRONT BUMPER CENTRE DIFFUSER - SILVER new /	1	\$ 1,105.60 678
FRONT BUMPER CENTRE LOWER GRILLE ? X 500	1	\$ 465.30
FRONT NUMBER PLATE GARNISH new /	1	\$ 321.60
FRONT BUMPER RUBBER SEAL ? X 500	1	\$ 299.50
TOWING COVER ? X 500	1	\$ 130.20
FRONT REINFORCEMENT ? X 500	1	\$ 798.10
FRONT BUMPER SPONGE ? X 500	1	\$ 297.50
SUPPORT PANEL TOP PANEL ? X 500	1	\$ 789.10
SUPPORT SIDE PANEL ? RH - LH - X 500	1	\$ 889.60
HEADLAMP new / RH - LH - ? X 500	2	\$ 7,733.80 @ 2360 (1pc)
HEADLAMP TOP PANEL ? X 500	2	\$ 884.60

19522

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: NTUC INCOME INSURANCE

DATE: 13/08/2019
VEHICLE NO: SGX2788M
MODEL: MERCEDES GLA 200
YEAR: 2016
ACCIDENT DATE: 10/8/2019
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

RH HEADLAMP NOZZLE COVER	mis / X one replace	1	\$	210.40
RH HEADLAMP NOZZLE	?	1	\$	390.70
RH HEADLAMP NOZZLE MOTOR	? X su	1	\$	415.30
RH HEADLAMP NOZZLE PIPE	? X su	1	\$	254.20
RH FOGLAMP COVER	? X su	1	\$	346.80
RH FRONT FENDER	repair	1	\$	1,657.30
RH FRONT FENDER INNER SHIELD	de /	1	\$	453.20
RH FRONT FENDER INNER SHIELD CLIPS	re /	10	\$	50.00
RH FRONT FENDER ARC GARNISH	su /	1	\$	476.40
RH FRONT FENDER ARC GARNISH CLIPS	re /	8	\$	40.00
RH FRONT DOOR		1		REPAIR
FRONT SENSOR	? X su	X 2 pcs	\$	1,052.40
FRONT SENSOR HOLDER	re / 106.40	X 2 pcs	\$	212.80
CONDENSER	X su	1	\$	1,997.50
RH FRONT ABSORBER	X su	1	\$	978.40
RH FRONT KNUCKLE ARM	? X su	1	\$	875.30
RH FRONT LOWER ARM	? X su	1	\$	653.20
RH FRONT UPPER ARM	X su	1	\$	675.30
RH FRONT CASTER ARM	X su	1	\$	587.40
RH FRONT WHEEL HUB	? X su	1	\$	432.10
RH FRONT WHEEL HUB BEARING	? X su	1	\$	396.40
RH FRONT TIE ROD	X	1	\$	299.50
RH FRONT TIE ROD END	X } 8 su	1	\$	298.40
RH FRONT STABILIZER LINK	X	1	\$	311.30

13064.7

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: NTUC INCOME INSURANCE

DATE: 13/08/2019
VEHICLE NO: SGX2788M
MODEL: MERCEDES GLA 200
YEAR: 2016
ACCIDENT DATE: 10/8/2019
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

RH FRONT RIM	1	\$	1,978.60
ENGINE LOWER DASH COVER	1	\$	646.30
ENGINE LOWER DASH COVER CLIPS	10	\$	50.00

TOTAL:	\$	28,077.40
DISCOUNT 10%:	\$	2,807.74
	\$	25,269.66

S/NET

COOLANT	1	\$	50.00
FRONT NUMBER PLATE	1	\$	45.00
TOTAL:	\$	95.00	

LABOUR

	PRICE
LABOUR FOR FACILITATE REPAIR	\$ 1,500.00
TO RESPRAY AFFECTED AREAS - BONNET	\$ 300.00
TO RESPRAY AFFECTED AREAS - FRONT BUMPER	\$ 300.00
TO RESPRAY AFFECTED AREAS - REINFORCEMENT AND SUPPORT	\$ 300.00
TO RESPRAY AFFECTED AREAS - RH FRONT FENDER	\$ 250.00

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: NTUC INCOME INSURANCE

DATE: 13/08/2019
VEHICLE NO: SGX2788M
MODEL: MERCEDES GLA 200
YEAR: 2016
ACCIDENT DATE: 10/8/2019
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

TO REMOVE AND REFIT AIRCON CONDENSER INCLUDING TOP UP AIRCON GAS
TO DIAGNOSE AND RESET BACK TO ORIGINAL SETTING
TO CHECK AND RECONNECT ALL NECESSARY WIRING
TO REMOVE AND REFIT RH FRONT UNDERCARRIAGE
WHEEL ALIGNMENT
TO REMOVE AND ROTATE RH FRONT RIM
TO REFIT FRONT SENSOR
SUNDARIES
RUST PROOFING

\$	200.00	100?	X 1.7
\$	350.00	200	
\$	100.00	30	
\$	350.00	100?	X 1.7
\$	120.00	60	
\$	80.00	50	
\$	150.00	60	
\$	80.00	20	
\$	100.00	50	
TOTAL: \$	4,180.00		

TOTAL: \$	29,544.66	36028.08
7% GST: \$	2,068.13	
\$	31,612.79	

Repaired
21/8/19
Hp 90010068

6 days
48

20/08/19 @ 1130

Repay after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: NTUC INCOME INSURANCE

DATE: 13/08/2019
VEHICLE NO: SGX2788M
MODEL: MERCEDES GLA 200
YEAR: 2016
ACCIDENT DATE: 10/8/2019
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louis@autowheels@yahoo.com

ESTIMATION

DESCRIPTION

QTY

LIST PRICE

PARTS

BONNET

BONNET LOCK X

FRONT GRILLE ASSY ? SVC

FRONT GRILLE CENTRE BRACKET ? SVC

FRONT GRILLE EMBLEM ? SVC

FRONT GRILLE CLIPS per /

FRONT EMBLEM ne /

FRONT BUMPER Taper /

FRONT BUMPER CLIPS ne /

RH FRONT BUMPER RETAINER ne /

FRONT BUMPER LOWER SPOILER side /

FRONT BUMPER CENTRE DIFFUSER - SILVER sea /

FRONT BUMPER CENTRE LOWER GRILLE ? SVC

FRONT NUMBER PLATE GARNISH sea /

FRONT BUMPER RUBBER SEAL ? X SVC

TOWING COVER ? SVC

FRONT REINFORCEMENT ? SVC

FRONT BUMPER SPONGE ? checked

SUPPORT PANEL TOP PANEL ? X SVC

SUPPORT SIDE PANEL ? RH - LH - X SVC

HEADLAMP CR / RH / LH - ? SVC

HEADLAMP TOP PANEL ? SVC

1

1

1

1

1

10

1

1

10

1

1

1

1

1

1

1

1

1

1

2

2

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

REPAIR

X 453.10

X 987.40

X 194.30

X 366.80

/ 30.00

/ 78.50

/ 2,310.90

/ 50.00

/ 188.60

/ 1,167.50

/ 1,105.60

X 465.30

/ 321.60

X 299.50

X 130.20

X 798.10

/ 297.50

X 789.10

X 889.60

/ 7,733.80

X 884.60

3,866.90

9,417.10

2-434

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: NTUC INCOME INSURANCE

DATE: 13/08/2019
VEHICLE NO: SGX2788M
MODEL: MERCEDES GLA 200
YEAR: 2016
ACCIDENT DATE: 10/8/2019
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louis@autowheels@yahoo.com

ESTIMATION

RH HEADLAMP NOZZLE COVER	mis	1	\$	210.40
RH HEADLAMP NOZZLE	? * ✓ crack.	1	\$	390.70
RH HEADLAMP NOZZLE MOTOR	? X SVC	1	\$	X 415.30
RH HEADLAMP NOZZLE PIPE	? X SVC	1	\$	X 254.20
RH FOGLAMP COVER	? X SVC	1	\$	X 346.80
RH FRONT FENDER	repair	1	\$	R 1,657.30
RH FRONT FENDER INNER SHIELD	de	1	\$	453.20
RH FRONT FENDER INNER SHIELD CLIPS	re	10	\$	50.00
RH FRONT FENDER ARC GARNISH	sea	1	\$	476.40
RH FRONT FENDER ARC GARNISH CLIPS	re	8	\$	40.00
RH FRONT DOOR		1		REPAIR
FRONT SENSOR	? X SVC	X 2 pcs	\$	X 1,052.40
FRONT SENSOR HOLDER	re	X 2 pcs	\$	212.80
CONDENSER	X	1	\$	X 1,997.50
RH FRONT ABSORBER	X	1	\$	X 978.40
RH FRONT KNUCKLE ARM	? SVC	1	\$	X 875.30
RH FRONT LOWER ARM	? SVC	1	\$	X 653.20
RH FRONT UPPER ARM	X	1	\$	X 675.30
RH FRONT CASTER ARM	X	1	\$	X 587.40
RH FRONT WHEEL HUB	? SVC	1	\$	X 432.10
RH FRONT WHEEL HUB BEARING	? SVC	1	\$	X 396.40
RH FRONT TIE ROD	X	1	\$	X 299.50
RH FRONT TIE ROD END	X	1	\$	X 298.40
RH FRONT STABILIZER LINK	X	1	\$	X 311.30

1,727.40

3-484

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: NTUC INCOME INSURANCE

DATE: 13/08/2019
 VEHICLE NO: SGX2788M
 MODEL: MERCEDES GLA 200
 YEAR: 2016
 ACCIDENT DATE: 10/8/2019
 TYPE OF CLAIM: TP
 CLAIM ADVISOR: LOUIS (91928963)
 EMAIL: louis@autowheels@yahoo.com

ESTIMATION

RH FRONT RIM *repair*
 ENGINE LOWER DASH COVER ? *✓ cracked*
 ENGINE LOWER DASH COVER CLIPS ? *✓ Nec.*

1	\$	R	1,978.60
1	\$	✓	645.30
10	\$	✓	50.00

TOTAL:	\$	28,077.40
DISCOUNT 10%:	\$	2,807.74
	\$	25,269.66

11,840.50
 10%
 10,656.45

S/NET
 COOLANT ?
 FRONT NUMBER PLATE X

1	\$	X	50.00
	\$	X	45.00
TOTAL:	\$		95.00

LABOUR

LABOUR FOR FACILITATE REPAIR
 TO RESPRAY AFFECTED AREAS - BONNET
 TO RESPRAY AFFECTED AREAS - FRONT BUMPER
 TO RESPRAY AFFECTED AREAS - REINFORCEMENT AND SUPPORT
 TO RESPRAY AFFECTED AREAS - RH FRONT FENDER

PRICE
\$ 1,500.00 <i>600</i>
\$ 300.00 <i>250</i>
\$ 300.00 <i>250</i>
\$ 300.00 <i>7 X</i>
\$ 250.00

1350

4-4

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: NTUC INCOME INSURANCE

DATE: 13/08/2019
VEHICLE NO: SGX2788M
MODEL: MERCEDES GLA 200
YEAR: 2016
ACCIDENT DATE: 10/8/2019
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

TO REMOVE AND REFIT AIRCON CONDENSER INCLUDING TOP UP AIRCON GAS	\$	X 200.00 100?
TO DIAGNOSE AND RESET BACK TO ORIGINAL SETTING	\$	350.00 200
TO CHECK AND RECONNECT ALL NECESSARY WIRING	\$	100.00 30
TO REMOVE AND REFIT RH FRONT UNDERCARRIAGE	\$	X 350.00 100?
WHEEL ALIGNMENT	\$	120.00 60
TO REMOVE AND ROTATE RH FRONT RIM	\$	80.00 50 470
TO REFIT FRONT SENSOR	\$	150.00 60
SUNDARIES	\$	80.00 20
RUST PROOFING	\$	100.00 50 L: 1820
TOTAL:	\$	4,180.00

TOTAL: \$ 29,544.66
7% GST: \$ 2,068.13
\$ 31,612.79

total: 12,476.45
LS 10,000/=

6 days

Rene
Hp 90010068

6 days
48

20/08/19 @ 1130

Ready after repair

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Ref: CS/INC19014647/R1vd3n2

Date: 09-09-2019



ATTN: CHRYLLIS QUAH

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMF 9355G	Veh. Inspected	SGX 2788M
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1057350-002	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	20/08/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ GLA200	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDC1569432J245761	Colour	RED
Odometer	83087 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50 R18	CONTINENTAL	6 mm
L/H Front Tyre	235/50 R18	CONTINENTAL	6 mm
R/H Rear Tyre	235/50 R18	CONTINENTAL	6 mm
L/H Rear Tyre	235/50 R18	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/08/2019	Inspect Date / Time	20/08/2019 (11:27 AM)
Survey held at	AUTO WHEELS MOTORWORKS PTE LTD NO 1 BUKIT BATOK CRESCENT #02-40 WCEGA PLAZA SINGAPORE 658064		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGX 2788M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET (NPA)	TO REPAIR SEE LABOUR	-	-
1	BONNET LOCK	SERVICEABLE	453.10	-
1	FRONT GRILLE ASSY	SERVICEABLE	987.40	-
1	FRONT GRILLE CENTRE BRACKET	SERVICEABLE	194.30	-
1	FRONT GRILLE EMBLEM	SERVICEABLE	366.80	-
10	FRONT GRILLE CLIPS	NECESSARY	30.00	30.00
1	FRONT EMBLEM	NECESSARY	78.50	78.50
1	FRONT BUMPER	TORN	2,310.90	1,645.00
10	FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	RH FRONT BUMPER RETAINER	NECESSARY	188.60	188.60
1	FRONT BUMPER LOWER SPOILER	DEFORMED	1,167.50	280.00
1	FRONT BUMPER CENTRE DIFFUSER-SILVER	SCRATCHED	1,105.60	678.00
1	FRONT BUMPER CENTRE LOWER GRILLE	SERVICEABLE	465.30	-
1	FRONT NUMBER PLATE GARNISH	SCRATCHED	321.60	321.60
1	FRONT BUMPER RUBBER SEAL	SERVICEABLE	299.50	-
1	TOWING COVER	SERVICEABLE	130.20	-
1	FRONT REINFORCEMENT	SERVICEABLE	798.10	-
1	FRONT BUMPER SPONGE	CRACKED	297.50	297.50
1	SUPPORT PANEL TOP PANEL	SERVICEABLE	789.10	-
2	SUPPORT SIDE PANEL	SERVICEABLE	889.60	-
2	HEADLAMP	O/S CRACKED / N/S SERVICEABLE	7,733.80	2,360.00
2	HEADLAMP TOP PANEL	SERVICEABLE	884.60	-
1	RH HEADLAMP NOZZLE COVER	MISSING	210.40	210.40
1	RH HEADLAMP NOZZLE	SERVICEABLE	390.70	-
1	RH HEADLAMP NOZZLE MOTOR	SERVICEABLE	415.30	-
1	RH HEADLAMP NOZZLE PIPE	SERVICEABLE	254.20	-
1	RH FOGLAMP COVER	SERVICEABLE	346.80	-
1	RH FRONT FENDER	TO REPAIR SEE LABOUR	1,657.30	-
1	RH FRONT FENDER INNER SHIELD	DEFORMED	453.20	453.20

Report Ref No. CS/INC19014647/R1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	RH FRONT FENDER INNER SHIELD CLIPS	NECESSARY	50.00	50.00
1	RH FRONT FENDER ARC GARNISH	SCRATCHED	476.40	476.40
8	RH FRONT FENDER ARC GARNISH CLIPS	NECESSARY	40.00	40.00
1	RH FRONT DOOR (NPA)	TO REPAIR SEE LABOUR	-	-
4	FRONT SENSOR	SERVICEABLE	1,052.40	-
4	FRONT SENSOR HOLDER	NECESSARY (2 PCS ONLY)	212.80	106.40
1	CONDENSER	SERVICEABLE	1,997.50	-
1	RH FRONT ABSORBER	SERVICEABLE	978.40	-
1	RH FRONT KNUCKLE ARM	SERVICEABLE	875.30	-
1	RH FRONT LOWER ARM	SERVICEABLE	853.20	-
1	RH FRONT UPPER ARM	SERVICEABLE	675.30	-
1	RH FRONT CASTER ARM	SERVICEABLE	587.40	-
1	RH FRONT WHEEL HUB	SERVICEABLE	432.10	-
1	RH FRONT WHEEL HUB BEARING	SERVICEABLE	396.40	-
1	RH FRONT TIE ROD	SERVICEABLE	299.50	-
1	RH FRONT TIE ROD END	SERVICEABLE	298.40	-
1	RH FRONT STABILIZER LINK	SERVICEABLE	311.30	-
1	RH FRONT RIM	SERVICEABLE	1,978.60	-
1	ENGINE LOWER DASH COVER	CRACKED	646.30	646.30
10	ENGINE LOWER DASH COVER CLIPS	NECESSARY	50.00	50.00
	LESS 10% DISCOUNT		-3,528.12	-796.19
			31,753.08	7,165.71
	<u>SPECIAL NETT ITEMS</u>			
1	COOLANT (SN)	NOT NECESSARY	50.00	-
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	45.00	-
1	SUNDARIES (SN)	NECESSARY	80.00	20.00
			175.00	20.00
	<u>LABOUR</u>			
	LABOUR FOR FACILITATE REPAIR.INCLUSIVE OF THE REPAIR OF BONNET,RH FRONT FENDER AND RH FRONT DOOR.		1,500.00	600.00
	TO RESPRAY AFFECTED AREAS-BONNET.		300.00	250.00

Report Ref No. CS/INC19014647/R1vd3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY AFFECTED AREAS-FRONT BUMPER.		300.00	250.00
	TO RESPRAY AFFECTED AREAS-REINFORCEMENT AND SUPPORT.	NOT NECESSARY	300.00	-
	TO RESPRAY AFFECTED AREAS-RH FRONT FENDER.		250.00	250.00
	TO REMOVE AND REFIT AIRCON CONDENSER INCLUDING TOP UP AIRCON GAS.	NOT NECESSARY	200.00	-
	TO DIAGNOSE AND RESET BACK TO ORIGINAL SETTING.		350.00	200.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRING.		100.00	30.00
	TO REMOVE AND REFIT RH FRONT UNDERCARRIAGE.	NOT NECESSARY	350.00	-
	WHEEL ALIGNMENT.		120.00	60.00
	TO REMOVE AND ROTATE RH FRONT RIM.		80.00	50.00
	TO REFIT FRONT SENSOR.		150.00	60.00
	RUST PROOFING.		100.00	50.00
			4,100.00	1,800.00
GRAND TOTAL			36,028.08	8,985.71
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				7,200.00

Report Ref No. CS/INC19014647/R1vd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.