

2007/2011
S.E. REC. 1538

REF: 08/INC/19014649/11yd3n2 Special Instruction:

Summary: Tyutuh

ASSIGNMENT (Office)

From (Person): Daniel Koh

of INC

Date/Time: 2011/11/09 9:39am

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLL 427 Y

Insured: SJP 7155Y

at Workshop in/s SK Automobile

Tel: 6266 0555

of 48 tuh Guan Rd East #01-121

Policy No: _____

Claim No: MT/1058341-001

Sum Insured: _____

Excess: _____

Make of Veh:
(Client's Record)

D.O.A. 15/8/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 10:30am 20/11/19

Person Contacted: _____

Yvette

Vehicle IN / OUT

Date/Time	Action/Instruction	Voluntary
	<u>SLL 427 Y - X</u>	
	<u>SJP 7155Y - NA/INC/11024871/s2</u>	<u>2011/11/20/2011</u>

Nivitha (LKK Auto)

From: Daniel Koh <daniel.koh@income.com.sg>
Sent: Tuesday, 20 August 2019 6:22 PM
To: 'assignments@lkkauto.com'
Cc: admin-d@lkkauto.com
Subject: FW: TP CASES FARMED OUT TO LKK ON 20/8/2019

R E S E N D with claim number & OIC

From: Daniel Koh
Sent: Tuesday, 20 August 2019 9:39 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: FW: TP CASES FARMED OUT TO LKK ON 20/8/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OIV	DOA	Additional Remarks
1	CHRYLLIS QUAH	MT/1057350- 002	SGX2788M	AUTO WHEELS MOTOR WORKS	No.1 BUKIT BATOK CRESCENT #02-40	Louis Ong / 91928963	10:00- 12:00	SMF9355G	10/8/2019	Customer waiting

2		Claim no and OIC will revert later	SFW113R	MTM PERFORMANCE AUTO PTE LTD	48 TOH GUAN ROAD EAST #01-78 ENTERPRISE HUB SINGAPORE 608583	Erwin Ho / 92210404				
3	CHRYLLIS QUAH	MT/1058341-001	SLL427Y	SK AUTOMOBILE PTE LTD	48 TOH GUAN ROAD EAST #01-121 ENTERPRISE HUB SINGAPORE 608586	Yvette Zhao / 6266 0555	SJP7455Y	15/8/2019		
4	AZHARI	MT/1058476-001	SKJ5161C	VAG SINGAPORE PTE. LTD.	48 TOH GUAN ROAD EAST #04-123 ENTERPRISE HUB SINGAPORE 608586	Jie Ren / 6267 9916	GBD8624C	17/8/2019		
5	MUHAMMAD AIRWAN	MT/1058234-002	SKK2543Z	VAG SINGAPORE PTE. LTD.	48 TOH GUAN ROAD EAST #05-155 ENTERPRISE HUB SINGAPORE 608586	Jie Ren / 94316186	SKE3933G	18/8/2019	Owner waiting	
6	MUHAMMAD AIRWAN	MT/1058310-002	SMJ888Z	WILLIAM'S AUTO PTE LTD	391B WOODLANDS ROAD BLK 3 YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965	Ang Ngho Tee / 67636811	SFQ3637H	15/8/2019		

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Daniel Koh
Senior Admin Assistant
Motor Insurance
T +65 6430 7901
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at Income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Yvonne Wong (LKK Auto)

From: Pioneer Workshop <pioneer@skauto.com.sg>
Sent: Thursday, September 12, 2019 5:30 PM
To: SUR
Subject: SLL427Y - Finalization
Attachments: Aft (3).jpeg; Aft (2).jpeg; Aft (1).jpeg; Aft (4).jpeg; Aft (5).jpeg; Aft (6).jpeg

Hi ,

As spoken, we confirm finalization @ lumsup \$5,100.00 and 7Days.

After repair photos attached.

--

Thanks & Regards,

Yvette Zhao

SK Automobile Pte Ltd

48 Toh Guan Road East # 01-121

Enterprise Hub, Singapore 608586

D: +65 6266 0555 | F: +65 6266 3155 | pioneer@skauto.com.sg

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/08/2019 08:42
Date Of Accident	15/08/2019 15:40
Exact Location Of Accident	BKE TWDS WOODLANDS CHECKPOINT BEFORE SLE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL427Y
Insured/Policyholder	
Name Of Registered Owner	CHEW SWEE SIANG
NRIC No	S8627565A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91016753
Alternative Phone No	OTHERS-91016753

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC 1.8L A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA466028/1
Cover Note Number	

Driver

Name of Driver	CHEW SWEE SIANG
NRIC No	S8627565A
Date Of Birth	22/09/1986
Occupation	INDOOR
Date Of Driving Pass	27/01/2010
Driving Experience	9 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91016753
Fax Number	
Contact Number	OTHERS-91016753
Email Address	NOEMAIL

Address	488C CHOA CHU KANG AVE 5 #08-153 SPORE 683488
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJP7455Y
Vehicle Make/Model/Colour	TOYOTA / VIOS E AUTO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: J. L. L.
NRIC/PPN No.: 1208-1111

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING ALONG BKE TOWARD WOODLANDS CHECK POINT ON THE 3RD LANE OF A LANE ROAD, EXPRESSWAY SOMEWHERE BEFORE SUE EXIT, VEHICLE IN FRONT OF ME SLOWED DOWN AND STOPPED DUE TO THE HEAVY TRAFFIC FLOW. AS SUCH, I ALSO APPLIED BRAKE AND MANAGE TO STOPPED COMPLETELY. OUT OF A SUDEN, I FELT A STRONG IMPACT FROM THE REAR PORTION OF MY VEHICLE. AFTER THE ACCIDENT, I ALIGHTED AND REALISE THAT VEHICLE (B) DROVE FROM THE REAR AND COLLIDED DIRECTLY ONTO THE REAR PORTION OF MY VEHICLE.

A - SLL 427 Y

B - SJP 7455 Y

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Capitol 5/1/21 10:29

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: J. L. M.

HRIC/IRI No.: 12002177A

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)
48 Toh Guan Road Esat #01-121
Enterprise Hub S(608586)
Tel: 6266 0555 Fax : 6266 3155

TO	: NTUC	DATE	: 17-Aug-19
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
ESTIMATE REPORT :			
OWNER PARTICULAR		VEHICLE DETAILS	
NAME	:	VEHICLE NO.	: SLL427Y
ADDRESS	:	MODEL / MAKE	: HONDA CIVIC
TEL. NO.	:	CHASSIS NO.	: JHMF163075218421
OWNER INSURANCE	: AXA	ACCIDENT DETAIL	
POLICY NO.	: GA466028/1	DATE	: 15-Aug-19
		TIME	: 15:40hrs
PERSON INCHARGE	:		

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BOOT LID	1	\$ 690.20	\$ <i>bt</i> 690.20
2	REAR BOOT LID LOGO EMBLEM	1	\$ 25.70	\$ <i>rel</i> 25.70
3	REAR BOOT LID CIVIC EMBLEM	1	\$ 29.10	\$ <i>rel</i> 29.10
4	REAR BOOT LID REFLECTOR LAMP LH/RH	2	\$ 165.90	\$ <i>rel</i> 331.80
5	REAR BOOT LID NUMBER PLATE LAMP LH/RH	2	\$ 28.20	\$ <i>x un</i> 56.40
6	REAR BOOT LID NUMBER PLATE LAMP GARNISH	1	\$ 121.60	\$ <i>x un</i> 121.60
7	REAR BOOT LID HINGE LH/RH	2	\$ 109.40	\$ <i>Rx</i> 218.80
8	REAR BOOT LID RUBBER GUIDE STOPPER LH/RH	4	\$ 21.60	\$ <i>x un</i> 86.40
9	REAR BOOT LID MECHANISM LOCK	1	\$ 115.10	\$ <i>bt</i> 115.10
10	REAR BOOT LID WEATHER STRIP	1	\$ 97.60	\$ <i>rel</i> 97.60
11	REAR TAILLAMP LH/RH	2	\$ 266.20	\$ <i>one</i> 532.40
12	REAR TAILLAMP INNER PANEL LH/RH	2	\$ 95.60	\$ <i>Rx</i> 191.20
13	REAR TAILLAMP LOWER BRACKET LH/RH	2	\$ 23.40	\$ <i>bt</i> 46.80
14	REAR BUMPER	1	\$ 678.20	\$ <i>dev</i> 678.20
15	REAR BUMPER SIDE RETAINER LH/RH	2	\$ 24.60	\$ <i>rel</i> 49.20
16	REAR END PANEL	1	\$ 360.40	\$ <i>bt</i> 360.40
17	REAR END PANEL INNER TOP GARNISH	1	\$ 96.10	\$ <i>de</i> 96.10
18	REAR END PANEL LOCK STRIKER	1	\$ 28.20	\$ <i>x un</i> 28.20
19	REAR END PANEL LOCK STRIKER COVER	1	\$ 22.80	\$ <i>x un</i> 22.80
20	REAR WINDSCREEN MOULDING	1	\$ 54.20	\$ <i>x un</i> 54.20
21	REAR FENDER RH	1	\$ 780.20	\$ <i>Rx</i> 780.20
22	REAR FENDER INNER AIR VENT RH	1	\$ 35.70	\$ <i>x un</i> 35.70
23	REAR FENDER INNER UPHOLSTERY TRIM RH	1	\$ 225.40	\$ <i>x un</i> 225.40
24	SPARE TYRE PANEL	1	\$ 992.20	\$ <i>Rx</i> 992.20
25	SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD	1	\$ 308.30	\$ <i>de</i> 308.30
26	REAR EXHAUST SILENCER BOX	1	\$ 535.40	\$ <i>bt</i> 535.40
27	REAR EXHAUST ALUMINIUM HEAT SHIELD	1	\$ 43.70	\$ <i>bt</i> 43.70

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	REAR EXHAUST RUBBER MOUNTING	2	\$ 28.20	\$ 56.40

TOTAL PRICE \$ 6,809.50

LESS -20% \$ (1,361.90)

SUB TOTAL PRICE \$ 5,447.60

3996.40

3197.12

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BOOT LID SEALANT	1	\$ 60.00	\$ 60.00
2	REAR BOOT LID REFLECTOR LAMP CLIPS SET LH/RH	2	\$ 30.00	\$ 60.00
3	REAR BOOT LID NUMBER PLATE WITH CASING SET	1	\$ 65.00	\$ 65.00
4	REAR BOOT LID NUMBER PLATE LAMP GARNISH CLIPS SET	1	\$ 40.00	\$ 40.00
5	REAR TAILLAMP INNER PANEL SEALANT LH/RH	2	\$ 40.00	\$ 80.00
6	REAR TAILLAMP CLIPS SET LH/RH	2	\$ 30.00	\$ 60.00
7	REAR BUMPER LOWER LIP (MUGEN)	1	\$ 1,480.00	\$ 1,480.00
8	REAR BUMPER REVERSE SENSOR SET	1	\$ 280.00	\$ 280.00
8	REAR BUMPER CLIPS SET	1	\$ 60.00	\$ 60.00
9	REAR END PANEL SEALANT	1	\$ 80.00	\$ 80.00
10	REAR END PANEL INNER TOP GARNISH CLIPS SET	1	\$ 40.00	\$ 40.00
11	REAR WINDSCREEN SEALANT WITH PRIMER SET	1	\$ 100.00	\$ 100.00
12	REAR FENDER SEALANT RH	1	\$ 100.00	\$ 100.00
13	REAR FENDER INNER UPHOLSTERY TRIM CLIPS SET RH	1	\$ 50.00	\$ 50.00
14	SPARE TYRE PANEL SEALANT	1	\$ 120.00	\$ 120.00
15	SPARE TYRE PANEL INSULATOR MAT	1	\$ 380.00	\$ 380.00
16	REAR EXHAUST GASKET	1	\$ 35.00	\$ 35.00

TOTAL

\$ 3,090.00

1135

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,800.00	800.
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,600.00	900/000
TO APPLY ANTI-RUST & TUFF KOTE	\$ 150.00	30
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30.
TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$ 380.00	X nh
TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR	\$ 250.00	X nh
TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM	\$ 150.00	X nh
TO PERFORM TRANSFER REAR BOOT LID MECHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION	\$ 150.00	60
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	30.
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT LH/RH TO PERFORM FACILITATE REPAIRS	\$ 280.00	X nh
TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	\$ 100.00	X nh
TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING	\$ 180.00	60.
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	60.
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	X nh.

TOTAL

\$ 5,560.00

2070

QUOTATION SUMMARY

PAGE 04

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	8,537.60
TOTAL LABOUR COST	:	\$	5,560.00
TOTAL REPAIR COST	:	\$	<u>14,097.60</u>

APPROVED DETAILS

EXCESS :
NO. OF REPAIR DAYS :
RE-SURVEY :
P / P OR L / S :

DATE / TIME OF SURVEY :
SURVEYED BY / FROM :
CONTACT NUMBER :
FAX NUMBER :
EMAIL ADDRESS :

Tamplin 97495749
20/8/19 @ 2:15pm
Lumpsum - WP
Repay after repair
sure want.com.
07 days.

3197.12.
1135
2070
6402.12.
41545100. #



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19014649/T1yd3n2
73 BRAS BASAH ROAD Date: 25-09-2019
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556



ATTN: CHRYLLIS QUAH

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJP 7455Y	Veh. Inspected	SLL 427Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1058341-001	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	20/08/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC 1.8L	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JHMF16307S218421	Colour	WHITE
Odometer	84926 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	GOODYEAR	6 mm
L/H Front Tyre	225/45 R17	GOODYEAR	6 mm
R/H Rear Tyre	225/45 R17	GOODYEAR	6 mm
L/H Rear Tyre	225/45 R17	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/08/2019	Inspect Date / Time	20/08/2019 (02:13 PM)
Survey held at	48 TOH GUAN RD EAST # 01-121		
Repairer	SK AUTOMOBILE PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 427Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	BENT	690.20	690.20
1	REAR BOOT LID LOGO EMBLEM	NECESSARY	25.70	25.70
1	REAR BOOT LID CIVIC EMBLEM	NECESSARY	29.10	29.10
2	REAR BOOT LID REFLECTOR LAMP LH/RH @\$165.90	CRACKED	331.80	331.80
2	REAR BOOT LID NUMBER PLATE LAMP LH/RH @\$28.20	NOT NECESSARY	56.40	-
1	REAR BOOT LID NUMBER PLATE LAMP GARNISH	NOT NECESSARY	121.60	-
2	REAR BOOT LID HINGE LH/RH @\$109.40	TO REPAIR SEE LABOUR	218.80	-
4	REAR BOOT LID RUBBER GUIDE STOPPER LH/RH @\$21.60	NOT NECESSARY	86.40	-
1	REAR BOOT LID MECHANISM LOCK	BENT	115.10	115.10
1	REAR BOOT LID WEATHER STRIP	TWISTED	97.60	97.60
2	REAR TAILLAMP LH/RH @\$266.20	CRACKED	532.40	532.40
2	REAR TAILLAMP INNER PANEL LH/RH @\$95.60	TO REPAIR SEE LABOUR	191.20	-
2	REAR TAILLAMP LOWER BRACKET LH/RH @\$23.40	BENT	46.80	46.80
1	REAR BUMPER	DEFORMED	678.20	678.20
2	REAR BUMPER SIDE RETAINER LH/RH @\$24.60	NECESSARY	49.20	49.20
1	REAR END PANEL	BENT	360.40	360.40
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	96.10	96.10
1	REAR END PANEL LOCK STRIKER	NOT NECESSARY	28.20	-
1	REAR END PANEL LOCK STRIKER COVER	NOT NECESSARY	22.80	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	54.20	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	780.20	-
1	REAR FENDER INNER AIR VENT RH	NOT NECESSARY	35.70	-
1	REAR FENDER INNER UPHOLSTERY TRIM RH	NOT NECESSARY	225.40	-
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	992.20	-
1	SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD	DEFORMED	308.30	308.30
1	REAR EXHAUST SILENCER BOX	BENT	535.40	535.40
1	REAR EXHAUST ALUMINIUM HEAT SHIELD	BENT	43.70	43.70

Report Ref No. CS/INC19014649/T1yd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR EXHAUST RUBBER MOUNTING @\$28.20	DEFORMED	56.40	56.40
	LESS 20% DISCOUNT		-1,361.90	-799.28
			5,447.60	3,197.12
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BOOT LID SEALANT (SN)	NOT NECESSARY	60.00	-
2	REAR BOOT LID REFLECTOR LAMP CLIPS SET LH/RH @\$30.00 (SN)	NOT NECESSARY	60.00	-
1	SET REAR BOOT LID NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	65.00	-
1	SET REAR BOOT LID NUMBER PLATE LAMP GARNISH CLIPS (SN)	NOT NECESSARY	40.00	-
2	REAR TAILLAMP INNER PANEL SEALANT LH/RH @\$40.00 (SN)	NOT NECESSARY	80.00	-
2	REAR TAILLAMP CLIPS SET LH/RH @\$30.00 (SN)	NECESSARY	60.00	20.00
1	REAR BUMPER LOWER LIP (MUGEN)(SN)	DEFORMED	1,480.00	700.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	NOT WORKING	280.00	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	40.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	40.00	10.00
1	SET REAR WINDSCREEN SEALANT WITH PRIMER (SN)	NOT NECESSARY	100.00	-
1	REAR FENDER SEALANT RH (SN)	NOT NECESSARY	100.00	-
1	REAR FENDER INNER UPHOLSTERY TRIM CLIPS SET RH (SN)	NOT NECESSARY	50.00	-
1	SPARE TYRE PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
1	SPARE TYRE PANEL INSULATOR MAT (SN)	CRACKED	380.00	100.00
1	REAR EXHAUST GASKET (SN)	NECESSARY	35.00	35.00
			3,090.00	1,135.00
	<u>LABOUR</u>			
	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION.INCLUSIVE OF THE REPAIR OF REAR BOOT LID HINGE LH/RH,REAR TAILLAMP INNER PANEL LH/RH,REAR FENDER RH AND SPARE TYRE PANEL.		1,800.00	800.00
	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA.		1,600.00	1,000.00
	TO APPLY ANTI-RUST & TUFF KOTE.		150.00	30.00

Report Ref No. CS/INC19014649/T1yd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PERFORM LIGHTING & WIRING CHECK.		80.00	30.00
	TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION.	NOT NECESSARY	380.00	-
	TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR.	NOT NECESSARY	250.00	-
	TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM.	NOT NECESSARY	150.00	-
	TO PERFORM TRANSFER REAR BOOT LID MACHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION.		150.00	60.00
	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING.		80.00	30.00
	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT LH/RH TO PERFORM FACILITATE REPAIRS.	NOT NECESSARY	280.00	-
	TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING.		180.00	60.00
	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR.		280.00	60.00
	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION.	NOT NECESSARY	80.00	-
			5,560.00	2,070.00
	GRAND TOTAL		14,097.60	6,402.12
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			5,100.00

Report Ref No. CS/INC19014649/T1yd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.