

LIAN HENG PAINTER COMPANY

160 Sin Ming Drive #06-10
Sin Ming AutoCity (S) 575722
Tel: 6453 5779

Vehicle No: E9A
Model: Lexus LX570
Chassis No: JTJHY00W104174472
Claim Type: OD

Date: 19.08.2019

1	Front bumper / CFA	1		\$	1,050.00
2	Front bumper number plate base X NN	1		\$	93.00
3	Front bumper centre grille / cc	1		\$	450.00
4	Front bumper retainer LH/RH < LH X NN	2		\$	145.00
5	Front bumper centre beam - BT HH	1		\$	155.00
6	Front bumper absorber / CFA	1		\$	190.00
7	Front bumper reinforcement ?	1		\$	700.00
8	Radiator grille A / BR	1		\$	1,220.00
9	Radiator grille base ?	1		\$	102.00
10	Radiator emblem X - SCR.	1		\$	756.00
11	Radiator grille seal ?	1		\$	29.00
12	Bonnet / Guc	1		\$	1,875.00
13	Bonnet hook X { NN	1		\$	137.50
14	Bonnet lock X { LH ?	1		\$	117.00
15	Headlamp LH/RH < RH - BR	2		\$	9,325.00
16	Radiator support panel X Repair.	1		\$	1,860.00
17	Radiator deflector LH/RH X ?	2		\$	286.00
18	Brace panel ?	1		\$	88.00
19	Oil cooler ?	1		\$	1,293.00
20	Aircon condenser ?	1		\$	1,970.00
21	Aircon fan assy ?	1		\$	1,255.00
22	Radiator ?	1		\$	3,375.00
23	Radiator fan shroud ?	1		\$	295.00
24	Radiator fan blade ?	1		\$	307.00
25	Radiator fan motor ?	1		\$	555.00

Bonnet Hinge x 2 - BT

Total: \$ 27,628.50
-10% \$ 2,762.85
List total: \$ 24,865.65

1	Front number plate / CFA	1		\$	50.00
2	Front bumper clips / MCC	1set		\$	50.00
3	Radiator support top cover clips / MCC	1set		\$	50.00
4	Bonnet insulator clips / MCC	1set		\$	30.00
5	Radiator coolant ?	1		\$	40.00

S.Nett total: \$ 220.00

Parts Total: \$ 25,085.65

- Rust proofing on affected area.
- To check lightings & wirings. Reset fault codes & programme all related.

AN \$ X 60.00
\$ 30 80.00

- | | | | | |
|---|---|------|--------|----------|
| 3 | Renew aircon condenser, refill gas R134. | \$ | 200.00 | ? |
| 4 | Renew intercooler & radiator. Depressurise & conduct cooling test. | \$ | 150.00 | ? |
| 5 | To remove and renew damaged parts. Re-align all affected area. | 4 no | \$ | 1,500.00 |
| 6 | To putty and respray all damaged parts. Touch up all affected area. | 6 no | \$ | 1,800.00 |

Labour Total: \$ 3,790.00

Grand Total: \$ 28,875.65

Remarks

This is only an estimate based on visual inspection. Should there be further damages found during process of repair, you will be informed prior before we carry out further repairs.

Lian Heng Painter Company

5 Days.

part by part.

before paint photos.

Lim Qiang - 82880282

21/8/19

Not Authorised

Excess \$1500

LEK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: