

ASS. REC. BY:

REF: CS/CTI 190 14653/UVF3/12

Special Instruction:

Surveyor: MORCUS

ASSIGNMENT (Office)

From (Person): Tan Kah Hong of CTI Date/Time: 21.8.19 15.17PM

Estimated Cost: Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBB 8359D Insured: GBD 7359A

at Workshop m/s Automobile Hub Tel: 9786 4483

of 1 Kaki Bukit Ave 5 # 2-4

Policy No: DMCRSV/6178719033 Claim No: SVM19D203848C02

Sum Insured: Excess:

Make of Veh: D.O.A. 19.8.19
(Client's Record)

CA / REV / REP. / REV 24 HRS "sup"

Date/Time: 21.8.19 340PM Person Contacted: Mr Lim H.O.D. Endorsement:

Vehicle: IN OUT

Date/Time	Action/Instruction (✓) Estimate
	GBB 8359D - AM/INC 190146491114 D.O.A. - 19/08/2019
	GBD 7359A - AM/INC 190146491114 REP. - 19/08/2019

Naiman

ASSIGNMENT

From: _____ Date: **22.8.2019**

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **GBB 8359 D**

at Workshop n/s: **Automobile Hub**

of: **1 Kaki Bukit Ave 5 # 2-11**

Insured: _____

Policy No.: _____

Claims No.: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: **GBB 8359 D** Yt Regn: **5, 07**

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**

Truck / Trailer or: **(M)**

Make: **Toyota hiace** c.c: **2982**

Colour: **white** A/C: **Insured / Std / NI / NA**

Sp. Reading: **372036** T/Ratio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: **JTFHT02P00'000'3850**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **Good** / Jammed / Leaked / Burnt or

Brake: **Good** / Jammed / Leaked / Burnt or

Modi: **(N)** / S/Rim / STD A/Rim or

Tyre Size: F: **195R15**

R: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: **20k**

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **4** days Res: Yes or No

Lum Sum: **20** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS **rep** **547B**

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **ULTIMEX**

Front	Rear
R/Bal. 5 mm	R/Bal. 5 mm
L/Bal. 5 mm	L/Bal. 5 mm

D.O.A. **19/8/19** D.O.I. **22/8/19**

Survey held at: **320th Ave. 12**

Des. of Damages: **Frnt / Rear / O/S / N/S / U/C / Rooftop or**

n/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	27.8.19
	Cor 29-5-2002 LTA 12328
26/8/19	n/s @ 2300 conf. with AH Xiong (Recd 12, 158-35, 847)

RECEIVED 27 AUG 2019

Date/Time, File Pass to? : Preli. Report : Final Report

1) _____

Date/Time, File Return to? **27/8 - typist**

2) _____

Report Format: **Merimen**

Lump Sum / I.B.I: (\$) **2300/-**

Days Of Repair: **4**

Resurvey No. of Trip: **1**

Add Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)

Survey Fee: _____

Transportation: _____

_____ \$ + RS. _____

TOTAL: **220**

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Aug 2019		21 Aug 2019 15:17 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

Main Claimant: **SING YI AN PLUMBING & SANITARY CONTRACTOR**, Co. Reg. No.: 52980547BVehicle Reg. No.: **GBB8359D** Date of Loss: 19/08/2019 13:00 - :59Claim Type: **TP / SNM19D203848C02** Policy/Cover Note No.: DMCVSN16178719033Vehicle Reg. No. (Insured): **GBD7359A** Policy No. (Claimant): 5104652703

Excess: S\$500.00

Repairer: **Automobile Hub Enterprise () 1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:**Handling Insurer: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]**Claimant's Insurer: **NTUC Income Insurance Co-operative Ltd (HQ) - Tel:**Adjuster: **LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/08/2019]**

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

[-]

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Wednesday, 21 August 2019 3:12 PM
To: Cindy Tan; assignments
Subject: RE: OUR REF: SNM19D203848-GBD7359A-TKL - RE: Yref: GBD 7359A Oref: KSG/5000/2019/S/ct

WITHOUT PREJUDICE

Dear Cindy,

We refer to your email dated 21.08.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Cindy Tan [mailto:cindy.tan@kannansg.com.sg]
Sent: Wednesday, 21 August, 2019 3:07 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D203848-GBD7359A-TKL - RE: Yref: GBD 7359A Oref: KSG/5000/2019/S/ct

Dear Mr Tan

WITHOUT PREJUDICE

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : SING YI AN PLUMBING & SANITARY CONTRACTOR (UEN NO: 52980547B)
ACCIDENT INVOLVING VEHICLES NO. GBB 8359D (OWNER), & GBD 7359A AT THE OPEN CARPARK OF BLOCK 283 YISHUN AVENUE 6 ON 19 AUGUST 2019 AT 1305 HRS
PRE-REPAIR INSPECTION NOTICE

We refer to the above matter and to your email dated 21 August 2019.

We are instructed to propose using Mr Marcus Chua as the single joint expert as listed in your said email.

Kindly contact Mr Lim at 9786 4483 to arrange for the pre-repair inspection soonest possible.

Regards

Cindy Tan

M/S KANNAN SG
Advocates & solicitors
50 Chin Swee Road
#08-03 Thong Chai Building
Singapore 169874

TEL: (+65) 6429 0253

FAX: (+65) 6223 1660

IMPORTANT: THIS E-MAIL IS INTENDED ONLY FOR THE USE OF THE ADDRESSEE AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE COVERED BY PROFESSIONAL PRIVILEGE. IT MUST NOT BE READ, USED OR DISCLOSED BY ANY PERSON OTHER THAN THE ADDRESSEE(S) NAMED. IF YOU HAVE RECEIVED THIS E-MAIL IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE (COLLECT INTERNATIONAL CALL IF APPROPRIATE) AT (+65) 6429 0252 OR BY E-MAIL AND DELETE THE E-MAIL IMMEDIATELY. THANK YOU.

From: Tan Kah Leong [<mailto:KahLeong.Tan@sg.cntaiping.com>]

Sent: Wednesday, 21 August, 2019 9:22 AM

To: Cindy Tan

Subject: RE: OUR REF: SNM19D203848-GBD7359A-TKL - RE: Yref: GBD 7359A Oref: KSG/5000/2019/S/ct

Without Prejudice

Dear Cindy,

We refer to your email dated 19 August 2019.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
LOW SAR HUEI
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
HONG FOOK CHOY
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Tuesday, 20 August, 2019 10:30 AM
To: Cindy Tan <cindy.tan@kannansg.com.sg>; Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>
Subject: OUR REF: SNM19D203848-GBD7359A-TKL - RE: Yref: GBD 7359A Oref: KSG/5000/2019/S/ct

Dear Kah Leong,

Please conduct PRS for GBB8359D.

Note Officer in charge – Kah Leong 63896193.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Cindy Tan [<mailto:cindy.tan@kannansg.com.sg>]
Sent: Monday, 19 August, 2019 5:25 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Yref: GBD 7359A Oref: KSG/5000/2019/S/ct

Dear Sirs / Mdm

WITHOUT PREJUDICE

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : SING YI AN PLUMBING & SANITARY CONTRACTOR (UEN NO: 52980547B)

ACCIDENT INVOLVING VEHICLES NO. GBB 8359D (OWNER), & GBD 7359A AT THE OPEN CARPARK OF BLOCK 283 YISHUN AVENUE 6 ON 19 AUGUST 2019 AT 1305 HRS
PRE-REPAIR INSPECTION NOTICE

We act for M/s Sing Yi An Plumbing & Sanitary Contractor, the owner of motor vehicle No. GBB 8395D, which was involved in the aforesaid accident.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle at our client's workshop. The details are as follows:-

Place: M/s Automobile Hub Enterprise
1 Kaki Bukit Avenue 6
#02-11 Autobay@Kaki Bukit
Singapore 417883

Contact Person: Mr Lim - 9786 4483

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Kindly revert.

Regards

Cindy Tan

M/S KANNAN SG
Advocates & solicitors
50 Chin Swee Road
#08-03 Thong Chai Building
Singapore 169874

TEL: (+65) 6429 0253
FAX: (+65) 6223 1660

IMPORTANT: THIS E-MAIL IS INTENDED ONLY FOR THE USE OF THE ADDRESSEE AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE COVERED BY PROFESSIONAL PRIVILEGE. IT MUST NOT BE READ, USED OR DISCLOSED BY ANY PERSON OTHER THAN THE ADDRESSEE(S) NAMED. IF YOU HAVE RECEIVED THIS E-MAIL IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE (COLLECT INTERNATIONAL CALL IF APPROPRIATE) AT (+65) 6429 0252 OR BY E-MAIL AND DELETE THE E-MAIL IMMEDIATELY. THANK YOU.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>



Hiace Price Range Depreciation > 10 year Vehicle Type Submit Advanced Search

Home > Used Cars > KSL Automotive Pte Ltd > Toyota Hiace 3.0M (COE till 08/2022)

Toyota Hiace 3.0M (COE till 08/2022)

Overview Financial Accessories Similar Research Photos Map



Price	\$24,800	Lifespan	16-Aug-2027
Depreciation	\$8,300 /yr	Reg Date	17-Aug-2007 (2yrs 11mths 25days COE left)
Mileage	N.A.	Manufactured	2007
Road Tax	N.A.	Transmission	Manual
Dereg Value	\$10,703 as of today (change)	OMV	\$24,590
COE	\$17,920	No. of Owners	2
Engine Cap	2,982 cc		
Curb Weight	1,820 kg		
Type of Vehicle	Van		



Shortlist Compare Add note Report Error More Actions

Features

One Of The Most Reliable Workhorse Van For Sale Now! Drive With No Worries! 100% Loan Available! View specs of the Toyota Hiace.

Accessories

DVD Player! Full Wooden Board!

Description

Best Selling 5 Doors Van In The Market! No Repair Needed! Handle By A Careful Driver! Door Step Viewing Can Be Arrange! Call Our Friendly Sales Person For More Information!

Category

COE Car

Status

Available

Resources

STA Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more

Compare Car Valuation - Free
Find out the market value of your existing car for free. Get started

Seller Information

Company	KSL Automotive Pte Ltd • dealer's pricelist • 30 vech sold 87 vech available	
Address	2A Kian Teck Avenue Level 3 Search cars nearby this location	
Office No	62660777	
Contact Person(s)	Yi Kai Dylan	91317600 86886676

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	547B
Vehicle Details	
Vehicle No.:	GBB8359D
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	1KD1631624
Chassis No.:	JTFHT02P000003850
Maximum Power Output:	-
Open Market Value:	\$24,590.00
Original Registration Date:	30 May 2007
First Registration Date:	30 May 2007
Transfer Count:	1
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$22,263.00
COE Rebate Amount:	\$12,328.00
Total Rebate Amount:	\$12,328.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 22 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/08/2019 16:03
Date Of Accident	19/08/2019 13:05
Exact Location Of Accident	283 YISHUN AVE 6 OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBB8359D
Insured/Policyholder	
Name Of Registered Owner	SING YI AN PLUMBING & SANITARY CONTRACTOR
Co Reg No	52980547B
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-93805950

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104652703
Cover Note Number	-

Driver

Name of Driver	JEE SOON SIANG
NRIC No	G7444379L
Date Of Birth	05/07/1985
Occupation	INDOOR
Date Of Driving Pass	05/09/2018
Driving Experience	0 YEAR AND 11 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-83878210
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 190 MIDDLE ROAD #19-05 FORTUNE CENTRE SINGAPORE
 Postcode 188979
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

MY VEH WAS PARKED AT THE BLK 283 YISHUN AVE 6, EVERYTHING WAS INTACT, I WENT TO THE NEARBY COFFEE SHOP HAVE MY LUNCH, SUDDENLY I HEAR A "BANG" SONG THEN I SAW A LORRY WHILE MOVING OUT FROM THE LOT AND HIT ONTO MY VEH LEFT REAR PORTION, AFTER THE IMPACT, THE LORRY REVERSED BACK TO THE LOT.


Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD7359A
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver LIM JET SUAN
 NRIC/Passport Number S7219245A
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to statement

DECLARATION

I/We declare that the following particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

AUTOMOBILE HUB ENTERPRISE

51 Defu Lane 9, Singapore 539291

H/P: 9786 4483 @Ah Siong

Fax: 6758 3325

Email: autohub325@gmail.com

*Not Authorized
Hah
2/8/19 - 1/5 @ 2300 / Hby
to kept. After 1/5*

Vehicle No.: GB88369D

Model: Toyota Hiace

<u>QTY</u>	<u>DESCRIPTION</u>	<u>AMT</u>	<u>SS</u>
	<u>List Items</u>		
1	Rear windscreen moulding	11	\$ 130.50 X
1	Rear tailgate	R	\$ 1,793.50 X
2	Rear tailgate dampers	11	\$ 508.40 X
2	Rear tailgate hinges	11	\$ 137.10 X
1	Rear tailgate inner board	11	\$ 286.90 X
1	Rear tailgate lock	11	\$ 223.30 X
1	Rear tailgate lock striker	11	\$ 48.50 X
1	Rear tailgate logo	11	\$ 61.90 X
1	Rear tailgate outer garnish	11	\$ 219.20 X
1	Rear tailgate rubber	11	\$ 328.50 X
2	Rear tailgate side stoppers	11	\$ 85.20 X
2	Rear tailgate number plate lamps	11	\$ 90.00 X
2	Rear taillamps	N/S 20	\$ 771.00 1PC
2	Rear taillamp panels	R	\$ 923.80 X
2	Rear taillamp lower garnishes	N/S 20	\$ 230.00 1PC
1	Rear end panel	11	\$ 887.90 X
1	Rear end panel top moulding	11	\$ 108.60 X
1	Rear end panel inner member	11	\$ 896.50 X
1	Rear bumper	R	\$ 695.20 X
2	Rear bumper brackets	11	\$ 57.20 X
1	Rear bumper clip (1 set)	11	\$ 50.00 X
2	Rear bumpers -side	11	\$ 270.00 X
2	Rear bumper side retainers	11	\$ 65.00 X
1	Rear floor panel	11	\$ 1,880.80 X
1	Rear spare tyre carrier	11	\$ 331.20 X
1	Rear spare tyre carrier lock catch	11	\$ 102.50 X
1	Rear exhaust pipe	11	\$ 832.40 X
2	Rear exhaust mountings	11	\$ 97.20 X
1	Rear side body panel - L/H	1429.10	Body 10 / \$ (Net 1,765.50)
			\$ 13,877.80
	Less 25%		\$ 3,469.45
			\$ 10,408.35

Special Nett Items

1	Rear windscreen sealant	\$ 11	80.00 X
1	Rear tailgate "70KM/H" sticker	\$ NF	15.00 X
1	Rear tailgate "8 PAX" sticker	\$ NF	15.00 X
1	Rear number plate	\$ 11	50.00 X
		\$	160.00

S/N. Labour Charges

1	To remove, replaced damaged lamps and check up rear wiring.	\$ 20	80.00
2	To remove and refit inner garnishes.	\$ 80	180.00
3	To remove and refit rear windscreen glass.	\$ 11	180.00 X
4	To remove, refit and replace exhaust silencer and mountings.	\$ 11	150.00 X
5	To apply undercoating.	\$ 50	200.00
6	Panel beating.	\$ 800	1,600.00
7	To respray painting.	\$ 500	1,500.00
		\$	3,890.00

Total Repair Cost : \$ 14,458.35

* Insurers Consultants hence notify
 the following:
 * To remove and refit inner garnishes
 * To remove and refit rear windscreen glass
 * To remove, refit and replace exhaust silencer and mountings
 * To apply undercoating
 * To respray painting
 * To remove, replaced damaged lamps and check up rear wiring
 * To remove and refit inner garnishes
 * To remove and refit rear windscreen glass
 * To remove, refit and replace exhaust silencer and mountings
 * To apply undercoating
 * Panel beating
 * To respray painting

Acknowledged by Reparer:
 Signature:
 Date:

P-192960
 252
 1447.20
 1450.00
 2897.20
 20%
 2317

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119014653/UVF3N2

Date: 04/09/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN16178719033		
Claimant Vehicle No :	GBB8359D	Insured Vehicle No :	GBD7359A		
Date of Loss:	19/08/2019	Nature of Claim:	TP	Claim No:	SNM19D203848C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB8359D	Engine No:	1KD1631624
Make & Model:	TOYOTA HIACE, 2.0 (M)	Chassis No:	JTFHT02P000003850
Reg. Date:	30/05/2007 (Man. Year: 2007)	Odometer:	372036 km
Colour:	White/Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	ULTIMAX 5 mm	Rear Left Side:	ULTIMAX 5 mm
Front Right Side:	ULTIMAX 5 mm	Rear Right Side:	ULTIMAX 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,568.35	1,447.20	9,121.15	86.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,890.00	1,450.00	2,440.00	62.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,458.35	2,897.20	11,561.15	79.96
Approved Total (Overridden) (S\$)		2,300.00		
Nett Amount (S\$)	14,458.35	2,300.00	12,158.35	84.09

INSPECTION

Date of Assignment:	21/08/2019		
Date Inspected:	22/08/2019	Inspected At:	Automobile Hub Enterprise 1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT Singapore 417883
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 04 Sep 2019)
Parts:	N/A TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB8359D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR WINDSCREEN MOULDING	Not Necessary	130.50 FL	*- FL
2	1	*REAR TAILGATE	Repair	1,793.50 FL	*- FL
3	2	*REAR TAILGATE DAMPERS	Not Necessary	508.40 FL	*- FL
4	2	*REAR TAILGATE HINGES	Not Necessary	137.10 FL	*- FL
5	1	*REAR TAILGATE INNER BOARD	Not Necessary	286.90 FL	*- FL
6	1	*REAR TAILGATE LOCK	Not Necessary	223.30 FL	*- FL
7	1	*REAR TAILGATE LOCK STRIKER	Not Necessary	48.50 FL	*- FL
8	1	*REAR TAILGATE LOGO	Not Necessary	61.90 FL	*- FL
9	1	*REAR TAILGATE OUTER GARNISH	Not Necessary	219.20 FL	*- FL
10	1	*REAR TAILGATE RUBBER	Not Necessary	328.50 FL	*- FL
11	2	*REAR TAILGATE SIDE STOPPERS	Not Necessary	85.20 FL	*- FL
12	2	*REAR TAILGATE NUMBER PLATE LAMPS	Not Necessary	90.00 FL	*- FL
13	1	*REAR TAILLAMP	N/s Broken	771.00 FL	*385.50 FL
14	2	*REAR TAILLAMP PANELS	Repair	923.80 FL	*- FL
15	1	*REAR TAILLAMP LOWER GARNISHES	N/s Twisted	230.00 FL	*115.00 FL
16	1	*REAR END PANEL	Not Necessary	887.90 FL	*- FL
17	1	*REAR END PANEL TOP MOULDING	Not Necessary	108.60 FL	*- FL
18	1	*REAR END PANEL INNER MEMBER	Not Necessary	896.50 FL	*- FL
19	1	*REAR BUMPER	Repair	695.20 FL	*- FL
20	2	*REAR BUMPER BRACKETS	Not Necessary	57.20 FL	*- FL
21	1	*SET REAR BUMPER CLIP	Not Necessary	50.00 FL	*- FL
22	2	*REAR BUMPER SIDE	Not Necessary	270.00 FL	*- FL
23	2	*REAR BUMPER SIDE RETAINERS	Not Necessary	65.00 FL	*- FL
24	1	*REAR FLOOR PANEL	Not Necessary	1,880.80 FL	*- FL
25	1	*REAR SPARE TYRE CARRIER	Not Necessary	331.20 FL	*- FL
26	1	*REAR SPARE TYRE CARRIER LOCK CATCH	Not Necessary	102.50 FL	*- FL
27	1	*REAR EXHAUST PIPE	Not Necessary	832.40 FL	*- FL
28	2	*REAR EXHAUST MOUNTINGS	Not Necessary	97.20 FL	*- FL
29	1	*REAR SIDE BODY PANEL-L/H	Badly Dented/Cracked	1,765.50 FL	*1,429.10 FL
30	1	*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
31	1	*REAR TAILGATE 70KM/H STICKER	Not fitted	15.00 FS	*- FS
32	1	*REAR TAILGATE 8 PAX STICKER	Not fitted	15.00 FS	*- FS
33	1	*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,037.80	1,929.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,469.45	482.40
Total Parts (\$\$)	10,568.35	1,447.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	80.00
3	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
4	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	0.00
5	TO APPLY UNDERCOATING	New	200.00	50.00
6	PANEL BEATING	New	1,600.00	800.00
7	TO RESPRAY PAINTING	New	1,500.00	500.00
Gross Labour Cost (S\$)			3,890.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >