

KARZ WORKS PTE LTD
53 UBI AVENUE 1 #01-23, PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934
(TEL) 6 8 4 4 5 9 3 4 (FAX) 6 8 4 4 2 4 7 4 - (E-MAIL) KARZWORKSSG@GMAIL.COM

AIG Singapore
78 Shenton Way
Singapore 079120

REPAIR PERFORMA INVOICE

Vehicle number JKG6806
Make / Model HONDA ANF125
Chassis number PMKJC38B07K014823
Accident date 16.08.19
Reference KK1908-46

LKK Auto Consultants is the primary
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Qty	Particulars	Unit Price	SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>			
1 SET	WING MIRROR	180.00	cut
1	HEADLAMP FAIRING	210.00	x
1	FRONT HEADLAMP	300.00	x
1	FRONT FAIRING	550.00	cut
1	FRONT FAIRING INNER GARNISH	210.00	x
1 SET	BALANCER	180.00	cut
1	FRONT LH SIDE FAIRING	350.00	cut
1	FRONT RH SIDE FAIRING	350.00	cut
2	FRONT SIGNAL LIGHT	280.00	RH-cut LH-cut
1 SET	FRONT FOOTREST WITH RUBBER	250.00	bt
1	FRONT FOOTREST BRACKET	150.00	x
1	ENGINE COVER	165.00	CM
1	ENGINE CAP	130.00	x
1	BRAKE PADAL	180.00	bt
1	BRAKE LEVEL	150.00	cut
1 SET	PILLION FOOTREST	150.00	del
1	EXHAUST COVER	160.00	cut
1	EXHAUST	550.00	x
1	REAR FENDER	210.00	x
1	FRONT FENDER	210.00	cut
1	BODY COVER	250.00	x
1	REAR FAIRING	350.00	x
1	FRONT RH FORK ASSY	180 450.00	?
1	FRONT LH FORK ASSY	180 450.00	?
1	TAILLAMP	210.00	x
2	BODY PANEL	1200.00	x
		7825.00	
Less 10%		782.50	
Subtotal		7042.50	
Balance C/F		7042.50	
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>			
Balance B/F		7042.50	
1	REAR BOX	500.00	200 cut
1	REAR CARPLATE	50.00	20 bt
1	RIM	500.00	180 cut
Subtotal		1050.00	
Balance C/F		8092.50	
<u>LABOUR AND MISCELLANEOUS CHARGES</u>			
Balance B/F		8092.50	
1	REPLACE, REALIGN AND ADJUST ABOVE DAMAGE PARTS AND CHECK WIRING AND LIGHTING SYSTEM	600.00	300
2	TO REMOVE/REFIT, REPLACE FRONT FORK	380.00	120
3	SPRAY PAINTING	400.00	200
Subtotal		1380.00	
Grand total		9472.50	

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Tan Kah 97495749
WP
21/8/19 345
Lumpsum
Resurvey after repair
sure lkkauto.com
4 days
* To check repair limit.