

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0987/2019/NS
Date : 20-Aug-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle no : **SLQ 2527 C**

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : MR. HAN TIANYANG
Address : 186 TOA PAYOH CENTRAL
#04-142
Singapore 310486
Telephone : (HP) + 65 90264093
Type of Claim : Third Party Claims
Policy No. : 1800043365-01
Vehicle No : **SLZ 957 K**
Model Code : A3 Sedan 1.0 TFSI
Model / Year : Apr-18
Engine No : CHZ 905953
Chassis No : WAUZZZ8V5J1056798
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-Aug-19
Place of Accident : PARKWAY PARADE CARPARK

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLZ 957 K

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed	\$ 1,050.00 700	
3	To respray front bumper.	\$ 900.00 700	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 2,502.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLZ 957 K

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Regis</i>	\$ 1,830.00	X
2	BUMPER FIXING PARTS	\$ 170.00	+
3	FRONT BUMPER GUIDE SECTION - LH / RH	2 \$ 70.00	+
4	FRONT BUMPER GRILLE - CENTRE	\$ 146.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 488.00	+
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	2 \$ 540.00	+
7	FRONT BUMPER COVER TRIM - LH / RH	2 \$ 296.00	+
8	WHEEL HOUSING LINER ADAPTER - LH / RH	2 \$ 68.00	+
9	RADIATOR GRILLE <i>cat</i>	4 \$ 1,301.00	✓
10	RADIATOR GRILLE CLOSING ELEMENT ?	\$ 174.00	?
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 342.00	+
12	FRONT BUMPER IMPACT BAR	\$ 660.00	+
13	FRONT BUMPER FOAM FILLER PIECE	\$ 172.00	+
14	IMPACT BAR COVER <i>ven</i>	\$ 111.00	+
15	AIRCON STICKER <i>3</i>	NEC \$ 7.00	✓
16	CAUTION STICKER <i>3</i>	NEC \$ 13.00	✓
17	SIGNAL HORN - LH HIGH TONE	\$ 182.00	+
18	SIGNAL HORN - RH LOW TONE	\$ 182.00	+
19	RADIATOR AIR GUIDE - LH / RH	2 \$ 44.00	+
20	RADIATOR AIR GUIDE - UPPER CENTRE	\$ 11.00	+
21	HEADLIGHT LIFT CYLINDER - LH / RH	2 \$ 256.00	+
22	FRONT NO. PLATE <i>vented</i>	S/N \$ 40.00	✓
23	SUNDRIES ?	\$ 200.00	?
TOTAL SPARE PARTS CHARGES		\$ 7,303.00	
TOTAL LABOUR CHARGES		\$ 2,502.00	
GRAND TOTAL		\$ 9,805.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lij
Surveyed Date : 21/08/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 days.

Please Note : This estimate is based on visual inspection of the affected
Should we require further labour charges and spare parts
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant