

KIANG MOTOR

Block 25 Kaki Bukit Road 4 #08-26 Synergy@KB Singapore 417800
HP: 92712214 Fax: (65) 69664526

SEE KWON KEONG
25 KAKI BUKIT ROAD4
08-26 SYNERGY @KB
Singapore 417800

16th August 2019

Accident date: 16th AUGUST 2019

Estimated repair cost for vehicle no: SKJ908Z HYUNDAI ELANTRA 1.6A '2013

S/n	Qty	Items	U/price	Amount
1	1	Rear Fender-LH		\$1,250.00
2	1	Rear Fender Inner Trim Board-LH		\$458.00
3	10	Rear Fender Inner Trim Board Clips	\$6.50	\$65.00
4	1	Rear door -LH		\$1,050.00
5	1	Rear tyre-LH		\$300.00
6	1	sport rim -LH		\$400.00
7	1	Rear lower arm-LH		\$224.00
8	1	Rear L/H knuckle arm		\$381.55
9	1	Rear L/H knuckle arm bearing		\$261.45
10	1	rear axle ASSY		\$2,550.00

Subtotal :- \$6,940.00

Labour charges

To remove & re-fix cushion	\$100.00
To Check Wiring System	\$60.00
Remove and refix Rear LH undercarriage / AXLE ASSY	\$250.00
Tuff Kote	\$100.00
Panel beating	\$700.00
Spray painting	\$700.00

Subtotal :- \$1,910.00

Total:- \$8,850.00