

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Jan 2020)
Parts:	N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	Sng Ah Tee Motor & Panel Service Pte Ltd/GBH7430E/03/01/2020 10:16
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*R/F BADGE <i>ren</i>	0.00	0.00	*15.00 F
2	1		*L/A-PILLAR REINF <i>bt</i>	0.00	0.00	*90.00 F
3	1		*R/A-PILLAR REINF <i>bt</i>	0.00	0.00	*90.00 F
4	1		*REAR PANEL REINF <i>bt</i>	0.00	0.00	*150.00 F
5	1		*L/R CORNER PILLAR <i>bt</i>	0.00	0.00	*150.00 F
6	1		*L/INNER ROOF FRAME <i>de</i>	0.00	0.00	*65.00 F
7	1		*L/INNER CORNER PILLAR <i>de</i>	0.00	0.00	*55.00 F
8	1		*L/R PILLAR REINF <i>bt</i>	0.00	0.00	*65.00 F
9	1		*UPPER GUIDE RAIL <i>de</i>	0.00	0.00	*95.00 F
10	1		*FRT ROOF CROSSMEMBER <i>bt</i>	0.00	0.00	*75.00 F
11	1		*L/R PILLAR TRIM <i>de</i>	0.00	0.00	*70.00 F
12	1		*R/F LWR D/F RAME SEAL <i>ren</i>	0.00	0.00	*35.00 F
13	1		*L/AIR DUCT <i>de</i>	0.00	0.00	*45.00 F
14	1		*L/LOCKING CLIP <i>ren</i>	0.00	0.00	*150.00 F
15	1		*LWR R/INST PNL COVER <i>de</i>	0.00	0.00	*110.00 F
16	1		*L/F UPPER AXLE LINK <i>bt</i>	0.00	0.00	*180.00 F
17	1		*L/F INN WHEEL BRG <i>ren</i>	0.00	0.00	*25.00 F
18	1		*L/F OUT WHEEL BRG <i>ren</i>	0.00	0.00	*25.00 F
19	1		*CYLINDER HEAD COVER <i>de</i>	0.00	0.00	*240.00 F
20	1		*W/ARCH PNL RUBBER <i>ren</i>	0.00	0.00	*60.00 F
21	1		*LOCK ACTUATOR LH <i>ren</i>	0.00	0.00	*75.00 F
22	1		*LOCK HANDLE LH RR <i>ren</i>	0.00	0.00	*150.00 F
23	1		*ROC STICKER FRT DOOR <i>ren</i>	0	0.00	*20.00 FS
24	1		*LIFT UP FRT CABIN <i>ren</i>	0	0.00	*250.00 FS
25	1		*LIFT UP REAR DECK <i>ren</i>	0	0.00	*350.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)

2,635.00

Sng Ah Tee Motor & Panel Service Pte Ltd/GBH7430E/03/01/2020 10:16. Not valid without Reference section.
Generated using Merimen e-Claims IEAS