

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

AXA
(LKK
Kenneth)

27/08/19
Tuesday

Not wither
61 Rm @ 2300
thruing After Rain
4 days

20/08/2019

Owner: ACE FLEET MANAGEMENT PTE LTD

ESTIMATE TO REPAIR TOYOTA WISH 1.8A - SLW8531T

1pc	front RH fender
1pc	front RH fender inner shield
8pcs	front RH fender inner shield clip @\$5.00
1pc	front RH door
2pcs	front RH door hinge @\$158.00
2pcs	front RH door firm sticker @\$121.50
1pc	front RH door inner rubber
1pc	RH side mirror
1pc	RH side mirror cover
1pc	RH side mirror lamp

<i>n</i>	\$	591.60	X
<i>sn</i>	\$	218.00	X
<i>nn</i>	\$	40.00	X
<i>nd/way</i>	\$	1,460.00	✓
<i>n</i>	\$	316.00	X
<i>nn</i>	\$	243.00	✓
<i>SL</i>	\$	295.00	X
<i>nn</i>	\$	581.50	✓
<i>n</i>	\$	121.80	X
<i>nn</i>	\$	185.50	✓

less 25%

\$ 4,052.40

\$ 1,013.10

\$ 3,039.30

remove & refit RH door glass
alignment
wiring
tuffkote
spray painting
labour charges
Total

	\$	120.00	<i>600</i>
<i>nn</i>	\$	60.00	X
	\$	120.00	<i>200</i>
	\$	120.00	<i>300</i>
	\$	800.00	<i>5200</i>
	\$	800.00	<i>5000</i>
	\$	5,059.30	<i>4000</i>



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: