

15/02/19

INS. CASE OWNER:

CC 4/QBE1901

4673, 466752

LKK:

IDAC:

Surveyor:

marcus.

DOI:

ASSIGNMENT

2/8/19

Date / Time:

2/8/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

YK 66555

Name of Insured:

SC CAR RENTAL VIC

Insured Tel No.:

HP:

Excess See II :SS

D.O.A.:

1/8/19

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age: GIOVINO ASHANY 47

Driver Tel No.:

(V/L: YES / NO )

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

YK 66555

SGT 7710

GBJ 64296

INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:YK  
Full  
TPINSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

SGT 66555 - K

YK 66555 - K

STAGE

DATE / PIC

26/08/19

- PUE REPAIRS. OLD RATE-BUDGET TP.  
SEND LETTER TO OI TO NOTIFY TP  
CLAIMS IN ACC IDUES  
- BUHAL LIABILITY CLATE  
- 3 VEH. C.C.I., OLD CAR CAR.  
- MINUTE

30/09/19

- ORIGINAL TP LOD IN  
- TYPE REPORT FOR MANDATE APPROVAL  
- REPORT DONE

06/11/19  
21/11/19

- OBBE MANDATE APPROVAL TO OBBE  
- OBBE APPROVED MANDATE.  
- SEND 1ST OFFER TO TP.  
- TP ACCEPTED OFFER.  
- ALL BOOK IN ORDER.  
- TO CLOSE

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 26/08/19-VIC

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time: 22/08/19

Sent By: 53

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P

SS

27,426.00

15

days) Reduction:

25

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

100%

Repair Cost: (w/loss)

SS

29,345.82

(3 VEH. C.C.I., OLD CAR)

Loss of Rental (LOR) (w/loss)

SS

2,140.00

(20

days)

x 100

Loss of Use (LOU):

SS

-

(S

x

days)

Loss of Income (LOI):

SS

-

(S

x

days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/TA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

1) Claim status: Non-Report/Reject/Private Settle

2) Report Format:

3) Survey fee:

4,400.00

Total:

SS

31,487.82

Global Sum \$:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

31,487.82

Name 1:

OQUE 4 CATERING - TULCO MOTOR DEALER PTE LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-





CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



## ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
QBE Insurance (Singapore) Pte Ltd 1 Raffles Quay #29-10 South Tower Singapore 048583	Cust No/Name /Mr Lin Junhong Reg No/Reg Date SJT731A / 16/08/2017 Date In/Mileage 19/08/2019/ 42035 Chassis No KNACC81CVJ5096512 Engine No G4LEHS216257 Make/Model KIA/NIRO 1.6 A G979 Colour/Trim C3U / WK
Contact No 64771154	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000056	Credit	20/08/2019/ 09:45	DS	218 / MarsLer	30725
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M SUNDRY					50.00
C & C LOGO					100.00
S MIPNT88088					750.00
204 FRONT AND REAR NUMBER PLATE WITH CASING					1200.00
S MIPNT88088					250.00
BLACKVUE DR430 (2 CHANNEL) video					160.00
S MIPNT88088					280.00
TO REMOVE AND RE-INSTALL REAR LOWER SEAT TO GIVE WAY ACCESS					4200.00
REMOVE AND RE-INSTALL HIGH VOLTAGE CABLE					200.00
S MIPNT88088					2100.00
DIAGNOSTIC / SCANNING					300.00
S MIPNT88088					100.00
TO CHECK LIGHTING AND WIRING ON FRONT & REAR ACCIDENT AFFECTED AREAS					220.00
S MIPNT88088					600.00
TO REMOVE AND RE-INSTALL RAD & A/C CONDENSOR TO GIVE WAY ACCESS					
REPAIR ON FRONT ACCIDENT AFFECTED AREAS					
S MIPNT88088					
TO REPLACE FRONT BUMPER, REINFORCEMENT, FRT CARRIER, HOOD PNL, RHF FENDER PNL, ETC					
-REPAIR RHF DOOR PNL					
STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS					
S MIPNT88088					
TO APPLY SEALANT KIT ON FRONT NEW PANEL					
S MIPNT98088					
SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS					
S MIPNT88088					
TO REPLACE FRONT TAILGATE GLASS					
S MIPNT88088					
SEALANT KIT ON TAILGATE GLASS					
S MIPNT88088					
TO INSTALL RIKE COOL SOLAR FILM ON TAILGATE GLASS					
S MIPNT88088					

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

## EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



### ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
QBE Insurance (Singapore) Pte Ltd 1 Raffles Quay #29-10 South Tower Singapore 048583	Cust No/Name /Mr Lin Junhong Reg No/Reg Date SJT731A / 16/08/2017 Date In/Mileage 19/08/2019/ 42035 Chassis No KNACC81CVJ5096512 Engine No G4LEHS216257 Make/Model KIA/NIRO 1.6 A G979 Colour/Trim C3U / WK
Contact No 64771154	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000056	Credit	20/08/2019/ 09:45	DS	218 / MarsLer	30725
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
TO REMOVE AND RE-INSTALL TRIMMING AND CARPENTERING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS					
S MIPNT88088			100		600.00
TO VACUUM & CLEAN GLASS DEBRIS ON INTERIOR CARPENTERING AND REAR SEAT					
S MIPNT88088			250		600.00
TO REPLACE REAR EXHAUST MUFFLER ASSY					
S MIPNT88088			300		600.00
TO TRANSFER TAILGATE COMPONENT & MECHANISMS PARTS					
S MIPNT88088			1800		3600.00
TO REPLACE TAILGATE PNL, REAR BUMPER, REINFORCEMENT, ETC - CUT & RE-WELD REAR END PANEL STRAIGHT, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS					
S MIPNT88088			100		300.00
TO APPLY SEALANT KIT ON REAR NEW PANEL					
S MIPNT98088			2000		2100.00
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS					
M KS 86511 G5 000	COVER - FRONT BUMPER	1.00	637.00	0.00	637.00
M KS 86512 G5 000	COVER ASSY - FRONT B	1.00	346.00	0.00	346.00
M KS 86357 G5 000	STRIP ASSY - FRONT B	1.00	28.00	0.00	28.00
P KS 86320 1W 250	LOGO ASSY - KIA SUB	1.00	51.00	0.00	51.00
M KS 86350 G5 000	GRILLE ASSY - RADIAT	1.00	441.00	0.00	441.00
M KS 86560 G5 000	GRILLE - FRONT BUMPE	1.00	232.00	0.00	232.00
M KS 86513 G5 000	LH SIDE BRACKET - FR	1.00	12.00	0.00	12.00
M KS 86514 G5 000	RH SIDE BRACKET - FR	1.00	12.00	0.00	12.00
M KS 86520 G5 000	ABSORBER - FRONT BUM	1.00	68.00	0.00	68.00
M KS 86571 G5 000	STIFFENER - FRONT BU	1.00	116.00	0.00	116.00
M KS 86951 G5 000	FLAP ASSY - ACTIVE A	1.00	328.00	0.00	328.00
M KS 86958 G5 000	DUCT ASSY-ACTIVE AIR	1.00	78.00	0.00	78.00
M KS 86568 G5 000	RH DUCT ASSY - AIR C	1.00	32.00	0.00	32.00
M KS 86558 G5 000	RH PIECE - FRONT BUM	1.00	16.00	0.00	16.00
M KS 86557 G5 000	LH PIECE - FRONT BUM	1.00	16.00	0.00	16.00
M KS 86517 G5 000	CAP - FRONT HOOK	1.00	7.00	0.00	7.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



## ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
QBE Insurance (Singapore) Pte Ltd 1 Raffles Quay #29-10 South Tower Singapore 048583	Cust No/Name /Mr Lin Junhong Reg No/Reg Date SGT731A / 16/08/2017 Date In/Mileage 19/08/2019/ 42035 Chassis No KNACC81CVJ5096512 Engine No G4LEHS216257 Make/Model KIA/NIRO 1.6 A G979 Colour/Trim C3U / WK
Contact No 64771154	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000056	Credit	20/08/2019/ 09:45	DS	218 / MarsLer	30725
Description of Goods / Services	Qty	Unit Price	Disc%	Amount	
M KS 91840 G5 040 WIRING HARNESS - FRO	1.00	134.00	0.00	134.00	X
M KS 92202 G5 000 RH LAMP ASSY - FRONT	1.00	638.00	0.00	638.00	X
P KS 06032 50 037A CLIP - FRONT BUMPER	10.00	2.00	0.00	20.00	X
M KS 92102 G5 020 RH HEADLAMP ASSY	1.00	904.00	0.00	904.00	X
M KS 64900 G5 000 BEAM COMPLETE - FRON	1.00	551.00	0.00	551.00	X
M KS 64101 G5 000 CARRIER ASSY - FRONT	1.00	675.00	0.00	675.00	X
M KS 66321 G5 000 RH FENDER PANEL	1.00	385.00	0.00	385.00	X
M KS 84142 G5 000 INSULATOR - FENDER,	1.00	46.00	0.00	46.00	X
M KS 66400 G5 000 HOOD PANEL ASSY	1.00	1438.00	0.00	1438.00	X
M KS 79120 G5 000 RH HINGE ASSY - HOOD	1.00	40.00	0.00	40.00	X
M KS 81130 G5 900 LATCH ASSY - HOOD	1.00	123.00	0.00	123.00	X
M KS 93880 G5 900 SWITCH ASSY - HOOD	1.00	50.00	0.00	50.00	X
M KS 81190 G5 800 CABLE ASSY - HOOD LA	1.00	27.00	0.00	27.00	X
M KS 86154 G5 000 RH COVER - COWL TOP	1.00	6.00	0.00	6.00	X
M KS 73700 G5 000 TAIL GATE PANEL ASSY	1.00	1309.00	0.00	1309.00	X
M KS 81771 G5 000 LIFTER ASSY - TAILGA	1.00	76.00	0.00	76.00	X
M KS 81781 G5 000 LIFTER ASSY - TAILGA	1.00	76.00	0.00	76.00	X
M KS 81230 G5 000 LATCH ASSY - TAILGAT	1.00	201.00	0.00	201.00	X
M KS 81720 G5 000 HANDLE ASSY - TAILGA	1.00	99.00	0.00	99.00	X
M KS 81750 G5 000W K TAILGATE TRIM PANEL	1.00	164.00	0.00	164.00	X
M KS 87321 G5 000 WEATHERSTRIP - TAILG	1.00	99.00	0.00	99.00	X
P KS 87110 G5 140 GLASS ASSY - TAILGAT	1.00	1179.00	0.00	1179.00	X
M KS 86114 3D 000 PAD-W/SHLD GLASS	8.00	2.00	0.00	16.00	X
M KS 87115 A4 000 STOPPER-RR WINDOW GL	2.00	15.00	0.00	30.00	X
M KS 95760 G5 000 CAMERA ASSY - BACK V	1.00	758.00	0.00	758.00	X
M KS 87210 G5 000 SPOILER - REAR	1.00	522.00	0.00	522.00	X
M KS 92700 G5 000 HIGH MOUNT STOP LAMP	1.00	0.00	0.00	0.00	X
M KS 87370 G5 000 RH GARNISH ASSY - "D	1.00	98.00	0.00	98.00	X
M KS 98812 G5 000 CAP - REAR WIPER ARM	1.00	3.00	0.00	3.00	X
M KS 98811 G5 000 ARM ASSY - REAR WIPE	1.00	59.00	0.00	59.00	X
P KS 98850 G5 000 BLADE ASSY - WIPER,	1.00	41.00	0.00	41.00	X
M KS 98700 G5 000 MOTOR & LINKAGE ASSY	1.00	357.00	0.00	357.00	X
M KS 92403 G5 120 LH INSIDE LAMP ASSY	1.00	636.00	0.00	636.00	X

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

## EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



### ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
QBE Insurance (Singapore) Pte Ltd 1 Raffles Quay #29-10 South Tower Singapore 048583	Cust No/Name /Mr Lin Junhong Reg No/Reg Date SJT731A / 16/08/2017 Date In/Mileage 19/08/2019/ 42035 Chassis No KNACC81CVJ5096512 Engine No G4LEHS216257 Make/Model KIA/NIRO 1.6 A G979 Colour/Trim C3U / WK
Contact No 64771154	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000056	Credit	20/08/2019/ 09:45	DS	218 / MarsLer	30725
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M KS 92404 G5 120	RH INSIDE LAMP ASSY	1.00	636.00	0.00	636.00
M KS 92401 G5 120	LH OUTSIDE LAMP ASSY	1.00	645.00	0.00	645.00
M KS 92402 G5 120	RH OUTSIDE LAMP ASSY	1.00	645.00	0.00	645.00
M KS 86310 G5 000	LOGO - KIA	1.00	42.00	0.00	42.00
M KS 86311 G5 000	EMBLEM-NIRO	1.00	25.00	0.00	25.00
M KS 86316 G5 000	EMBLEM-ECO HYBRID	1.00	29.00	0.00	29.00
M KS 86611 G5 010	COVER - REAR BUMPER,	1.00	423.00	0.00	423.00
M KS 86612 G5 010	COVER - REAR BUMPER	1.00	392.00	0.00	392.00
M KS 86665 G5 000	SKID PLATE - REAR BU	1.00	122.00	0.00	122.00
P KS 86628 G5 000	RH PIECE-RR BUMPER S	1.00	16.00	0.00	16.00
M KS 86696 G5 001	COVER-RR BUMPER SIDE	1.00	27.00	0.00	27.00
M KS 86681 G5 000	LH SIDE MOULDING ASS	1.00	20.00	0.00	20.00
P KS 86682 G5 000	RH SIDE MOULDING ASS	1.00	20.00	0.00	20.00
M KS 86613 G5 000	LH SIDE BRACKET ASSY	1.00	25.00	0.00	25.00
M KS 86614 G5 000	RH SIDE BRACKET ASSY	1.00	25.00	0.00	25.00
M KS 95720 D3 000C 3U	SENSOR ASSY-PARKING	3.00	135.00	0.00	405.00
M KS 91880 G5 030	WIRING HARNESS-RR BU	1.00	361.00	0.00	361.00
M KS 92501 F6 000	LH LAMP ASSY - LICEN	1.00	27.00	0.00	27.00
M KS 92502 F6 000	RH LAMP ASSY - LICEN	1.00	27.00	0.00	27.00
M KS 92406 G5 000	RH REFLECTOR/REFLEX	1.00	104.00	0.00	104.00
P KS 86631 G5 100	BEAM - REAR BUMPER	1.00	261.00	0.00	261.00
M KS 86635 G5 000	BRACKET - REAR RAIL	1.00	6.00	0.00	6.00
M KS 86636 G5 100	BRACKET - REAR BEAM	1.00	6.00	0.00	6.00
M KS 86637 C5 000	BRACKET-SMART KEY MT	1.00	5.00	0.00	5.00
M KS 86633 G5 000	BRACKET - REAR BEAM	1.00	6.00	0.00	6.00
P KS 86634 G5 000	BRACKET - REAR BEAM	1.00	6.00	0.00	6.00
P KS 86641 G5 000	LH STAY - REAR BUMPE	1.00	67.00	0.00	67.00
P KS 86642 G5 000	RH STAY - REAR BUMPE	1.00	67.00	0.00	67.00
M KS 95420 G2 300	ANTENNA ASSY-SMARTKE	1.00	39.00	0.00	39.00
M KS 87712 G5 000	GARNISH ASSY - FENDE	1.00	123.00	0.00	123.00
M KS 87742 G5 000	GARNISH ASSY - QUART	1.00	144.00	0.00	144.00
M KS 85910 G5 000	SCREEN ASSY - CARGO	1.00	812.00	0.00	812.00
M KS 85770 G5 100W K	TRIM ASSY - REAR TRA	1.00	60.00	0.00	60.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



## ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
QBE Insurance (Singapore) Pte Ltd 1 Raffles Quay #29-10 South Tower Singapore 048583	Cust No/Name /Mr Lin Junhong Reg No/Reg Date SJT731A / 16/08/2017 Date In/Mileage 19/08/2019/ 42035 Chassis No KNACC81CVJ5096512 Engine No G4LEHS216257 Make/Model KIA/NIRO 1.6 A G979 Colour/Trim C3U / WK
Contact No 64771154	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000056	Credit	20/08/2019/ 09:45	DS	218 / MarsLer	30725

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M KS 69100 G5 500 PANEL ASSY - BACK	1.00	526.00	0.00	526.00
M KS 28710 G5 130 MUFFLER ASSY-REAR	1.00	840.00	0.00	840.00
P KS 0G032 50 037A CLIP - RR BUMPER	10.00	2.00	0.00	20.00
M JJMZ313950 COOLANT	4.00	26.00	0.00	104.00

Z NOTES

ACCIDENT ON 19/08/2019 ALONG BKE TWDS PIE AFTER EXIT 7

OWNER CLAIMING THIRD PARTY

REQUIRED REPLACEMENT CAR

TP # YK6655S TP INS : QBE

+ GST

# Estimate

526.00  
840.00  
20.00  
104.00

40953.00

40953.00

Confirm &amp; accepted by

Parts	20,288.00
Labour	0.00
Standard Menu	0.00
Specialist Job	18,260.00
Others(Lub,etc)	0.00
Sundry	50.00
Total(w/o GST)	38,598.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD  
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



## ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
QBE Insurance (Singapore) Pte Ltd 1 Raffles Quay #29-10 South Tower Singapore 048583	Cust No/Name /Mr Lin Junhong
Contact No 64771154	Reg No/Reg Date SJT731A / 16/08/2017
	Date In/Mileage 19/08/2019/ 42035
	Chassis No KNACC81CVJ5096512
	Engine No G4LEHS216257
	Make/Model KIA/NIRO 1.6 A G979
	Colour/Trim C3U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000056	Credit	12/09/2019/ 11:37	DS	218 / MarsLer	30725

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X KS 96610 G5 500 HORN ASSY - LOW PITC <i>CRU</i>	1.00	79.00	0.00	79.00
X KS 29134 G5 000 GUARD - AIR, RH <i>Dis</i>	1.00	29.00	0.00	29.00
X KS 29150 G2 000 DAM - AIR <i>Re</i>	1.00	27.00	0.00	27.00
X KS 81190 G5 900 CABLE ASSY - HOOD LA <i>Repaired CRU/SM</i>	1.00	27.00	0.00	27.00
X KS 25308 G2 000 RADIATOR ASSY - INVE <i>Repaired CRU/SM</i>	1.00	768.00	0.00	768.00
X KS 25310 G2 000 RADIATOR ASSY <i>Repaired CRU/SM</i>	1.00	492.00	0.00	492.00
X KS 25380 G2 000 BLOWER ASSY <i>CRU</i>	1.00	546.00	0.00	546.00
X KS 25450 G2 000 HOSE & CLAMP ASSY <i>CRU</i>	1.00	31.00	0.00	31.00
X KS 97761 G2 000 TUBE - LIQUID <i>Repaired CRU/SM</i>	1.00	216.00	0.00	216.00
M KS 86360 G5 000 COVER ASSY - RADIATO <i>CRU</i>	1.00	40.00	0.00	40.00

Z NOTES

SUPPLEMENTARY ITEMS

Estimate

Confirm &amp; accepted by

Supplementary

Authorized signatory and company stamp

Parts	2,255.00
Labour	0.00
Standard Menu	0.00
Specialist Job	0.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	2,255.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD**  
**EUNOS LINK SERVICE CENTRE**

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
QBE Insurance (Singapore) Pte Ltd 1 Raffles Quay #29-10 South Tower Singapore 048583  Contact No 64771154	Cust No/Name	/Mr Lin Junhong
	Reg No/Reg Date	SJT731A / 16/08/2017
	Date In/Mileage	19/08/2019/ 42035
	Chassis No	KNACC81CVJ5096512
	Engine No	G4LEHS216257
	Make/Model	KIA/NIRO 1.6 A G979
	Colour/Trim	C3U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
F0000056	Credit	20/09/2019/ 14:19	DS	218 / MarsLer	30725		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	SUNDRY						50.00
	C & C LOGO						
S	MIPNT88088						100.00
	FRONT AND REAR NUMBER PLATE WITH CASING						
S	MIPNT88088						750.00
	THINKWARE F770 (2 CHANNEL)						
S	MIPNT88088						600.00
	TO REMOVE AND RE-INSTALL REAR LOWER SEAT TO GIVE WAY ACCESS						
	REMOVE AND RE-INSTALL HIGH VOLTAGE CABLE						
S	MIPNT88088						250.00
	DIAGNOSTIC / SCANNING						
S	MIPNT88088						160.00
	TO CHECK LIGHTING AND WIRING ON FRONT & REAR ACCIDENT						
	AFFECTED AREAS						
S	MIPNT88088						180.00
	TO REMOVE AND RE-INSTALL RAD & A/C CONDENSOR TO GIVE WAY ACCESS						
	REPAIR ON FRONT ACCIDENT AFFECTED AREAS						
S	MIPNT88088						2400.00
	TO REPLACE FRONT BUMPER,REINFORCEMENT,FRT CARRIER,HOOD PNL,						
	RHF FENDER PNL,ETC						
	-REPAIR RHF DOOR PNL						
	STRAIGHTEN,REFORM,ALIGN ON FRONT ACCIDENT AFFECTED AREAS						
S	MIPNT88088						100.00
	TO APPLY SEALANT KIT ON FRONT NEW PANEL						
S	MIPNT98088						2000.00
	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS						
S	MIPNT88088						300.00
	TO REPLACE FRONT TAILGATE GLASS						
S	MIPNT88088						100.00
	SEALANT KIT ON TAILGATE GLASS						
S	MIPNT88088						220.00
	TO INSTALL RIKE COOL SOLAR FILM ON TAILGATE GLASS						
S	MIPNT88088						300.00

Confirm &amp; accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



## ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
QBE Insurance (Singapore) Pte Ltd 1 Raffles Quay #29-10 South Tower Singapore 048583	Cust No/Name /Mr Lin Junhong Reg No/Reg Date SJT731A / 16/08/2017 Date In/Mileage 19/08/2019/ 42035 Chassis No KNACC81CVJ5096512 Engine No G4LEHS216257 Make/Model KIA/NIRO 1.6 A G979 Colour/Trim C3U / WK
Contact No 64771154	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
F0000056	Credit	20/09/2019/ 14:19	DS	218 / MarsLer	30725		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
TO REMOVE AND RE-INSTALL TRIMMING AND CARPERTING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS							
S	MIPNT88088						100.00
TO VACUUM & CLEAN GLASS DEBRIS ON INTERIOR CARPERTING AND REAR SEAT							
S	MIPNT88088						250.00
TO REPAIR REAR EXHAUST MUFFLER ASSY							
S	MIPNT88088						300.00
TO TRANSFER TAILGATE COMPONENT & MECHANISMS PARTS							
S	MIPNT88088						1800.00
TO REPLACE TAILGATE PNL, REAR BUMPER, REINFORCEMENT, ETC - CUT & RE-WELD REAR END PANEL STRAIGHT, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS							
S	MIPNT88088						100.00
TO APPLY SEALANT KIT ON REAR NEW PANEL							
S	MIPNT98088						2000.00
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS							
X	KS 86511 G5 000	COVER - FRONT BUMPER	1.00	637.00	0.00		637.00
X	KS 86512 G5 000	COVER ASSY - FRONT B	1.00	346.00	0.00		346.00
X	KS 86357 G5 000	STRIP ASSY - FRONT B	1.00	28.00	0.00		28.00
X	KS 86320 1W 250	LOGO ASSY - KIA SUB	1.00	51.00	0.00		51.00
X	KS 86350 G5 000	GRILLE ASSY - RADIAT	1.00	441.00	0.00		441.00
X	KS 86560 G5 000	GRILLE - FRONT BUMPE	1.00	232.00	0.00		232.00
X	KS 86514 G5 000	RH SIDE BRACKET - FR	1.00	12.00	0.00		12.00
X	KS 86520 G5 000	ABSORBER - FRONT BUM	1.00	68.00	0.00		68.00
X	KS 92202 G5 000	RH LAMP ASSY - FRONT	1.00	638.00	0.00		638.00
X	KS 0G032 50 037A	CLIP - FRONT BUMPER	10.00	2.00	0.00		20.00
X	KS 92102 G5 020	RH HEADLAMP ASSY	1.00	904.00	0.00		904.00
X	KS 64101 G5 000	CARRIER ASSY - FRONT	1.00	675.00	0.00		675.00
X	KS 66400 G5 000	HOOD PANEL ASSY	1.00	1438.00	0.00		1438.00
X	KS 79120 G5 000	RH HINGE ASSY - HOOD	1.00	40.00	0.00		40.00
X	KS 81130 G5 900	LATCH ASSY - HOOD	1.00	123.00	0.00		123.00
X	KS 93880 G5 900	SWITCH ASSY - HOOD	1.00	50.00	0.00		50.00

Confirm &amp; accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

## EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



### ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
QBE Insurance (Singapore) Pte Ltd 1 Raffles Quay #29-10 South Tower Singapore 048583	Cust No/Name /Mr Lin Junhong
Contact No 64771154	Reg No/Reg Date SGT731A / 16/08/2017
	Date In/Mileage 19/08/2019/ 42035
	Chassis No KNACC81CVJ5096512
	Engine No G4LEHS216257
	Make/Model KIA/NIRO 1.6 A G979
	Colour/Trim C3U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000056	Credit	20/09/2019/ 14:19	DS	218 / MarsLer	30725
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X KS 81190 G5 800	CABLE ASSY - HOOD LA	1.00	27.00	0.00	27.00
X KS 73700 G5 000	TAIL GATE PANEL ASSY	1.00	1309.00	0.00	1309.00
X KS 81230 G5 000	LATCH ASSY - TAILGAT	1.00	201.00	0.00	201.00
X KS 87110 G5 140	GLASS ASSY - TAILGAT	1.00	1179.00	0.00	1179.00
M KS 86114 3D 000	PAD-W/SHLD GLASS	8.00	2.00	0.00	16.00
M KS 87115 A4 000	STOPPER-RR WINDOW GL	2.00	15.00	0.00	30.00
X KS 95760 G5 000	CAMERA ASSY - BACK V	1.00	758.00	0.00	758.00
X KS 98812 G5 000	CAP - REAR WIPER ARM	1.00	3.00	0.00	3.00
X KS 98811 G5 000	ARM ASSY - REAR WIPE	1.00	59.00	0.00	59.00
X KS 98850 G5 000	BLADE ASSY - WIPER,	1.00	41.00	0.00	41.00
X KS 92403 G5 120	LH INSIDE LAMP ASSY	1.00	636.00	0.00	636.00
X KS 92404 G5 120	RH INSIDE LAMP ASSY	1.00	636.00	0.00	636.00
X KS 92402 G5 120	RH OUTSIDE LAMP ASSY	1.00	645.00	0.00	645.00
X KS 86310 G5 000	LOGO - KIA	1.00	42.00	0.00	42.00
X KS 86311 G5 000	EMBLEM-NIRO	1.00	25.00	0.00	25.00
X KS 86316 G5 000	EMBLEM-ECO HYBRID	1.00	29.00	0.00	29.00
X KS 86611 G5 010	COVER - REAR BUMPER,	1.00	423.00	0.00	423.00
X KS 86612 G5 010	COVER - REAR BUMPER	1.00	392.00	0.00	392.00
X KS 86665 G5 000	SKID PLATE - REAR BU	1.00	122.00	0.00	122.00
X KS 86628 G5 000	RH PIECE-RR BUMPER S	1.00	16.00	0.00	16.00
X KS 86682 G5 000	RH SIDE MOULDING ASS	1.00	20.00	0.00	20.00
X KS 86614 G5 000	RH SIDE BRACKET ASSY	1.00	25.00	0.00	25.00
X KS 95720 D3 000A BT	SENSOR ASSY-PACK ASS	1.00	135.00	0.00	135.00
X KS 92501 F6 000	LH LAMP ASSY - LICEN	1.00	27.00	0.00	27.00
X KS 92502 F6 000	RH LAMP ASSY - LICEN	1.00	27.00	0.00	27.00
X KS 92406 G5 000	RH REFLECTOR/REFLEX	1.00	104.00	0.00	104.00
X KS 86631 G5 100	BEAM - REAR BUMPER	1.00	261.00	0.00	261.00
X KS 86635 G5 000	BRACKET - REAR RAIL	1.00	6.00	0.00	6.00
X KS 86636 G5 100	BRACKET - REAR BEAM	1.00	6.00	0.00	6.00
X KS 86637 C5 000	BRACKET-SMART KEY MT	1.00	5.00	0.00	5.00
X KS 86633 G5 000	BRACKET - REAR BEAM	1.00	6.00	0.00	6.00
X KS 86634 G5 000	BRACKET - REAR BEAM	1.00	6.00	0.00	6.00
X KS 86642 G5 000	RH STAY - REAR BUMPE	1.00	67.00	0.00	67.00

Confirm &amp; accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

## EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



### ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
QBE Insurance (Singapore) Pte Ltd 1 Raffles Quay #29-10 South Tower Singapore 048583	Cust No/Name /Mr Lin Junhong Reg No/Reg Date SJT731A / 16/08/2017 Date In/Mileage 19/08/2019/ 42035 Chassis No KNACC81CVJ5096512 Engine No G4LEHS216257 Make/Model KIA/NIRO 1.6 A G979 Colour/Trim C3U / WK
Contact No 64771154	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
F0000056	Credit	20/09/2019/ 14:19	DS	218 / MarsLer	30725	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
X	KS 06032 50 037A	CLIP - RR BUMPER	10.00	2.00	0.00	20.00
X	JJMZ313950	COOLANT	4.00	26.00	0.00	104.00
X	KS 96610 G5 500	HORN ASSY - LOW PITC	1.00	79.00	0.00	79.00
X	KS 29134 G5 000	GUARD - AIR, RH	1.00	29.00	0.00	29.00
X	KS 29150 G2 000	DAM - AIR	1.00	27.00	0.00	27.00
X	KS 81190 G5 900	CABLE ASSY - HOOD LA	1.00	27.00	0.00	27.00
X	KS 25308 G2 000	RADIATOR ASSY - INVE	1.00	768.00	0.00	768.00
X	KS 25310 G2 000	RADIATOR ASSY	1.00	492.00	0.00	492.00
X	KS 25380 G2 000	BLOWER ASSY	1.00	546.00	0.00	546.00
X	KS 25450 G2 000	HOSE & CLAMP ASSY	1.00	31.00	0.00	31.00
X	KS 97761 G2 000	TUBE - LIQUID	1.00	216.00	0.00	216.00
M	KS 86360 G5 000	COVER ASSY - RADIATO	1.00	40.00	0.00	40.00
Z	NOTES					
ACCIDENT ON 19/08/2019 ALONG BKE TWDS PIE AFTER EXIT 7						
OWNER CLAIMING THIRD PARTY						
REQUIRED REPLACEMENT CAR (CHAN'S)						
TP # YK6655S TP INS : QBE						

Confirm &amp; accepted by

Finalization

Authorized signatory and company stamp

Parts	15,366.00
Labour	0.00
Standard Menu	0.00
Specialist Job	12,010.00
Others(Lub,etc)	0.00
Sundry	50.00
Total(w/o GST)	27,426.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring removal of the windscreen.



> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 574H

### Vehicle Details

Vehicle No.: SJT731A  
Vehicle to be Exported: No  
Intended Deregistration Date: 22 Aug 2019  
Vehicle Make: KIA  
Vehicle Model: NIRO HYBRID 1.6 GDI DCT SUNROOF  
Primary Colour: Blue  
Manufacturing Year: 2017  
Engine No.: G4LEHS216257  
Chassis No.: KNACC81CVJ5096512  
Maximum Power Output: 103.6 kW (138 bhp)  
Open Market Value: \$27,378.00  
Original Registration Date: 16 Aug 2017  
First Registration Date: 16 Aug 2017  
Transfer Count: 0  
Actual ARF Paid: \$5,000.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 15 Aug 2027  
PARF Rebate Amount: \$3,750.00

### Intended COE Rebate Details

COE Expiry Date: 15 Aug 2027  
COE Category: E - Open - all except motorcycle  
COE Period(Years): 10  
QP Paid: \$50,526.00  
COE Rebate Amount: \$39,993.00  
**Total Rebate Amount: \$43,743.00**

The information contained herein is correct as at 22 Aug 2019

OK



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC4/QBE19014673/Uhb3

Date: 22.08.2019

The Motor Claims Department  
M/s QBE INSURANCE (INTERNATIONAL) LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**


**SJT731A**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21.08.2019 at the premises of M/s Cycle & Carriage Fulco Motor Dealer Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	38,598.00
Revised Estimate Amount	: S\$	22,673.00
"Check" Items Amount	: S\$	7,353.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:  
The vehicle sustained damages at the  
Front & Rear Portion



Comments/Present Status:  
Damages Consistent  
Estimated normal period for repairs: 15 days

Yours faithfully,

MARCUS CHUA  
Licensed Appraiser

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Singapore NRIC

Owner ID:

574H

**Vehicle Details**

Vehicle No.:

SJT731A

Vehicle to be Exported:

No

Intended Deregistration Date:

31 Aug 2019

Vehicle Make:

KIA

Vehicle Model:

NIRO HYBRID 1.6 GDI DCT SUNROOF

Primary Colour:

Blue

Manufacturing Year:

2017

Engine No.:

G4LEHS216257

Chassis No.:

KNACC81CVJ5096512

Maximum Power Output:

103.6 kW (138 bhp)

Open Market Value:

\$27,378.00

Original Registration Date:

16 Aug 2017

First Registration Date:

16 Aug 2017

Transfer Count:

0

Actual ARF Paid:

\$5,000.00

**Intended PARF Rebate Details**

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

15 Aug 2027

PARF Rebate Amount:

\$3,750.00

**Intended COE Rebate Details**

COE Expiry Date:

15 Aug 2027

COE Category:

E - Open - all except motorcycle

COE Period(Years):

10

QP Paid:

\$50,526.00

COE Rebate Amount:

\$39,872.00

**Total Rebate Amount:****\$43,622.00**

The information contained herein is correct as at 19 Aug 2019

OK



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

2012 Rightly Priced Maserati Quattroporte...



Superior Condition, Very Low  
Mileage, Guarantee Headliner  
With No Messy Mark,  
Direct Owner - Starke



Browse by Category

Sort by Date Posted

20 results/page

6 vehicles

KIA NIRO

Advanced Search

Search Selection

KIA NIRO

Any

Any

2017

Any

Any

Any

Available

**Kia Niro Hybrid 1.6A****\$77,955****\$9,330 /yr****20-Sep-2017****1,580 cc****24,000 km****SUV****Available****Fuel Type:** Petrol-Electric

New SMN Number, Low Mileage Done 24,000 Km, 5 Years Warranty Plus 10 Years Warranty On Engine And Hybrid Battery By C&C Kia.  
Drive It With A Peace Of Mind, Very High Specs And Features With Very Economical Fuel Consumption, Owner Upgraded Himself To A M...

Posted: 17-Aug-2019 Tags: 2017 Kia Niro, 2017 kia niro, Kia Niro, kia niro, Kia, Niro, niro, Used Kia

**Kia Niro Hybrid 1.6A****\$78,500****\$9,370 /yr****28-Sep-2017****1,580 cc****40,000 km****SUV****Available****Fuel Type:** Petrol-Electric

Cheapest In Town! Grab It Before Coe Shoot Up! New Arrival Best Selling Suv 1 Owner Sporty Black With Low Km Done At 40000 Fuel At  
26.3km/liter Car With Clean N Still New Car Smell N Still Under 10years Warranty By Agent Is A Huge Save To Get This Unit So Do Call F...

Posted: 16-Aug-2019 Tags: 2017 Kia Niro, 2017 kia niro, Kia Niro, kia niro, Kia, Niro, niro, Used Kia

**Kia Niro Hybrid 1.6A****\$79,000****\$9,940 /yr****28-Apr-2017****1,580 cc****61,000 km****SUV****Available****Fuel Type:** Petrol-Electric

1 Meticulous Owner, Mileage Done At Approximate 57000 Km, 10 Year Battery And Engine Warranty With Kia, 2 Serviced Package Left  
With CNC, Accident Free, Beautiful Blue With Black Interior, As Good As New.

Posted: 03-Aug-2019 Tags: 2017 Kia Niro, 2017 kia niro, Kia Niro, kia niro, Kia, Niro, niro, Used Kia

**Kia Niro Hybrid 1.6A****\$86,800****\$10,090 /yr****27-Dec-2017****1,580 cc****40,000 km****SUV****Available****Fuel Type:** Petrol-Electric

Car Of The Year For 2017! 10 Years Battery And Engine Warranty, As Good As New, Less Than 1 Years, C&C New At \$134,999 And  
Above, Save Back Close To \$21k For A Few Months Old Car, Condition Of The Car As Good As New! Fuel Efficient Hybrid Car, Full Of Fea...

Prem Roy Motoring

Posted: 23-Jul-2019 Tags: 2017 Kia Niro, 2017 kia niro, Kia Niro, kia niro, Kia, Niro, niro, Used Kia

**Improves Air Quality & Reduces Allergens**

Mitsubishi Lancer CS3 Charcoal Aircon Filter

Find out more!

**Kia Niro Hybrid 1.6A****\$78,888****\$9,170 /yr****31-Oct-2017****1,580 cc****45,500 km****SUV****Available****Fuel Type:** Petrol-Electric

1 Owner, Mileage Done At Approx 46500km, 10 Year Battery And Engine Warranty With Kia, Accident Free, Beautiful Pearl White With  
Black Interior, Still Has 2 Servicing Packages With Kia, As Good As New, Tyres And 12v Battery Have Just Been Changed, Car Plate No...

Posted: 15-Jul-2019 Tags: 2017 Kia Niro, 2017 kia niro, Kia Niro, kia niro, Kia, Niro, niro, Used Kia

**Kia Niro Hybrid 1.6A****\$75,000****\$9,460 /yr****18-Apr-2017****1,580 cc****36,000 km****SUV****Available****Fuel Type:** Petrol-Electric

1 Owner, Low Mileage Done! Rare On The Road! In Almost New Condition, C&C Unit With 10 Years Engine And Hybrid Battery Warranty,  
5 Years Warranty On Other Standard Components And 3 x Free Service Packages. Comes With 5 Years Ceramic Coating, Drive In Comfo...

Bavarian Marques Pte Ltd

Posted: 12-Jul-2019 Tags: 2017 Kia Niro, 2017 kia niro, Kia Niro, kia niro, Kia, Niro, niro, Used Kia

Save this search cri

whenever a match is found.

Compare



New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



**ALL-NEW**  
Mercedes-Benz GLE450 AMG  
Premium Plus

**TEST DRIVE TODAY!**  
☎ 6250 6696 / 9637 5329

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

One Fussy Lady Owner. Depre About \$6600 Per Year.



Owner Upgrade To Cross Over.  
Direct Owner StarAd

**Aut**  
An Inspiration

click here to view  
our **PRISTINE**  
at




Browse by Category ▼

Sort by Date Posted

6 vehicles

Kia Niro

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
<b>Search Selection</b>	Kia Niro		Any	Any	2017	Any	Any	
	Kia Niro Hybrid 1.6A		\$77,955	\$9,340 /yr	20-Sep-2017	1,580 cc	24,000 km	
<b>Fuel Type:</b> Petrol-Electric New SMN Number. Low Mileage Done 24,000 Km. 5 Years Warranty Plus 10 Years Warranty On Engine And Hybrid Battery By C&C Kia. Drive It With A Peace Of Mind. Very High Specs And Features With Very Economical Fuel Consumption. Owner Upgraded Himself To A N								
Posted: 17-Aug-2019 Tags: 2017 Kia Niro, 2017 kia niro, Kia Niro, kia niro, Kia, Niro, niro, Used Kia								
	Kia Niro Hybrid 1.6A		\$77,800	\$9,290 /yr	28-Sep-2017	1,580 cc	40,000 km	
<b>Fuel Type:</b> Petrol-Electric Cheapest In Town! Grab It Before Coe Shoot Up! New Arrival Best Selling Suv 1 Owner Sporty Black With Low Km Done At 40000 Fuel At 26.3km/liter Car With Clean N Still New Car Smell N Still Under 10years Warranty By Agent Is A Huge Save To Get This Unit So Do Call f								
Posted: 16-Aug-2019 Tags: 2017 Kia Niro, 2017 kia niro, Kia Niro, kia niro, Kia, Niro, niro, Used Kia								
	Kia Niro Hybrid 1.6A		\$79,000	\$9,950 /yr	28-Apr-2017	1,580 cc	61,000 km	
<b>Fuel Type:</b> Petrol-Electric 1 Meticulous Owner, Mileage Done At Approximate 57000 Km. 10 Year Battery And Engine Warranty With Kia. 2 Serviced Package Left With CNC. Accident Free. Beautiful Blue With Black Interior, As Good As New.								
Posted: 03-Aug-2019 Tags: 2017 Kia Niro, 2017 kia niro, Kia Niro, kia niro, Kia, Niro, niro, Used Kia								
	Kia Niro Hybrid 1.6A		\$86,800	\$10,090 /yr	27-Dec-2017	1,580 cc	40,000 km	
<b>Fuel Type:</b> Petrol-Electric Car Of The Year For 2017! 10 Years Battery And Engine Warranty, As Good As New, Less Than 1 Years, C&C New At \$134,999 And Above, Save Back Close To \$21k For A Few Months Old Car, Condition Of The Car As Good As New! Fuel Efficient Hybrid Car, Full Of Fei								
Prem Roy Motoring								
Posted: 23-Jul-2019 Tags: 2017 Kia Niro, 2017 kia niro, Kia Niro, kia niro, Kia, Niro, niro, Used Kia								
<div> <div>Car Buying</div> <div>Car Aftermarket</div> </div> <div> <div>Car Selling</div> <div>On The Move</div> </div> <div> <div>Car Ownership</div> <div>Lifestyle</div> </div> <div> <div>Buy Tyres Online!</div> <div>Latest Special Offers fr</div> </div>								
	Kia Niro Hybrid 1.6A		\$78,888	\$9,180 /yr	31-Oct-2017	1,580 cc	45,500 km	
<b>Fuel Type:</b> Petrol-Electric Mileage Done At Approx 46500km. 10 Year Battery And Engine Warranty With Kia. Accident Free. Beautiful Pearl White With rior. Still Has 2 Servicing Packages With Kia. As Good As New. Tyres And 12v Battery Have Just Been Changed. Car Plate No...								

Compare

## Nivitha (LKK Auto)

---

**From:** Janice Goh Siew Geok <janice.goh@qbe.com>  
**Sent:** Wednesday, 21 August 2019 12:07 PM  
**To:** mars.ler@ccfulco.com.sg; assignments@lkkauto.com  
**Cc:** Chris Bulaclac; Renemer Bagang  
**Subject:** RE: Re:Accident On 19/08/2019 Involving Our Insured SJT731A And Your Insured YK6655S ; QBE'S REF VC012899  
**Attachments:** SJT731A.pdf

12:37pm 21/8/19  
person @ Mars  
vehicle in

Without PREJUDICE

Hi Mars

Thank you for your email.

Liability is clear for direct settlement.  
We will appoint LKK for the survey.

Hi LKK

Please assist.

Thank you.

---

**Janice Goh**

Executive, Claims

Claims | Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583

+65 6477 1243

Website LinkedIn Twitter



---

**From:** Mars Ler <mars.ler@ccfulco.com.sg>  
**Sent:** Tuesday, 20 August 2019 9:53 AM  
**To:** Jenny Toh <jenny.toh@qbe.com>  
**Cc:** Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>; Chris Bulaclac <chris.bulaclac@ccfulco.com.sg>; Renemer Bagang <renemer.bagang@ccfulco.com.sg>  
**Subject:** Re:Accident On 19/08/2019 Involving Our Insured SJT731A And Your Insured YK6655S

Dear Motor Claims,

Our client is looking to make a claim against your insurer for property damage caused to her vehicle.

Please confirm if your insurance company is prepared to engage in a direct settlement for property damage only.

This settlement excludes out client's right to recover further loss arising from rental of alternative / replacement vehicle.

As our client requires the use of a vehicle during this period that her vehicle is in our workshop, our client has will rented a vehicle and will be looking towards your company to make good her loss/rental cost.

Please confirm that you understand that any direct settlement reached for the cost of repairs to our client's vehicle does not prejudice her rights to recover any other damages he has suffered.

**Please arrange for survey , vehicle already in workshop (330 Ubi Road 3 Singapore 408650) .**

Thank you,

Best regards

Mars Ler  
Senior Advisor - Motor Claims  
Cycle & Carriage Fulco Motor Dealer Pte Ltd  
330 Ubi Road 3 Singapore 408650  
D/D 65949163 H/P 91792566

----- IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

## Mars Ler

---

**From:** Janice Goh Siew Geok <janice.goh@qbe.com>  
**Sent:** Wednesday, 21 August 2019 12:07 PM  
**To:** Mars Ler; assignments@lkkauto.com  
**Cc:** Chris Bulaclac; Renemer Bagang  
**Subject:** RE: Re:Accident On 19/08/2019 Involving Our Insured SJT731A And Your Insured YK6655S ; QBE'S REF VC012899  
**Attachments:** SJT731A.pdf

Without PREJUDICE

Hi Mars

Thank you for your email.

Liability is clear for direct settlement.  
We will appoint LKK for the survey.

Hi LKK

Please assist.

Thank you.

---

**Janice Goh**  
Executive, Claims  
Claims | Asia  
1 Raffles Quay, #29-10 South Tower, Singapore 048583  
+65 6477 1243  
Website LinkedIn Twitter



**From:** Mars Ler <mars.ler@ccfulco.com.sg>  
**Sent:** Tuesday, 20 August 2019 9:53 AM  
**To:** Jenny Toh <jenny.toh@qbe.com>  
**Cc:** Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>; Chris Bulaclac <chris.bulaclac@ccfulco.com.sg>; Renemer Bagang <renemer.bagang@ccfulco.com.sg>  
**Subject:** Re:Accident On 19/08/2019 Involving Our Insured SJT731A And Your Insured YK6655S

Dear Motor Claims,

Our client is looking to make a claim against your insurer for property damage caused to her vehicle.

Please confirm if your insurance company is prepared to engage in a direct settlement for property damage only.



## Mars Ler

---

**From:** Vic (LKKAUTO) <vicalpeh@lkkauto.com>  
**Sent:** Monday, 26 August 2019 3:17 PM  
**To:** Mars Ler  
**Cc:** Admin A; Vic (LKKAUTO)  
**Subject:** Your Ref: SJT 731A\_ACCIDENT INVOLVING VEHICLES YK 6655S / SJT 731A / OTHERS ON 19/08/2019 LKK REF CC4/QBE19014673/Uhb3

WITHOUT PREJUDICE

Dear Mars,

### ACCIDENT INVOLVING VEHICLES YK 6655S / SJT 731A / OTHERS ON 19/08/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is clear subject to the BOLA guideline settlement.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle and admission of any liability to our Insured's part. The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor and approved by our principal.

Kindly forward the LOD and all supporting documents to us if available to proceed with the settlement.

Thank you.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth  
Print only when necessary

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC4/QBE19014673/Uhb3s2	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 26-12-2019	
		Code : QBE	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	YK 6655S	Veh. Inspected	SJT 731A
Policy No.	8-V0015848-MVA-E004	Coverage (\$)	0.00
Claim No.	VC012899	Excess (\$)	0.00
Assign From	JENNY TOH	Assign Date	21/08/2019
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	KIA NIRO HYBRID (A)	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KNACC81CVJ5096512	Colour	BLUE
Odometer	42038	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	BRIDGESTONE	5 mm
L/H Front Tyre	215/55 R17	BRIDGESTONE	5 mm
R/H Rear Tyre	215/55 R17	BRIDGESTONE	5 mm
L/H Rear Tyre	215/55 R17	BRIDGESTONE	5 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	19/08/2019	Inspection Date	21/08/2019
Survey held at	CYCLE & CARRIAGE.FULCO MOTOR DEALER PL NO.330 UBI ROAD 3 SINGAPORE 408650		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 731A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	COVER - FRONT BUMPER (SN)	DISTORTED	637.00	637.00
1	COVER ASSY - FRONT B (SN)	CUT	346.00	346.00
1	STRIP ASSY - FRONT B (SN)	NECESSARY	28.00	28.00
1	LOGO ASSY - KIA SUB (SN)	NECESSARY	51.00	51.00
1	GRILLE ASSY - RADIAT (SN)	CRACKED	441.00	441.00
1	GRILLE - FRONT BUMPE (SN)	SCRATCHED	232.00	232.00
1	LH SIDE BRACKET - FR (SN)	NOT NECESSARY	12.00	-
1	RH SIDE BRACKET - FR (SN)	BENT	12.00	12.00
1	ABSORBER - FRONT BUM (SN)	TORN	68.00	68.00
1	STIFFENER - FRONT BU (SN)	NOT NECESSARY	116.00	-
1	FLAP ASSY - ACTIVE A (SN)	NOT NECESSARY	328.00	-
1	DUCT ASSY - ACTIVE AIR (SN)	NOT NECESSARY	78.00	-
1	RH DUCT ASSY - AIR C (SN)	NOT NECESSARY	32.00	-
1	RH PIECE - FRONT BUM (SN)	NOT NECESSARY	16.00	-
1	LH PIECE - FRONT BUM (SN)	NOT NECESSARY	16.00	-
1	CAP - FRONT HOOK (SN)	NOT NECESSARY	7.00	-
1	WIRING HARNESS - FRO (SN)	SERVICEABLE	134.00	-
1	RH LAMP ASSY - FRONT (SN)	CRACKED	638.00	638.00
10	CLIP - FRONT BUMPER (SN)	NECESSARY	20.00	20.00
1	RH HEADLAMP ASSY (SN)	CRACKED	904.00	904.00
1	BEAM COMPLETE - FRON (SN)	TO REPAIR SEE LABOUR	551.00	-
1	CARRIER ASSY - FRONT (SN)	CRACKED	675.00	675.00
1	RH FENDER PANEL (SN)	TO REPAIR SEE LABOUR	385.00	-
1	INSULATOR - FENDER (SN)	NOT NECESSARY	46.00	-
1	HOOD PANEL ASSY (SN)	BUCKLED	1,438.00	1,438.00
1	RH HINGE ASSY - HOOD (SN)	BENT	40.00	40.00
1	LATCH ASSY - HOOD (SN)	TWISTED	123.00	123.00
1	SWITCH ASSY - HOOD (SN)	CRACKED	50.00	50.00
1	CABLE ASSY - HOOD LA (SN)	CRACKED / JAMMED	27.00	27.00

Report Ref No. CC4/QBE19014673/Uhb3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RH COVER - COWL TOP (SN)	NOT NECESSARY	6.00	-
1	TAIL GATE PANEL ASSY (SN)	BADLY DENTED	1,309.00	1,309.00
1	LIFTER ASSY - TAILGA (SN)	NOT NECESSARY	76.00	-
1	LIFTER ASSY - TAILGA (SN)	NOT NECESSARY	76.00	-
1	LATCH ASSY - TAILGAT (SN)	TWISTED	201.00	201.00
1	HANDLE ASSY - TAILGA (SN)	NOT NECESSARY	99.00	-
1	TAILGATE TRIM PANEL (SN)	NOT NECESSARY	164.00	-
1	WEATHERSTRIP - TAILG (SN)	NOT NECESSARY	99.00	-
1	GLASS ASSY - TAILGAT (SN)	SHATTERED	1,179.00	1,179.00
8	PAD-W/SHLD GLASS (SN)	NECESSARY	16.00	16.00
2	STOPPER - RR WINDOW GL (SN)	NECESSARY	30.00	30.00
1	CAMERA ASSY - BACK V (SN)	SHORTED	758.00	758.00
1	SPOILER - REAR (SN)	TO REPAIR SEE LABOUR	522.00	-
1	HIGH MOUNT STOP LAMP (NPA) (SN)	SERVICEABLE	-	-
1	RH GARNISH ASSY - "D" (SN)	SERVICEABLE	98.00	-
1	CAP - REAR WIPER ARM (SN)	CRACKED	3.00	3.00
1	ARM ASSY - REAR WIPE (SN)	BENT	59.00	59.00
1	BLADE ASSY - WIPER, (SN)	TWISTED	41.00	41.00
1	MOTOR & LINKAGE ASSY (SN)	SERVICEABLE	357.00	-
1	LH INSIDE LAMP ASSY (SN)	SCRATCHED	636.00	636.00
1	RH INSIDE LAMP ASSY (SN)	CRACKED	636.00	636.00
1	LH OUTSIDE LAMP ASSY (SN)	SERVICEABLE	645.00	-
1	RH OUTSIDE LAMP ASSY (SN)	CRACKED	645.00	645.00
1	LOGO - KIA (SN)	NECESSARY	42.00	42.00
1	EMBLEM - NIRO (SN)	NECESSARY	25.00	25.00
1	EMBLEM - ECO HYBRID (SN)	NECESSARY	29.00	29.00
1	COVER - REAR BUMPER (SN)	DISTORTED	423.00	423.00
1	COVER - REAR BUMPER (SN)	DISTORTED	392.00	392.00
1	SKID PLATE - REAR BU (SN)	DEFORMED	122.00	122.00
1	RH PIECE - RR BUMPER S (SN)	NECESSARY	16.00	16.00
1	COVER - RR BUMPER SIDE (SN)	NOT NECESSARY	27.00	-
1	LH SIDE MOUNTING ASS (SN)	NOT NECESSARY	20.00	-

Report Ref No. CC4/QBE19014673/Uhb3s2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RH SIDE MOUNTING ASS (SN)	DEFORMED	20.00	20.00
1	LH SIDE BRACKET ASSY (SN)	NOT NECESSARY	25.00	-
1	RH SIDE BRACKET ASSY (SN)	BENT	25.00	25.00
3	SENSOR ASSY - PARKING (SN)	SHORTED	405.00	135.00
1	WIRING HARNESS - RR BU (SN)	SERVICEABLE	361.00	-
1	LH LAMP ASSY - LICEN (SN)	CRACKED	27.00	27.00
1	RH LAMP ASSY - LICEN (SN)	CRACKED	27.00	27.00
1	RH REFLECTOR / REFLEX (SN)	BROKEN	104.00	104.00
1	BEAM - REAR BUMPER (SN)	BENT	261.00	261.00
1	BRACKET - REAR RAIL (SN)	NECESSARY	6.00	6.00
1	BRACKET - REAR BEAM (SN)	NECESSARY	6.00	6.00
1	BRACKET - SMART KEY MT (SN)	NECESSARY	5.00	5.00
1	BRACKET - REAR BEAM (SN)	NECESSARY	6.00	6.00
1	BRACKET - REAR BEAM (SN)	NECESSARY	6.00	6.00
1	LH STAY - REAR BUMPE (SN)	NOT NECESSARY	67.00	-
1	RH STAY - REAR BUMPE (SN)	BENT	67.00	67.00
1	ANTENNA ASSY - SMARTKE (SN)	NOT NECESSARY	39.00	-
1	GARNISH ASSY - FENDE (SN)	NOT NECESSARY	123.00	-
1	GARNISH ASSY - QUART (SN)	NOT NECESSARY	144.00	-
1	SCREEN ASSY - CARGO (SN)	NOT NECESSARY	812.00	-
1	TRIM ASSY - REAR TRA (SN)	NOT NECESSARY	60.00	-
1	PANEL ASSY - BACK (SN)	TO REPAIR SEE LABOUR	526.00	-
1	MUFFLER ASSY - REAR (SN)	TO REPAIR SEE LABOUR	840.00	-
10	CLIP - RR BUMPER (SN)	NECESSARY	20.00	20.00
4	COOLANT (SN)	NECESSARY	104.00	104.00
1	C&C LOGO (SN)	NECESSARY	50.00	50.00
2	FRONT AND REAR NUMBER PLATE WITH CASING (SN)	BENT	100.00	100.00
1	BLACKVUE DR430 (2 CHANNEL) (SN)	DAMAGED / SHORTED	750.00	750.00
1	HORN ASSY - LOW PTIC (SN) (ADDITIONAL)	CRACKED	79.00	79.00
1	GUARD - AIR, RH (SN) (ADDITIONAL)	DISTORTED	29.00	29.00
1	DAM - AIR (SN) (ADDITIONAL)	NECESSARY	27.00	27.00

Report Ref No. CC4/QBE19014673/Uhb3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CABLE ASSY - HOOD LA (SN) (ADDITIONAL)	CRACKED / JAMMED	27.00	27.00
1	RADIATOR ASSY - INVE (SN) (ADDITIONAL)	BENT / PUNCTURE	768.00	768.00
1	RADIATOR ASSY (SN) (ADDITIONAL)	BENT / TWISTED	492.00	492.00
1	BLOWER ASSY (SN) (ADDITIONAL)	CRACKED	546.00	546.00
1	HOSE & CLAMP ASSY (SN) (ADDITIONAL)	TWISTED	31.00	31.00
1	TUBE - LIQUID (SN) (ADDITIONAL)	BENT / PUNCTURE	216.00	216.00
1	COVER ASSY - RADIATO (SN) (ADDITIONAL)	CRACKED	40.00	40.00
			23,443.00	16,266.00
	<b>LABOUR</b>			
	TO REMOVE AND RE-INSTALL REAR LOWER SEAT TO GIVE WAY ACCESS REMOVE AND RE-INSTALL HIGH VOLTAGE CABLE.		1,200.00	600.00
	TO DIAGNOSTIC / SCANNING.		250.00	250.00
	TO CHECK LIGHTING AND WIRING ON FRONT & REAR ACCIDENT AFFECTED AREAS.		160.00	160.00
	TO REMOVE AND RE-INSTALL RAD & A/C CONDENSOR TO GIVE WAY ACCESS REPAIR ON FRONT ACCIDENT AFFECTED AREAS.		280.00	180.00
	TO REPLACE FRONT BUMPER, REINFORCEMENT, FRT CARRIER, HOOD PNL, RHF FENDER PNL, ETC - REPAIR RHF DOOR PNL STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF BEAM COMPLETE - FRON AND RH FENDER PANEL.		4,200.00	2,400.00
	TO APPLY SEALANT KIT ON FRONT NEW PANEL.		200.00	100.00
	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS.		2,100.00	2,000.00
	TO REPLACE FRONT TAILGATE GLASS.		300.00	300.00
	SEALANT KIT ON TAILGATE GLASS.		100.00	100.00
	TO INSTALL RIKE COOL SOLAR FILM ON TAILGATE GLASS.		220.00	220.00
	TO REMOVE AND RE-INSTALL TRIMMING AND CARPETING TO GIVE WAT ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS.		600.00	300.00
	TO VACUUM & CLEAN GLASS DEBRIS ON INTERIOR CARPETING AND REAR SEAT.		600.00	100.00
	TO REPLACE REAR EXHAUST MUFFLER ASSY.		600.00	250.00

Report Ref No. CC4/QBE19014673/Uhb3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER TAILGATE COMPONENT & MECHANISMS PARTS.		600.00	300.00
	TO REPLACE TAILGATE PNL, REAR BUMPER, REINFORCEMENT, ETC - CUT & RE-WELD REAR END PANEL STRAIGH, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF SPOILER - REAR, PANEL ASSY - BACK AND MUFFLER ASSY - REAR.		3,600.00	1,800.00
	TO APPLY SEALANT KIT ON REAR NEW PANEL.		300.00	100.00
	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS.		2,100.00	2,000.00
			17,410.00	11,160.00
GRAND TOTAL			40,853.00	27,426.00
RECOMMENDED COST OF REPAIRS				27,426.00

Report Ref No. CC4/QBE19014673/Uhb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.