

ASS. REC. BY:

REF: CS/CT1 19014674/ Etf3n2 Special Instruction:

Surveyor

Steve

ASSIGNMENT (Office)

From (Person):

Fangqing Yan

of

CT1

Date/Time: 20.8.19 16.43p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 2900J

Insured:

SJW 3212X

at Workshop m/s

CYS Automobile

Tel:

62192098

of

32 Woodlands Industrial Park East 1 #107-17

Policy No:

DMP C9V3048261900

Claim No:

SNM18D0390802

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time:

2.8.19 10.17a.m

Person Contacted:

ms Tu

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time

Action/Instruction

(✓) Estimate

YP 2900J - X

SJW 3212 X - X

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: YP 2900J

Yr Regn: 26/5/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi Canter C.C. 2998

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 19046 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FEB 21 EA 20571

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: 195/85R15
R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 15/8/19 D.O.I. 21/8/19

Survey held at CYS Automobile

Des. of Damages: Frt / Rear / OIS / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-SSK 25/9/19 Finalize confirm \$1395.59, 3 days (Wei Sin)
cred: 1011.05; 42%

RECEIVED 20 SEP 2019

Date/Time, File Pass to?

25/9/19 Typist

Date/Time, File Return to?

2)

Report Form(s): _____

Lump Sum / T.B.H. is _____

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Aug 2019		20 Aug 2019 16:43 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS			[Created by insurer]																					
Insured:																								
Main Claimant:	FONG YIP KAYA PTE LTD, Co. Reg. No.: 199305902H																							
Vehicle Reg. No.:	YP2900J	Date of Loss:	15/08/2019 13:00 - :59																					
Claim Type:	TP / SNM18D03808C02	Policy/Cover Note No.:	DMPCSN3048261900																					
Vehicle Reg. No. (Insured):	SJW3212X	Policy No. (Claimant):	M0006568																					
		Excess:	S\$3,750.00																					
Repairer:	CYS Automobile Services Pte Ltd (Woodlands) 38 Woodlands Industrial Park East 1, #07-17, Admiralty Industrial Park, 757700 Woodlands - Tel: 6219 2098																							
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Fang Qingyan]																							
Claimant's Insurer:	Etiqa Insurance Pte Ltd (HQ) - Tel: 63360477																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/08/2019]																							
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail																				
There are no mail for this case.																								
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	902H
Vehicle Details	
Vehicle No.:	YP2900J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Aug 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER4SDEB (CBU)
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	4P10C22112
Chassis No.:	FEB21EA20571
Maximum Power Output:	-
Open Market Value:	\$32,616.00
Original Registration Date:	26 May 2016
First Registration Date:	26 May 2016
Transfer Count:	0
Actual ARF Paid:	\$1,631.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 May 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$19,473.00
COE Rebate Amount:	\$13,159.00
Total Rebate Amount:	\$13,159.00

The information contained herein is correct as at 16 Aug 2019

OK



進友成汽車服務私人有限公司

CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR FONG YIP KAYA PTE LTD
NO 1 SENOKO AVE
#03-08 SINGAPORE 758297

POLICY NO : THIRD PARTY CLAIM
YOUR REF : SJW 3212 X (CHINA)
OUR REF : TP 6060
VEHICLE NO : YP 2900 J
MAKE/MODEL : MIT FUSO
DATE OF ACCIDENT : 15.08.19

SURVEY BY

DATE : 16.08.19

1 PC TAILBAORD "MITSUBISHI" STICKER / MK		SS	159.60	
1/2 PCS TAILLAMP ASSY (WITH BRACKETS) (LH) / CH	268.06		536.12	268.06
1 PC REAR NO. PLATE LAMP (WITH BRACKET) / DR			76.86	
		SS	772.58	504.52
	LESS 25%		193.15	-25%
		SS	579.44	378.39
1 PC TAILBOARD "60KM/H" STICKER / MK		SS	15.00	S/NETT
1 PC TAILBOARD "23 PAX" STICKER / MK			15.00	"
1 PC REAR NO. PLATE / CH			35.00	"
1 PC SAFETY BAR (WITH BRACKET) X BT (L R)			900.00	300
1 PCS SAFETY BAR SCREW / DR	5.00		30.00	90
		SS	995.00	385
TO CHECK WIRING FUNCTION		SS	30.00	
LABOUR CHARGES			500.00	300
TO PUTTY AND SPRAY PAINTING CHARGES			300.00	
		SS	2,404.44	650

P- 378.39
M- 385
L- 630
1393.39

SIN DOLLARS: TWO THOUSAND FOUR HUNDRED FOUR AND CENTS FORTY-FOUR ONLY

YOUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

38 Woodlands Industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700

Tel: 6219 2098 (3 Lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

Steve CLKK)
8322 8813

27/8/19

W/L M/L 21/8/19, 12.00p
3 days

P/P
Ry AL M

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119014674/ETF3N2

Date: 30/09/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3048261900
Claimant Vehicle No :	YP2900J	Insured Vehicle No :	SJW3212X
Date of Loss:	15/08/2019	Nature of Claim:	TP
		Claim No:	SNM18D03808C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP2900J	Engine No:	4P10C22112
Make & Model:	MITSUBISHI FUSO, 3.0 D FE83 (M)	Chassis No:	FEB21EA20571
Reg. Date:	26/05/2016 (Man. Year: 2016)	Odometer:	19046 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/85R15	Rear Tyre Size:	195/85R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,574.43	763.39	811.04	51.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	830.00	630.00	200.00	24.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,404.43	1,393.39	1,011.04	42.05
+ GST 7.00/7.00% (\$\$)	168.31	97.54	70.77	42.05
Nett Amount (\$\$)	2,572.74	1,490.93	1,081.81	42.05

INSPECTION

Date of Assignment:	20/08/2019	
Date Inspected:	21/08/2019	Inspected At:
		CYS Automobile Services Pte Ltd (Woodlands) 38 Woodlands Industrial Park East 1, #07-17, Admiralty Industrial Park Singapore 757700
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Sep 2019)	
Parts:	N/A	MITSUBISHI FUSO 3.0 D FE83 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP2900J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILBOARD MITSUBISHI STICKER	Necessary	159.60 FL	*159.60 FL
2	1		*TAILLAMP ASSY (WITH BRACKETS)	N/s Cut	536.12 FL	*268.06 FL
3	1		*REAR NO PLATE LAMP (WITH BRACKET)	Broken	76.86 FL	*76.86 FL
4	1		*TAILBOARD 60KM/H STICKER	Necessary	15.00 FS	*15.00 FS
5	1		*TAILBOARD 23PAX STICKER	Necessary	15.00 FS	*15.00 FS
6	1		*REAR NO PLATE	Cut	35.00 FS	*35.00 FS
7	1		*SAFETY BAR (WITH BRACKET)(LOCAL REPAIR)	Bent	900.00 FS	*300.00 FS
8	1		*SAFETY BAR SCREW	Broken	30.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,767.58	889.52
- List Item Discount on L Items 25.00/25.00% (S\$)	193.15	126.13
Total Parts (S\$)	1,574.43	763.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING FUNCTION	New	30.00	30.00
2	LABOUR CHARGES	New	500.00	300.00
3	TO PUTTY AND SPRAY PAINTING CHARGES	New	300.00	300.00
Gross Labour Cost (\$\$)			830.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >