



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMD525C

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No **36169**
Reg No/Reg Date **SMD525C / 08/11/2018**
Date In/Mileage **/ 0**
Chassis No **WDD2462422J5143468**
Engine No **27091031737371**
Make/Model **MB/MB B 180 STYLE**
Colour/Trim **028 890 Cavansite B/ 041 118 Lther ARTIC**

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	19/08/2019/ 14:21	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 1800132909 // 17.08.19 DRIVE IN/EXCESS : 19.08.19 // TP CAR NO.: GBC5871E DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB "USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT"			0.10	380.00
A BPILAB REMOVE & REPLACE ON REAR BUMPER				1200.00
A BPIRES RESPRAY ON REAR BUMPER				1200.00
M REAR BUMPER	1.00	1499.14	00.00	1499.14
M CENTRE BASIC MOUNTING FOR BUMPER	1.00	109.76	00.00	109.76
M [STR] FOOTPLATE	1.00	239.22	00.00	239.22
M REAR LOWER BUMPER	1.00	152.11	00.00	152.11
M REAR BUMPER CHROME MOULDING	1.00	207.93	00.00	207.93
M REAR CROSS MEMBER	1.00	473.66	00.00	473.66

Confirmed & accepted by

Nett **5,461.82**
7% GST on **5461.82** **382.33**

Authorized signatory and company stamp

Total Payable **5,844.15**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg