



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

KHALAP PRANJAL PRAKASH

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

19/08/2019

TP III
Ceilia.

Accident date: 18/08/2019

Estimated repair cost for vehicle no: SLZ9392E MERCEDES C180 1.6 A '15

CHASSIS: WDD2050402R040337

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>Dented</i>		\$2,426.00	2254
2	2	Rear Boot Lid Hinge <i>Not New</i>	\$262.00	\$524.00	x
3	1	Rear Boot Lid Emblem Logo		\$51.00	✓
4	3	Rear Boot Lid Emblem Logo Clip	\$8.00	\$24.00	✓
5	1	Rear Boot Lid C180 Logo		\$90.00	✓
6	1	Rear Boot Lid C&C Logo		\$60.00	✓
7	1	Rear Boot Lid Number Plate <i>cracked</i>		\$50.00	✓
8	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$335.00	✓
9	1	Rear Boot Lid Inner Rubber <i>OK</i>		\$191.00	✓
10	1	Rear Boot Lid Inner Trim Board <i>2 ALP</i>		\$248.00	x
11	10	Rear Boot Lid Inner Trim Board Clip <i>1 new</i>	\$6.50	\$65.00	x
12	1	Rear Boot Lid Centre Chrome Moulding <i>Not New</i>		\$244.00	x
13	1	Rear Boot Lid Camera <i>Not New</i>		\$680.00	x
14	2	Rear Tail Lamp <i>cracked</i>	\$816.00	\$1,632.00	✓
15	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00	✓
16	2	Rear Tail Lamp Lower Bracket <i>cracked</i>	\$68.00	\$136.00	✓
17	1	Rear Bumper <i>Distorted</i>		\$1,877.00	1687
18	1	Rear Bumper Lower Lid (Matt Black) <i>Distorted</i>		\$280.00	✓
19	1	Rear Bumper Lower Chrome <i>Distorted</i>		\$306.00	✓
20	2	Rear Bumper Side Chrome <i>Damaged</i>	\$193.00	\$386.00	✓
21	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00	✓
22	2	Rear Bumper Side Retainer <i>new</i>	\$68.00	\$136.00	✓
23	4	Rear Bumper Reverse Sensor <i>3 pieces damaged</i>	\$232.00	\$928.00	696.
24	1	Rear Bumper Towing Cover <i>Not New</i>		\$70.00	x
25	1	Rear Bumper Reinforcement <i>Bent</i>		\$682.00	✓
26	1	Rear Bumper Top Beam <i>3 Distorted</i>		\$110.00	✓
27	1	Rear Bumper Center Bracket		\$110.00	✓

28	2	Rear Bumper Side Bracket <i>new</i>	\$82.00	\$164.00 ✓
29	1	Rear R/H Bumper Side Under Cover <i>Del'd</i>		\$126.00 ✓
30	1	Rear Bumper Hands-Free Access Sensor <i>Del'd</i>		\$682.00 458.
31	2	Rear Fender Inner Trim Board <i>3MP</i>	\$381.00	\$762.00 x
32	16	Rear Fender Inner Trim Board Clip <i>new</i>	\$6.50	\$104.00 x
33	1	Rear End Panel Assy <i>Dented</i>		\$1,480.00 1330
34	1	Rear End Panel Top Garnish <i>cracked</i>		\$168.00 ✓
35	1	Rear Spare Tyre Panel <i>cracked</i>		\$655.00 ✓
36	1	Rear Spare Tyre Panel Top Cover <i>Del'd</i>		\$692.00 ✓
37	1	Rear Spare Tyre Panel Inner Foam <i>cracked</i>		\$246.00 ✓
38	1	Rear Spare Tyre Panel Inner Trim Cover <i>new</i>		\$328.00 x
39	1	Rear Spare Tyre Panel Sealant <i>new</i>		\$450.00 100
40	1	Rear R/H Spare Tyre Panel Under Cover <i>cracked</i>		\$301.00 ✓
41	1	Rear Exhaust <i>Bent</i>		\$1,255.00 ✓
42	1	Rear Centre Exhaust <i>new</i>		\$1,300.00 x
43	2	Rear Exhaust Mounting <i>new</i>	\$55.00	\$110.00 x
44	1	Rear Exhaust Aluminium Cover <i>cracked</i>		\$189.00 ✓

14984
13785-60

Subtotal :- \$20,737.00

Labour charges

To remove & refit cushion	\$280.00 80
To remove & refit reverse sensor	\$100.00 60
To remove & refit camera	\$180.00 60
To remove & refit rear & centre exhaust	\$380.00 180.
To reset computer	\$380.00 150
To check wiring	2660 \$100.00 30
Tuff kote	\$150.00 80
Panel beating	total 16145-60 \$1,600.00 1100
Spray painting	1/s: 12.9K \$1,600.00 1750

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :- \$4,770.00

Total:- \$25,507.00

12.9K

10 days