

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

ANH208253889

YAP POH KEONG
5 JALAN SERULING 44
TAMAN KLANG JAYA
41200 KLANG

TP chin
Ichanchan

Date :23.08.2019
Vehicle No :VBE 665
Make/Model :TOYOTA VELLFIRE
Accident date :16.08.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear bumper Distorted.	1	\$ 2149.2 1539.
2	Rear bumper side holder @ \$ 108.90 LH Dmgd.	2	\$ 217.8 108.90.
3	Rear bumper towing hook cover missing	1	\$ 59.1 ✓
4	Rear bumper LH reflector cruked	1	\$ 188.6 ✓
5	Rear bumper reverse sensor (1 set) Danged.	1	\$ 1679.2 880
6	Rear bumper clips (1 set) New	1	\$ 60.5 30.
7	Rear LH lamp Lt ?	1	\$ 535.2 ✓
8	Rear LH lamp lower garnish New	1	\$ 306.4 +
9	Rear LH fender Reps	1	\$ 1760.6 X
10	Rear LH fender quater glass rubber New	1	\$ 181.5 X
11	Rear LH fender lower garnish missing	1	\$ 357 ✓
12	Rear LH fender inner shield 3 New	1	\$ 446.1 X
13	Rear LH fender inner shield clips (1 set)	1	\$ 60.5 X
14	Rear LH centre door Dented.	1	\$ 1815 ✓
15	Rear LH centre door lower cover Deltd	1	\$ 1573 621
16	Rear LH centre door lower rubber New	1	\$ 121 X
17	Rear LH centre door rear rubber 3 New	1	\$ 115 X
18	Rear LH centre door front rubber	1	\$ 640.1 X
19	Rear LH centre door inner board cruked	1	\$ 1339.6 1007.
20	Rear LH centre door power window motor New	1	\$ 804.5 X
21	Rear LH centre door power window regulator 3 New	1	\$ 310.1 ✓
22	Rear LH centre door sunrise Visor New	1	\$ 121 50(SW)
23	Rear LH centre door glass outer moulding New	1	\$ 304.8 +
24	Rear LH centre door top hinge	1	\$ 189.3 +
25	Rear LH centre door lower hinge 2 New	1	\$ 187.1 +
26	Rear LH centre door top roller New	1	\$ 262.2 +
27	Rear LH centre door lower roller	1	\$ 381.2 +
28	Rear LH knuckle arm New	1	\$ 2780.6 +
29	Rear LH knuckle arm bearing New	1	\$ 1116.8 450
30	Rear Axel assy Best	1	\$ 3103.9 ✓
31	Rear LH fender mud flap Deltd	1	\$ 298.6 ✓

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

YAP POH KEONG
5 JALAN SERULING 44
TAMAN KLANG JAYA
41200 KLANG

Date :23.08.2019
Vehicle No :VBE 665
Make/Model :TOYOTA VELLFIRE
Accident date :16.08.2019

No	DESCRIPTION	Qty	Amount (\$\$)
32	Tailgate	1	\$ 1884 +
33	Tailgate VellFire emblem	1	\$ 133.5 +
34	Tailgate upper lock	1	\$ 617.8 +
			\$ 26100.8
		Less 25% Disc	\$ 6525.2
		Total	\$ 19575.6

Special Nett Items

1	Rear LH sport rim	1	\$ 1050 680
2	Rear LH tyre	1	\$ 480 x
			\$ 1530
		Less 10% Disc	\$ 153
		Total	\$ 1377

Labour Cost

1	To check wheel alignment	\$ 100 80
2	Remove & reinstall bootlid inner garnish	\$ 200 x
3	Remove & reinstall door glass fittings	\$ 200 80
4	Remove & reinstall reverse sensor	\$ 200 60
5	Remove & reinstall rear LH suspension	\$ 500 300
6	Remove, replace & repair consistent to the accident	\$ 2000 800
7	Respray painting	\$ 1700 900
8	Tuff kote	\$ 150 60
	Total	\$ 5050

Grand Total \$ 26002.6

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 10813.60

W/S 86K. ✓

07 Days