

Surveyor:

RASUL

DOI: 20/08/19

ASSIGNMENT

Date / Time : 20/08/19

Registered in Merimen: 21/08/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SHC 3754C

Claim No. : _____

Name of Insured : COMFORT TRANSPORTATION PTE LTD

Policy No. : _____

Insured Tel No. : _____

HP: _____

Make / Model : _____

Excess Sec II : S\$

D.O.A : 18/08/2019 02:35

Place of Accident : JUNG OF KITCHENER RD / SERANGOON RD

Is driver the owner? (YES / NO)

Nature of Accident : _____

If NO, Driver Name / Age : _____

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : _____

(V/L YES / NO)

Insured Liability : % Final ? Yes / No

GBG5872G



INSRS:

WSP: SIN SHENG

Tel : _____

Liability : _____

RMKS: _____



INSRS:

WSP: _____

Tel : _____

Liability : _____

RMKS: _____



INSRS:

WSP: _____

Tel : _____

Liability : _____

RMKS: _____



INSRS:

WSP: _____

Tel : _____

Liability : _____

RMKS: _____

Date/ Time	STAGE	DATE / PIC
	SHC 3754C - CC3/AXA13013874/Yey3c3; DOA: 29/7/13	
	- CS/MSG19014554/Dsf3; DOA: 18/8/19	
	GBG 5872G - CS/MSG19014554/Dsf3; DOA: 18/8/19	
21/9	Recd AUF from OI. Sek III approval to reject TP claim. OID driving straight TPV turning right. CX Junction 7. (After ab per III approval) mbly	Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: After call ltr to OI:
22/10	Rejection email to TP	
16/12	Provide Mr Yew show 2 sign. Can get lit lit from Panel 2 * No estimate given * * Get Rasul to draft 23 list in order to change III. 19/3 - Ptd pass me to close	Documentation Check List: Handler Typist Notification ltr (if non-pickup) After call ltr to OI: Authorisation To Act: Release Voucher: Final Repair Bill: Car Rental Invoice: Towing Invoice LTA / GIA : Medical Bill: PIR: Mandate/Reject Instruction: LOD Payment Breakdown Form: Post-Repair Photos: Others:
PRELIMINARY ADVICE Date/Time: _____ Sent By: _____		
FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____		
Repair Cost:	S\$ _____ (_____ days) Reduction: _____ %	Email ☐ Call ☐
FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email ☐ Call ☐		
Final Liability:	% ☐ (Agreed / Assessed) BOLA S/N No. : _____	If NO or B 28, Ass. Lia : _____
Repair Cost:	S\$ _____	
Loss of Rental (LOR):	S\$ _____ (_____ days)	
Loss of Use (LOU):	S\$ _____ (\$ x _____ days)	
Loss of Income (LOI):	S\$ _____ (\$ x _____ days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]		
GIA/LTA Search	S\$ _____	
Medical:	S\$ _____	
Disbursement:	S\$ _____ (e.g. Tow/ Independent)	
Legal Cost	S\$ _____	
Total:	S\$ _____ Global Sum S\$:	
FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email ☐ Call ☐		
Payee 1:	S\$ _____ Name 1: _____	
Payee 2: (Strike if N.A.)	S\$ _____ Name 2: _____	
Payee 3: (Strike if N.A.)	S\$ _____ Name 3: _____	

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format: _____

3) Survey fee: #45012 *

MOTOR CAR (UC)

Undercarriage

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber	498	?	
1373	991944	Frt LH Shock Absorber Mounting	300	?	
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm	685	61	1
1376	995199	Frt LH Knuckle Arm Bearing	250	2	1
1377	995178	Frt LH Lower Arm	458	61	1
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod			
1380	995143	Frt LH Drive Shaft			
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion			
1391	994435	Steering Cross Member			
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage			
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
	990534	Centre Exhaust Pipe Assy			
	990532	Centre Exhaust Mounting			
1404	991134	Floor Panel			
1405	993719	Rear LH Shock Absorber			
1406	993723	Rear LH Shock Absorber Mounting			
1407	993170	Rear LH Coil Spring			
1408	993550	Rear LH Knuckle Arm			
1409	993551	Rear LH Knuckle Arm Bearing			
1410	993597	Rear LH Lower Arm			
1411	993884	Rear LH Upper Arm			
1412	995161	Rear LH Drive Shaft			
1413	995216	Rear LH Control Arm			
1414	993881	Rear LH Trailing Arm			
1415	993573	Rear LH Leaf Spring			
1416	992941	Rear LH Brake Disc Rotor			
1417	992937	Rear LH Brake Caliper Assy			
1418	990434	Rear LH Brake Pipe			
1419	992946	Rear LH Brake Hose			
1420	993819	Rear Sub Frame			
1421	993820	Rear Sub Frame Mounting			
1422	992813	Rear Anti Roll Bar			
1423	990168	Rear Anti Roll Bar Linkage			
1424	990202	Axle Beam			
1425	990170	Rear Axle Panhard Rod			
1426	990810	Differential Assy			
1427	992706	Propeller Shaft			

Vehicle No:

NAC	INC	Item	CON	AC	Qty
1428	991935	Frt RH Shock Absorber			
1429	991944	Frt RH Shock Absorber Mounting			
1430	990632	Frt RH Coil Spring			
1431	991844	Frt RH Knuckle Arm			
1432	991845	Frt RH Knuckle Arm Bearing			
1433	991851	Frt RH Lower Arm			
1434	992064	Frt RH Upper Arm			
1435	992040	Frt RH Tie Rod			
1436	991692	Frt RH Drive Shaft			
1437	990661	Frt RH Control Arm			
1438	992062	Frt RH Trailing Arm			
1439	991848	Frt RH Leaf Spring			
1440	991293	Frt RH Brake Disc Rotor			
1441	991281	Frt RH Brake Caliper			
1442	991292	Frt RH Brake Pipe			
1443	991287	Frt RH Brake Hose			
1444	991295	Frt RH Brake Sensor Wire			
1445	993720	Rear RH Shock Absorber			
1446	993723	Rear RH Shock Absorber Mounting			
1447	993173	Rear RH Coil Spring			
1448	993550	Rear RH Knuckle Arm			
1449	993551	Rear RH Knuckle Arm Bearing			
1450	993601	Rear RH Lower Arm			
1451	993885	Rear RH Upper Arm			
1452	993322	Rear RH Drive Shaft			
1453	993178	Rear RH Control Arm			
1454	995117	Rear RH Trailing Arm			
1455	995110	Rear RH Leaf Spring			
1456	992942	Rear RH Brake Disc Rotor			
1457	992938	Rear RH Brake Caliper Assy			
1458	990434	Rear RH Brake Pipe			
1459	992947	Rear RH Brake Hose			
		wrap			
		Labour - 1000			2000
		spray - 1000			2000
		undercarriage labor - 150			150 / 250
		Seat belt labor - 300			350
		Air bag - 250			300

No of Items: _____ Assessor: _____

Original copy

8 days

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 20 August 2019 1:25 PM
To: sinsheng engineeringservices; sur@lkkauto.com; Admin-D (LKKAuto)
Cc: Pooi Chin Han Daniel
Subject: RE: Accident Involving GBG5872G with SHC3754C(III) on 18/08/2019

Dear Sir / Mdm,

Please conduct a survey on TP vehicle GBG5872G and let us have your report urgently.

This claim will be handled by Daniel.

*Kindly upload this survey request email to merimen.

Thank You.

Daniel Pooi
Motor Claims Department
India International Insurance Pte Ltd
64 Cecil Street #04-02 IOB Building
Singapore 049711
Tel: 6347 6100 Ext 202 Fax: 6224 4174
S&P 'A-' rated Company



From: sinsheng engineeringservices [mailto:sinsheng1981@gmail.com]
Sent: Tuesday, 20 August, 2019 10:34 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: Accident Involving GBG5872G with SHC3754C(III) on 18/08/2019

Hi Daniel Pooi,

We select LKK Auto Consultants Pte Ltd.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You
Regards

Pei Jin
Sin Sheng Engineering Services
No 8 Tuas Ave 18
Singapore 638892
(Level 3 Office)
(Level 5 Workshop)

1:53pm 20/8/19
person @ pei jin
vehicle in

From: sinsheng engineering services [mailto:sinsheng1981@gmail.com]
Sent: Monday, 19 August, 2019 5:20 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Accident Involving GBG5872G with SHC3754C on 18/08/2019

Dear Officer In charge,

We are repairer of motor vehicle GBG5872G. Enclosed Accident Statement and LTA search fee for your attention please. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two (2) workings days upon received this email.

Kindly let us have your list of 10 nominated surveyors to conduct the Single-Joint Inspection.

Kindly assist to revert the liability issue or offer if direct settlement is in order

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You
Regards

Pei Jin
Sin Sheng Engineering Services
No 8 Tuas Ave 18

Singapore 638892

(Level 3_Office)

(Level 5_Workshop)

Tel: 6863 9595
Fax: 6863 6477

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

On Tue, 20 Aug 2019 at 09:53, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Daniel Pooi

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street #04-02 IOB Building

Singapore 049711

Tel: 6347 6100 Ext 202 Fax: 6224 4174

S&P 'A-' rated Company



Print Received Message

This mail is associated with :

***GBG5872G (MCT19080434)**
[SHC3754C]
TP
GOLDBELL LEASING PTE LTD
Aug 18 2019 2:00AM
[COMFORT TRANSPORTATION PTE LTD]
Sin Sheng Engineering Services - Tuas

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 30/09/2019 11:34 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - GBG5872G - Claim Handler: Pool Chin Han Daniel

Approved:0.00:Reject TP claim

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Wednesday, 23 October 2019 6:27 PM
To: sinsheng engineeringservices
Subject: YOUR REF: GBG 5872G (OUR REF: CC4/III19014692/R1ga3) *** ACCIDENT INVOLVING SHC 3754C & GBG 5872G ON 18/08/2019 ***
Attachments: Video - Accident MCT19080434 SHC3754C 18-08-2019 NAF.MP4

Your Ref: **GBG 5872G** Without Prejudice
Our Ref: CC4/III19014692/R1ga3

Dear Sirs/Madam,

ACCIDENT INVOLVING SHC 3754C (III) & GBG 5872G ON 18/08/2019

We refer to the above matter.

Attached is a copy of our insured car video footage for your easy reference. We have reviewed the matter and we are of the view that our driver is not liable for the accident. The traffic light was green which means our driver has the right of way. And your client is making a right turn without checking for oncoming vehicles going straight.

In view of the above, we have our principal instruction to deny liability (Under Bola S5) and unable to look into your client's matter.

Thank you.

Note: This video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

Rasul (LKKAuto)

From: sinsheng engineeringservices <sinsheng1981@gmail.com>
Sent: Tuesday, 17 December, 2019 11:33 AM
To: Rasul (LKKAuto)
Subject: Re: GBG 5872G DOA : 18/08/19

Hi Mr. Rasul,

Please be informed that this accident case already changed to reporting only. So no claim for this case.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You
Regards

Pei Jin

Sin Sheng Engineering Services
No 8 Tuas Ave 18
Singapore 638892
(Level 3 Office)
(Level 5 Workshop)
Tel: 6863 9595
Fax: 6863 6477

On Tue, 17 Dec 2019 at 10:18, Rasul (LKKAuto) <Rasul@lkkauto.com> wrote:

Hi Pei Jin,

Is this case provide estimate?

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315



Auto
Components
Pte Ltd

Save the Earth. Print only when necessary.

...CLAIM SUBFOLDER...(Pending for Survey Report)
WP:

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Aug 2019 Edit Reg		20 Aug 2019 00:00 Edit Adj Rpt	\$517,776.00 Edit Estimates	\$517,776.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS		[Created by adjuster]
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R	
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N	
Vehicle Reg. No.:	GBG5872G	Date of Loss: 18/08/2019 02:00 - :59 [23 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT19080434	Policy/Cover Note No.: MCOM0015 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	SHC3754C	Policy No. (Claimant): 29090793
		Excess:
Repairer:	Sin Sheng Engineering Services - Tuas (HQ) 8 Tuas Avenue 18 Level 5, 638892 Tuas - Tel:	
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pool Chin Han Daniel]	
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 30/08/2019]	

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

• III_SG (30/09/2019): Alert - Adj Mandate Approved (\$50.00) - GBG5872G - Claim Handler: Pool Chin Han ...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBG5872G (MCT19080434)
[SHC3754C]
TP
GOLDBELL LEASING PTE LTD
Aug 18 2019 2:00AM
[COMFORT TRANSPORTATION PTE LTD]
Sin Sheng Engineering Services - Tuas

Upload DocumentsUpload PhotosCompose New LetterViewView in Browser

Video			1 per page	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	30/09/19 10:59	Video - Accident MCT19080434 SHC3754C 18-08-2019 NAF	1 Load MP4	
Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/12/19 18:01	General View	1 Load JPG	
2	16/12/19 18:01	General View	1 Load JPG	
3	16/12/19 18:01	General View	1 Load JPG	
4	16/12/19 18:01	General View	1 Load JPG	
5	16/12/19 18:01	General View	1 Load JPG	
6	16/12/19 18:01	General View	1 Load JPG	
7	16/12/19 18:01	General View	1 Load JPG	
8	16/12/19 18:01	General View	1 Load JPG	
9	16/12/19 18:01	General View	1 Load JPG	
10	16/12/19 18:01	General View	1 Load JPG	
11	16/12/19 18:01	General View	1 Load JPG	
12	16/12/19 18:01	General View	1 Load JPG	
13	16/12/19 18:01	General View	1 Load JPG	
14	16/12/19 18:01	General View	1 Load JPG	
15	16/12/19 18:01	General View	1 Load JPG	
16	16/12/19 18:01	General View	1 Load JPG	
17	16/12/19 18:01	General View	1 Load JPG	
18	16/12/19 18:01	General View	1 Load JPG	
19	16/12/19 18:01	General View	1 Load JPG	
20	16/12/19 18:01	General View	1 Load JPG	
21	16/12/19 18:01	General View	1 Load JPG	
22	16/12/19 18:01	General View	1 Load JPG	
23	16/12/19 18:01	General View	1 Load JPG	
24	16/12/19 18:01	General View	1 Load JPG	
25	16/12/19 18:01	General View	1 Load JPG	
26	16/12/19 18:01	General View	1 Load JPG	
27	16/12/19 18:01	General View	1 Load JPG	
28	16/12/19 18:01	General View	1 Load JPG	
29	16/12/19 18:01	General View	1 Load JPG	
30	16/12/19 18:01	General View	1 Load JPG	
31	16/12/19 18:01	General View	1 Load JPG	
32	16/12/19 18:01	General View	1 Load JPG	
33	16/12/19 18:01	General View	1 Load JPG	
34	16/12/19 18:01	General View	1 Load JPG	
35	16/12/19 18:01	General View	1 Load JPG	
36	16/12/19 18:01	General View	1 Load JPG	
37	16/12/19 18:01	General View	1 Load JPG	
38	16/12/19 18:01	General View	1 Load JPG	
39	16/12/19 18:01	General View	1 Load JPG	
40	16/12/19 18:01	General View	1 Load JPG	

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
				☒
41	16/12/19 18:01	General View	 Load JPG	☒
42	16/12/19 18:01	General View	 Load JPG	☒
43	16/12/19 18:01	General View	 Load JPG	☒
44	16/12/19 18:01	General View	 Load JPG	☒
45	16/12/19 18:01	General View	 Load JPG	☒
46	16/12/19 18:01	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/08/19 17:31	TP GIA REPORT	 Load PDF	
2	21/08/19 17:31	NOTIFICATION FROM WORKSHOP	 Load PDF	
3	21/08/19 17:31	ACKNOWLEDGEMENT EMAIL TO III DD 20.08.2019	 Load PDF	
4	21/08/19 17:31	LTA SEARCH	 Load PDF	
5	16/12/19 18:03	REJECTION EMAIL TO TP	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	23/08/19 14:54	Singapore Accident Statement IV SHC3754C	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19014692/R1GA3Q2

Date: 16/03/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant: GBG5872G Insured Vehicle No: SHC3754C
 Vehicle No: GBG5872G
 Date of Loss: 18/08/2019 Nature of Claim: TP Claim No: MCT19080434

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBG5872G
 Make & Model: FIAT DOBLO CARGO MAXI, 1.6 D MTJ AMT GLAZE (M) Engine No: 198A30008146386
 Reg. Date: 12/09/2017 (Man. Year: 2017) Chassis No: ZFA26300006H21689
 Colour: White Odometer: 0 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16
 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
 Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,931.00	15,076.00	1,855.00	10.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,900.00	2,700.00	2,200.00	44.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,831.00	17,776.00	4,055.00	18.57
+ GST 7.00/7.00% (S\$)	1,528.17	1,244.32	283.85	18.57
Nett Amount (S\$)	23,359.17	19,020.32	4,338.85	18.57
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 20/08/2019
 Date Inspected: 20/08/2019 Inspected At: Sin Sheng Engineering Services -
 Tuas (HQ)
 8 Tuas Avenue 18 Level 5
 Singapore 638892
 Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Mar 2020)
Parts:	213	FIAT DOBLO CARGO MAXI 1.6 D MTJ AMT GLAZE (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG5872G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	865.00 F	*865.00 F
2	1		*FRT BUMPER CLIPS	Necessary	58.00 F	*58.00 F
3	2		*FRT BUMPER BRACKET	Necessary	342.00 F	*342.00 F
4	2		*FRT BUMPER SIDE RETAINER	Necessary	256.00 F	*256.00 F
5	1		*FRT BUMPER REINFORCEMENT	*Check	155.00 F	*- F
6	1		*FRT BUMPER SPONGE	*Check	155.00 F	*- F
7	1		*FRT BUMPER LOWER SPOILER	Deformed	229.00 F	*229.00 F
8	1		*FRT LH BUMPER FOG LAMP COVER	Scratched	188.00 F	*188.00 F
9	1		*FRT GRILLE	Deformed	485.00 F	*485.00 F
10	1		*FRT GRILLE EMBLEM	Necessary	142.00 F	*142.00 F
11	1		*FRT LH HEADLAMP ASSY	Cracked	630.00 F	*630.00 F
12	1		*FRT RH HEADLAMP ASSY	*Check	630.00 F	*- F
13	1		*BONNET	Bent	984.00 F	*984.00 F
14	1		*WIPER WASHER TANK	Deformed	180.00 F	*180.00 F
15	1		*WIPER WASHER TANK MOTOR	*Check	120.00 F	*- F
16	1		*ENGINE TOP COVER	Cracked	235.00 F	*235.00 F
17	1		*FRT LH FENDER	Buckled	699.00 F	*699.00 F
18	1		*FRT LH FENDER INNER PANEL	Buckled	672.00 F	*672.00 F
19	1		*FRT LH FENDER INNER SHIELD	Deformed	265.00 F	*265.00 F
20	1		*FRT LH WHEEL RIM	Bent	300.00 F	*300.00 F
21	1		*FRT LH RIM COVER	Cracked	87.00 F	*87.00 F
22	1		*FRT LH TYRE	Punctured	120.00 F	*120.00 F
23	1		*FRT RH FENDER	Buckled	699.00 F	*699.00 F
24	1		*FRT RH FENDER INNER PANEL (NPA)	Repair	0.00 F	*- F
25	1		*STEERING WHEEL AIRBAG	Activated	2,250.00 F	*2,250.00 F
26	1		*STEERING WHEEL AIRBAG SENSOR	Necessary	700.00 F	*700.00 F
27	1		*AIRBAG CONTROL UNIT	Activated	1,500.00 F	*1,500.00 F
28	1		*FRT RH SEAT BELT ASSY	Activated	900.00 F	*900.00 F
29	1		*FRT LH SEAT BELT ASSY	Activated	900.00 F	*900.00 F
30	1		*FRT RH DOOR (NPA)	Repair	0.00 F	*- F
31	1		*FRT LH SHOCK ABSORBER	*Check	495.00 F	*- F
32	1		*FRT LH SHOCK ABSORBER MOUNTING	*Check	300.00 F	*- F
33	1		*FRT LH KNUCKLE ARM	Bent	685.00 F	*685.00 F
34	1		*FRT LH KNUCKLE ARM BEARING	Necessary	250.00 F	*250.00 F
35	1		*FRT LH LOWER ARM	Bent	455.00 F	*455.00 F
Total Parts (S\$)					16,931.00	15,076.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	2,000.00	1,000.00
2	SPRAY	New	2,000.00	1,000.00
3	UNDERCARRIAGE LABOUR	New	250.00	150.00
4	SEAT BELT LABOUR	New	350.00	300.00
5	AIRBAG	New	300.00	250.00
Gross Labour Cost (S\$)			4,900.00	2,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >