

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0986/2019/NS
Date : 20-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR. SENG KOK ANN IVAN
Address : 455B ANG MO KIO ST 44
#18-15
Singapore 562455
Telephone : HP +65 90681101
Type of Claim : Own Damage Claims
Policy No. : 1800152116
Vehicle No : **SKU 8789 P**
Model Code : Audi A3 SB 1.0 TFSI
Model / Year : 28/12/2018
Engine No : CHZ B21941
Chassis No : WAUZZZ8V1KA010998
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Aug-19
Place of Accident : SLIP RD FROM ANG MO KIO AVE 5 TO ANG MO KIO AVE 3

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKU 8789 P

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To dismantle and renew front bumper, bonnet and both headlights. Re-organise rear crash management components. Reinstall all parts removed.	\$ 2,800.00	500
3	To respray front bumper and bonnet.	\$ 2,000.00	1100
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,352.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SKU 8789 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER COVER <i>Regis</i>	\$ 1,698.00	<i>x</i>
2	FRONT BUMPER FIXING PARTS <i>seen</i>	\$ 170.00	<i>+</i>
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>seen</i>	\$ 70.00	<i>+</i>
4	FRONT BUMPER GRILLE - CENTRE <i>seen</i>	\$ 146.00	<i>x</i>
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>seen</i>	\$ 270.00	<i>+</i>
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>seen</i>	\$ 540.00	<i>+</i>
7	FRONT RADIATOR GRILLE <i>checked</i>	\$ 1,301.00	<i>✓</i>
8	RADIATOR GRILLE CLOSING ELEMENT <i>?</i>	\$ 174.00	<i>?</i>
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>seen</i>	\$ 342.00	<i>x</i>
10	FRONT BUMPER IMPACT BAR <i>?</i>	\$ 660.00	<i>?</i>
11	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	\$ 172.00	<i>?</i>
12	FRONT BUMPER IMPACT BAR COVER <i>?</i>	\$ 111.00	<i>?</i>
13	AIR CON STICKER <i>?</i>	NEC \$ 7.00	<i>✓</i>
14	CAUTION SIGN <i>seen</i>	NEC \$ 13.00	<i>✓</i>
15	SIGNAL HORN - LH HIGH TONE <i>?</i>	\$ 182.00	<i>x</i>
16	SIGNAL HORN - RH LOW TONE <i>seen</i>	\$ 182.00	<i>x</i>
17	BONNET <i>Regis</i>	\$ 2,501.00	<i>x</i>
18	BONNET ATTACHMENT PARTS <i>?</i>	\$ 149.00	<i>+</i>
19	BONNET EDGE PROTECTION <i>seen</i>	NEC \$ 25.00	<i>+</i>
20	BONNET STRIKER - LH / RH <i>?</i>	2 \$ 200.00	<i>+</i>
SUB TOTAL SPARE PARTS		: \$ 8,913.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No.SKU 8789 P**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	BONNET CATCH HOOK	\$	81.00 ✓
22	BONNET LID LOCK WITH MICRO-SWITCH	2 \$	367.00 ✓
23	BONNET BOWDEN CABLE - CENTRE	\$	53.00 ✓
24	LID LOCK CABLE	\$	67.00 ✓
25	LED HEADLIGHT - LH / RH	2 \$	10,058.00 ✓
26	HEADLIGHT LIFT CYLINDER - LH / RH	2 \$	256.00 ✓
27	LIFT CYLINDER HOSE	\$	61.00 ✓
28	RADIATOR AIR GUIDE - LH / RH	2 \$	44.00 ✓
29	RADIATOR AIR GUIDE - UPPER CENTRE	\$	11.00 ✓
30	FRONT NO. PLATE	S/N \$	60.00 ✓
31	SUNDRIES	\$	300.00 ?
TOTAL SPARE PARTS		\$ 20,271.00	
TOTAL LABOUR CHARGES		\$ 5,352.00	
GRAND TOTAL		\$ 25,623.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lim*
Surveyed Date : *21/08/19*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 04 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant