

ASS. FEL. BY

REF:

A19 C31A1919014694/Avf3N2

Merimen

ASSIGNMENT

From:

Date:

21/8/19

Veh No:

SKV8789P

Yr Regn:

2018/ Dec

Estimated Cost:

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

SKU 8789P

Make:

Audi A3.

C.C.

999

at Workshop m/s

Premium Automobile

Colour:

Grey.

A/C:

Insured / Std / NI / NA

of

55 Ubi Road 1

Sp. Reading

8957.

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

1800152116

C/No:

WAUZZZ8V1KA010998

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

600

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:

10-30am (waiting)

Modi: Nil / ☒ R / STD A/Rim or

(Policy Condition)

Tyre Size:

F:

205/55R16.

R:

205/55R16.

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

100K.

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

06

mm

R/Bal.

06

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

06

mm

L/Bal.

06

mm

Est. Repairs:

18/4

days

Res.: Yes or No

D.O.A.

15/8/19

D.O.I.

21/08/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

Premium.

CA / ☒ REV / REP. / 24 HRSDes. of Damages: ☒ Fr / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD A16.

SKU 8789P-X

RECEIVED 18 DEC 2019

22/8/19

Revert via merimen

22/8/19

Rere approved \$3533 from victor by merimen

22/8/19

Informed Tony C/A ex \$600 by email

4/11/19

Final fig \$3406.48 (Red 22, 216.52, 8790) confirmed by email

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair:

4

1)

☐

: Final Report

Resurvey No. of Trip:

1

Date/Time, File Return to?

2) 18/12 - typist

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invt (\$

☐

: Wash and (\$

Survey Fee:

Transportation:

3 = PS. \$1

Photo:

Other:

TOTAL

200

11

211

Report Format:

Merimen

Lump Sum / L.B.:

3406.48

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Yap, Weijoe

Date: 22 Aug 2019

Preliminary Advice

Vehicle No	: SKU8789P	Accident Date	: 15/08/2019
Make	: AUDI A3	Policy No.	: 1800152116
Assignment Date	: 21/08/2019	Excess	: S\$0.00
Date of Inspection	: 21/08/2019	Est. Duration of Repair	: 4.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,623.00
Revised Amount	:S\$	3,533.00
Check Items (Estimated)	:S\$	1,417.00
Total	:S\$	4,950.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	100,000.00
COE / PARF Rebate	:S\$	40,523.00
Salvage Value	:S\$	
Margin for Repair	:S\$	59,477.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 22 August 2019 5:54 PM
To: Claims Dept; SUR
Cc: (nora.khai@premiumauto.com.sg)
Subject: RE: OD CLAIM FOR SKU 8789 P ON 15/8/2019

Dear Tony,

As instructed by our client , please proceed to repair the **insured vehicle SKU 8789P (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Thursday, 22 August 2019 3:57 PM
To: Claims Dept <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: OD CLAIM FOR SKU 8789 P ON 15/8/2019

Dear Tony,

Pending approval from AIG.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Thursday, 22 August 2019 3:19 PM
To: SUR <sur@lkkauto.com>

Cc: "Claims Dept" <claims@premiumauto.com.sg>

Subject: RE: OD CLAIM FOR SKU 8789 P ON 15/8/2019

Dear all,

Kindly assist follow up repair approval.

Thank you.

Best Regards,
Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Singapore 408699

p. +65 6366 2323, d. +65 67689911

e.<mailto:claims@premiumauto.com.sg> w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Admin-D (LKKAuto) [<mailto:admin-d@lkkauto.com>]

Sent: Tuesday, 20 August 2019 3:03 PM

To: 'Claims'; Admin A; SUR

Subject: RE: OD CLAIM FOR SKU 8789 P ON 15/8/2019

Dear Syafiq,

Appointment confirmed.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Friday, 16 August 2019 1:58 PM
To: 'Admin A' <admin-a@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>; 'SUR' <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: OD CLAIM FOR SKU 8789 P ON 15/8/2019

Dear All,

Kindly register OD claims for this vehicle. Attached is GIA report for your reference.

We will forward you the estimate once is available.

Please arrange survey on 21/8/2019, 10.30am. owner waiting

Best Regards,
Syafiq
Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

This email has been checked for viruses by AVG antivirus software.
www.avg.com

View Received Message

This mail is associated with :

***SKU8789P (3542683054SG)**

OD

Aug 15 2019 7:00PM

[SENG KOK ANN IVAN]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 22/08/2019 17:03 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$3533.00) - SKU8789P - Claim Handler: Yap, Weijoe

Approved:3533.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Nivitha (LKK Auto)

From: Claims <claims@premiumauto.com.sg>
Sent: Friday, 16 August 2019 1:59 PM
To: 'Admin A'; 'Admin-D (LKKAuto)'; 'SUR'
Cc: 'Claims'
Subject: OD CLAIM FOR SKU 8789 P ON 15/8/2019
Attachments: SKU 8789 P - 15082019.PDF; SAftersales19081613570_0004.jpg;
SAftersales19081613570_0003.jpg

Dear All,

Kindly register OD claims for this vehicle. Attached is GIA report for your reference.

We will forward you the estimate once is available.

Please arrange survey on 21/8/2019, 10.30am. owner waiting

Best Regards,
Syafiq
Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 4 November 2019 3:47 PM
To: 'jiayee.yap@premiumauto.com.sg'; SUR; Admin A; CS A Team
Cc: 'Boo seng yak'; 'Chang Chee Sing'; 'Carrine Leong'
Subject: RE: FINAL REVISION - SKU8789P - OD AIG - SURVEYED 21 AUG 19

Dear Jia Yee,

Confirm repair cost of \$3406.48 before excess \$600 and GST @ 4 days of repair.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jiayee.yap@premiumauto.com.sg <jiayee.yap@premiumauto.com.sg>
Sent: Friday, 1 November 2019 10:33 AM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: 'Boo seng yak' <boojohnny@gmail.com>; 'Chang Chee Sing' <claims@premiumauto.com.sg>; 'Carrine Leong' <carrine.leong@premiumauto.com.sg>
Subject: FINAL REVISION - SKU8789P - OD AIG - SURVEYED 21 AUG 19

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$3406.48 @ 4 days of repair.

Your early closure is well appreciated.

Thanks & Best Regard
JiaYee Yap
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. jiayee.yap@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	998D
Vehicle Details	
Vehicle No.:	5KU8789P
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Aug 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SPORTBACK 1.0 TFSI S TRONIC (LED)
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	CHZB21941
Chassis No.:	WAUZZZ8V1KA010998
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$21,568.00
Original Registration Date:	28 Dec 2018
First Registration Date:	28 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$22,196.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2028
PARF Rebate Amount:	\$16,647.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,501.00
COE Rebate Amount:	\$23,876.00
Total Rebate Amount:	\$40,523.00

The information contained herein is correct as at 16 Aug 2019

OK

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : SENG KOK ANN, IVAN
Period of Insurance : 28 Dec 2018 To 27 Dec 2020
Engine No. : CHZ B21941
Chassis No. : WAUZZZ8V1KA010998

Vehicle No. : SKU8789P
Policy No. : 1800152116
Endorsement No. :
Issued Date : 11 Jan 2019

ABOUT THE COVER

Make/Model : AUDI A3 Sportback 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC **Sum Insured** : Market Value **First Year of Registration** : 2018
Driver Restriction : NA **Off Peak Car** : No **Insuring with COE/PARF** : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

SENG KOK ANN, IVAN - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 93662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125287

PREMIUM LEASING - OYY

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mobile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Shirley Loh

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0986/2019/NS
Date	:	20-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	MR. SENG KOK ANN IVAN
Address	:	455B ANG MO KIO ST 44 #18-15 Singapore 562455
Telephone	:	HP +65 90681101
Type of Claim	:	Own Damage Claims
Policy No.	:	1800152116
Vehicle No	:	SKU 8789 P
Model Code	:	Audi A3 SB 1.0 TFSI
Model / Year	:	28/12/2018
Engine No	:	CHZ B21941
Chassis No	:	WAUZZZ8V1KA010998
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	15-Aug-19
Place of Accident	:	SLIP RD FROM ANG MO KIO AVE 5 TO ANG MO KIO AVE 3

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183



Telefax

Estimated Labour Charges for Accident Vehicle SKU 8789 P

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew front bumper, bonnet and both headlights. Re-organise rear crash management components. Reinstall all parts removed.	\$ 2,800.00 500 ✓	✓
3	To respray front bumper and bonnet.	\$ 2,000.00 1100 ✓	✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ <u>5,352.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SKU 8789 P

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
1	FRONT BUMPER COVER <i>Regis</i>	\$	1,698.00	X.
2	FRONT BUMPER FIXING PARTS <i>piece</i>	\$	170.00	+
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 \$	70.00	+
4	FRONT BUMPER GRILLE - CENTRE <i>new</i>	\$	146.00	X
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$	270.00	+
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2 \$	540.00	+
7	FRONT RADIATOR GRILLE <i>cracked</i>	\$	1,301.00	✓ 1044.50
8	RADIATOR GRILLE CLOSING ELEMENT <i>cracked</i>	\$	174.00	? 1388.00
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2 \$	342.00	+
10	FRONT BUMPER IMPACT BAR <i>Not New</i>	\$	660.00	? X
11	FRONT BUMPER FOAM FILLER PIECE <i>Not New</i>	\$	172.00	? X
12	FRONT BUMPER IMPACT BAR COVER <i>Not New</i>	\$	111.00	? X
13	AIR CON STICKER <i>new</i>	NEC \$	7.00	✓ 5.12
14	CAUTION SIGN <i>new</i>	NEC \$	13.00	✓ 9.76
15	SIGNAL HORN - LH HIGH TONE <i>new</i>	\$	182.00	X
16	SIGNAL HORN - RH LOW TONE <i>new</i>	\$	182.00	+
17	BONNET <i>Regis</i>	\$	2,501.00	+
18	BONNET ATTACHMENT PARTS <i>new</i>	\$	149.00	+
19	BONNET EDGE PROTECTION <i>new</i>	NEC \$	25.00	+
20	BONNET STRIKER - LH / RH <i>new</i>	2 \$	200.00	+
SUB TOTAL SPARE PARTS		:	\$	<u>8,913.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No.SKU 8789 P**

S/N	Parts Description	<u>Damaged Parts & Prices</u>		Remark
		S/Nett		
21	BONNET CATCH HOOK	\$	81.00	✓
22	BONNET LID LOCK WITH MICRO-SWITCH	2 \$	367.00	✓
23	BONNET BOWDEN CABLE - CENTRE	\$	53.00	✓
24	LID LOCK CABLE	\$	67.00	✓
25	LED HEADLIGHT - LH / RH	2 \$	10,058.00	✓
26	HEADLIGHT LIFT CYLINDER - LH / RH	2 \$	256.00	✓
27	LIFT CYLINDER HOSE	\$	61.00	✓
28	RADIATOR AIR GUIDE - LH / RH	2 \$	44.00	✓
29	RADIATOR AIR GUIDE - UPPER CENTRE	\$	11.00	✓
30	FRONT NO. PLATE	S/N \$	60.00	✓
31	SUNDRIES	\$	300.00	✓
TOTAL SPARE PARTS		:	\$ 20,271.00	
TOTAL LABOUR CHARGES			\$ 5,352.00	
GRAND TOTAL			\$ 25,623.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *21/08/19*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 04 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0986/2019/NS
Date	:	20-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian,

4 days - ok - Jy - 01 Nov 2019

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	MR. SENG KOK ANN IVAN
Address	:	455B ANG MO KIO ST 44 #18-15 Singapore 562455
Telephone	:	HP +65 90681101
Type of Claim	:	Own Damage Claims
Policy No.	:	1800152116
Vehicle No	:	SKU 8789 P
Model Code	:	Audi A3 SB 1.0 TFSI
Model / Year	:	28/12/2018
Engine No	:	CHZ B21941
Chassis No	:	WAUZZZ8V1KA010998
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	15-Aug-19
Place of Accident	:	SLIP RD FROM ANG MO KIO AVE 5 TO ANG MO KIO AVE 3

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKU 8789 P

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
2	To dismantle and renew front bumper, bonnet and bothe headlights. Re-organise rear crash management components. Reinstall all parts removed.	\$	2,800.00	\$ 500.00
3	To respray front bumper and bonnet.	\$	2,000.00	\$ 1,100.00
4	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 5,352.00	\$ 2,152.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No.SKU 8789 P**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remark</u>
1	FRONT BUMPER COVER	\$ 1,698.00	
2	FRONT BUMPER FIXING PARTS	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - LH / RH	2 \$ 70.00	
4	FRONT BUMPER GRILLE - CENTRE	\$ 146.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 270.00	
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	2 \$ 540.00	
7	FRONT RADIATOR GRILLE	\$ 1,301.00	\$ 1,040.80
8	RADIATOR GRILLE CLOSING ELEMENT	\$ 174.00	\$ 138.80
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 342.00	
10	FRONT BUMPER IMPACT BAR	\$ 660.00	
11	FRONT BUMPER FOAM FILLER PIECE	\$ 172.00	
12	FRONT BUMPER IMPACT BAR COVER	\$ 111.00	
13	AIR CON STICKER	NEC \$ 7.00	\$ 5.12
14	CAUTION SIGN	NEC \$ 13.00	\$ 9.76
15	SIGNAL HORN - LH HIGH TONE	\$ 182.00	
16	SIGNAL HORN - RH LOW TONE	\$ 182.00	
17	BONNET	\$ 2,501.00	
18	BONNET ATTACHMENT PARTS	\$ 149.00	
19	BONNET EDGE PROTECTION	NEC \$ 25.00	
20	BONNET STRIKER - LH / RH	2 \$ 200.00	
SUB TOTAL SPARE PARTS		\$ 8,913.00	\$ 1,194.48

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No.SKU 8789 P**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
			\$ 1,194.48
21	BONNET CATCH HOOK	\$ 81.00	
22	BONNET LID LOCK WITH MICRO-SWITCH	2 \$ 367.00	
23	BONNET BOWDEN CABLE - CENTRE	\$ 53.00	
24	LID LOCK CABLE	\$ 67.00	
25	LED HEADLIGHT - LH / RH	2 \$ 10,058.00	
26	HEADLIGHT LIFT CYLINDER - LH / RH	2 \$ 256.00	
27	LIFT CYLINDER HOSE	\$ 61.00	
28	RADIATOR AIR GUIDE - LH / RH	2 \$ 44.00	
29	RADIATOR AIR GUIDE - UPPER CENTRE	\$ 11.00	
30	FRONT NO. PLATE	S/N \$ 60.00	\$ 60.00
31	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS		\$ 20,271.00	\$ 1,254.48
TOTAL LABOUR CHARGES		\$ 5,352.00	\$ 2,152.00
GRAND TOTAL		\$ 25,623.00	\$ 3,406.48

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKU 8789 P

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0986/2019/NH

12 Dec 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SKU 8789 P, Audi A3 SB 1.0 TFSI.

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SKU 8789 P**, claimant, **Mr. Seng Kok Ann Ivan**, please find the related document per attached.

1. A copy of the Original invoice no. 85014584 – S\$ 3,002.93
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SKU 8789 P

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6386 2323
Main Telefax 6641 1163

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 16:01

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014584 Date : 09/12/2019 Order : SKU8789F Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SKU8789F (V 39961)	Regn Date: 28/12/2018	Mileage: 10544	WIP No.: 64336
Model: A3 SPORTSBACK 1.0 TFSI BVFANG	Chassis: WAUZZZ8V1KA010998	Engine: CHZ B21941	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	60.00	1.00	60.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNES FOR HEADLIGHT,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND REPAIR BONNET AND FRONT BUMPER.REORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND BONNET	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8V3853651AA3FZ	GRILLE	Less 020%	1.00	1301.00
X	A8K0010520A	PLATE	Less 020%	1.00	12.20
X	A8V0010515A	STICKER	Less 020%	1.00	6.40
X	A8V3853949	PLATE	Less 020%	1.00	173.50

Parts 1,194.48
Labour 0.00
Sublet 2,212.00
Menus 0.00
Lubricant 0.00

Sub-Total 2,806.48

7% GST 196.45

Grand Total 3,002.93



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKU8789P

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/10986/2019/TF
27 September 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

1

total pages

Make & Model : Audi A3 SPORTSBACK 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V1KA010998
Vehicle Regn No. : **SKU8789P**
Vehicle Mileage : 10544 KM
Vehicle Owner : Mr. Seng Kok Ann Ivan
Certificate No : 1800152116
Own Damage Excess : \$642.00 (Inclusive 7% GST)
Accident Date : 15/08/2019
Place : Slip Rd from AMK Ave 5 Twds AMK Ave 3
Repair Cost : \$ 3002.93
WIP No. : 64336
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 1825
Date : 27 09 19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth ed	Status
Main	19 Aug 2019		21 Aug 2019 17:30 Edit Adj Rpt	S\$3,406.48 Edit Estimates	S\$3,406.48 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured:	SENG KOK ANN IVAN, ID: S8710998D, Tel: +6590681101, Email: SENG.IVAN@GMAIL.COM		
Vehicle Reg. No.:	SKU8789P	Date of Loss:	15/08/2019 19:00 - :59 [7 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 3542683054SG	Policy/Cover Note No.:	(Comprehensive)
		Excess:	S\$600.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Yap, Weijoe] Weijoe.Yap@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 30/08/2019]		
Driver/Custodian:	SENG KOK ANN IVAN (32 / Male), NRIC: S8710998D, Tel: +6590681101 Email: SENG.IVAN@GMAIL.COM		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (22/08/2019): Alert - Adj Mandate Approved (S\$3533.00) - SKU8789P - Claim Handler: Yap, Weijoe
- AIG_SG (22/08/2019): SKU8789P / OD / 15/08/2019 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKU8789P (3542683054SG)

OD

Aug 15 2019 7:00PM

[SENG KOK ANN IVAN]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Assessment Reports															1 per page		☒	
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	22/08/19 10:23		Adjuster Immediate Advice											1	Load HTM			
Photos/Images															3 per page		☒	
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	22/08/19 09:24		General View											1	Load JPG	☒		
2	22/08/19 09:24		General View											1	Load JPG	☒		
3	22/08/19 09:24		General View											1	Load JPG	☒		
4	22/08/19 09:24		General View											1	Load JPG	☒		
5	22/08/19 09:24		General View											1	Load JPG	☒		
6	22/08/19 09:24		General View											1	Load JPG	☒		
7	22/08/19 09:24		General View											1	Load JPG	☒		
8	22/08/19 09:24		General View											1	Load JPG	☒		
9	22/08/19 09:24		General View											1	Load JPG	☒		
10	22/08/19 09:24		General View											1	Load JPG	☒		
11	22/08/19 09:24		General View											1	Load JPG	☒		
12	22/08/19 09:24		General View											1	Load JPG	☒		
13	22/08/19 09:24		General View											1	Load JPG	☒		
14	22/08/19 09:24		General View											1	Load JPG	☒		
15	22/08/19 09:24		General View											1	Load JPG	☒		
16	22/08/19 09:24		General View											1	Load JPG	☒		
17	22/08/19 09:24		General View											1	Load JPG	☒		
18	22/08/19 09:24		General View											1	Load JPG	☒		
19	22/08/19 09:24		General View											1	Load JPG	☒		
20	22/08/19 09:24		General View											1	Load JPG	☒		
21	04/11/19 15:10		Reinspection Photo											1	Load JPG	☒		
22	04/11/19 15:10		Reinspection Photo											1	Load JPG	☒		
23	04/11/19 15:10		Reinspection Photo											1	Load JPG	☒		
24	04/11/19 15:10		Reinspection Photo											1	Load JPG	☒		
25	04/11/19 15:10		Reinspection Photo											1	Load JPG	☒		
26	04/11/19 15:10		Reinspection Photo											1	Load JPG	☒		
27	04/11/19 15:10		Reinspection Photo											1	Load JPG	☒		
Documentation															1 per page		☒	
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	22/08/19 09:35		Singapore Accident Statement											1	Load PDF			
2	22/08/19 09:35		Certificate of Insurance											1	Load PDF			
3	22/08/19 09:36		Insured's Driving License											1	Load PDF			
4	22/08/19 09:36		MARK ESTIMATE											1	Load PDF			
5	30/12/19 09:34		WORKSHOP INVOICE											1	Load PDF			
6	30/12/19 09:34		DISCHARGE VOUCHER											1	Load PDF			

Linked Accident Report Documents

View View in Browser ▼

Assessment Reports			1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	04/09/19 02:11	Accident Statement	 Load HTM	☒
Photos/Images			3 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	16/08/19 13:50	Accident Photo	 Load JPG	☒
2	16/08/19 13:50	Accident Photo	 Load JPG	☒
3	16/08/19 13:50	Accident Photo	 Load JPG	☒
4	16/08/19 13:50	Accident Photo	 Load JPG	☒
5	16/08/19 13:50	Accident Photo	 Load JPG	☒
6	16/08/19 13:50	Accident Photo	 Load JPG	☒
7	16/08/19 13:50	Accident Photo	 Load JPG	☒
8	16/08/19 13:50	Accident Photo	 Load JPG	☒
9	16/08/19 13:50	Accident Photo	 Load JPG	☒
10	16/08/19 13:50	Accident Photo	 Load JPG	☒
11	16/08/19 13:50	Accident Photo	 Load JPG	☒
12	16/08/19 13:50	Accident Photo	 Load JPG	☒
13	16/08/19 13:50	Accident Photo	 Load JPG	☒
14	16/08/19 13:50	Accident Photo	 Load JPG	☒
15	16/08/19 13:50	Accident Photo	 Load JPG	☒
16	16/08/19 13:50	Accident Photo	 Load JPG	☒
17	16/08/19 13:50	Accident Photo	 Load JPG	☒
18	16/08/19 13:50	Accident Photo	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	16/08/19 13:52	Sketch Plan	 Load JPG	☒
2	16/08/19 13:52	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☒ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19014694/AVF3N2

Date: 30/12/2019

REFERENCE

Insured/Claimant: SENG KOK ANN IVAN

Policy No:

Date of Loss: 15/08/2019

Nature of Claim:

OD Claim No: 3542683054SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKU8789P

Make & Model: AUDI A3, 999cc TFSI (A)

Engine No: CHZB21941

Reg. Date: 28/12/2018 (Man. Year: 2018)

Chassis No: WAUZZZ8V1KA010998

Colour: Grey

Odometer: 8957 km

Engine Capacity: 999 cc

Market Value/New Car Price: S\$100,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16

Rear Tyre Size:

205/55R16

Front Left Side: Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,271.00	1,254.48	19,016.52	93.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,352.00	2,152.00	3,200.00	59.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,623.00	3,406.48	22,216.52	86.71
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	25,023.00	2,806.48	22,216.52	88.78
+ GST 7.00/7.00% (S\$)	1,751.61	196.45	1,555.16	88.78
Nett Amount (S\$)	26,774.61	3,002.93	23,771.68	88.78

INSPECTION

Date of Assignment: 21/08/2019

Date Inspected:

21/08/2019

Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Repair	1,698.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION-LH/RH	Not Necessary	70.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTRE	Not Necessary	146.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	270.00 FS	*- FS
6	2		*FRONT BUMPER CLOSING ELEMENT-LH/RH	Not Necessary	540.00 FS	*- FS
7	1		*FRONT RADIATOR GRILLE	Cracked	1,301.00 FS	*1,040.80 FS
8	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	174.00 FS	*138.80 FS
9	2		*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	Not Necessary	342.00 FS	*- FS
10	1		*FRONT BUMPER IMPACT BAR	Not Necessary	660.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	172.00 FS	*- FS
12	1		*FRONT BUMPER IMPACT BAR COVER	Not Necessary	111.00 FS	*- FS
13	1		*AIR CON STICKER	Necessary	7.00 FS	*5.12 FS
14	1		*CAUTION SIGN	Necessary	13.00 FS	*9.76 FS
15	1		*SIGNAL HORN-LH HIGH TONE	Not Necessary	182.00 FS	*- FS
16	1		*SIGNAL HORN-RH LOW TONE	Not Necessary	182.00 FS	*- FS
17	1		*BONNET	Repair	2,501.00 FS	*- FS
18	1		*BONNET ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
19	1		*BONNET EDGE PROTECTION	Not Necessary	25.00 FS	*- FS
20	2		*BONNET STRIKER-LH/RH	Not Necessary	200.00 FS	*- FS
21	1		*BONNET CATCH HOOK	Not Necessary	81.00 FS	*- FS
22	2		*BONNET LID LOCK WITH MICRO-SWITCH	Not Necessary	367.00 FS	*- FS
23	1		*BONNET BOWDEN CABLE-CENTRE	Not Necessary	53.00 FS	*- FS
24	1		*LID LOCK CABLE	Not Necessary	67.00 FS	*- FS
25	2		*LED HEADLIGHT-LH/RH	Not Necessary	10,058.00 FS	*- FS
26	2		*HEADLIGHT LIFT CYLINDER-LH/RH	Not Necessary	256.00 FS	*- FS
27	1		*LIFT CYLINDER HOSE	Not Necessary	61.00 FS	*- FS
28	2		*RADIATOR AIR GUIDE-LH/RH	Not Necessary	44.00 FS	*- FS
29	1		*RADIATOR AIR GUIDE-UPPER CENTRE	Not Necessary	11.00 FS	*- FS
30	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
31	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **20,271.00** **1,254.48**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND BOTHE HEADLIGHTS.RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,800.00	500.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,352.00	2,152.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >