

REF: CS/CTI/9014695/Ktd3⁷² Special Instruction:

REC BY: Kenneth
Assigner:

ASSIGNMENT (Office)

From (Person): chong Boon Sen of CTI

Date/Time: 21/8/19 10:58am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLS 52209

Insured: QBD 88754

at Workshop in/s Hui Yung Motor

Tel: 64515752

of Blk 176 Sin Ming Drive # 04-02

Policy No: DMCSN30482419000

Claim No: SNM19D203823

Sum Insured: Excess:

Make of Veh:
(Client's Record)

D.O.A. 15/08/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:19pm 21/8/19 Person Contacted: Zel

Vehicle IN / OUT

Date/Time	Action/Instruction	Initials
	SLS 52209 - NBA/CTI/9014330/PY	
	QBD 88754 - NBA/CTI/9014330/EY	

D.O.A. 15/8/2019

D.O.A. 15/8/2019

27/8 11pm @ 3800 confirmed (Red: 2855.24, 42%)

ASS. REC. BY:

REF:

C121

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / PWS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

09 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLS520G

Yr Regn:

09, 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Honda Shuttle

c.c

1496

Colour:

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

96580

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GP7 1115762

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Falken

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

15/8/19

D.O.I.

22/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

RECEIVED 2 OCT 2019

Date/Time, File Pass to?



: Prell. Report



: Final Report

11/10/19

Date/Time, File Return to?

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + R.S. \$

Fees

Others

TOTAL

220

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

Tp 3800/-

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 21 August 2019 10:58 AM
To: Hui Yang Motor
Cc: assignments
Subject: RE: OUR REF : SNM19D203823-GBD8875U-CBS - FW: TP Claim for SLS5220G against GBD8875U / DOA: 15/08/2019

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle. Please merimen as usual.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Hui Yang Motor [mailto:hui_yang_motor@hotmail.com]

Sent: Tuesday, 20 August, 2019 3:21 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: Re: OUR REF : SNM19D203823-GBD8875U-CBS - FW: TP Claim for SLS5220G against GBD8875U / DOA: 15/08/2019

Importance: High

Dear Sir/Mdm,

I couldn't reach anyone when I tried to call in.

Please, kindly advice when can we arrange vehicle SLS5220G for survey cos vehicle owner keep chasing.

Thank you & Regards,

Bel
Tel: 64515752

From: Hui Yang Motor <hui_yang_motor@hotmail.com>
Sent: Tuesday, August 20, 2019 1:34 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>
Subject: Re: OUR REF : SNM19D203823-GBD8875U-CBS - FW: TP Claim for SLS5220G against GBD8875U / DOA: 15/08/2019

Dear Sir/Mdm,

May I know when can we arrange vehicle SLS5220G for survey?

Thank you & Regards,
Bel
Tel: 64515752

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Monday, August 19, 2019 4:45 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; hui_yang_motor@hotmail.com <hui_yang_motor@hotmail.com>
Subject: OUR REF : SNM19D203823-GBD8875U-CBS - FW: TP Claim for SLS5220G against GBD8875U / DOA: 15/08/2019

Dear Boon Sen,

Please conduct PRS for SLS5220G.

Note : officer in charge – Boon Sen 63896171.

Regards,
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Hui Yang Motor [mailto:hui_yang_motor@hotmail.com]
Sent: Monday, 19 August, 2019 10:04 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: TP Claim for SLS5220G against GBD8875U / DOA: 15/08/2019
Importance: High

Dear Sir/Mdm,

Please refer to attached Estimate and GIA Report.

Kindly let us know when can we arrange our vehicle in for survey.

*Vehicle not in yet.

Thank you & Regards,
Bel
Tel: 6451 5752

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

辉 陽 汽 車 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

15/08/2019

Owner: FAVORIDE PTE LTD

ESTIMATE TO REPAIR HONDA SHUTTLE - SLS5220G

1pc	front LH door
1pc	front LH door firm sticker front
1pc	front LH door firm sticker rear
1pc	front LH door handle
1pc	front LH door handle side cover
1pc	front LH door glass gear & motor
1pc	front LH door glass moulding
1pc	front LH door inner rubber
1pc	front LH inner lock
1pc	front LH side mirror
1pc	front LH side mirror cover
1pc	rear LH door
1pc	rear LH door firm sticker
1pc	rear LH door top hinge
1pc	rear LH door front rubber

less 20%

remove & refit LH 2 door glass
wiring
tuffkote
spray painting
labour charges
Total

By	\$ 1,150.00	✓
Mr	\$ 122.80	—
Mr	\$ 128.50	✓
Mr	\$ 258.50	✓
Mr	\$ 121.50	✓
	\$ 381.20	?
Mr	\$ 181.50	✓
Mr	\$ 195.50	X
	\$ 381.50	* ?
Mr	\$ 681.50	* ?
Mr	\$ 181.20	X
Mr	\$ 1,100.00	✓
Mr	\$ 122.85	✓
	\$ 128.50	X
	\$ 121.50	* ?
	\$ 5,256.55	
	\$ 1,051.31	
	\$ 4,205.24	

\$ 150.00	120
\$ 150.00	200
\$ 150.00	600
\$ 1,000.00	550
\$ 1,000.00	450
\$ 6,655.24	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Vehicle in 22/8
vehicle out 26/8
4 days only

K+

China
LKK
22/08/19

辉 阳 汽 车 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

15/08/2019

Owner: FAVORIDE PTE LTD

Not withain
11 Lp @ 3800h
Punary After Paint
4 days

ESTIMATE TO REPAIR HONDA SHUTTLE - SLS5220G

1pc	front LH door
1pc	front LH door firm sticker front
1pc	front LH door firm sticker rear
1pc	front LH door handle
1pc	front LH door handle side cover
1pc	* front LH door glass gear & motor
1pc	front LH door glass moulding
1pc	front LH door inner rubber
1pc	* front LH inner lock
1pc	* front LH side mirror
1pc	* front LH side mirror cover
1pc	rear LH door
1pc	rear LH door firm sticker
1pc	rear LH door top hinge
1pc	* rear LH door front rubber

By	\$ 1,150.00	✓
Na	\$ 122.80	✓
Na	\$ 128.50	✓
Na	\$ 258.50	X
Na/La	\$ 121.50	X
Dil/Th	\$ 381.20	✓
Bu	\$ 181.50	✓
La	\$ 195.50	X
Na SP	\$ 381.50	X
Na/La	\$ 681.50	X
La	\$ 181.20	X
By	\$ 1,100.00	✓
Na	\$ 122.85	✓
Na	\$ 128.50	X
Na/Dil	\$ 121.50	X
	\$ 5,256.55	
	\$ 1,051.31	
	\$ 4,205.24	

less 20%

remove & refit LH 2 door glass

wiring

tuffkote

spray painting

labour charges


Total

\$ 150.00	1201
\$ 150.00	201
\$ 150.00	601
\$ 1,000.00	5501
\$ 1,000.00	4501
\$ 6,655.24	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19014695/KTD3N2

Date: 03/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30482419000	
Claimant Vehicle No :	SLS5220G	Insured Vehicle No :	GBD8875U	
Date of Loss:	15/08/2019	Nature of Claim:	TP	Claim No: SNM19D203823C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS5220G	Engine No:	LEB6319462
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GP71115762
Reg. Date:	27/09/2017 (Man. Year: 2017)	Odometer:	96580 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,205.24	3,594.28	610.96	14.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	1,200.00	1,250.00	51.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,655.24	4,794.28	1,860.96	27.96
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	6,655.24	3,800.00	2,855.24	42.90
+ GST 7.00/7.00% (S\$)	465.87	266.00	199.87	42.90
Nett Amount (S\$)	7,121.11	4,066.00	3,055.11	42.90

INSPECTION

Date of Assignment:	01/10/2019
Date Inspected:	22/08/2019 Inspected At:

Hui Yang Motor Pte Ltd (HQ)
Blk 176 Sin Ming Drive #04-02, Sin
Ming Autocare
Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Oct 2019)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS5220G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Bent	1,150.00 FL	*1,150.00 FL
2	1		*FRONT LH DOOR FIRM STICKER FRONT	Necessary	122.80 FL	*122.80 FL
3	1		*FRONT LH DOOR FIRM STICKER REAR	Necessary	128.50 FL	*128.50 FL
4	1		*FRONT LH DOOR HANDLE	Serviceable	258.50 FL	*- FL
5	1		*FRONT LH DOOR HANDLE SIDE COVER	Dented	121.50 FL	*121.50 FL
6	1		*FRONT LH DOOR GLASS GEAR & MOTOR	Distorted/Jammed	381.20 FL	*381.20 FL
7	1		*FRONT LH DOOR GLASS MOULDING	Buckled	181.50 FL	*181.50 FL
8	1		*FRONT LH DOOR INNER RUBBER	Serviceable	195.50 FL	*- FL
9	1		*FRONT LH INNER LOCK	Dented	381.50 FL	*381.50 FL
10	1		*FRONT LH SIDE MIRROR	Mtg Cracked	681.50 FL	*681.50 FL
11	1		*FRONT LH SIDE MIRROR COVER	Serviceable	181.20 FL	*- FL
12	1		*REAR LH DOOR	Bent	1,100.00 FL	*1,100.00 FL
13	1		*REAR LH DOOR FIRM STICKER	Necessary	122.85 FL	*122.85 FL
14	1		*REAR LH DOOR TOP HINGE	Repair	128.50 FL	*- FL
15	1		*REAR LH DOOR FRONT RUBBER	Dented/Distorted	121.50 FL	*121.50 FL
					Sub Total (S\$)	5,256.55 4,492.85
					- List Item Discount on L Items 20.00/20.00% (S\$)	1,051.31 898.57
					Total Parts (S\$)	4,205.24 3,594.28

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIT LH 2 DOOR GLASS	New	150.00	120.00
2	WIRING	New	150.00	20.00
3	TUFFKOTE	New	150.00	60.00
4	SPRAY PAINTING	New	1,000.00	550.00
5	LABOUR CHARGES	New	1,000.00	450.00
Gross Labour Cost (\$\$)			2,450.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >