

ASS. REC. BY:

REF: CS / MSN 19014708 / Guf307

Special Instruction:

SUIVAJOK G2

ASSIGNMENT (Office)

From (Person): Pauline Tham of MSIG Date/Time: 21.8.19 9.52a.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJX 1594B Insured: SKZ 61469

at Workshop m/s 6 Speed AutoWerkz Tel: 85332934

of 68 Kaki Bukit Ave 6 #02-05

Policy No: 28270938MCY Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 17.8.19
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 21.8.19 22pm Person Contacted: Sun Sun H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJX 1594B - MA/RC 10/04/2019
	SKZ 61469 - MA/RC 10/04/2019
23/8/19	Informed Pauline pending workshop est by email

ASS. REC. BY:

GR.

REF: MS19

ASSIGNMENT

From:

Date: 22.8.2019

Estimated Cost:

OD (TP / WS / TP RES / OD RES / EVA / INV / MV)

To Inspect Vehicle No:

SJX 15948

at Workshop m/s

L Spod Automotex

of 66 kaki Bukit Ave L #02-05

Insured:

Policy No.

Class No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Contact: 8532934 Sun Sun

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$20k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJX 15948

Yr Regn:

20 May 2010

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

2.4

Make:

Hyundai i45

C.C.

2359

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp Reading:

250601

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMH EC41CM BA 135/96

Gen. Cond:

Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

215/55 R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Tut

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

22-08-19

Survey held at

w/s

1pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/8

Estimate given later

02/9

repair limit \$6000
initial \$5300 (LS) with Anson (Ref 9632.64 6490)

RECEIVED 03 SEP 2019

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

3/9- typist

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Work exp (\$)

Survey Fee:

200

Transportation:

S + RS 34

Photos

Others

11

TOTAL

211

Report Format:

Merimen

Lump Sum / T.B.J.:

5300k

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Aug 2019 14:51		21 Aug 2019 09:52 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	ATS LANDSCAPING & CONSTRUCTION PTE LTD, Co. Reg. No.: 198103776G		
Main Claimant:	BENEFIT AUTO, Co. Reg. No.: 53121670E		
Vehicle Reg. No.:	SJX1594B	Date of Loss:	17/08/2019 00:00 - :59 [110 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	28870938MCY (Comprehensive) Coverage: 26/01/2019 - 27/01/2020
Vehicle Reg. No. (Insured):	SKZ6146G	Policy No. (Claimant):	
		Excess:	
Repairer:	6 Speed Autowerkz Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6, #02-05 ARK@KB, 417896 Kaki Bukit - Tel: 85332934		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/08/2019]		
Adj Asg. Remarks:	on WP, Liab: Dispute(NR). Disagree on SJE. Assign: LKK Auto Consultants Pte Ltd, Contact: Sun Sun @ 8533 2934.		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS		View All	Search Tasks
Due Date	Priority	Type	Task Group
Subject	Handler	Assigned By	Completed On
Created On	Done?		
No results.			

View Sent Message

This mail is associated with :

***SJX1594B (603572)**
[SKZ6146G]

TP

BENEFIT AUTO

Aug 17 2019 8:00PM

[ATS LANDSCAPING & CONSTRUCTION PTE LTD]
6 Speed Autowerkz Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **23/08/2019 10:18 AM**.
To SGSGPAUT
Subject TP SURVEY SJX 1594B

Dear Pauline,

Please be informed that we inspected the vehicle SJX 1594B on 22/8/2019.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	670E
Vehicle Details	
Vehicle No.:	SJX1594B
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Aug 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	I45 2.4 AT ABS AIRBAG 2WD 4DR GAS/D
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	G4KEAA406602
Chassis No.:	KMHEC41CMBA135196
Maximum Power Output:	131.0 kW (175 bhp)
Open Market Value:	\$21,738.00
Original Registration Date:	20 May 2010
First Registration Date:	20 May 2010
Transfer Count:	1
Actual ARF Paid:	\$21,738.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 May 2020
PARF Rebate Amount:	\$10,869.00
Intended COE Rebate Details	
COE Expiry Date:	19 May 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$40,001.00
COE Rebate Amount:	\$2,959.00
Total Rebate Amount:	\$13,828.00

The information contained herein is correct as at 22 Aug 2019

OK

▶ Hyundai i45 Used Vehicle List (1 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Hyundai i45 2.4A Sunroof	\$21,800	\$10,140 /yr	08-Sep-2010	2,359 cc	141,500 km	Tan Wei Auto Pte Ltd	Availal

Well Maintained Unit, With Service Records Available. Quiet Undercarriage With A Very Healthy, Bulletproof Engine. Comes With Aftermarket DVD Player, Original Player Is Available. Good Fuel Efficient ...

Office No. - 64575535

Bobby Tan - 86855535 | Joel Ong - 88219191

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

$$\frac{10000}{12} \approx 833$$

$$833 \times 9 = 7499$$

$$10869 + 7499 = 18K.$$

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5110923222-000003

Cover : drive CLASSIC

- | | |
|---|--------------------|
| 1. Index mark and Registration Number of Vehicle | : SJX1594B |
| Chassis Number | : KMHEC41CMB135196 |
| 2. Name of Policyholder | : BENEFIT AUTO |
| 3. Effective Date of Insurance | : 14 Jul 2019 |
| 4. Expiry Date of Insurance | : 13 Jul 2020 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use# | |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business. | |

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (c) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$2,000
EXCESS (SECTION 2)	: S\$1,500
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: N/A
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: MAYBANK SINGAPORE LIMITED
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : BENEFIT AUTO INSURANCE AGENCY (00000573333)

Date of Issue : 04 Jul 2019 14:43 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

 Authorised Officer



 Chief Executive

REPUBLIC OF SINGAPORE
DRIVING LICENCE

Portrait of Wong Soon Fatt

License Number: **S1803109D**
Name: **WONG SOON FATT**

Birth Date: **30 Apr 1967**
Issue Date: **16 Feb 2004**

Barcode: 001122446H

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S1803109D**

Portrait of Wong Soon Fatt

WONG SOON FATT

Race: **CHINESE**
Date of Birth: **30-04-1967**
Country of Birth: **SINGAPORE**

Sex: **M**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	Valid Date
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	27 Mar 1997

License No: **S1803109D**

0142254

Barcode

NRIC No: **S1803109D**

Fingerprint

Blood Group: **O+** Date of Issue: **25-10-1991**

Address: **APT BLK 62 LORONG 4 TOA PAYOH #03-105 SINGAPORE 310062**

NRIC No: **S1803109D** Date: **10/05/2010** No: **6452083**

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GfA Records Management Centre established by the General Insurance Association of Singapore (GfA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/08/2019 11:57
Date Of Accident	17/08/2019 20:35
Exact Location Of Accident	CLEMENTI RD TWDS MAJU CAMP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJX1594B
Insured/Policyholder	
Name Of Registered Owner	BENEFIT AUTO
Co Reg No	53121670E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-99999999
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	145
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5110923222
Cover Note Number	
Driver	
Name of Driver	WONG SOON FATT
NRIC No	S1803109D
Date Of Birth	30/04/1967
Occupation	OUTDOOR
Date Of Driving Pass	27/03/1997
Driving Experience	22 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98784647
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 62 LORONG 4 TOA PAYOH #03-105
Postcode	310062
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TOA PAYOH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING , POSTCODE: 319194 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2519999 - FAX NO: 63548749
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE POLICE REPORT: T/20190818/2042

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ6146G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG NAM THAT
NRIC/Passport Number	S1163289J
Contact Number	96277838
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHF724T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver KWOK CHONG YUN

NRIC/Passport Number S0005272H

Contact Number 91386727

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name WONG SOON FATT

Approximate Age

Injuries Sustain NECK & BACK

Injured person in which vehicle? SJX1594B

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Accident Sketch Plan



John Smith

But, $\frac{1}{2} \times 100 = 50$ days (50%)

1294 1295 1296 1297 1298

[11-12]

$$I = 5.24 \text{ mV/dec}$$

© 1997 by John Wiley & Sons, Inc.

from 20/6/73



Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/08/2019 12:00	Vide Report No.:	Station Diary No.: 58
--	------------------	--------------------------

Informant's Particulars

Name of Informant: WONG SOON FATT			Address: APT BLK 62 LORONG 4 TOA PAYOH #03-105 SINGAPORE 310062		
ID Type / ID No.: NRIC NO / S1803109D			Contact No.: Home/Office: Mobile: 98784647		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 52	Date of Birth: 30/04/1967	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: PRIVATE-HIRER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 17/08/2019 20:35	Type of Location: Straight Road
Location: Along Road 1 CLEMENTI ROAD Along Clementi Road towards Maju Camp. Lamp Post Number: 145				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: BETWEEN MOVING VEHICLE - CHAIN COLLISION			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHF724T	Car					2
SJX1594B	Car				Seriously Damaged	0
SKZ6146G	Car					0



SINGAPORE POLICE FORCE



T/20190818/2042

2 of 4

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

Report No. T/20190818/2042

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	KWOK CHONG YUN	ID No.	S0005272H
Related Vehicle	SHF724T (Car)	Contact No.	91386727
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	WONG SOON FATT	ID No.	S1803109D
Related Vehicle	SJX1594B (Car)	Contact No.	98784647
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	17/08/2019	Date Discharge	18/08/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	NG NAM THAT	ID No.	S1163289J
Related Vehicle	SKZ6146G (Car)	Contact No.	96277838
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 17 August 2019 at about 2036hrs, I was driving my Hyundai vehicle bearing reg no SJX1594B along Clementi Road towards Maju Camp. As I was approaching to a controlled traffic light, I slowed down my vehicle as the traffic light was red.

I managed to stop my vehicle behind a Transcab Renault taxi bearing reg no SHF724T. Straight after I stopped my vehicle, I felt a huge impact from the rear. Due to the huge impact, my vehicle collided onto the front taxi vehicle which resulted into a chain collision between 3 vehicles. I then came out of my vehicle and discovered that a Toyota vehicle bearing reg no SKZ6146G had collided onto my vehicle.



**SINGAPORE
POLICE FORCE**



T/20190818/2042

3 of 4

Report No. T/20190818/2042

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

CONTINUATION OF REPORT

We managed to exchanged our particulars and the accident was near to lamp post 145. As my vehicle was no longer in functional condition, I called a tow truck vehicle over. The damages on my vehicle was serious dents at the rear bumper and slight dent at the front bumper.

Due to the accident, I felt pain of my neck area and I went to consult a doctor at Tan Tock Seng Hospital. I was also given 05 days of MC from 17 August 2019 to 21 August 2019. I wish to state that I do not have any in-build camera installed inside my vehicle.



**SINGAPORE
POLICE FORCE**



T/20190818/2042

4 of 4

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

CONTINUATION OF REPORT

Report No. T/20190818/2042

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

E /

Sgt 1 DARREN TAN YUANJIE

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

SI ANG YI TING, STEPHANIE

Contact No.: 65476414

Signature Of Informant:

Date/Time:

18/08/2019 12:00

Classification Of Case:

SN 168

Authentication Stamp

NP168



SINGAPORE
POLICE FORCE

SIGNATURE



Speed Autowerkz Pte Ltd

Location: 68 Kaki Bukit Ave 6 #02-05 ARK @ Kaki Bukit Singapore 417896

Tel: 6384 7037 Fax: 6384 7039

UEN No.: 201727121K

Estimate

22/8

Vehicle: SJX 1594B

Make & Model: Hyundai i45

No	Particular	Qty	Amount
	<u>List Price</u>		
1	Front bumper / <i>de</i>	1	538.60
2	Front bumper fog lamp LH X	1	212.60
3	Front bumper lower moulding X	1	122.10
4	Front bumper inner sponge X	1	136.20
5	Front bumper reinforcement X	1	504.10
6	Front bumper side retainer @\$29.20 X	2	58.40
7	Front bumper undercover X	1	89.60
8	Front grille assy / <i>cut</i>	1	341.60
9	Front headlamp assy @\$ 797.90 X	2	1595.80
10	Front headlamp lower bracket @\$68.50 X	2	137.00
11	Front headlamp side garnish @\$48.60 X	2	97.20
12	Rear bumper / <i>Pis</i>	1	776.10
13	Rear bumper retainer @\$66.70 / <i>de</i>	2	133.40
14	Rear bumper foam / <i>CRA</i>	1	166.60
15	Rear bumper reflector @\$110.00 / <i>CRA</i>	2	220.00
16	Rear bumper reinforcement / <i>CRA</i>	1	283.40
17	Taillamp @\$360.00 / <i>CRA</i>	2	720.00
18	Taillamp lower bracket @\$64.20 / <i>BT</i>	2	128.40
19	Taillamp panel @\$ 265.40 X	2	520.80
20	Rear fender @\$ 990.00 X	2	1980.00
21	Rear fender air vent @\$65.10 X	2	130.20
22	Rear fender inner trim @\$ 285.60 X	2	571.20
23	Rear fender outer shield @\$ 77.60 X	2	155.20
24	Rear windscreen inner seal X	1	197.10
25	Rear quarter glass moulding & glass X	1	220.60
26	Bootlid emblem (logo) / <i>miss mlt.</i>	1	72.00
27	Bootlid emblem (Hyundai) / <i>miss mlt.</i>	1	68.00
28	Bootlid emblem (I45) X	1	70.00
29	Rear end panel / <i>blue</i>	1	520.10
30	Rear end panel garnish / <i>de</i>	1	316.00
31	Rear floor panel X	1	780.00
32	Rear weatherstrip / <i>twi</i>	1	80.00
33	Rear fender inner matt @\$48 X	2	96.00
34	Rear boot / <i>BT</i>	1	633.00
35	Rear chrome moulding X	1	148.00
36	Rear boot switch X	1	38.00
37	License lamp ganish X	1	48.00
38	Rear boot lock catch X	1	142.00

~~Boot lid lamp~~ @ 347 < *CH XNN* 2 694
 (SN) fit Bumper clips = *3mc* 40 30
 (SN) Rear bumper clips = *3mc* 40 30
 (SN) Reverse Sensor / *DM* 250 200

39	Rear boot lock	1	48.00
40	Rear boot hinge @\$ 58	2	116.00
41	Spare tyre top panel cover	1	98.00
	Less 20%		-2661.86
	Sub-Total cost for parts		10647.44
	Labour Description		
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning		50.00
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs		100.00
3	To remove and refit rear bumper sensor		150.00
4	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools		1500.00
5	To spray painting on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available		1500.00
6	To apply undercoating on the repaired and replaced panels for rust protection		100.00
			3400.00
	Grand Total		14047.44

14,932.64

30

60

40

1000 900

1400

80.

2680
2510

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

6685.28

20% = 5300

7 Days.

4894.1

20% = 3915.28

...CLAIM SUBFOLDER...(Pending for Survey Report)












































CLAIM SUBFOLDER TRACKING




















































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Aug 2019 14:51		21 Aug 2019 09:52 Edit Adj Rpt	S\$5,300.00 Edit Estimates	S\$5,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ATS LANDSCAPING & CONSTRUCTION PTE LTD. Co. Reg. No.: 198103776G								
Main Claimant:	BENEFIT AUTO, Co. Reg. No.: 53121670E								
Vehicle Reg. No.:	SJX1594B	Date of Loss:	17/08/2019 20:00 - :59 [110 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 603572	Policy/Cover Note No.:	28870938MCY (Comprehensive) Coverage: 28/01/2019 - 27/01/2020						
Vehicle Reg. No. (Insured):	SKZ6146G	Policy No. (Claimant):							
		Excess:							
Repairer:	6 Speed Autowerkz Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6, #02-05 ARK@KB, 417896 Kaki Bukit - Tel: 85332934								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 22/08/2019]								
Adj Asg. Remarks:	on WP. Liab: Dispute(NR). Disagree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Sun Sun @ 8533 2934.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJX1594B (603572)
 [SKZ6146G]
 TP
 BENEFIT AUTO
 Aug 17 2019 8:00PM
 [ATS LANDSCAPING & CONSTRUCTION PTE LTD]
 6 Speed Autowerkz Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
2	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
3	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
4	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
5	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
6	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
7	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
8	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
9	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
10	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
11	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
12	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
13	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
14	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
15	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
16	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
17	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
18	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
19	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
20	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
21	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
22	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
23	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
24	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
25	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
26	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
27	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
28	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
29	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
30	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
31	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
32	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
33	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
34	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
35	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
36	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
37	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
38	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
39	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
40	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
41	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
42	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	
43	02/09/19 17:14	General View					Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
45	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
46	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
47	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
48	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
49	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
50	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
51	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
52	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
53	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
54	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
55	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
56	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
57	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
58	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
59	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
60	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
61	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
62	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
63	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
64	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
65	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
66	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
67	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
68	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
69	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
70	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
71	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
72	02/09/19 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
73	02/09/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
74	02/09/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
75	02/09/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
76	02/09/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
77	02/09/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
78	02/09/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
79	02/09/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
80	02/09/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
81	02/09/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
82	02/09/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
83	02/09/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
84	02/09/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
85	02/09/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
86	02/09/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
87	02/09/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
88	02/09/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
89	02/09/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
90	02/09/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
91	02/09/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
92	02/09/19 17:15	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
93	02/09/19 17:15	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
94	02/09/19 17:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
95	02/09/19 17:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
96	02/09/19 17:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
97	02/09/19 17:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
98	02/09/19 17:15	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
99	02/09/19 17:15	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
101	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
102	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
103	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
104	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
105	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
106	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
107	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
108	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
109	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
110	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
111	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
112	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
113	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
114	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
115	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
116	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
117	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
118	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
119	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
120	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
121	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
122	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
123	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
124	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
125	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
126	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
127	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
128	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
129	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
130	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
131	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
132	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
133	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
134	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
135	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
136	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
137	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
138	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
139	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
140	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
141	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
142	02/09/19 17:15	Dismantled Parts		<input checked="" type="checkbox"/>
143	02/09/19 17:23	After Repair Photo		<input checked="" type="checkbox"/>
144	02/09/19 17:23	After Repair Photo		<input checked="" type="checkbox"/>
145	02/09/19 17:23	After Repair Photo		<input checked="" type="checkbox"/>
146	02/09/19 17:23	After Repair Photo		<input checked="" type="checkbox"/>
147	02/09/19 17:23	After Repair Photo		<input checked="" type="checkbox"/>
148	02/09/19 17:23	After Repair Photo		<input checked="" type="checkbox"/>
149	02/09/19 17:23	After Repair Photo		<input checked="" type="checkbox"/>
150	02/09/19 17:23	After Repair Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/08/19 14:52	PRI from Catherine Lim LLC		<input checked="" type="checkbox"/>
2	20/08/19 15:55	Disagree on SJE		<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014708/GVF3E2

Date: 16/09/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28870938MCY

Claimant Vehicle No: SJX1594B

Insured Vehicle No: SKZ6146G

Date of Loss: 17/08/2019

Nature of Claim: TP

Claim No: 603572

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJX1594B

Make & Model: HYUNDAI I45, 2.4 ABS AIRBAG 2WD 4DR
GAS/D (A)

Engine No: G4KEAA406602

Reg. Date: 20/05/2010 (Man. Year: 2010)

Chassis No: KMHEC41CMBA135196

Colour: Grey

Odometer: 250601 km

Engine Capacity: 2359 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size:

215/55 R17

Front Left Side: Michelin 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,532.64	4,175.28	7,357.36	63.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	2,510.00	890.00	26.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,932.64	6,685.28	8,247.36	55.23
Approved Total (Overridden) (S\$)		5,300.00		
Nett Amount (S\$)	14,932.64	5,300.00	9,632.64	64.51

INSPECTION

Date of Assignment: 21/08/2019

Date Inspected: 22/08/2019 Inspected At:

6 Speed Autowerkz Pte Ltd (HQ)
68 KAKI BUKIT AVENUE 6, #02-05
ARK@KB
Singapore 417896

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Sep 2019)
Parts: 143	HYUNDAI I45 2.4 ABS AIRBAG 2WD 4DR GAS/D (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX1594B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	538.60 FL	*538.60 FL
2	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	212.60 FL	*- FL
3	1		*FRONT BUMPER LOWER MOULDING	Not Necessary	122.10 FL	*- FL
4	1		*FRONT BUMPER INNER SPONGE	Not Necessary	136.20 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	504.10 FL	*- FL
6	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	58.40 FL	*- FL
7	1		*FRONT BUMPER UNDERCOVER	Not Necessary	89.60 FL	*- FL
8	1		*FRONT GRILLE ASSY	Cut	341.60 FL	*341.60 FL
9	2		*FRONT HEADLAMP ASSY	Not Necessary	1,595.80 FL	*- FL
10	2		*FRONT HEADLAMP LOWER BRACKET	Not Necessary	137.00 FL	*- FL
11	2		*FRONT HEADLAMP SIDE GARNISH	Not Necessary	97.20 FL	*- FL
12	1		*REAR BUMPER	Distorted	776.10 FL	*568.00 FL
13	2		*REAR BUMPER RETAINER	Deformed	133.40 FL	*85.20 FL
14	1		*REAR BUMPER FOAM	Cracked	166.60 FL	*166.60 FL
15	2		*REAR BUMPER REFLECTOR	Cracked	220.00 FL	*171.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Cracked	283.40 FL	*283.40 FL
17	2		*TAILLAMP	Cracked	720.00 FL	*720.00 FL
18	2		*TAILLAMP LOWER BRACKET	Bent	128.40 FL	*99.60 FL
19	2		*TAILLAMP PANEL	Repair	520.80 FL	*- FL
20	2		*REAR FENDER	Repair	1,980.00 FL	*- FL
21	2		*REAR FENDER AIR VENT	Not Necessary	130.20 FL	*- FL
22	2		*REAR FENDER INNER TRIM	Not Necessary	571.20 FL	*- FL
23	2		*REAR FENDER OUTER SHIELD	Not Necessary	155.20 FL	*- FL
24	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	197.10 FL	*- FL
25	1		*REAR QUARTER GLASS MOULDING & GLASS	Not Necessary	220.60 FL	*- FL
26	1		*BOOTLID EMBLEM (LOGO)	Necessary	72.00 FL	*28.50 FL
27	1		*BOOTLID EMBLEM (HYUNDAI)	Necessary	68.00 FL	*32.50 FL
28	1		*BOOTLID EMBLEM (I45)	Not Necessary	70.00 FL	*- FL
29	1		*REAR END PANEL	Buckled	520.10 FL	*410.60 FL
30	1		*REAR END PANEL GARNISH	Deformed	316.00 FL	*82.50 FL
31	1		*REAR FLOOR PANEL	Repair	780.00 FL	*- FL
32	1		*REAR WEATHERSTRIP	Twisted	80.00 FL	*80.00 FL
33	2		*REAR FENDER INNER MATT	Not Necessary	96.00 FL	*- FL
34	1		*REAR BOOT	Bent	633.00 FL	*633.00 FL
35	1		*REAR CHROME MOULDING	Not Necessary	148.00 FL	*- FL
36	1		*REAR BOOT SWITCH	Not Necessary	38.00 FL	*- FL
37	1		*LICENSE LAMP GARNISH	Not Necessary	48.00 FL	*- FL
38	1		*REAR BOOT LOCK CATCH	Bent	142.00 FL	*142.00 FL
39	1		*BOOT LID LAMP	N/S Not Necessary / O/S Cut	694.00 FL	*347.00 FL
40	1		*REAR BOOT LOCK	Bent	48.00 FL	*48.00 FL
41	2		*REAR BOOT HINGE	Bent	116.00 FL	*116.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*SPARE TYRE TOP PANEL COVER	Not Necessary	98.00 FL	*- FL
43	1		*FRT BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS
44	1		*REAR BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS
45	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **14,333.30** **5,154.10**

- List Item Discount on L Items 20.00/20.00% (S\$) **2,800.66** **978.82**

Total Parts (S\$) **11,532.64** **4,175.28**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING	New	50.00	30.00
2	TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIRS	New	100.00	60.00
3	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	150.00	40.00
4	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,500.00	900.00
5	TO SPRAY PAINTING ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	1,500.00	1,400.00
6	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	100.00	80.00
Gross Labour Cost (S\$)			3,400.00	2,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >