

SLK 76704

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

22 AUG 2019

ESTIMATE

Estimate No. : b1 52434	Page No. : 1 of 5
Date Estimated : 22/08/2019	
Prepared By : Han Kwan Yong	

- ESTIMATE REPAIR FOR - Sim Peng Shin 76 Bayshore Road #06-20 Singapore 469990	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK7670U	V725446	26/01/2017	116d	0

DESCRIPTION	VALUE
To replace front & rear bumper & attachments including to knock out boot lid, tail panel and dented area caused by the accident	3400 3260 4,280.00
To respray front bumper, rear bumper, boot lid and tail panel	3333 3,704.00
To check electrical wiring system at the front and rear sections for proper function including adjustment of headlights.	250 295.00
To supply front and rear emboss number plate. b1 ✓	165.00
Sundries.	80? 150.00
Total Labour 1:	8,564.00

DESCRIPTION	QTY	PRIC	VALUE
EXPANDING RIVET ? x an	10	0.50	5.00
# FRT BUMPER TOP MOUNT ? x an	1	378.10	378.10
MOUNTING SUPPORT ? x su	1	10.90	10.90
# SUPPORT CENTER ? x su	1	11.35	11.35
LH CLOSED GRID (BASIS) ? x su	1	92.70	92.70
# RH CLOSED GRID (BASIS) ? x su	1	92.70	92.70
# IMPACT ABSORNER TOP ? x an	1	44.35	44.35
# GRILLE MIDDLE BOTTOM ? x su	1	128.15	128.15
# FRONT BUMPER TOWING COVER PR ? x su	1	38.95	38.95
# FRT BUMPER PANEL PRIMED de	1	829.65	829.65
REAR BUMPER CARRIER ? x su	1	416.45	416.45
REAR BUMPER CENTRE GUIDE (M) ? x su	1	67.05	67.05
# REAR BUMPER TOWING EYE COVER ? x su	1	38.95	38.95
# REAR BUMPER LH MOUNT ? x su	1	142.55	142.55
REAR BUMPER RH MOUNT ? x su	1	142.55	142.55
# REAR BUMPER PRIMED (RFC) de	1	1,015.00	1,015.00
REAR PDC HOLDER SET ne	1	24.60	24.60
LH GRILLE (BASIS) ? x su	1	91.10	91.10

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 52434
Date Estimated : 22/08/2019
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK7670U	V725446	26/01/2017	116d	0

DESCRIPTION

RH GRILLE (BASIS) ? xon x
EMBLEM GROMMET x x x
FRT BUMPER LOWER MOUNT x x x
AIR DUCT RADIATOR ? cm
AIR DUCT MIDDLE LOWER SECTION ? x x x
PLAQUE 82MM x x x
LH REFLECTOR ? x x x
RH REFLECTOR ? x x x
NUMBER-PLATE LIGHT LED ? x x x
PDC sensor x x x
DECOUPLING RING PDC TORQUE CONVERTE x x x
(DG/SL) ADHESIVE SET K6 x x x

QTY	PRIC	VALUE
1	91.10	91.10
4	0.80	3.20
1	133.80	133.80
1	61.50	61.50
1	55.95	55.95
2	71.25	142.50
1	36.80	36.80
1	36.80	36.80
2	26.75	53.50
2	368.80	737.60
2	5.05	10.10
1	53.05	53.05

Total Parts : 4,986.00

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time 05/09/19 @ 1610	Excess \$ _____
Surveyor's Name <u>Rafael</u>	Sign _____
Surveyor's Tel <u>900 10068</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>8 days</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts at driving room only

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Labour 1	:	8,564.00
Parts	:	4,986.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	948.50
Grand Total	:	14,498.50

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 52434**
Date Estimated : **22/08/2019**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -
Sim Peng Shin
76 Bayshore Road
#06-20

Singapore 469990

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK7670U	WBA1V72090V725446	26/01/2017	116d	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments, front LH/RH inserts, air duct radiator, rear bumper and attachments including make good the bootlid, tail end panel and knock out dented area caused by the accident.	3,400.00		3,400.00 ✓
To respray front bumper, rear bumper, bootlid and tail end panel.	3,333.00		3,333.00 ✓
To check electrical wiring system at the front and rear sections for proper function.	250.00		250.00 ✓
To supply front and rear emboss number plate.	165.00		165.00 ✓
Sundries.	80.00		80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLAMP	3.35	10.00		33.50 (S)
FRT BUMPER TOP MOUNT	378.10	1.00		378.10 ✓
IMPACT ABSORNER TOP	44.35	1.00		44.35 ✓
# FRT BUMPER LH INSERT	60.15	1.00		60.15 (S)
# FRT BUMPER RH INSERT	60.15	1.00		60.15 (S)
FRT BUMPER PANEL PRIMED	829.65	1.00		829.65 ✓
# SET PDC HOLDER FRONT	25.60	1.00		25.60 (S)
REAR BUMPER PRIMED (RFC)	1,015.00	1.00		1,015.00 ✓
REAR PDC HOLDER SET	25.60	1.00		25.60 ✓
# LICENCE PLATE BASE ECE	69.25	1.00		69.25 (S)
AIR DUCT RADIATOR	105.35	1.00		105.35 ✓
PLAQUE 82MM	71.25	1.00		71.25 ✓
DECOUPLING RING PDC TORQUE CONVERTE	5.05	2.00		10.10 ✓
(DG/SL) ADHESIVE SET K6	53.05	2.00		106.10 ✓

SUPPLEMENTARY ITEMS

Total Labour :	7,228.00
Total Parts :	2,834.15
Total Labour & Parts :	10,062.15
Deduction for Excess :	0.00
Total Repair Costs less Excess:	10,062.15
GST @7%:	704.35
Grand Total :	10,766.50

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 52434**
Date Estimated : **22/08/2019**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -

Sim Peng Shin
76 Bayshore Road
#06-20

Singapore 469990

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK7670U	WBA1V72090V725446	26/01/2017	116d	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLAMP <i>re</i>	3.35	10.00		33.50
# FRT BUMPER LH INSERT <i>ca</i>	60.15	1.00		60.15
# FRT BUMPER RH INSERT <i>ca</i>	60.15	1.00		60.15
# SET PDC HOLDER FRONT <i>re</i>	25.60	1.00		25.60
# LICENCE PLATE BASE ECE <i>de</i>	69.25	1.00		69.25

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	248.65
Total Labour & Parts :	248.65