**FASTECH AUTO PTE LTD** BLK1 KAKI BUKIT AVE 6 #01-46,48,50 AUTOBAY SINGAPORE 417883

## **VEHICLE NO:SJV 7392M**

QTY	PARTICULAR	
1 PCS	REAR BUMPER	1065.20
1 PCS	REAR BUMPER REFLECTORS O	/S
1 PCS	REAR BUMPER REINFORCEMEN	TI
1 SET	REAR BUMPER CLIPS	
1 PCS	REAR BUMPER SIDE RETAINER	O/S
1 PCS	REAR BUMPER SPLASH SHIELD O/S	
1 PCS	TAILLAMP ASSY O/S	981.10
1 PCS	REAR END PANEL	
1 PCS	REAR END PANEL TOP GARNIS	Н
1 PCS	REAR AIR VENT	
1 PCS	REAR FENDER O/S	966.21
1 PCS	REAR FENDER INNER TRIM O/S	
1 PCS	REAR WHEEL HUB BEARING O/	s 450.00
1 PCS	REAR KNUCKLE ARM O/S	
1 PCS	REAR LOWER ARM O/S	
1 PCS	REAR WHEEL HOUSING PANEL	O/S
1 SET	REAR WINDSCREEN MOULDING	3
1 PCS	REAR WINDSCREEN SEALANT	
1 PCS	REAR SPORT RIM O/S	

LABOUR CHARGES TO CHECK WIRING TO DISMANTLE & REFIX REVERSE SENSOR TO DISMANTLE & REFIX REVERSE SENSOR TO DISMANTLE & REFIX FUEL TANK TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY TO DISMANTLE & REPLACING REAR UNDERCARRIAGE TO CONDUCT WHEEL ALIGNMENT TO SPRAY RUST PROOFING LABOUR FOR PANEL BEATING & REPLACING PARTS

\$80.00 20 \$80.00 \$150.00 🗶 \$100.00 \$120.00 \$280.00 /20 \$100.00 60 \$120.00 \$1,500.00 800 \$1,500.00 \$13,935.90 TOTAL

LKK Auto Consultants hence notify the Repairer of the following:

- > To resulter before after spray painting
- To display damaged part(s) during resurvey
- Parts price: are subject to confirmation
- Third is advisarively is on a "Without Prejudice" basis
- No i<sup>n</sup> igo, modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

TO PUTTY & SPRAY PAINTING

Not Allows 248/19 4/5 = 4250

\$65.30 \$433.20 -\$50.00 \$66.50 X 170,0 \$129.10 -SUM C/9\$1,049.50\_ **1** \$366.20 **○** 1/1 \$315.00 YN1 \$89.20 \$1,205.10 \$322.60 🗶 Dege \$565.10 SU(\$1,220.30 ) \$688.50 \$922.30 \$122.50 \$50.00 \$980.00 400 S.N \$9,905.90

\$1,265.50