

ASS. REC. BY:

REF: CS/PC19014753/T19 f3ⁿ²

Special Instruction:

Surveyor: Toufik

ASSIGNMENT (Office)

From (Person): Henny Kao

of

PC1Date/Time: 22.8.19 8.53AM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJD 8286AInsured: SHC 0629Bat Workshop m/s: PerformancaTel: 63190174of 303 Alexandra

Policy No:

Claim No: D19005310MPSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 14.8.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 22.8.19 2.34p.mPerson Contacted: CarolineVehicle IN/OUT: IN

Date/Time	Action/Instruction (✓) Estimate
	SJD 8286A - X
	SHC 0629B - X
17/9 @ 11:44am	- Sent preli advise via email.
31/10/19	12pm confirmed with Sharon final fig \$6487.95, 4 days.
	cred \$1164, (15%)

ASS. BY: Tanpin

REP: PCI

ASSIGNMENT

From: _____ Date: 16/9/19

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 8JD8286A
at Workshop m/s Performance Motor
of 303 Alexandra Road

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Moring Inthiran

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1wp

Date: _____ Person Contacted: Inthiran Vehicle: IN / OUT

Veh No: 5JD8286A Yr Regn: 2018 / Sep.

Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW m5 Seloon C.C. 4395

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 14198 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBS SF 020569A0527

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/35R20

R: 225/35R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 16/9/19 @ 1140

Survey held at PM L

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Int N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 3 OCT 2019

31/10/2019

Date/Time, File Pass to?

1) 31/10 tyrisr

Date/Time, File Return to?

2) _____

Report Format: TI

Lump Sum / L.E.C: 6487.95

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp. (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others:

TOTAL

150

50

50

18

268



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005310MFSH

Date: 17/09/2019

Our Ref: CS/FCI19014753/T1qf3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJD 8286A

Please be informed that we had conducted the inspection of the abovementioned vehicle
16/09/2019 at the premises of M/s Performance Motor have the following to report: -

Workshop Estimate Amount	: S\$ <u>7,651.95</u>
Revised Estimate Amount	: S\$ <u>6,407.95</u>
"Check" Items Amount	: S\$ <u>80.00</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the
Front n/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Taufikh

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	16-08-2019	Our Ref No. D19005310MFSH
Accident Date	14-08-2019	Claim Type. Third Party
Insured Vehicle	SHC0629B	Third Party Vehicle. SJD8286A
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63190174/ 0	Fax No. 64794601
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Nivitha (LKK Auto)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Tuesday, 10 September 2019 2:41 PM
To: assignments
Cc: Inthiran Thurasamy
Subject: Re: SURVEYOR APPOINTED; OUR REF : D19005310MFSH ; YOUR REF: SJD8286A

Dear Sirs

Please arrange survey on 16 September 2019.

Owner leaving car in for survey + repair by 10am

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP
Sent: Thursday, 22 August 2019 9:02 AM
To: Inthiran Thurasamy <inthiran.thurasamy@simedarby.com.sg>
Subject: Fw: SURVEYOR APPOINTED; OUR REF : D19005310MFSH ; YOUR REF: SJD8286A

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Thursday, 22 August 2019 8:53 AM
To: PBSP <pml-pbsp@simedarby.com.sg>
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao <HenryKao@msfirstcapital.com.sg>
Subject: SURVEYOR APPOINTED; OUR REF : D19005310MFSH ; YOUR REF: SJD8286A

Dear Sir/Madam

PRI Request For **SJD8286A** Accident Involving **SHC0629B** On 14-08-2019 AT 16:10:00HRS.

Please find below details for your reference

- **Claim number :** D19005310MFSH
- **Insured vehicle number :** SHC0629B
- **Accident date :** 14-08-2019
- **Third-party vehicle number :** SJD8286A
- **Assignment type :** DIRECT SETTLEMENT
- **Surveyor :** LKK AUTO CONSULTANTS PTE LTD
- **Officer-in-Charge :** HENRY KAO

PS: This is a system generated mail. Please do not reply to this mail.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 31 October 2019 12:00 PM
To: Sharon Heng L K
Cc: Toh Jing Xuan; Bernard Wan Chong Huat; SUR
Subject: RE: DIRECT SETTLEMENT FINAL REPORT - SJD8286A

Dear Sharon,

WITHOUT PREJUDICE

Confirm final fig \$6,487.95 before GST and 4 repair days.

Kindly send the relevant documents to MS First Capital Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Sharon Heng L K <sharon.heng.leekun@simedarby.com.sg>

Sent: Wednesday, 30 October 2019 12:46 PM

To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>

Cc: Toh Jing Xuan <toh.jing.xuan@simedarby.com.sg>; Bernard Wan Chong Huat <bernard.wan@simedarby.com.sg>

Subject: DIRECT SETTLEMENT FINAL REPORT - SJD8286A

Dear Taufikh

For your perusal :

Labor	\$4191.00
Part	\$2296.95
Total	\$6487.95

Owner is claiming LOSS OF USE = \$120 X4 DAYS.

Note : 4 working days.

Please reply me directly.

Best Regards

Sharon Heng

Performance Motors Ltd

Body & Paint

DID : 63190123

Fax : 64743229

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 17 September 2019 11:44 AM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments; SUR
Cc: 'Henry Kao'
Subject: RE: SURVEY ASSESSMENT - D19005310MFSH/1
Attachments: PRELI ADVISED OF SJD 8286A.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SJD 8286A**
Number of days (estimated) : 4 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 22 August 2019 2:35 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Henry Kao' <HenryKao@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19005310MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- Sime Darby Business Centre
- Singapore 159944
- Fax: 64756601
- 64756624 (Motorrad)
- is subject to final approval from Insurance Company



GST REG. NO : M2 - 0020081 - X

ESTIMATE

20 AUG 2019

Estimate No. : b1 52384
Date Estimated : 20/08/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Chin Yong Kok
133 Namly Avenue

Singapore 267701

- ACCOUNT - 303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJD8286A	GA03527	20/09/2018	M5 SEDAN	0

DESCRIPTION

To remove & install front bumper, repair front bumper
and repair fender left.

VALUE

1700 / 2,550.00

Painting front bumper and fender left.

1730 / 1,923.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

150 / 177.00

To replace tyre and wheel rim including balancing. (1x).

80 / 94.00

To check steering geometry and conduct wheel alignment in
accordance with BMW specifications. (1x)

451 / 531.00

Sundries.

W1 /
? 80.00

Total Labour 1: 5,355.00

DESCRIPTION

ALLOY RIM 9.5JX20 M DOUBLE SPK 706M

QTY PRIC
1 2,296.95

VALUE

W1 / 2,296.95

Total Parts : 2,296.95

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 16/9/1401140 Claim No.

Date & Time 16/9/1401140 Excess \$

Surveyor's Name Inthiran Sign Inthiran

Surveyor's Tel 92495444 Authorised Yes / No

Authorised Date 16/9/1401140 Time

SURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail Inthiran@Performance.com

Working Days Recommend 4 days

Labour 1 : 5,355.00

Parts : 2,296.95

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 535.64

Grand Total : 8,187.59

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 52384**
Date Estimated : **20/08/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -

Chin Yong Kok
133 Namly Avenue

Singapore 267701

- ACCOUNT - 303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJD8286A	WBSJF02050GA0352	20/09/2018	M5 SEDAN	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	303 DISC. %	NETT
To make good front bumper, front left fender and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	1,700.00	0	1,700.00
To respray front bumper and front left fender.	1,730.00	0	1,730.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00	0	150.00
To replace front left wheel rim including balancing.	80.00	0	80.00
To check steering geometry and conduct wheel alignment according to BMW specification.	451.00	0	451.00
Sundries.	80.00	0	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
ALLOY RIM 9.5JX20 M DOUBLE SPK 706M	2,296.95	1.00	0	2,296.95

ESTIMATE NO.	DATE	WORKING DAYS
b1 52384	20/08/19	4
Taufik LKR		
FAX TO	FAX NO	
FAX TO	FAX NO	
CONFIRMED DATE		
RECEIVED BY		

Total Labour :	4,191.00
Total Parts :	2,296.95
Total Labour & Parts :	6,487.95
GST @7%:	454.16
Grand Total :	6,942.11

LOSS OF USE = \$120 X 4 DAYS



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19014753/T1qf3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-11-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 629B	Veh. Inspected	SJD 8286A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005310MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	22/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. M5 SALOON	c.c	4395	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WBSJF02050GA03527	Colour	SILVER	
Odometer	14198	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/35 R20	PIRELLI	6 mm	
L/H Front Tyre	275/35 R20	PIRELLI	6 mm	
R/H Rear Tyre	275/35 R20	PIRELLI	6 mm	
L/H Rear Tyre	275/35 R20	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/08/2019	Inspection Date	16/09/2019	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJD 8286A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	ALLOY RIM 9.2JX20 M DOUBLE SPK 706M (SN)	CUT	2,296.95	2,296.95
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
			2,376.95	2,376.95
	LABOUR			
	TO REMOVE & INSTALL FRONT BUMPER, REPAIR FRONT BUMPER AND REPAIR FENDER LEFT.		2,550.00	1,700.00
	PAINTING FRONT BUMPER AND FENDER LEFT.		1,923.00	1,730.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.		177.00	150.00
	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING (1X).		94.00	80.00
	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS (1X).		531.00	451.00
			5,275.00	4,111.00
	GRAND TOTAL		7,651.95	6,487.95
RECOMMENDED COST OF REPAIRS				6,487.95

Report Ref No. CS/FC119014753/T1qf3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.