

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19014760/APS3Q2

Date: 16/04/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MCV0002330
Claimant Vehicle No :	SGZ4027C	Insured Vehicle No :	GBD5053U
Date of Loss:	21/08/2019	Nature of Claim:	TP
		Claim No:	MCV2019D0000937

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGZ4027C		Engine No:	R16A13000394
Make & Model:	HONDA CIVIC, 1.6 VTI (A)		Chassis No:	JHMF46208S200055
Reg. Date:	29/10/2007 (Man. Year: 2007)		Odometer:	254525 km
Colour:	White			
Engine Capacity:	1595 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,956.00	3,055.60	2,900.40	48.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,530.00	1,160.00	1,370.00	54.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,486.00	4,215.60	4,270.40	50.32
Approved Total (Overridden) (S\$)		3,350.00		
Nett Amount (S\$)	8,486.00	3,350.00	5,136.00	60.52
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,957.45		
Global Sum Settlement (S\$)		3,950.00		

INSPECTION

Date of Assignment:	22/08/2019	
Date Inspected:	22/08/2019 Inspected At:	Best Solution Autocare Pte Ltd (HQ) 53 UBI AVE 1 #03-01 PAYA UBI INDUSTRIAL PARK Singapore 408934
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Market Value: \$46,000.00(est) less LTA Rebate: \$34,829.00(est) = Nett Value :\$11,171.00(est).

Please note that third party vehicle COE expiry date is 28 Oct 2027.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Feb 2020)
Parts: 143	HONDA CIVIC 1.6 VTI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGZ4027C)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	785.00 F	*638.00 FL
2	1		*FRONT BUMPER SIDE RETAINER	O/S Damaged	58.00 F	*29.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Bent	280.00 F	*280.00 FL
4	1		*FRONT BUMPER LOWER SKIRT	Damaged	380.00 F	*155.00 FL
5	1		*FRONT GRILLE	Not Necessary	395.00 F	*- FL
6	1		*O/S HEAD LAMP	Cut	879.00 F	*879.00 FL
7	1		*O/S HEAD LAMP LOWER BRACKET	Bent	59.00 F	*59.00 FL
8	1		*O/S FRONT FENDER	Dented	637.00 F	*553.00 FL
9	1		*O/S FRONT FENDER INNER SHIELD	Torn	134.00 F	*134.00 FL
10	1		*O/S FRONT BUMPER FOG LAMP GARNISH	Not Necessary	90.00 F	*- FL
11	1		*O/S FRONT SPORT RIM	Cut	850.00 FS	*450.00 FS
12	1		*O/S FRONT SHOCK ABSORBER	Not Necessary	435.00 F	*- FL
13	1		*O/S FRONT LOWER ARM	Bent	310.00 F	*310.00 FL
14	1		*O/S FRONT KNUCKLE ARM	Not Necessary	354.00 F	*- FL
15	1		*O/S FRONT KNUCKLE ARM BEARING	Damaged	190.00 F	*190.00 FL
16	1		*SET FRONT BUMPER CLIP	Necessary	30.00 F	*30.00 FL
17	1		*SET FORNT GRILLE CLIP	Not Necessary	30.00 F	*- FL
18	1		*NUMBER PLATE	Not Necessary	60.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,956.00	3,707.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	651.40
Total Parts (\$\$)	5,956.00	3,055.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PARTS ,PANEL BEAT ,REPAIR	New	1,000.00	500.00
2	TO PUTTY AND SPRAY PAINTING ON AFFECTED AREA	New	900.00	400.00
3	AIR CON	New	80.00	0.00
4	ANTI RUST	New	150.00	0.00
5	UNDERCARRIAGE	New	250.00	180.00
6	WHEEL ALIGNMENT	New	150.00	80.00
			Gross Labour Cost (\$)	1,660.00
			2,530.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >