

ASS. REC. BY:

REF:

CS/INC/9014762/Ksf3<sup>n2</sup>

Special Instruction:

Assigner: Kenneth

## ASSIGNMENT (Office)

From (Person): Daniel Koh

of

INC

Date/Time: 9:45am @ 21/8/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 5845K

Insured:

XE 13174

at Workshop m/s

Thurs cab

Tel:

6287 6666

of

No. 2 Amie St. 63

Policy No:

Claim No:

MT/1058708-001

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 17/08/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:30am @ 21/8/19

Person Contacted:

Candy

Vehicle IN OUT

Date/Time

Action/Instruction

estimate /

ASS. REC. BY:

REF:

INC /

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 5845K

Yr Regn:

03/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Longitude

c.c

1895

Colour:

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

469927

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1 ABL15AUC 281422

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

Sailun 215/60R16

R:

GTT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

17/8/19

Rear

R/Bal.

8

mm

L/Bal.

8

mm

D.O.I.

21/8/19

Survey held at

11.06 am

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

L12y 84500h

CE 31,829.41

Red - 88% ?

RECEIVED 10 SEP 2019

Date/Time, File Pass to?



: Prell. Report

1) Typ: st



: Final Report

Date/Time, File Return to?

Days Of Repair:

4

Resurvey No. of Trlp:

1

Survey Fee:

Transportation:

S + RS. \$

Parking

Others

TOTAL

250

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

4,500/- 4/5

**Nivitha (LKK Auto)**

**From:** Daniel Koh <daniel.koh@income.com.sg>  
**Sent:** Wednesday, 21 August 2019 3:43 PM  
**To:** 'assignments@lkkauto.com'  
**Cc:** admin-d@lkkauto.com  
**Subject:** FW: TP CASES FARMED OUT TO LKK ON 21/8/2019

Dear LKK,

**RESEND WITH CLAIM NUMBER & OIC**

**From:** Daniel Koh  
**Sent:** Wednesday, 21 August 2019 9:45 AM  
**To:** 'assignments@lkkauto.com' <assignments@lkkauto.com>  
**Cc:** 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>  
**Subject:** FW: TP CASES FARMED OUT TO LKK ON 21/8/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	OIV	DOA	Additional Remarks
----	-----	-----------	---------	---------------	------------------	------------------	-----	-----	--------------------

1	FIONA SHEN	MT/1057247-002	SKS9427M	CARZ AUTO SERVICES PTE LTD	61 WOODLANDS INDUSTRIAL PARK E9 (E9 PREMIUM) #04-04 SINGAPORE 757047	Jeslyn Chua / 8322 7418	SLG4424E	13/8/2019	
2	HELENA TAN	MT/1052090-002	GBC4504Y	CYS AUTOMOBILE SERVICES PTE LTD	38 WOODLANDS INDUSTRIAL PARK E1 #07-17 ADMIRALTY IND PARK SINGAPORE 757700	Ms Tee Wee Sin / 62192098	FBL5374B	5/7/2019	
3	JEFF LIN	MT/1057583-002	SLV2243U	LIAN HER MOTORS	BLK 5038 #01-405 ANG MO KIO INDUSTRIAL PARK 2	Anthony Cheong / 91082728	SMJ284R	14/8/2019	1/8/2019
4	WO JESSIE	MT/1058357-002	SHB6644Y	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Ms Lynn or Ms Irene / 65425119	PC7436A	17/8/2019	6542 7162
5	WO JESSIE	MT/1058567-001	SHD3069S	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Ms Lynn or Ms Irene / 65425119	SGC269T	18/8/2019	6542 7162

6	QUEK SWEE KENG	MT/1058552-001	SHC286G	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Ms Lynn or Ms Irene / 65425119	GW57H	19/8/2019	6542 7162
7	CYNDIIE YONG	MT/1058466-002	SHD9692C	TRANS-CAB AUTO SERVICES PTE. LTD.	2 ANG MO KIO STREET 63	Kek Zhewei / 62876666	SJJ4142B	19/8/2019	Avoid Lunch time : 12pm - 1pm.
8	WO JESSIE	MT/1058662-002	SHF724T	TRANS-CAB AUTO SERVICES PTE. LTD.	2 ANG MO KIO STREET 63	Candy Kong / 62876666	SJX1594B	17/8/2019	Avoid Lunch time : 12pm - 1pm.
9	CYNDIIE YONG	MT/1058299-002	SHD9594C	TRANS-CAB AUTO SERVICES PTE. LTD.	2 ANG MO KIO STREET 63	Candy Kong / 62876666	SJV6028Y	19/8/2019	avoid Lunch time : 12pm - 1pm.
10	WO JESSIE	MT/1058686-001	SHC5166L	TRANS-CAB AUTO SERVICES PTE. LTD.	2 ANG MO KIO STREET 63	Kek Zhewei / 62876666	FW7741G	19/8/2019	
11	OFFICER IN CHARGE WILL REVERT LATER	MT/1058708-001	SHC5845K	TRANS-CAB AUTO SERVICES PTE. LTD.	2 ANG MO KIO STREET 63	Candy Kong / 62876666	XE1317U	17/8/2019	Avoid Lunch time : 12pm - 1pm.
12	QUEK SWEE KENG	MT/1058335-002	SHD448B	TRANS-CAB AUTO SERVICES PTE. LTD.	2 ANG MO KIO STREET 63	Amanda Tay / 62876666	SKF2699J	17/8/2019	Avoid Lunch time : 12pm - 1pm.

## Summer Lee (LKK Auto)

---

**From:** Daniel Koh <daniel.koh@income.com.sg>  
**Sent:** Thursday, 22 August, 2019 8:20 AM  
**To:** 'assignments@lkkauto.com'  
**Cc:** admin-d@lkkauto.com  
**Subject:** FW: TP CASES FARMED OUT TO LKK ON 21/8/2019

Dear LKK,

11	QUEK SWEE KENG	MT/1058708- 001	SHC5845K	TRANS-CAB AUTO SERVICES PTE. LTD.	2 ANG MO KIO STREET 63	Candy Kong / 62876666	XE1317U	17/8/2019	Avoid Lunch time : 12pm - 1pm.
----	----------------------	--------------------	----------	--	------------------------------	-----------------------------	---------	-----------	--

Daniel Koh  
Senior Admin Assistant  
Motor Insurance  
[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
**Find out more at [Income.com.sg/careers](http://Income.com.sg/careers)**

**in** with you

---

**From:** Daniel Koh  
**Sent:** Wednesday, 21 August 2019 3:43 PM  
**To:** 'assignments@lkkauto.com' <assignments@lkkauto.com>  
**Cc:** 'admin-d@lkkauto.com' <admin-d@lkkauto.com>  
**Subject:** FW: TP CASES FARMED OUT TO LKK ON 21/8/2019

Dear LKK,

**RESEND WITH CLAIM NUMBER & OIC**

From: Daniel Koh

Sent: Wednesday, 21 August 2019 9:45 AM

To: 'assignments@lkkauto.com' <assignments@lkkauto.com>

Cc: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>

Subject: FW: TP CASES FARMED OUT TO LKK ON 21/8/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	OIV	DOA	Additi Remai
1	FIONA SHEN	MT/1057247-002	SKS9427M	CARZ AUTO SERVICES PTE LTD	61 WOODLANDS INDUSTRIAL PARK E9 (E9 PREMIUM) #04-04 SINGAPORE 757047	Jeslyn Chua / 8322 7418	SLG4424E	13/8/2019	
2	HELENA TAN	MT/1052090-002	GBC4504Y	CYS AUTOMOBILE SERVICES PTE LTD	38 WOODLANDS INDUSTRIAL PARK E1 #07-17 ADMIRALTY IND PARK SINGAPORE 757700	Ms Tee Wee Sin / 62192098	FBL5374B	5/7/2019	
3	JEFF LIN	MT/1057583-002	SLV2243U	LIAN HER MOTORS	BLK 5038 #01-405 ANG MO KIO INDUSTRIAL PARK 2	Anthony Cheong / 91082728	SMJ284R	14/8/2019	1/8/;
4	WO JESSIE	MT/1058357-002	SHB6644Y	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Ms Lynn or Ms Irene / 65425119	PC7436A	17/8/2019	6542 7162
5	WO JESSIE	MT/1058567-001	SHD3069S	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Ms Lynn or Ms Irene / 65425119	SGC269T	18/8/2019	6542 7162

6	QUEK SWEE KENG	MT/1058552-001	SHC286G	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Ms Lynn or Ms Irene / 65425119	GW57H	19/8/2019	6542 7162
7	CYNDIE YONG	MT/1058466-002	SHD9692C	TRANS-CAB AUTO SERVICES PTE. LTD.	2 ANG MO KIO STREET 63	Kek Zhewei / 62876666	SJJ4142B	19/8/2019	Avoid Lunch time : 12pm 1pm.
8	WO JESSIE	MT/1058662-002	SHF724T	TRANS-CAB AUTO SERVICES PTE. LTD.	2 ANG MO KIO STREET 63	Candy Kong / 62876666	SJX1594B	17/8/2019	Avoid Lunch time : 12pm 1pm.
9	CYNDIE YONG	MT/1058299-002	SHD9594C	TRANS-CAB AUTO SERVICES PTE. LTD.	2 ANG MO KIO STREET 63	Candy Kong / 62876666	SJV6028Y	19/8/2019	avoid Lunch time : 12pm 1pm.
10	WO JESSIE	MT/1058686-001	SHC5166L	TRANS-CAB AUTO SERVICES PTE. LTD.	2 ANG MO KIO STREET 63	Kek Zhewei / 62876666	FW7741G	19/8/2019	
11	OFFICER IN CHARGE WILL REVERT LATER	MT/1058708-001	SHC5845K	TRANS-CAB AUTO SERVICES PTE. LTD.	2 ANG MO KIO STREET 63	Candy Kong / 62876666	XE1317U	17/8/2019	Avoid Lunch time : 12pm 1pm.
12	QUEK SWEE KENG	MT/1058335-002	SHD448B	TRANS-CAB AUTO SERVICES PTE. LTD.	2 ANG MO KIO STREET 63	Amanda Tay / 62876666	SKF2699J	17/8/2019	Avoid Lunch time : 12pm 1pm.

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.



Daniel Koh  
Senior Admin Assistant  
Motor Insurance  
T +65 6430 7901  
[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

**Find out more at [income.com.sg/careers](http://income.com.sg/careers)**



---

#### Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	878K

**Vehicle Details**

Vehicle No.:	SHC5845K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	19 Aug 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002548
Chassis No.:	VF1ABL15AUC281422
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	06 Mar 2015
First Registration Date:	06 Mar 2015
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Mar 2023
PARF Rebate Amount:	\$9,373.00

**Intended COE Rebate Details**

COE Expiry Date:	05 Mar 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,092.00
COE Rebate Amount:	\$22,609.00
<b>Total Rebate Amount:</b>	<b>\$31,982.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 19 Aug 2019

OK

**FW: TCS REF: AAD1908-125--Accident involving SHC 5845K & XE 1317U on 17/08/2019**

Ng Wai Yin <waiyin.ng@transcab.com.sg>

Fri 30/8/2019 3:39 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

📎 2 attachments (462 KB)

image001.wmz; ESTIMATE MARKED .pdf;

Hi Shirley

Amount confirmed \$ 4,500 (before GST).

Will send you the photo after I get it from our workshop.

Thank You

Best Regards,

**Ng Wai Yin**

Finance Department

TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**

**TRANS-CAB SERVICES PTE LTD**

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: [www.transcab.com.sg](http://www.transcab.com.sg)



This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

**Sent:** Friday, 30 August, 2019 12:14 PM

**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>

**Cc:** SUR <sur@lkkauto.com>

**Subject:** TCS REF: AAD1908-125--Accident involving SHC 5845K & XE 1317U on 17/08/2019

Dear Wai Yin,

Please confirm final fig \$ 4,500.00 (lump sum) @ 4 days of repairs before GST.

Kindly provide us after paint photo.

Thank you.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/08/2019 09:29
Date Of Accident	17/08/2019 22:10
Exact Location Of Accident	BARTLEY ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5845K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666
<b>Vehicle Particulars</b>	
Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

### Driver

Name of Driver	TAN CHYE LEONG
NRIC No	S0376564D
Date Of Birth	12/03/1949
Occupation	OUTDOOR
Date Of Driving Pass	30/11/1967
Driving Experience	51 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86501434
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 222 LOR 8 TOA PAYOH #16-695
Postcode	310222
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

On 17.08.2019 at about 2210hours, I was travelling straight along Bartley Road. Suddenly I felt an impact. Vehicle B (XE1317U) which was travelling on my right swerved into my lane and hit onto my taxi's right side rear portion.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE1317U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KERK SER CHIONG
NRIC/Passport Number	S1411928J
Contact Number	90906338
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**


**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach GA Report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5845K****AAD1908-125***Not Authored  
1/1/2019 @ 4500/*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

*21 AUG 2019*

Date of Accident :

Third Party Insurer :

Date of Registration:

**SHC 5845K**

VF1ABL15AUC281422

RENAULT

LATITUDE

17.8.19

**NTUC Income**

6/3/2015

PART		LIST	
1	DOOR PANEL REAR RH	\$	<i>n</i> 2,844.66 <i>X</i>
1	ROCKER PANEL INNER GARNISH RH	\$	<i>Sn</i> 466.51 <i>X</i>
1	ROCKER PANEL INNER RH	\$	<i>n</i> 1,024.79 <i>X</i>
1	ROCKER PANEL OUTER RH	\$	<i>n</i> 1,184.99 <i>X</i>
1	ROCKER PANEL CENTER RH	\$	<i>n</i> 990.25 <i>X</i>
1	BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35 <i>X</i>
1	FENDER PANEL REAR RH	\$	<i>Bu</i> 3,299.13 <i>✓</i>
1	FENDER PANEL INNER TRIM REAR RH	\$	<i>Sn</i> 671.45 <i>X</i>
1	WHEELARCH REAR RH	\$	<i>Sn</i> 543.47 <i>X</i>
1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 <i>✓</i>
1	BUMPER LOWER REAR	\$	<i>Sn</i> 768.84 <i>X</i>
1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 <i>X</i>
1	BUMPER BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 <i>X</i>
1	BUMPER RETAINER RH REAR	\$	<i>n</i> 44.99 <i>✓</i>
1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61 <i>X</i>
1	BUMPER BEAM REAR	\$	<i>n</i> 777.52 <i>X</i>
1	BUMPER BEAM BRACKET RH REAR	\$	<i>n</i> 225.95 <i>X</i>
1	TAILLAMP RH	\$	<i>Sn</i> 552.55 <i>X</i>
1	TAILLAMP PANEL RH	\$	<i>n</i> 986.70 <i>X</i>
1	EXHAUST REAR	\$	<i>n</i> 7,489.05 <i>X</i>
1	EXHAUST CAP REAR	\$	<i>n</i> 230.49 <i>X</i>
<b>TOTAL</b>		<b>\$</b>	<b>23,996.21</b>
<b>10%</b>		<b>\$</b>	<b>2,399.62</b>
		<b>\$</b>	<b>21,596.59</b>
<b>Special Nett</b>			
1	REAR DOOR STICKER '6555-3333'	\$	<i>nn</i> 80.00 <i>X</i>

**Trans-cab Auto Services Pte Ltd**

AAD1908-125

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5845K

1	FENDER INNER TRIM CLIP RH	\$	nn	28.00	X
1	TAILLAMP CLIP RH	\$	nn	5.00	X
1SET	FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	X
2	REAR WINDSCREEN SEALANT	\$	nn	80.00	405n
1	WINDSCREEN MOULDING	\$	nn	100.00	✓
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	305n
1	REAR RIGHT TYRE	\$	Sh	300.00	X
1	REAR RIGHT TYRE RIM	\$	Sh	380.00	X
1SET	PARKING AID	\$	Sh	700.00	X
1SET	REAR BUMPER CLIP	\$	nn	66.00	✓
1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	✓
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
1SET	BUMPER RETAINER CLIP RH RR	\$	nn	20.00	X
1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	X
1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	X
1	EXHAUST MOUNTING REAR	\$	nn	17.82	X

<b>TOTAL</b>	<b>\$</b>	<b>2,042.82</b>
--------------	-----------	-----------------

<b>TOTAL PARTS</b>	<b>\$</b>	<b>23,639.41</b>
--------------------	-----------	------------------

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	4,500.00	600
----	----------	-----

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$	nn	380.00	X
----	----	--------	---

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$		380.00	100
----	--	--------	-----

To check steering geometry and computer wheel alignment

\$	nn	220.00	X
----	----	--------	---

To transfer of rear windscreen fittings and conduct water seepage test.

\$		170.00	1200
----	--	--------	------

**Trans-cab Auto Services Pte Ltd**

AAD1908-125

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5845K

To rust-proofing of the affected areas.	\$	170.00	301
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	nn 380.00	X
Putty and spray painting of the affected portion.	\$	4,500.00	4401
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
<b>TOTAL</b>	<b>\$</b>	<b>12,690.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>36,329.41</b>	

**LUMP SUM (REPAIR DAY)****15 DAYS**

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged panel during resurvey
- Parts prices are subject to confirmation
- Third party supply is on a "Firm Price" basis
- No illegal modification is allowed
- Supplementary items must be returned and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**DAMAGE ASSESSMENT REPORT**

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19014762/Ksf3n2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 23-09-2019



ATTN: QUEK SWEE KENG

Code: INC

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	XE 1317U	Veh. Inspected	SHC 5845K
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1058708-001	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	21/08/2019

**2. Vehicle Particulars & Condition**

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	VF1ABL15AUC281422	Colour	METALLIC WHITE / RED
Odometer	469927 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	215/60 R16	SAILUN	9 mm
L/H Front Tyre	215/60 R16	SAILUN	9 mm
R/H Rear Tyre	215/60 R16	GITI	8 mm
L/H Rear Tyre	215/60 R16	GITI	8 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

**5. General Information**

Accident Date	17/08/2019	Inspect Date / Time	21/08/2019 ( 11:06 AM )
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5845K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,844.66	-
1	ROCKER PANEL INNER GARNISH RH	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER RH	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL OUTER RH	TO REPAIR SEE LABOUR	1,184.99	-
1	ROCKER PANEL CENTER RH	TO REPAIR SEE LABOUR	990.25	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	FENDER PANEL REAR RH	BENT	3,299.13	3,299.13
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	DISTORTED	44.99	44.99
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
	LESS 10% DISCOUNT		-2,399.62	-445.26
			21,596.58	4,007.32



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR DOOR STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
1	FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	REAR RIGHT TYRE (SN)	SERVICEABLE	300.00	-
1	REAR RIGHT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP RH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	66.00	-
1	EXHAUST MOUNTING REAR (SN)	NOT NECESSARY	17.82	-
			2,042.82	269.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR PANEL REAR RH,ROCKER PANEL INNER RH,ROCKER PANEL OUTER RH,ROCKER PANEL CENTER RH,BUMPER BEAM REAR,BUMPER BEAM BRACKET RH REAR,TAILLAMP PANEL RH,EXHAUST REAR AND EXHAUST CAP REAR.		4,500.00	600.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.		380.00	100.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-

Report Ref No. CS/INC19014762/Ksf3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	440.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
			12,690.00	1,370.00
<b>GRAND TOTAL</b>			<b>36,329.40</b>	<b>5,646.32</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>4,500.00</b>

Report Ref No. CS/INC19014762/Ksf3n2

KONG SENG CHEONG

Licensed Appraiser

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.