

ASS. REC. BY:

REF: CS/MSG/19014764/R2vF307

Special Instruction:

SURVEYOR: Rusu

ASSIGNMENT (Office)

From (Person): Chia Nguk Rui

of MS19

Date/Time: 22.8.19 8:40 AM

Estimated Cost:

Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLT 7859X

Insured: SMK 41057

at Workshop m/s Kah motor

Tel: 64715419 / 90721769

of 255 Alexandra Road

Policy No: 29110539

Claim No: 603306

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 19.8.19

CA / REV / REP. / REV 24 HRS

Date/Time: 22.8.19 11:07 AM

Person Contacted:

Sin Hai

H.O.D. Endorsement:

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SMK 41057 X

SLT 7859X X

26/8/19

Send pte li revised via merimen

11/10/19

final fig \$ 31,106.19 confirmed by email (Ref 16,375.51, 3496)

REF: REC BY

REF: MS29

611M

08 2027/MV

ASSIGNMENT

From:

Date: 22.8.2019

Veh No:

SLT 7859X

Yr Regn: 2017 / NOV

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SLT 7859X

Make:

HONDA CITY 1.5 SV CVT C.C. 1497

at Workshop m/s

Kah motor

Colour:

BLACK

A/C: Insured / Std / NI / NA

at

255 Alexandra Road

Sp. Reading

-

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No:

MR4GM616 0J T000215

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: in order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: in order / Jammed / Leaked / Burnt or

Make of Veh:

Mod: Nil / S/Rim / STD A/Rim or

(Policy Condition)


Tyre Size:

F:

185/55R14

R:

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

71K

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

5

mm

R/Bal.

5

mm

G/A / PR Seen:

Consistent? : Yes or No

L/Bal.

5

mm

L/Bal.

5

mm

Est. Repairs:

days

Res: Yes or No

D.O.A.

19/08/19

D.O.I.

23/08/19

Lum Sum:

%

3 Val: Yes or No

Survey held at

Kah motor

CA / REV / REP. / 24 HRS

my?

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

repair / int 31k

RECEIVED

Date/Time, File Path to?



: Prel. Report

Days Of Repair:

23

1)



: Final Report

Resurvey No. of Trip:

1

Date/Time, File Path to?

Survey Fee:

290

2) 11/10 - typist

Add Fee:



: Site Insp (\$

Transportation:

3 x RS. 50



: Interview (\$

Phone



: Tech. Inve (\$

Office



: Wheel and (\$

TOTAL

261

Report Format:

mermen

Lump Sum / I.B.C. #

31,106.19

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Aug 2019		22 Aug 2019 08:40 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	FAVOURITE CAR RENTAL PTE LTD, Co. Reg. No.: 201838589K								
Main Claimant:	B. W. TRANS, Co. Reg. No.: 53369611M								
Vehicle Reg. No.:	SLT7859X	Date of Loss:	19/08/2019 07:00 - :59 [21 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 603305	Policy/Cover Note No.:	29110539 (Comprehensive) Coverage: 06/12/2018 - 05/12/2019						
Vehicle Reg. No. (Insured):	SMK4105T	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pul - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/08/2019]								
Driver/Custodian (Insured):	SOH HWA BENG (55 / Male), NRIC: S1628911F, Tel: +6594872351 Email:								
Adj Asg. Remarks:	on WP, Liab: 100%. Contact: Sin Hai @ 6471 5419 / 9072 1769, Manual assign to LKK via email on 21/08/2019.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 26 Aug 2019

Preliminary Advice

Insured Vehicle No	: SMK4105T	Accident Date	: 19/08/2019
TP Vehicle No	: SLT7859X	Assignment Date	: 22/08/2019
Make	: HONDA CITY	Est. Duration of Repair	: 10.00
Date of Inspection	: 23/08/2019		
Inspection At	: KAH MOTOR CO SDN BHD (ALEXANDRA) 255 ALEXANDRA ROAD SINGAPORE -		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	38,812.83
Revised Amount	:S\$	9,104.29
Check Items (Estimated)	:S\$	22,460.98
Total	:S\$	31,565.27

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	611M
Vehicle Particulars	
Vehicle No.:	SLT7859X
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	CITY 1.5 SV CVT
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	L15Z15204215
Chassis No.:	MRHGM6660JT000215
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$17,701.00
Original Registration Date:	13 Nov 2017
First Registration Date:	13 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$12,701.00
Intended PARF/COE Particulars	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Nov 2027
PARF Rebate Amount:	\$9,525.00
Intended COE Rebate Particulars	
COE Expiry Date:	12 Nov 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,001.00
COE Rebate Amount:	\$29,598.00
Total Rebate Amount:	\$39,123.00

The information contained herein is correct as at 23 Aug 2019

OK

71,000
 39,123

 31,877
 (31k)

Veron Chen (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Friday, 23 August 2019 4:11 PM
To: shng@kahmotor.onmicrosoft.com
Cc: Veron Chen (LKKAUTO)
Subject: SLT 7859X DOA : 19/08/19

Hi Sin Hai,

As per our message, repair limit for this case is 31K

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/08/2019 19:36
Date Of Accident	19/08/2019 07:50
Exact Location Of Accident	TELOK BLANGAH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT7859X
Insured/Policyholder	
Name Of Registered Owner	B. W. TRANS
Co Reg No	53369611M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90709169

Vehicle Particulars

Manufacturer	HONDA
Model	CITY-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	WONG SIN HOW
NRIC No	S8633633B
Date Of Birth	22/11/1986
Occupation	INDOOR
Date Of Driving Pass	04/10/2005
Driving Experience	13 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90709169
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address S

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : GERALDINE LIN
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY

Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 65470000 - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMK4105T MSIG

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

Vehicle Number: _____

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time: _____


Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

refer to police report T/20190820/2104

I/We declare the foregoing particulars are true in every respect.

I/We declare the foregoing particular

WAF.



**SINGAPORE
POLICE FORCE**



T/20190820/2104

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20190820/2104

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/08/2019 15:26	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: WONG SIN HOW			Address: APT BLK 264 TOA PAYOH EAST #16-32 TOA PAYOH APEX SINGAPORE 310264		
ID Type / ID No.: NRIC NO / S8633633B			Contact No.:		
Nationality: SINGAPORE CITIZEN			Home/Office:		Mobile: 90709169
Sex: Male			Email:		
Age: 32			Type of Informant: Driver		
Date of Birth: 22/11/1986			Institution / School Name:		
Race: Chinese			Language:		
Occupation: SHIPPING EXECUTIVE			Driving Licence Information: Class: 3		
			Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 19/08/2019 07:55	Type of Location: X-Junction
Location: TELOK BLANGAH ROAD HARBOURFRONT AVENUE JUNCTION OF TELOK BLANGAH AND HARBOURFRONT AVE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head On				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLT7859X	Car	HONDA	CITY 1.5 SV CVT	Black	Totally Damaged	1
SMK4105T	Car	TOYOTA	PRIUS HYBRID 1.8S CVT	Grey		1

Details of Person Involved

Any Pedestrian Involved: No		
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA	



**SINGAPORE
POLICE FORCE**



T/20190820/2104

2 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190820/2104

CONTINUATION OF REPORT

Driver			
Name	WONG SIN HOW	ID No.	S8633633B
Related Vehicle	SLT7859X (Car)	Contact No.	90709169
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	19/08/2019	Date Discharge	20/08/2019
No. of Days granted Medical Leave	16	Degree of Injury	Slight

Brief Details.

ON THE MENTIONED DATE TIME AND LOCATION,

I WAS TRAVELLING STRAIGHT TOWARDS PASIR PANJANG ROAD IN FAVOUR OF THE AMBER LIGHT, WHEN AN ONCOMING VEHICLE MISJUDGED ON DISCRETIONARY RIGHT TURN WHICH IN TURN CAUSE AN ACCIDENT. I WAS CONVEYED TO SGH TOGETHER WITH MY WIFE. WE WERE GIVEN 16 AND 21 DAYS MC RESPECTIVELY. THATS ALL



T/20190820/2104

3 of 3

Report No. T/20190820/2104

CONTINUATION OF REPORT

Informant is not able to provide sketch plan

Signature _____



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: MSIG INSURANCE (SINGAPORE) PTE LTD 16 RAFFLES QUAY HONG LEONG BUILDING SINGAPORE 048581	Document No.	: SQT19003664	Page	1
Registration No	: SLT7859X	Date	: 21. Aug 2019	Customer No.	: WZM003
Chassis No	: MRHGM6660JT000215	Svc Advisor	:	Engine No	: L15Z15204215
Model	: CITY 1.5SV CVT 2018 (EURO 6)	Date Time	: 21. Aug 2019 12:17:25 PM	Surveyor Name	:
Owner's Name	: B.W. TRANS	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 19/8/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
71101-T9A-T00ZZ	FACEFR.BUMPER <i>de</i>	1	459.80	25	344.85 ✓	24.14	368.99
71102-T9A-T50	GARNISHR.FR.FOGLIGHT <i>MIS / 9.45</i>	1	23.60	25	17.70 ✓	1.24	18.94
71103-T9A-T00	GRILLEFR.BUMPER LOWER <i>? X SUC</i>	1	88.00	25	66.00 X	4.62	70.62
71104-T9A-T00ZB	COVERFR.TOWING HOOK T99 <i>cut / 842</i>	1	14.80	25	11.10 ✓	0.78	11.88
71107-T9A-T50	GARNISHL.FR.FOG LIGHT <i>X SUC</i>	1	23.60	25	17.70	1.24	18.94
71111-T9A-T00	SCREENR.FR.BUMPER AIR <i>? X SUC</i>	1	19.60	25	14.70 X	1.03	15.73
71113-T9A-T00	SPOILERFR.BUMPER LIP <i>X SUC</i>	1	11.20	25	8.40	0.59	8.99
71116-T9A-T00	SCREENL.FR.BUMPER AIR <i>? X SUC</i>	1	19.60	25	14.70 X	1.03	15.73
71130-T9A-T00ZZ	BEAM COMPFR.BUMPER <i>bl / R</i>	1	243.10	25	182.32 ✓	12.76	195.08
71140-T9A-T00	BEAMR.FR.BUMPER UPPER <i>? R</i>	1	27.50	25	20.62 ✓	1.44	22.06
71190-T9A-T00	BEAML.FR.BUMPER UPPER <i>? L</i>	1	27.50	25	20.62 ✓	1.44	22.06
71193-T9A-T00	SPACERR.FR.BUMPER SIDE <i>ne</i>	1	10.40	25	7.80 ✓	0.55	8.35
71198-T9A-T00	SPACERL.FR.BUMPER SIDE <i>ne</i>	1	10.40	25	7.80 ✓	0.55	8.35
91505-TM8-003	CLIP.BUMPER <i>ne</i>	11	2.30	25	18.97 ✓	1.33	20.30
71121-T9A-T00	BASEFR.GRILLE <i>? X SUC</i>	1	86.90	25	65.17 X	4.56	69.73
71122-T9A-T20	MOLDINGFR.GRILLE UPPER <i>? X SUC</i>	1	184.30	25	138.22 X	9.68	147.90
71123-T9A-T00	COVERFR.GRILLE <i>cut</i>	1	32.90	25	24.67 ✓	1.73	26.40
71125-T9A-T10	MOLDINGFR.GRILLE LOWER <i>cut / 34.87</i>	1	45.10	25	33.82 ✓	2.37	36.19
71126-T9A-T00	SCREENFR.GRILLE UPPER AIR <i>? X SUC</i>	1	15.00	25	11.25 X	0.79	12.04

Printed on 22/8/2019 8:38:43 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY
 HONG LEONG BUILDING
 SINGAPORE 048581

Registration No : SLT7859X

Chassis No : MRHGM6660JT000215

Model : CITY 1.5SV CVT 2018 (EURO 6)

Owner's Name : B.W. TRANS

Ins Policy No. :

Date of Accident : 19/8/2019

Document No. : SQT19003664 Page 2

Date : 21. Aug 2019

Customer No. : WZM003

Svc Advisor :

Engine No : L15Z15204215

Date | Time : 21. Aug 2019 12:17:25 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71128-T9A-T00	STAYFR.GRILLE <i>new</i>	1	6.90	25	5.17 ✓	0.36	5.53
75700-TF0-000	EMBLEM (H) <i>new</i> 11.25	1	22.90	25	17.17 ✓	1.20	18.37
90301-ST0-003	NUTPUSH 3MM <i>new</i> 3-15 (24cs) ←	1	2.10	25	1.57 ✓	0.11	1.68
33100-T9A-T01	HEADLIGHT ASSY.R <i>new</i> 424.27 ←	1	324.10	25	243.07 ✓	17.01	260.08
33150-T9A-T01	HEADLIGHT ASSYL <i>new</i>	1	324.10	25	243.07 ✓	17.01	260.08
33900-T0A-H01	LIGHT ASSYFR.FOG ? 229.42 <i>new</i> ←	1	277.90	25	208.42 ✓	14.59	223.01
73111-T9A-T03	GLASS SET.FR.WINDSHIELD GREEN ?	1	1076.10	25	807.07	56.49	863.56
73125-T9A-T01	MOLDINGFR.WINDSHIELD SIDE ?	2	5.80	25	8.70	0.61	9.31
73126-SYY-000	RUBBER BFR W/SHIELD ?	1	3.70	25	2.77	0.19	2.96
73126-SR3-000	RUBBER, W/SHIELD ?	1	14.40	25	10.80	0.76	11.56
73150-T9A-T01	MOLDINGFR.WINDSHIELD ?	1	18.80	25	14.10	0.99	15.09
BO-IU-BKT(NEW)	IU BRACKET TAPE(N) ?	1	26.00		26.00	1.82	27.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N) ?	2	60.00		120.00	8.40	128.40
60100-T9A-T00ZZ	HOOD COMPENGINE <i>repair</i>	1	418.30	25	313.72	21.96	335.68
60120-T9A-T00ZZ	HINGE COMPR.HOOD <i>X</i>	1	32.60	25	24.45	1.71	26.16
60170-T9A-T00ZZ	HINGE COMPL.HOOD <i>X</i>	1	32.60	25	24.45	1.71	26.16
74120-T9A-T01	LOCK ASSYHOOD <i>X</i>	1	89.50	25	67.12	4.70	71.82
74121-T9A-T00	RUBBERR.FR.HOOD SEAL <i>X</i>	1	6.40	25	4.80	0.34	5.14
74128-T9A-T00	RUBBERL.FR.HOOD SEAL <i>X</i>	1	6.40	25	4.80	0.34	5.14
74130-T9A-T01	WIRE ASSYHOOD <i>X</i>	1	28.50	25	21.37	1.50	22.87
74141-T9A-T00	INSULATORHOOD <i>X</i>	1	41.60	25	31.20	2.18	33.38
74142-T9A-T00	RUBBERR.HOOD SEAL <i>X</i>	1	11.40	25	8.55	0.60	9.15
74143-T9A-T01	RUBBERRR.HOOD SEAL <i>new</i> <i>SVC</i>	1	21.90	25	16.42 ✓	1.15	17.57
74144-T9A-T01	RUBBERHOOD SIDE SEAL <i>X</i>	1	3.60	25	2.70	0.19	2.89
74145-T9A-T00	STAYHOOD OPEN <i>X</i>	1	12.50	25	9.37	0.66	10.03
74149-T9A-T00	RUBBERL.HOOD SEAL <i>new</i> <i>SVC</i>	1	11.40	25	8.55 ✓	0.60	9.15
74218-T9A-T00	COWL TOP SETFR <i>X</i> ←	1	55.60	25	41.70 ✓	2.92	44.62
76810-T9A-T01	NOZZLE ASSY <i>X</i>	1	15.90	25	11.92	0.83	12.75
76830-SL0-003	JOINT YTUBE <i>X</i>	1	8.90	25	6.67	0.47	7.14

Printed on 22/8/2019 8:38:43 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581

Registration No : SLT7859X

Chassis No : MRHGM6660JT000215

Model : CITY 1.5SV CVT 2018 (EURO 6)

Owner's Name : B.W. TRANS

Ins Policy No. :

Date of Accident : 19/8/2019

Document No. : SQT19003664 Page 3

Date : 21. Aug 2019

Customer No. : WZM003

Svc Advisor :

Engine No : L15Z15204215

Date | Time : 21. Aug 2019 12:17:25 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
80050-SP0-000	LABELAIR CONDITIONER CAUTION X an	1	1.80	25	1.35	0.09	1.44
19043-PLA-E00	LABELCOOLANT INFORMATION X an	1	5.00	25	3.75	0.26	4.01
60210-T9A-T50ZZ	PANEL COMP.R.FR.FENDER bu -	1	270.60	25	202.95	14.21	217.16
60260-T9A-T50ZZ	PANEL COMPL.FR.FENDER X suc	1	270.60	25	202.95	14.21	217.16
74100-T9A-T00	FENDER ASSYR.FR INNER de -	1	76.80	25	57.60	4.03	61.63
74105-T9A-T10	ENCLOSURER.FR.FENDER ne -	1	6.70	25	5.02	0.35	5.37
74111-T9A-T00	COVERENGINE UNDER ? de -	1	50.50	25	37.87	2.65	40.52
74115-T9A-T00	GUARDR.FR.SPLASH ? de -	1	20.10	25	15.07	1.05	16.12
74150-T9A-T00	FENDER ASSYL.FR INNER X	1	76.80	25	57.60	4.03	61.63
74155-T9A-T10	ENCLOSUREL.FR.FENDER X	1	6.70	25	5.02	0.35	5.37
74165-T9A-T00	GUARDL.FR.SPLASH X } X suc	1	19.50	25	14.62	1.02	15.64
74213-T9A-T00	COVERR.FR.FENDER X	1	19.50	25	14.62	1.02	15.64
74223-T9A-T00	COVERL.FR.FENDER X	1	19.50	25	14.62	1.02	15.64
91501-TR0-003	CLIP INNER FENDER ne -	18	2.80	25	37.80	2.65	40.45
91514-TG1-T01	CLIPUNDER COVER ne -	1	1.60	25	1.20	0.08	1.28
60400-T9A-T01ZZ	BULKHEAD COMP.FR. ? bt -	1	337.80	25	253.35	17.73	271.08
04674-T9A-T00ZZ	EXTENSION SETR.FR.SHOCK ABS ? bt -	1	84.00	25	63.00	4.41	67.41
04684-T9A-T00ZZ	EXTENSION SETL.FR.SHOCK ABS X suc	1	84.00	25	63.00	4.41	67.41
60619-T9A-T00ZZ	BRACKETR.FR.FENDER B ne -	1	22.90	25	17.17	1.20	18.37
60623-T9A-T00ZZ	BRACKETR.FR.FENDER A ne -	1	28.80	25	21.60	1.51	23.11
60630-T9A-T00ZZ	BASE COMPBATTERY SETTING X suc	1	25.90	25	19.42	1.36	20.78
60650-T9A-315ZZ	HOUSING SETR.FR.SHOCK ABS ? bt -	1	219.30	25	164.47	11.51	175.98
60710-T9A-T00ZZ	MEMBER COMPL.FR.WHEELHOUSE UP X bt -	1	78.20	25	58.65	4.11	62.76
60719-T9A-T00ZZ	BRACKETL.FR.FENDER B X	1	24.80	25	18.60	1.30	19.90
60723-T9A-T00ZZ	BRACKETL.FR.FENDER A X } X suc	1	28.80	25	21.60	1.51	23.11
60750-T9A-315ZZ	HOUSING SETL.FR.SHOCK ABS X	1	219.30	25	164.47	11.51	175.98
60810-T9A-T00ZZ	FRAME COMPR.FR.SIDE 5 bt -	1	519.50	25	389.62	27.27	416.89
60812-T9A-T00ZZ	PLATER.FR.SIDE BACK ? bt -	1	99.70	25	74.77	5.23	80.00
60844-T9A-T00ZZ	PLATER.SIDE FRAME GUSSET ? ne -	1	44.50	25	33.37	2.34	35.71

Printed on 22/8/2019 8:38:43 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY
 HONG LEONG BUILDING
 SINGAPORE 048581

Registration No : SLT7859X

Chassis No : MRHGM6660JT000215

Model : CITY 1.5SV CVT 2018 (EURO 6)

Owner's Name : B.W. TRANS

Ins Policy No :
 Date of Accident : 19/8/2019

Document No. : SQT19003664 Page 4

Date : 21. Aug 2019

Customer No. : WZM003

Svc Advisor :

Engine No : L15Z15204215

Date | Time : 21. Aug 2019 12:17:25 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
60845-T9A-T00ZZ	GUSSETR.FR.SIDE FRAME ? <i>bt</i>	1	54.10	25	40.57	2.84	43.41
60910-T9A-T00ZZ	FRAME COMPL.FR.SIDE X	1	519.50	25	389.62	27.27	416.89
60912-T9A-T00ZZ	PLATEL.FR.SIDE BACK X	1	99.70	25	74.77	5.23	80.00
60944-T9A-T00ZZ	PLATEL.SIDE FRAME GUSSET X <i>svc</i>	1	44.50	25	33.37	2.34	35.71
60945-T9A-T00ZZ	GUSSETL.FR.SIDE FRAME X	1	54.10	25	40.57	2.84	43.41
50200-T9A-T01	SUB FRAME COMPFR.SUSPENSION ? <i>bt</i>	1	340.50	25	255.37	17.88	273.25
50275-T5A-000	STAYRR.SUB FRAME ?	1	2.20	25	1.65	0.12	1.77
50290-T5A-000	STAYR.GEAR BOX ?	1	2.70	25	2.02	0.14	2.16
50295-T5A-000	STAYL.GEAR BOX ?	1	2.70	25	2.02	0.14	2.16
50690-T5A-003	BRACKETTORQUE ROD CVT ? <i>svc</i>	1	35.80	25	26.85	1.88	28.73
50822-T9A-013	RUBBER SUB ASSYENGINE SIDE MTG ?	1	127.80	25	95.85	6.71	102.56
50850-T9A-003	RUBBER ASSYTRANSMISSION MTG ?	1	111.40	25	83.55	5.85	89.40
50890-T5A-003	RODORQUE CVT ?	1	43.40	25	32.55	2.28	34.83
50620-T5B-003	BRACKETENGINE SIDE MOUNTING ?	1	54.00	25	40.50	2.84	43.34
50825-T5A-003	RUBBER ENGINE SIDE MOUNTING ?	1	2.50	25	1.87	0.13	2.00
80110-T9A-T01	CONDENSER COMP <i>bt</i> ?	1	406.50	25	304.87	21.34	326.21
80107-SZH-000	MOUNTCONDENSER UPPER ?	1	3.70	25	2.77	0.19	2.96
80111-T9A-T00	BRACKETR.CONDENSER UPPER ?	1	1.60	25	1.20	0.08	1.28
80175-T2F-A00	MOUNTCONDENSER LOWER ? <i>svc</i>	1	3.70	25	2.77	0.19	2.96
80311-T9A-T01	HOSE COMPSUCTION ?	1	94.40	25	70.80	4.96	75.76
80315-T9A-T01	HOSE COMPDISCHARGE ?	1	91.10	25	68.32	4.78	73.10
80321-T5A-003	PIPE COMPAIR CONDITIONER ?	1	97.60	25	73.20	5.12	78.32
80341-T9A-T01	PIPE COMPRECEIVER ? <i>bt</i>	1	98.10	25	73.57	5.15	78.72
80525-T2F-A01	SENSOR ASSYAMBIENT ? <i>svc</i>	1	43.40	25	32.55	2.28	34.83
91555-T9D-K01	CLIPAMBIENT SENSOR ? <i>svc</i>	1	1.10	25	0.82	0.06	0.88
19010-55A-Z51	RADIATOR COMP ? <i>bt</i>	1	1100.50	25	825.37	57.78	883.15
19015-55A-Z01	SHROUD COMP ? <i>svc</i>	1	57.70	25	43.27	3.03	46.30
19020-55A-Z01	FAN COMPCOOLING ?	1	21.40	25	16.05	1.12	17.17
19030-55A-Z01	MOTOR.COOLING FAN ?	1	211.10	25	158.32	11.08	169.40

Printed on 22/8/2019 8:38:43 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SLT7859X
Chassis No : MRHGM6660JT000215
Model : CITY 1.5SV CVT 2018 (EURO 6)
Owner's Name : B.W. TRANS
Ins Policy No :
Date of Accident : 19/8/2019

Document No. : SQT19003664 Page 5
Date : 21. Aug 2019
Customer No. : WZM003
Svc Advisor :
Engine No : L15Z15204215
Date | Time : 21. Aug 2019 12:17:25 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
38611-R1A-A02	FAN COMPCOOLING ?	1	55.20	25	41.40	2.90	44.30
38615-55A-Z01	SHROUD COMP ?	1	22.20	25	16.65	1.17	17.82
38616-55A-Z01	MOTORCOOLING FAN ?	1	200.30	25	150.22	10.52	160.74
90403-P5M-004	SPACER ?	1	3.80	25	2.85	0.20	3.05
19101-55A-Z00	TANKRESERVE ?	1	10.20	25	7.65	0.54	8.19
19102-RNA-A00	CAP RESERVE TANK X	1	8.30	25	6.22	0.44	6.66
19104-55A-Z00	HOSERESERVE TANK X	1	2.10	25	1.57	0.11	1.68
19106-RSA-G00	JOINTRESERVE TANK X	1	7.10	25	5.32	0.37	5.69
19501-55A-Z50	HOSEWATER UPPER X	1	6.70	25	5.02	0.35	5.37
19502-55A-Z00	HOSEWATER LOWER X	1	12.20	25	9.15	0.64	9.79
74171-T9A-T00	BRACKETR.RADIATOR UPPER MOUNT X ?	1	5.60	25	4.20	0.29	4.49
74172-SWA-000	CUSHIONRADIATOR LOWER X ?	1	11.40	25	8.55	0.60	9.15
74173-SJ4-000	CUSHIONRADIATOR UPP ?	1	4.00	25	3.00	0.21	3.21
74176-T9A-T00	BRACKETL.RADIATOR UPPER MOUNT ?	1	5.60	25	4.20	0.29	4.49
17201-55A-Z01	CASE SETAIR CLEANER X	1	53.40	25	40.05	2.80	42.85
17210-55C-E01	COVER COMPAIR CLEANER X	1	21.00	25	15.75	1.10	16.85
17211-55A-Z50	STAY COMP BAIR CLEANER X	1	2.30	25	1.72	0.12	1.84
17215-55A-Z00	STAY COMP AAIR CLEANER X	1	7.20	25	5.40	0.38	5.78
17220-55A-Z01	ELEMENT ASSYAIR CLEANER X	1	32.00	25	24.00	1.68	25.68
37880-RE1-Z01	SENSOR ASSYAIR TEMP X	1	10.00	25	7.50	0.53	8.03
37881-P2A-000	GROMMETTA SENSOR X	1	2.40	25	1.80	0.13	1.93
17249-55A-Z00	SEPARATORSPLASH X	1	5.70	25	4.27	0.30	4.57
17251-55A-Z01	TUBEAIR INTAKE X	1	18.60	25	13.95	0.98	14.93
17252-55A-Z00	DUCT ASSYAIR INTAKE X	1	43.00	25	32.25	2.26	34.51
91512-R21-013	CLIPINNER FENDER X	1	0.60	25	0.45	0.03	0.48
BB-42B20L	BATTERY - MAINTENANCE FREE X	1	125.00		125.00	8.75	133.75
77810-T9A-T82ZA	MODULE ASSYDRIVER ?	1	1780.50	25	1335.37	93.48	1428.85
77820-T9A-J80	MODULE ASSYPASSENGER ?	1	2236.80	25	1677.60	117.43	1795.03
77930-T5A-J01	SENSOR ASSYFR.CRASH ?	1	63.40	25	47.55	3.33	50.88

Printed on 22/8/2019 8:38:43 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above-estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: MSIG INSURANCE (SINGAPORE) PTE LTD	Document No.	: SQT19003664	Page	6
	16 RAFFLES QUAY	Date	: 21. Aug 2019		
	HONG LEONG BUILDING	Customer No.	: WZM003		
	SINGAPORE 048581	Svc Advisor	:		
Registration No	: SLT7859X	Engine No	: L15Z15204215		
Chassis No	: MRHGM6660JT000215	Date Time	: 21. Aug 2019 12:17:25 PM		
Model	: CITY 1.5SV CVT 2018 (EURO 6)	Surveyor Name	:		
Owner's Name	: B.W. TRANS	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 19/8/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
77960-T9A-Z41	SRS UNIT ? <i>yes</i> ✓	1	806.70	25	605.02 ✓	42.35	647.37
81450-T9A-T01ZD	TONGUE ASSY, FR. SEATBELT OUT ? <i>yes</i> ✓	1	404.60	25	303.45 ✓	21.24	324.69
81850-T9A-T01ZD	TONGUE ASSY, L. FR. SEATBELT ? <i>yes</i> ✓	1	404.60	25	303.45 ✓	21.24	324.69
Sum Item					12972.83	908.10	13,880.93
BOSUN	SUNDRIES	1	100.00 <i>30</i> ✓		100.00	7.00	107.00
BOJSE	SEALANT FOR RHF DOOR	1	80.00 <i>Xan</i> ✓		80.00	5.60	85.60
BKBH01M	REMOVE & RENEW BULKHEAD, STRAIGHTEN	1	9000.00 <i>2800</i> ✓		9000.00	630.00	9630.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00 ✓		180.00	12.60	192.60
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	1	5000.00 <i>1800</i> ✓		5000.00	350.00	5350.00
BMI00D	REMOVE & INSTALL DASHBOARD INSTRUMENTAL PANEL	1	1500.00 <i>1200</i> ✓		1500.00	105.00	1605.00
BKB01R	REMOVE AND RENEW RHF WHEEL	1	50.00 ✓		50.00	3.50	53.50
BMS00R	RENEW BOTH DRIVER & PASSENGER AIRBAG ASSY ECU &	1	1500.00 <i>1200</i> ✓		1500.00	105.00	1605.00
BKOT00A	PLACE VEHICLE TO BENCH FOR CHASSIS FRAME ALIGNMENT	1	1500.00 <i>1200</i> ✓		1500.00	105.00	1605.00
BKDR11R	REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST	1	560.00 <i>Xan</i> ✓		560.00	39.20	599.20
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	380.00 ✓		380.00	26.60	406.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	330.00 ✓		330.00	23.10	353.10
BMU01R	REMOVE & REPLACE FR UNDERCARRIAGE PARTS.(N)	1	1800.00 <i>1680</i> ✓		1800.00	126.00	1926.00
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	560.00 ✓		560.00	39.20	599.20
BML12R	REMOVE & RENEW ENGINE WIRE HARNESS, RESET ECU	1	1500.00 <i>1120</i> ✓		1500.00	105.00	1605.00
BMS02R	REMOVE & RENEW SEATBELT TENSIONER, ECU & CRASH SEN	1	1500.00 <i>1120</i> ✓		1500.00	105.00	1605.00
Sum Labor					25540.00	1,787.80	27,327.80
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00 ✓		180.00	12.60	192.60
TowinK - 120 ✓					Sum Ext. Service	180.00	12.60
							192.60

Printed on 22/8/2019 8:38:43 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581

Registration No : SLT7859X
Chassis No : MRHGM6660JT000215
Model : CITY 1.5V CVT 2018 (EURO 6)
Owner's Name : B.W. TRANS
Ins Policy No. :
Date of Accident : 19/8/2019

Document No. : SQT19003664
Date : 21. Aug 2019
Customer No. : WZM003
Svc Advisor :
Engine No : L15Z15204215
Date | Time : 21. Aug 2019 12:17:25 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 7

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Survey By	RASUL - Hp 90010068						
Date & Time	23/08/19 @ 0900						
Excess	7-10 days						
Status							
Signature							
Resurvey before print							
23 days							
Total Amount					38,692.83	2,708.50	41,401.33
Total (Inclusive of GST)							41,401.33
					38,812.83		
					47,481.70		

47614 08

Printed on 22/8/2019 8:38:43 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0002895 / MSIG INSURANCE
Chassis No: MRHGM6660JT000215
License No: SLT7859X
Mileage: 49931
Engine No: L15Z15204215

Document No: SVO19054154
Printed By: SHNG
Order Date: 23. August 2019
Order Time: 2:36:28 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:B.W.TRANS						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
	SUPPLEMENTARY PARTS AND LABOUR						
71101-T9A-T20ZZ	FACE, FR. BUMPER	1	459.80	25	344.85	24.14	368.99
71102-T9D-K10	GARNISH, R. FR. FOG LIGHT	1	12.60	25	9.45	0.66	10.11
71104-T9D-K10ZA	COVER, FR. TOWING HOOK	1	11.90	25	8.92	0.62	9.54
71130-T9A-T00ZZ	BEAM COMPFR.BUMPER	1	243.10	25	182.32	12.76	195.08
71140-T9A-T11	BEAM, R. FR. BUMPER UPPER	1	27.50	25	20.62	1.44	22.06
71190-T9A-T11	BEAM, L. FR. BUMPER UPPER	1	27.50	25	20.62	1.44	22.06
71193-T9A-T00	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
71198-T9A-T00	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIP,BUMPER	11	2.30	25	18.97	1.33	20.30
71123-T9A-T00	COVERFR.GRILLE	1	32.90	25	24.67	1.73	26.40
71125-T9A-T90	MOLDING, FR. GRILLE LOWER	1	46.50	25	34.87	2.44	37.31
71128-T9A-T00	STAYFR.GRILLE	1	6.90	25	5.17	0.36	5.53
75700-T5A-000	EMBLEM H	1	15.00	25	11.25	0.79	12.04
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
33100-T9A-T61	HEADLIGHT ASSY, R.	1	565.70	25	424.27	29.70	453.97
33900-TBA-A01	LIGHT ASSYR.FR.FOG	1	305.90	25	229.42	16.06	245.48
74143-T9A-T01	RUBBERRR.HOOD SEAL	1	21.90	25	16.42	1.15	17.57
74218-T9A-T00	COWL TOP SETFR.	1	55.60	25	41.70	2.92	44.62
60210-T9A-T50ZZ	PANEL COMP,R.FR.FENDER	1	270.60	25	202.95	14.21	217.16
74100-T9A-T10	FENDER ASSY, R. FR. INNER	1	76.60	25	57.60	4.03	61.63
74105-T9A-T10	ENCLOSURER.FR.FENDER	1	6.70	25	5.02	0.35	5.37
74111-T9A-T00	COVERENGINE UNDER	1	50.50	25	37.87	2.65	40.52
74115-T9A-T00	GUARDR.FR.SPLASH	1	20.10	25	15.07	1.05	16.12
91501-TR0-003	CLIP,INNER FENDER	18	2.80	25	37.80	2.65	40.45
91514-TG1-T01	CLIPUNDER COVER	1	1.60	25	1.20	0.08	1.28
60400-T9A-T10ZZ	BULKHEAD COMP, FR.	1	337.80	25	253.35	17.73	271.08
04674-T9A-T00ZZ	EXTENSION SETR.FR.SHOCK ABS	1	84.00	25	63.00	4.41	67.41
60619-T9A-T00ZZ	BRACKETR.FR.FENDER B	1	22.90	25	17.17	1.20	18.37
60623-T9A-T00ZZ	BRACKETR.FR.FENDER A	1	28.80	25	21.60	1.51	23.11
60650-T9A-315ZZ	HOUSING SETR.FR.SHOCK ABS	1	219.30	25	164.47	11.51	175.98
60810-T9A-T00ZZ	FRAME COMPR.FR.SIDE	1	519.50	25	389.62	27.27	416.89
60812-T9A-T00ZZ	PLATER.FR.SIDE BACK	1	99.70	25	74.77	5.23	80.00
60844-T9A-T00ZZ	PLATER.SIDE FRAME GUSSET	1	44.50	25	33.37	2.34	35.71
60845-T9A-T00ZZ	GUSSETR.FR.SIDE FRAME	1	54.10	25	40.57	2.84	43.41
50200-T9A-T01	SUB FRAME COMPFR.SUSPENSION	1	340.50	25	255.37	17.88	273.25
80110-T9A-T01	CONDENSER COMP	1	406.50	25	304.87	21.34	326.21
80341-T9A-T01	PIPE COMPRECEIVER	1	96.10	25	73.57	5.15	78.72
19010-55A-Z51	RADIATOR COMP	1	1,100.50	25	825.37	57.78	883.15
91512-R21-013	CLIPINNER FENDER	1	0.60	25	0.45	0.03	0.48

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3583 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0002895 / MSIG INSURANCE
 Chassis No: MRHGM6660JT000215
 License No: SLT7859X
 Mileage: 49931
 Engine No: L15Z15204215

Document No: SVO19054154
 Printed By: SHNG
 Order Date: 23. August 2019
 Order Time: 2:36:28 PM
 Service Advisor: NG SIN HAI

77810-T9A-T82ZA	MODULE ASSYDRIVER	1	1,780.50	25	1,335.37	93.48	1,428.85
77820-T9A-J80	MODULE ASSYPASSENGER	1	2,236.80	25	1,677.60	117.43	1,795.03
77930-T5A-J01	SENSOR ASSYFR.CRASH	2	63.40	25	95.10	6.66	101.76
77960-T9A-M41	SRS UNIT	1	806.70	25	605.02	42.35	647.37
81450-T9A-T01ZD	TONGUE ASSYR.FR.SEATBELT OUT	1	404.60	25	303.45	21.24	324.69
81850-T9A-T02ZD	TONGUE ASSY,L.FR.SEATBELT	1	404.60	25	303.45	21.24	324.69
60610-T9A-T00ZZ	MEMBER COMPR.FR.WHEELHOUSE UP	1	78.20	25	58.65	4.11	62.76
60843-T9A-T00ZZ	BRACKETR.FR.BUMPER BEAM EXT	1	43.90	25	32.92	2.30	35.22
60846-T9A-T00ZZ	PATCHR.BUMPER BEAM	1	37.20	25	27.90	1.95	29.85
90682-SEA-003	CLIP ABUMPER	4	2.60	25	7.80	0.55	8.35
44305-T9A-T03	DRIVESHAFT ASSYR.	1	685.60	25	514.20	35.99	550.19
51211-T9A-T02	KNUCKLER.FR.	1	94.30	25	70.72	4.95	75.67
51320-T5A-003	LINK COMPR.FR.STABILIZER	1	44.40	25	33.30	2.33	35.63
51350-T5A-J02	ARM ASSY,R.FR.LOWER	1	166.80	25	125.10	8.76	133.86
51611-T9A-T52	ABSORBER UNITR.FR.SHOCK	1	126.90	25	95.17	6.66	101.83
51726-SFA-005	BEARINGDAMPER MT	2	17.60	25	26.40	1.85	28.25
46376-T9A-T00	PIPE W COMPBRAKE	1	5.00	25	3.75	0.26	4.01
53400-T9A-003	BOX ASSYSTEERING GEAR	1	466.70	25	350.02	24.50	374.52
53540-T5R-003	END COMPR.TIE ROD	1	42.90	25	32.17	2.25	34.42
53560-T5R-003	END COMPLTIE ROD	1	42.90	25	32.17	2.25	34.42
76805-T9A-T01	HOSE	1	14.90	25	11.17	0.78	11.95
76806-SYP-N02	MOTORWASHER	1	51.30	25	38.47	2.69	41.16
76841-T9A-T01	TANKWASHER	1	22.20	25	16.65	1.17	17.82
77100-T9A-T10ZA	PANEL COMP, INSTRUMENT	1	1,746.10	25	1,309.57	91.67	1,401.24
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	5	23.20	25	87.00	6.09	93.09
60811-T9A-T00ZZ	FRAMER.FR.SIDE	0	105.90	25	0.00	0.00	0.00
44300-T9C-T61	BEARING ASSY,FR.HUB	1	114.90	25	86.17	6.03	92.20
44600-T5B-J00	HUB ASSYFR.	1	138.30	25	103.72	7.26	110.98
30485005-812000020	IDEMITSU BRAKE FLUID DOT4 0.5L	3	8.23	25	18.52	1.30	19.82
08269-P99-Z8FM1	HONDA HCF 2 CVT FLUID 2 3.5L	1	80.50	25	60.37	4.23	64.60
51300-T9A-T01	SPRINGFR.STABILIZER	1	93.60	25	70.20	4.91	75.11
51306-T9C-T01	BUSHR.FR.STABILIZER HOLDER	1	6.80	25	5.10	0.36	5.46
51307-T9C-T01	BUSHL.FR.STABILIZER HOLDER	1	6.80	25	5.10	0.36	5.46
51308-SWW-P50	BRACKETFR.STABILIER	2	1.80	25	2.70	0.19	2.89
42700-T9A-T72	DISK, ALUMINIUM WHEEL 16X5J	1	415.50	25	311.62	21.81	333.43
19200-RB0-003	PUMP COMPWATER	1	180.30	25	135.22	9.47	144.69
19224-RB0-000	PULLEYWATER PUMP	1	37.00	25	27.75	1.94	29.69
75490-T9A-T01	GARNISH ASSYR.FR.PILLAR CORNE	1	9.60	25	7.20	0.50	7.70
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
76208-T9A-T12	MIRROR SET, R.	1	254.30	25	190.72	13.35	204.07
72410-T9A-T01	MOLDING ASSYR.FR.DOOR	1	21.80	25	16.35	1.14	17.49
	SUM PARTS:				12,566.19	879.61	13,445.80
BOSUN	0701	1	30.00		30.00	2.10	32.10
	SUNDRIES						
BKBH01M	0669	1	2,800.00		2,800.00	196.00	2,996.00
	REMOVE & RENEW BULKHEAD.						
	STRAIGHTEN						
	ALIGN CHASSIS & RENEW DAMAGE						
	PARTS.						
BML01I	1757	1	180.00		180.00	12.60	192.60
	INSPECT FR LIGHTING MECHANISMS &						
	FOCUS						
	HEADLIGHTS.(N)						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0002895 / MSIG INSURANCE
Chassis No: MRHGM6660JT000215
License No: SLT7859X
Mileage: 49931
Engine No: L15Z15204215

Document No: SVO19054154
Printed By: SHNG
Order Date: 23. August 2019
Order Time: 2:36:28 PM
Service Advisor: NG SIN HAI

BP06R	1610	1	1,800.00	1,800.00	126.00	1,926.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)					
BMI00D	0669	1	1,200.00	1,200.00	84.00	1,284.00
	REMOVE & INSTALL DASHBOARD INSTRUMENTAL PANEL					
	AUDIO WIRING HARNESS & ETC.(N)					
BKB01R	0669	1	50.00	50.00	3.50	53.50
	REMOVE AND RENEW RHF WHEEL					
BMS00R	1757	1	1,200.00	1,200.00	84.00	1,284.00
	RENEW BOTH DRIVER & PASSENGER AIRBAG ASSY ECU & RESET SRS SYSTEM.(N)					
BKOT00A	0669	1	1,200.00	1,200.00	84.00	1,284.00
	PLACE VEHICLE TO BENCH FOR CHASSIS FRAME ALIGNMENT					
BMC01D	1757	1	380.00	380.00	26.60	406.60
	REMOVE & INSTALL RADIATOR WITH FITTINGS.					
	PRESSURE TEST COOLING SYSTEM.(N)					
BMA01D	1757	1	330.00	330.00	23.10	353.10
	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.					
	VACUUM & RECHARGE A/C GAS.(N)					
BMU01R	1757	1	1,680.00	1,680.00	117.60	1,797.60
	REMOVE & REPLACE FR UNDERCARRIAGE PARTS.(N)					
BC012R	1757	1	560.00	560.00	39.20	599.20
	RESET VEHICLE SMART ENTRY SYSTEM					
BML12R	1757	1	1,120.00	1,120.00	78.40	1,198.40
	REMOVE & RENEW ENGINE WIRE HARNESS. RESET ECU MEMORIES					
BMS02R	1757	1	1,120.00	1,120.00	78.40	1,198.40
	REMOVE & RENEW SEATBELT TENSIONER, ECU & CRASH SEN RESET SYSTEM.					
BKBH12M		1	1,680.00	1,680.00	117.60	1,797.60
	RENEW WHEELHOUSE & CHASSIS FRAME.					
	INCLUDING STRAIGHTEN AND FITTING ATTACHMENT ITEMS (A)					
BME00D		1	1,680.00	1,680.00	117.60	1,797.60
	REMOVE & INSTALL ENGINE ASSY GEARBOX & OTHERS ATTACHMENT PARTS.(N) (A)					
BP03R		1	1,350.00	1,350.00	94.50	1,444.50
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P) (A)					
SUM LABOUR:			18,360.00	1,285.20		19,645.20
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	180.00	12.60	192.60
SUM EXT SERVICE:			180.00	12.60		192.60
TOTAL SGD			31,106.19	2,177.41		33,283.60
Total Payable (SGD)						33,283.60

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0002895 / B.W. TRANS
Chassis No: MRHGM6660JT000215
License No: SLT7859X
Mileage: 49931
Engine No: L15Z15204215

Document No: SVO19054154
Printed By: SHNG
Order Date: 23. August 2019
Order Time: 2:36:28 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incl GST
	SUPPLEMENTARY PARTS AND LABOUR						
60610-T9A-T00ZZ	MEMBER COMPR.FR.WHEELHOUSE UP	1	78.20	25	58.65	4.11	62.76
60843-T9A-T00ZZ	BRACKETR.FR.BUMPER BEAM EXT <i>ren</i>	1	43.90	25	32.92	2.30	35.22
60846-T9A-T00ZZ	PATCHR.BUMPER BEAM <i>ren</i>	1	37.20	25	27.90	1.95	29.85
90682-SEA-003	CLIP ABUMPER <i>ren</i>	4	2.50	25	7.80	0.55	8.35
44305-T9A-T03	DRIVESHAFT ASSYR. <i>bt</i>	1	685.60	25	514.20	35.99	550.19
51211-T9A-T02	KNUCKLER.FR. <i>bt</i>	1	94.30	25	70.72	4.95	75.67
51320-T5A-003	LINK COMPR.FR.STABILIZER <i>bt</i>	1	44.40	25	33.30	2.33	35.63
51350-T5A-J02	ARM ASSY,R.FR.LOWER <i>bt</i>	1	166.80	25	125.10	8.76	133.86
51611-T9A-T52	ABSORBER UNITR.FR.SHOCK <i>bt</i>	1	126.90	25	95.17	6.66	101.83
51726-SFA-005	BEARINGDAMPER MT <i>ren</i>	2	17.60	25	26.40	1.85	28.25
46376-T9A-T00	PIPE W COMPBRAKE <i>ren</i>	1	5.00	25	3.75	0.26	4.01
53400-T9A-003	BOX ASSYSTEEING GEAR <i>5cc</i>	1	466.70	25	350.02	24.50	374.52
53540-T5R-003	END COMPR.TIE ROD <i>bt</i>	1	42.90	25	32.17	2.25	34.42
53560-T5R-003	END COMPL.TIE ROD <i>bt</i>	1	42.90	25	32.17	2.25	34.42
76805-T9A-T01	HOSE <i>cut</i>	1	14.90	25	11.17	0.78	11.95
76806-SYP-N02	MOTORWASHER <i>ren</i>	1	51.30	25	38.47	2.69	41.16
76841-T9A-T01	TANKWASHER <i>ren</i>	1	22.20	25	16.65	1.17	17.82
77100-T9A-T10ZA	PANEL COMP. INSTRUMENT <i>bt</i>	1	1,746.10	25	1,309.57	91.67	1,401.24
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2 <i>ren</i>	5	23.20	25	87.00	6.09	93.09
60811-T9A-T00ZZ	FRAMER.FR.SIDE <i>bt x 5cc</i>	0	105.90	25	0.00	0.00	0.00
44300-T9C-T61	BEARING ASSY,FR.HUB <i>bt</i>	1	114.90	25	86.17	6.03	92.20
44600-T5B-J00	HUB ASSYFR <i>bt</i>	1	138.30	25	103.72	7.26	110.98
30485005-812000020	IDEMITSU BRAKE FLUID DOT4 0.5L <i>ren</i>	3	8.23	25	18.52	1.30	19.82
08269-P99-Z8FM1	HONDA HCF 2 CVT FLUID 2 3.5L <i>ren</i>	1	80.50	25	60.37	4.23	64.60
51300-T9A-T01	SPRINGFR.STABILIZER <i>ren</i>	1	93.60	25	70.20	4.91	75.11
51306-T9C-T01	BUSHR.FR.STABILIZER HOLDER <i>ren</i>	1	6.80	25	5.10	0.36	5.46
51307-T9C-T01	BUSHL.FR.STABILIZER HOLDER <i>ren</i>	1	6.80	25	5.10	0.36	5.46
51308-SWW-P50	BRACKETFR.STABILIER <i>ren</i>	2	1.80	25	2.70	0.19	2.89
42700-T9A-T72	DISK, ALUMINIUM WHEEL 16X6J <i>cut</i>	1	415.50	25	311.62	21.81	333.43
19200-RB0-003	PUMP COMPWATER <i>cut</i>	1	180.30	25	135.22	9.47	144.69
19224-RB0-000	PULLEYWATER PUMP <i>cut</i>	1	37.00	25	27.75	1.94	29.69
75490-T9A-T01	GARNISH ASSYR.FR.PILLAR CORNE <i>ren</i>	1	9.60	25	7.20	0.50	7.70
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>mt</i>	1	45.00		45.00	3.15	48.15
76208-T9A-T12	MIRROR SET, R. <i>cut</i>	1	254.30	25	190.72	13.35	204.07
72410-T9A-T01	MOLDING ASSYR.FR.DOOR <i>ren</i>	1	21.80	25	16.35	1.14	17.49
	SUM PARTS:				3,958.87	277.11	4,235.98
BKBH12M	RENEW WHEELHOUSE & CHASSIS FRAME. INCLUDING STRAIGHTEN AND FITTING ATTACHMENT ITEMS	1	1,680.00		1,680.00	117.60	1,797.60
BME00D	REMOVE & INSTALL ENGINE ASSY GEARBOX & OTHERS ATTACHMENT PARTS.(N)	1	1,680.00		1,680.00	117.60	1,797.60
BP03R		1	1,350.00		1,350.00	94.50	1,444.50

Rept



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0002895 / B.W. TRANS
Chassis No: MRHGM6660JT000215
License No: SLT7859X
Mileage: 49931
Engine No: L15Z15204215

Document No: SVO19054154
Printed By: SHNG
Order Date: 23. August 2019
Order Time: 2:36:28 PM
Service Advisor: NG SIN HAI

SPRAY PAINTING ON REPAIRED OR
REPLACED AREAS.(3P)

SUM LABOUR:	4,710.00	329.70	5,039.70
TOTAL SGD	8,668.87	606.81	9,275.68

Total Payable (SGD) **9,275.68**

GST Amount is calculated from individual line(s)

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 11 October 2019 12:25 PM
To: Rasul (LKKAUTO); Ng Sin Hai; SUR
Subject: RE: Submission Pre-Invoice for vehicle SLT7859X

Dear Sin Hai,

WITHOUT PREJUDICE

Confirmed cost of repair : \$31,106.19 (before GST)
No of working days : **23 days**

Kindly send Final invoice and all supporting documents directly to MSIG INSURANCE

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Friday, 11 October 2019 12:14 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; Ng Sin Hai <shng@kahmotor.onmicrosoft.com>; SUR <sur@lkkauto.com>
Subject: RE: Submission Pre-Invoice for vehicle SLT7859X

Dear Sin Hai,

WITHOUT PREJUDICE

Confirmed cost of repair : \$31,106.19 (before GST)
No of working days : **20 days** instead of 24 days.

Please check and confirm

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Sent: Thursday, 3 October 2019 10:09 AM
To: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>

Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: RE: Submission Pre-Invoice for vehicle SLT7859X

Hi Sin Hai,

As spoken, kindly assist

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Rasul (LKKAuto)

Sent: Monday, 30 September, 2019 1:58 PM

To: Ng Sin Hai

Subject: RE: Submission Pre-Invoice for vehicle SLT7859X

Hi Sin Hai,

Which photos shows box,assy steering gear, end compr tie rod, panel comp. instrument? For end compr tie rod is it 2 pieces?

And as for the labour part, can I have the photos for the remove engine and gearbox photos?

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Ng Sin Hai [<mailto:shng@kahmotor.onmicrosoft.com>]

Sent: Thursday, 26 September, 2019 2:04 PM

To: Rasul (LKKAuto); SUR

Subject: RE: Submission Pre-Invoice for vehicle SLT7859X

Dear Rasul,

Due to the extra labour and the intensive repair of this car, we would like to request for 24 days for the repair.

Kindly refer to the attached pdf for the pre-invoice final repair cost amount for abovementioned vehicle .

Cost of repair : \$31,106.19 (before GST)

No of working days : 24 days. (LOR)

We will proceed for closing after 1 week of submission to you.

Kindly contact me if there is any discrepancy.

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

HP: 9072 1769

E-mail: shng@honda.com.sg



BLUE SKIES FOR
OUR CHILDREN



Visit our
Facebook page



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Aug 2019		22 Aug 2019 08:40 Edit Adj Rpt	S\$31,106.19 Edit Estimates	S\$31,106.19 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	FAVOURITE CAR RENTAL PTE LTD, Co. Reg. No.: 201838589K								
Main Claimant:	B. W. TRANS, Co. Reg. No.: 53369611M								
Vehicle Reg. No.:	SLT7859X	Date of Loss:	19/08/2019 07:00 - :59 [21 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 603305	Policy/Cover Note No.:	29110539 (Comprehensive) Coverage: 06/12/2018 - 05/12/2019						
Vehicle Reg. No. (Insured):	SMK4105T	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 21/09/2019]								
Driver/Custodian (Insured):	SDH HWA BENG (55 / Male), NRIC: S1628911F, Tel: +6594872351 Email:								
Adj Asg. Remarks:	on WP. Liab: 100%. Contact: Sin Hai @ 6471 5419 / 9072 1769. Manual assign to LKK via email on 21/08/2019.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT7859X (603305)
[SMK4105T]
TP
B. W. TRANS
Aug 19 2019 7:00AM
[FAVOURITE CAR RENTAL PTE LTD]
Kah Motor Co Sdn Bhd

Upload Documents

Upload Photos

Compose New Letter

ViewView in Browser

Video

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/08/19 10:40	Video - Accident (TP)	Load MOV	

Assessment Reports

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/08/19 16:43	Accident Statement From: SC - Reg. No: SMK4105T, Claimant: FAVOURITE CAR RENTAL PTE LTD	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/08/19 09:45	Adjuster Immediate Advice	Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/10/19 11:46	General View	Load JPG	☒
2	11/10/19 11:46	General View	Load JPG	☒
3	11/10/19 11:46	General View	Load JPG	☒
4	11/10/19 11:46	General View	Load JPG	☒
5	11/10/19 11:46	General View	Load JPG	☒
6	11/10/19 11:46	General View	Load JPG	☒
7	11/10/19 11:46	General View	Load JPG	☒
8	11/10/19 11:46	General View	Load JPG	☒
9	11/10/19 11:46	General View	Load JPG	☒
10	11/10/19 11:46	General View	Load JPG	☒
11	11/10/19 11:46	General View	Load JPG	☒
12	11/10/19 11:46	General View	Load JPG	☒
13	11/10/19 11:46	General View	Load JPG	☒
14	11/10/19 11:46	General View	Load JPG	☒
15	11/10/19 11:46	General View	Load JPG	☒
16	11/10/19 11:46	General View	Load JPG	☒
17	11/10/19 11:46	General View	Load JPG	☒
18	11/10/19 11:46	General View	Load JPG	☒
19	11/10/19 11:46	General View	Load JPG	☒
20	11/10/19 11:46	General View	Load JPG	☒
21	11/10/19 11:46	General View	Load JPG	☒
22	11/10/19 11:46	General View	Load JPG	☒
23	11/10/19 11:46	General View	Load JPG	☒
24	11/10/19 11:46	General View	Load JPG	☒
25	11/10/19 11:46	General View	Load JPG	☒
26	11/10/19 11:46	General View	Load JPG	☒
27	11/10/19 11:46	General View	Load JPG	☒
28	11/10/19 11:46	General View	Load JPG	☒
29	11/10/19 11:46	General View	Load JPG	☒
30	11/10/19 11:46	General View	Load JPG	☒
31	11/10/19 11:46	General View	Load JPG	☒
32	11/10/19 11:46	General View	Load JPG	☒
33	11/10/19 11:46	General View	Load JPG	☒
34	11/10/19 11:46	General View	Load JPG	☒

Video			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
35	11/10/19 11:46	General View	 Load JPG	☒
36	11/10/19 11:46	General View	 Load JPG	☒
37	11/10/19 11:46	General View	 Load JPG	☒
38	11/10/19 11:46	General View	 Load JPG	☒
39	11/10/19 11:46	General View	 Load JPG	☒
40	11/10/19 11:46	General View	 Load JPG	☒
41	11/10/19 11:46	General View	 Load JPG	☒
42	11/10/19 11:46	General View	 Load JPG	☒
43	11/10/19 11:46	General View	 Load JPG	☒
44	11/10/19 11:46	General View	 Load JPG	☒
45	11/10/19 11:46	General View	 Load JPG	☒
46	11/10/19 11:46	General View	 Load JPG	☒
47	11/10/19 11:46	General View	 Load JPG	☒
48	11/10/19 11:46	General View	 Load JPG	☒
49	11/10/19 11:46	General View	 Load JPG	☒
50	11/10/19 11:46	General View	 Load JPG	☒
51	11/10/19 11:46	General View	 Load JPG	☒
52	11/10/19 11:46	General View	 Load JPG	☒
53	11/10/19 11:46	General View	 Load JPG	☒
54	11/10/19 11:46	General View	 Load JPG	☒
55	11/10/19 11:46	General View	 Load JPG	☒
56	11/10/19 11:46	General View	 Load JPG	☒
57	11/10/19 11:46	General View	 Load JPG	☒
58	11/10/19 11:46	General View	 Load JPG	☒
59	11/10/19 11:46	General View	 Load JPG	☒
60	11/10/19 11:46	General View	 Load JPG	☒
61	11/10/19 11:46	General View	 Load JPG	☒
62	11/10/19 11:46	General View	 Load JPG	☒
63	11/10/19 11:47	General View	 Load JPG	☒
64	11/10/19 11:47	General View	 Load JPG	☒
65	11/10/19 11:47	General View	 Load JPG	☒
66	11/10/19 11:47	General View	 Load JPG	☒
67	11/10/19 11:47	General View	 Load JPG	☒
68	11/10/19 11:47	General View	 Load JPG	☒
69	11/10/19 11:47	General View	 Load JPG	☒
70	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
71	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
72	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
73	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
74	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
75	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
76	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
77	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
78	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
79	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
80	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
81	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
82	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
83	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
84	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
85	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
86	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
87	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
88	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
89	11/10/19 12:03	Reinspection Photo	Load JPG	☒
90	11/10/19 12:03	Reinspection Photo	Load JPG	☒

Video			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
91	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
92	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
93	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
94	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
95	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
96	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
97	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
98	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
99	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
100	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
101	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
102	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
103	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
104	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
105	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
106	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
107	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
108	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
109	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
110	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
111	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
112	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
113	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
114	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
115	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
116	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
117	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
118	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
119	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
120	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
121	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
122	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
123	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
124	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
125	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
126	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
127	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
128	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
129	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
130	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
131	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
132	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
133	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
134	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
135	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
136	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
137	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
138	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
139	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
140	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
141	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
142	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
143	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
144	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
145	11/10/19 12:03	Reinspection Photo	 Load JPG	☒
146	11/10/19 12:03	Reinspection Photo	Load JPG	☒

Video			1 per page	☒
No.	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
147	11/10/19 12:03	Reinspection Photo		☒
148	11/10/19 12:03	Reinspection Photo		☒
149	11/10/19 12:03	Reinspection Photo		☒
150	11/10/19 12:03	Reinspection Photo		☒
151	11/10/19 12:03	Reinspection Photo		☒
152	11/10/19 12:03	Reinspection Photo		☒
153	11/10/19 12:03	Reinspection Photo		☒
154	11/10/19 12:03	Reinspection Photo		☒
155	11/10/19 12:03	Reinspection Photo		☒
156	11/10/19 12:03	Reinspection Photo		☒
157	11/10/19 12:03	Reinspection Photo		☒
158	11/10/19 12:03	Reinspection Photo		☒
159	11/10/19 12:03	Reinspection Photo		☒
160	11/10/19 12:03	Reinspection Photo		☒
161	11/10/19 12:03	Reinspection Photo		☒
162	11/10/19 12:03	Reinspection Photo		☒
163	11/10/19 12:03	Reinspection Photo		☒
164	11/10/19 12:03	Reinspection Photo		☒
165	11/10/19 12:03	Reinspection Photo		☒
166	11/10/19 12:03	Reinspection Photo		☒
167	11/10/19 12:03	Reinspection Photo		☒
168	11/10/19 12:03	Reinspection Photo		☒
169	11/10/19 12:03	Reinspection Photo		☒
170	11/10/19 12:03	Reinspection Photo		☒
171	11/10/19 12:03	Reinspection Photo		☒
172	11/10/19 12:03	Reinspection Photo		☒
173	11/10/19 12:03	Reinspection Photo		☒
174	11/10/19 12:03	Reinspection Photo		☒
175	11/10/19 12:03	Reinspection Photo		☒
176	11/10/19 12:03	Reinspection Photo		☒
177	11/10/19 12:03	Reinspection Photo		☒
178	11/10/19 12:03	Reinspection Photo		☒
179	11/10/19 12:03	Reinspection Photo		☒
180	11/10/19 12:03	Reinspection Photo		☒
181	11/10/19 12:03	Reinspection Photo		☒
182	11/10/19 12:03	Reinspection Photo		☒
183	11/10/19 12:03	Reinspection Photo		☒
184	11/10/19 12:03	Reinspection Photo		☒
185	11/10/19 12:03	Reinspection Photo		☒
186	11/10/19 12:03	Reinspection Photo		☒
187	11/10/19 12:03	Reinspection Photo		☒
188	11/10/19 12:03	Reinspection Photo		☒
189	11/10/19 12:03	Reinspection Photo		☒
190	11/10/19 12:03	Reinspection Photo		☒
191	11/10/19 12:03	Reinspection Photo		☒
192	11/10/19 12:03	Reinspection Photo		☒
193	11/10/19 12:03	Reinspection Photo		☒
194	11/10/19 12:03	Reinspection Photo		☒
195	11/10/19 12:03	Reinspection Photo		☒
196	11/10/19 12:03	Reinspection Photo		☒
197	11/10/19 12:03	Reinspection Photo		☒
198	11/10/19 12:03	Reinspection Photo		☒
199	11/10/19 12:03	Reinspection Photo		☒
200	11/10/19 12:03	Reinspection Photo		☒
201	11/10/19 12:03	Reinspection Photo		☒
202	11/10/19 12:03	Reinspection Photo		☒

Video				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
203	11/10/19 12:03	Reinspection Photo		Load JPG	☒
204	11/10/19 12:03	Reinspection Photo		Load JPG	☒
205	11/10/19 12:03	Reinspection Photo		Load JPG	☒
206	11/10/19 12:03	Reinspection Photo		Load JPG	☒
207	11/10/19 12:03	Reinspection Photo		Load JPG	☒
208	11/10/19 12:03	Reinspection Photo		Load JPG	☒
209	11/10/19 12:03	Reinspection Photo		Load JPG	☒
210	11/10/19 12:03	Reinspection Photo		Load JPG	☒
211	11/10/19 12:03	Reinspection Photo		Load JPG	☒
212	11/10/19 12:03	Reinspection Photo		Load JPG	☒
213	11/10/19 12:03	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	21/08/19 16:45	TPD SLT7859X GIA REPORT		Load PDF	
2	21/08/19 16:46	TPD SMK4105T - PRI		Load PDF	
3	21/08/19 17:28	Acknowledge PRI		Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail	Print
1	21/08/19 17:46	email from pic		Load PDF	
2	22/08/19 08:37	Survey Request - Manual Assigned		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014764/R1VF3E2

Date: 23/10/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29110539

Claimant Vehicle No : SLT7859X

Insured Vehicle No : SMK4105T

Date of Loss: 19/08/2019

Nature of Claim: TP

Claim No: 603305

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT7859X

Make & Model: HONDA CITY, 1.5 SV CVT (A)

Engine No: L15Z15204215

Reg. Date: 13/11/2017 (Man. Year: 2017)

Chassis No: MRHGM6660JT000215

Colour: Black

Odometer: 0 km

Engine Capacity: 1497 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R14

Rear Tyre Size: 185/55 R14

Front Left Side: Dunlop 5 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,284.08	12,596.19	4,687.89	27.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	30,330.00	18,510.00	11,820.00	38.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	47,614.08	31,106.19	16,507.89	34.67
+ GST 7.00/7.00% (S\$)	3,332.99	2,177.43	1,155.56	34.67
Nett Amount (S\$)	50,947.07	33,283.62	17,663.45	34.67

INSPECTION

Date of Assignment: 22/08/2019

Date Inspected: 23/08/2019 Inspected At:

Kah Motor Co Sdn Bhd
(ALEXANDRA)
255 ALEXANDRA ROAD
Singapore 159937

Estimated Period of Repair: 23.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Oct 2019)
Parts:	143	HONDA CITY 1.5 SV CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT7859X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACEFR.BUMPER	Deformed	344.85 FS	*344.85 FS
2	1		*GARNISHR.FR.FOGLIGHT	Missing	17.70 FS	*9.45 FS
3	1		*GRILLEFR.BUMPER LOWER	Serviceable	66.00 FS	*- FS
4	1		*COVERFR.TOWING HOOK T99	Cut	11.10 FS	*8.92 FS
5	1		*GARNISHL.FR.FOG LIGHT	Serviceable	17.70 FS	*- FS
6	1		*SCREENR.FR.BUMPER AIR	Serviceable	14.70 FS	*- FS
7	1		*SPOILERFR.BUMPER LIP	Serviceable	8.40 FS	*- FS
8	1		*SCREENL.FR.BUMPER AIR	Serviceable	14.70 FS	*- FS
9	1		*BEAM COMPFR.BUMPER	Bent	182.32 FS	*182.32 FS
10	1		*BEAMR.FR.BUMPER UPPER	Necessary	20.62 FS	*20.62 FS
11	1		*BEAML.FR.BUMPER UPPER	Necessary	20.62 FS	*20.62 FS
12	1		*SPACERR.FR.BUMPER SIDE	Necessary	7.80 FS	*7.80 FS
13	1		*SPACERL.FR.BUMPER SIDE	Necessary	7.80 FS	*7.80 FS
14	1		*CLIP, BUMPER (11PCS)	Necessary	18.97 FS	*18.97 FS
15	1		*BASEFR.GRILLE	Serviceable	65.17 FS	*- FS
16	1		*MOLDINGFR.GRILLE UPPER	Serviceable	138.22 FS	*- FS
17	1		*COVERFR.GRILLE	Cut	24.67 FS	*24.67 FS
18	1		*MOLDINGFR.GRILLE LOWER	Cut	34.87 FS	*34.87 FS
19	1		*SCREENFR.GRILLE UPPER AIR	Serviceable	11.25 FS	*- FS
20	1		*STAYFR.GRILLE	Necessary	5.17 FS	*5.17 FS
21	1		*EMBLEM (H)	Necessary	17.17 FS	*11.25 FS
22	1		*NUTPUSH 3MM (2PCS)	Necessary	3.15 FS	*3.15 FS
23	1		*HEADLIGHT ASSY, R	Cracked	424.27 FS	*424.27 FS
24	1		*HEADLIGHT ASSYL	Serviceable	243.07 FS	*- FS
25	1		*LIGHT ASSYFR.FOG	Cracked	229.42 FS	*229.42 FS
26	2		*MOLDINGFR.WINDSHIELD SIDE	Serviceable	8.70 FS	*- FS
27	1		*RUBBER BFR W/SHIELD	Serviceable	2.77 FS	*- FS
28	1		*RUBBER, W/SHIELD	Serviceable	10.80 FS	*- FS
29	1		*MOLDINGFR.WINDSHIELD	Serviceable	14.10 FS	*- FS
30	1		*IU BRACKET TAPE	Serviceable	26.00 FS	*- FS
31	2		*WINDSCREEN SEALANT	Serviceable	120.00 FS	*- FS
32	1		*HOOD COMPENGINE	Repair	313.72 FS	*- FS
33	1		*HINGE COMPR.HOOD	Serviceable	24.45 FS	*- FS
34	1		*HINGE COMPL.HOOD	Serviceable	24.45 FS	*- FS
35	1		*LOCK ASSYHOOD	Serviceable	67.12 FS	*- FS
36	1		*RUBBERR.FR.HOOD SEAL	Serviceable	4.80 FS	*- FS
37	1		*RUBBERL.FR.HOOD SEAL	Serviceable	4.80 FS	*- FS
38	1		*WIRE ASSYHOOD	Serviceable	21.37 FS	*- FS
39	1		*INSULATORHOOD	Serviceable	31.20 FS	*- FS
40	1		*RUBBERR.HOOD SEAL	Serviceable	8.55 FS	*- FS
41	1		*RUBBERRR.HOOD SEAL	Necessary	16.42 FS	*16.42 FS
42	1		*RUBBERHOOD SIDE SEAL	Serviceable	2.70 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*STAYHOOD OPEN	Serviceable	9.37 FS	*- FS
44	1		*RUBBERL.HOOD SEAL	Serviceable	8.55 FS	*- FS
45	1		*COWL TOP SETFR.	Necessary	41.70 FS	*41.70 FS
46	1		*NOZZLE ASSY	Serviceable	11.92 FS	*- FS
47	1		*JOINT YTUBE	Serviceable	6.67 FS	*- FS
48	1		*LABELAIR CONDITIONER CAUTION	Not Necessary	1.35 FS	*- FS
49	1		*LABELCOOLANT INFORMATION	Not Necessary	3.75 FS	*- FS
50	1		*PANEL COMP,R.FR.FENDER	Buckled	202.95 FS	*202.95 FS
51	1		*PANEL COMPL.FR.FENDER	Serviceable	202.95 FS	*- FS
52	1		*FENDER ASSYR.FR INNER	Deformed	57.60 FS	*57.60 FS
53	1		*ENCLOSURER.FR.FENDER	Necessary	5.02 FS	*5.02 FS
54	1		*COVERENGINE UNDER	Deformed	37.87 FS	*37.87 FS
55	1		*GUARDR.FR.SPLASH	Deformed	15.07 FS	*15.07 FS
56	1		*FENDER ASSYL.FR INNER	Serviceable	57.60 FS	*- FS
57	1		*ENCLOSUREL.FR.FENDER	Serviceable	5.02 FS	*- FS
58	1		*GUARDL.FR.SPLASH	Serviceable	14.62 FS	*- FS
59	1		*COVERR.FR.FENDER	Serviceable	14.62 FS	*- FS
60	1		*COVERL.FR.FENDER	Serviceable	14.62 FS	*- FS
61	18		*CLIP, INNER FENDER	Necessary	37.80 FS	*37.80 FS
62	1		*CLIPUNDER COVER	Necessary	1.20 FS	*1.20 FS
63	1		*BULKHEAD COMP,FR.	Bent	253.35 FS	*253.35 FS
64	1		*EXTENSION SETR.FR.SHOCK ABS	Bent	63.00 FS	*63.00 FS
65	1		*EXTENSION SETL.FR.SHOCK ABS	Serviceable	63.00 FS	*- FS
66	1		*BRACKETR.FR.FENDER B	Necessary	17.17 FS	*17.17 FS
67	1		*BRACKETR.FR.FENDER A	Necessary	21.60 FS	*21.60 FS
68	1		*BASE COMPBATTERY SETTING	Serviceable	19.42 FS	*- FS
69	1		*HOUSING SETR.FR.SHOCK ABS	Bent	164.47 FS	*164.47 FS
70	1		*MEMBER COMPL.FR.WHEELHOUSE UP	Bent	58.65 FS	*58.65 FS
71	1		*BRACKETL.FR.FENDER B	Serviceable	18.60 FS	*- FS
72	1		*BRACKETL.FR.FENDER A	Serviceable	21.60 FS	*- FS
73	1		*HOUSING SET,L.FR.SHOCK ABS	Serviceable	164.47 FS	*- FS
74	1		*FRAME COMPR.FR.SIDE	Buckled	389.62 FS	*389.62 FS
75	1		*PLATER.FR.SIDE BACK	Bent	74.77 FS	*74.77 FS
76	1		*PLATER.SIDE FRAME GUSSET	Necessary	33.37 FS	*33.37 FS
77	1		*GUSSETR.FR.SIDE FRAME	Necessary	40.57 FS	*40.57 FS
78	1		*FRAME COMPL.FR.SIDE	Serviceable	389.62 FS	*- FS
79	1		*PLATEL.FR.SIDE BACK	Serviceable	74.77 FS	*- FS
80	1		*PLATEL.SIDE FRAME GUSSET	Serviceable	33.37 FS	*- FS
81	1		*GUSSET.FR.SIDE FRAME	Serviceable	40.57 FS	*- FS
82	1		*SUB FRAME COMPFR.SUSPENSION	Bent	255.37 FS	*255.37 FS
83	1		*STAYRR.SUB FRAME	Serviceable	1.65 FS	*- FS
84	1		*STAYR.GEAR BOX	Serviceable	2.02 FS	*- FS
85	1		*STAYL.GEAR BOX	Serviceable	2.02 FS	*- FS
86	1		*BRACKETTORQUE ROD CVT	Serviceable	26.85 FS	*- FS
87	1		*RUBBER SUB ASSYENGIN SIDE MTG	Serviceable	95.85 FS	*- FS
88	1		*RUBBER ASSYTRANSMISSION MTG	Serviceable	83.55 FS	*- FS
89	1		*RODTORQUE CVT	Serviceable	32.55 FS	*- FS
90	1		*BRACKET ENGINE SIDE MOUNTING	Serviceable	40.50 FS	*- FS
91	1		*RUBBER ENGINE SIDE MOUNTING	Serviceable	1.87 FS	*- FS
92	1		*CONDENSER COMP	Bent	304.87 FS	*304.87 FS
93	1		*MOUNTCONDENSER UPPER	Serviceable	2.77 FS	*- FS
94	1		*BRACKETR.CONDENSER UPPER	Serviceable	1.20 FS	*- FS
95	1		*MOUNTCONDENSER LOWER	Serviceable	2.77 FS	*- FS
96	1		*HOSE COMPSUCTION	Serviceable	70.80 FS	*- FS
97	1		*HOSE COMPDISCHARGE	Serviceable	68.32 FS	*- FS
98	1		*PIPE COMPAIR CONDITIONER	Serviceable	73.20 FS	*- FS
99	1		*PIPE COMPRECEIVER	Bent	73.57 FS	*73.57 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
100	1		*SENSOR ASSYAMBIENT	Serviceable	32.55 FS	*- FS
101	1		*CLIPAMBIENT SENSOR	Serviceable	0.82 FS	*- FS
102	1		*RADIATOR COMP	Bent	825.37 FS	*825.37 FS
103	1		*SHROUD COMP	Serviceable	43.27 FS	*- FS
104	1		*FAN COMPCOOLING	Serviceable	16.05 FS	*- FS
105	1		*MOTOR, COOLING FAN	Serviceable	158.32 FS	*- FS
106	1		*FAN COMPCOOLING	Serviceable	41.40 FS	*- FS
107	1		*SHROUD COMP	Serviceable	16.65 FS	*- FS
108	1		*MOTORCOOLING FAN	Serviceable	150.22 FS	*- FS
109	1		*SPACER	Serviceable	2.85 FS	*- FS
110	1		*TANK RESERVE	Serviceable	7.65 FS	*- FS
111	1		*CAP RESERVE TANK	Serviceable	6.22 FS	*- FS
112	1		*HOSERESERVE TANK	Serviceable	1.57 FS	*- FS
113	1		*JOINTRESERVE TANK	Serviceable	5.32 FS	*- FS
114	1		*HOSEWATER UPPER	Serviceable	5.02 FS	*- FS
115	1		*HOSEWATER LOWER	Serviceable	9.15 FS	*- FS
116	1		*BRACKETR.RADIATOR UPPER MOUNT	Serviceable	4.20 FS	*- FS
117	1		*CUSHIONRADIATOR LOWER	Serviceable	8.55 FS	*- FS
118	1		*CUSHIONRADIATOR UPP	Serviceable	3.00 FS	*- FS
119	1		*BRACKETL.RADIATOR UPPER MOUNT	Serviceable	4.20 FS	*- FS
120	1		*CASE SETAIR CLEANER	Serviceable	40.05 FS	*- FS
121	1		*COVER COMPAIR CLEANER	Serviceable	15.75 FS	*- FS
122	1		*STAY COMP BAIR CLEANER	Serviceable	1.72 FS	*- FS
123	1		*STAY COMP AAIR CLEANER	Serviceable	5.40 FS	*- FS
124	1		*ELEMENT ASSYAIR CLEANER	Serviceable	24.00 FS	*- FS
125	1		*SENSOR ASSYAIR TEMP	Serviceable	7.50 FS	*- FS
126	1		*GROMMETTA SENSOR	Serviceable	1.80 FS	*- FS
127	1		*SEPARATORSPLASH	Serviceable	4.27 FS	*- FS
128	1		*TUBEAIR INTAKE	Serviceable	13.95 FS	*- FS
129	1		*DUCT ASSYAIR INTAKE	Serviceable	32.25 FS	*- FS
130	1		*CLIPINNER FENDER	Necessary	0.45 FS	*0.45 FS
131	1		*BATTERY-MAINTENANCE FREE	Serviceable	125.00 FS	*- FS
132	1		*MODULE ASSYDRIVER	Activated	1,335.37 FS	*1,335.37 FS
133	1		*MODULE ASSYPASSENGER	Activated	1,677.60 FS	*1,677.60 FS
134	2		*SENSOR ASSYFR.CRASH	Necessary	95.10 FS	*95.10 FS
135	1		*SRS UNIT	Activated	605.02 FS	*605.02 FS
136	1		*TONGUE ASSYR.FR.SEATBELT OUT	Activated	303.45 FS	*303.45 FS
137	1		*TONGUE ASSY,L.FR.SEATBELT	Activated	303.45 FS	*303.45 FS
138	1		*GLASS SET, FR.WINDSHIELD GREEN	Serviceable	807.07 FS	*- FS
139	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
140	1		*MEMBER COMPR.FR.WHEELHOUSE UP	Repeated	58.65 FS	*- FS
141	1		*BRACKETR.FR.BUMPER BEAM EXT	Necessary	32.92 FS	*32.92 FS
142	1		*PATCHR.BUMPER BEAM	Necessary	27.90 FS	*27.90 FS
143	4		*CLIP ABUMPER	Necessary	7.80 FS	*7.80 FS
144	1		*DRIVESHAFT ASSYR	Bent	514.20 FS	*514.20 FS
145	1		*KNUCKLER.FR	Bent	70.72 FS	*70.72 FS
146	1		*LINK COMPR.FR.STABILIZER	Bent	33.30 FS	*33.30 FS
147	1		*ARM ASSY,R.FR.LOWER	Bent	125.10 FS	*125.10 FS
148	1		*ABSORBER UNITR.FR.SHOCK	Bent	95.17 FS	*95.17 FS
149	2		*BEARINGDAMPER MT	Necessary	26.40 FS	*26.40 FS
150	1		*PIPE W COMPBRAKE	Necessary	3.75 FS	*3.75 FS
151	1		*BOX ASSYSTEEING GEAR	Scratched	350.02 FS	*350.02 FS
152	1		*END COMPR.TIE ROD	Bent	32.17 FS	*32.17 FS
153	1		*END COMPL.TIE ROD	Bent	32.17 FS	*32.17 FS
154	1		*HOSE	Cut	11.17 FS	*11.17 FS
155	1		*MOTORWASHER	Necessary	38.47 FS	*38.47 FS
156	1		*TANKWASHER	Necessary	16.65 FS	*16.65 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
157	1		*PANEL COMP.INSTRUMENT	Bent	1,309.57 FS	*1,309.57 FS
158	5		*COOLANT ANTI-FREEZE TYPE 2	Necessary	87.00 FS	*87.00 FS
159	1		*FRAMER.FR.SIDE (NPA)	Serviceable	0.00 FS	*- FS
160	1		*BEARING ASSY,FR.HUB	Bent	86.17 FS	*86.17 FS
161	1		*HUB ASSYFR.	Bent	103.72 FS	*103.72 FS
162	1		*IDEMITSU BRAKE FLUID DOT 4 0.5L (3PCS)	Necessary	18.52 FS	*18.52 FS
163	1		*HONDA HCF 2 CVT FLUID 2 3.5L	Necessary	60.37 FS	*60.37 FS
164	1		*SPRINGFR.STABILIZER	Necessary	70.20 FS	*70.20 FS
165	1		*BUSHR.FR.STABIIZER HOLDER	Necessary	5.10 FS	*5.10 FS
166	1		*BUSHL.FR.STABILIZER HOLDER	Necessary	5.10 FS	*5.10 FS
167	2		*BRACKETFR.STABILIZER	Necessary	2.70 FS	*2.70 FS
168	1		*DISK,ALUMINIUM WHEEL 16X6J	Cut	311.62 FS	*311.62 FS
169	1		*PUMP COMPWATER	Cut	135.22 FS	*135.22 FS
170	1		*PULLEYWATER PUMP	Cut	27.75 FS	*27.75 FS
171	1		*GARNISH ASSYR.FR.PILLAR CORNE	Necessary	7.20 FS	*7.20 FS
172	1		*NUMBER PLATE WITH CASING - L	Missing	45.00 FS	*45.00 FS
173	1		*MIRROR SET,R.	Cracked	190.72 FS	*190.72 FS
174	1		*MOLDING ASSYR.FR.DOOR	Necessary	16.35 FS	*16.35 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	17,284.08	12,596.19
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SEALANT FOR RHF DOOR	New	80.00	0.00
2	REMOVE & RENEW BULKHEAD. STRAIGHTEN	New	9,000.00	2,800.00
3	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	180.00	180.00
4	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	New	5,000.00	1,800.00
5	REMOVE & INSTALL DASHBOARD INSTRUMENTAL PANEL	New	1,500.00	1,200.00
6	REMOVE AND RENEW RHF PANEL	New	50.00	50.00
7	RENEW BOTH DRIVER & PASSENGER AIRBAG ASSY ECU &	New	1,500.00	1,200.00
8	PLACE VEHICLE TO BENCH FOR CHASSIS FRAME ALIGNMENT	New	1,500.00	1,200.00
9	REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST	New	560.00	0.00
10	REMOVE & INSTALL RADIATOR WITH FITTINGS	New	380.00	380.00
11	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS	New	330.00	330.00
12	REMOVE & REPLACE FR UNDERCARRIAGE PARTS	New	1,800.00	1,680.00
13	RESET VEHICLE SMART ENTRY SYSTEM	New	560.00	560.00
14	REMOVE & RENEW ENGINE WIRE HARNESS. RESET ECU	New	1,500.00	1,120.00
15	WHEEL ALIGNMENT X4	New	180.00	180.00
16	RENEW WHEELHOUSE & CHASSIS FRAME. INCLUDING STRAIGHTEN AND FITTING ATTACHMENT ITEMS	New	1,680.00	1,680.00
17	REMOVE & INSTALL ENGINE ASSY GEARBOX & OTHERS ATTACHMENT PARTS	New	1,680.00	1,680.00
18	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (3P)	New	1,350.00	1,350.00
19	REMOVE & RENEW SEATBELT TENSIONER, ECU & CRASH SEN	New	1,500.00	1,120.00
Gross Labour Cost (S\$)			30,330.00	18,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >