

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7591J**AAD1908-113***Not Authorized
Resurvey B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

20 AUG 2019

SHB 7591J

JTDKB3FU803081455

TOYOTA

PRIUS

14.8.19

AXA

27/6/2019

		PART		LIST	
1	1	REAR BUMPER	\$	Bu 458.60	✓
2	1	REAR BUMPER RE-INFORCEMENT	\$	318.80	7
3	1	REAR BUMPER TOWING COVER	\$	n 14.70	✓
4	1	REAR BUMPER UNDER COVER (BLACK)	\$	Bu 552.60	✓
5	1	ANTENNA, ELECTRICAL KEY	\$	SL 61.40	} X
6	1	REAR BUMPER SIDE RETAINER LH	\$	SL 112.70	
7	1	REAR BUMPER SIDE RETAINER RH	\$	SL 112.70	
8	1	REAR TAILGATE	\$	n 1,547.27	
9	1	REAR TAILGATE OUTER GARNISH	\$	SL 910.40	
10	1	COVER, REAR COMBINATION LAMP, RH	\$	SL 54.70	
11	1	COVER, REAR COMBINATION LAMP, LH	\$	SL 54.70	
12	1	GARNISH, BACK DOOR SIDE, LH	\$	SL 93.60	
13	1	GARNISH, BACK DOOR SIDE, RH	\$	SL 93.60	
14	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	SL 55.40	
15	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	SL 55.40	
16	1	BOARD ASSY, BACK DOOR TRIM	\$	SL 254.40	
17	1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$	SL 51.20	
18	1	REAR TAILGATE WEATHERSTRIP	\$	SL 365.20	
19	1	PANEL SUB-ASSY, BODY LOWER BACK (REAR END PANEL)	\$	n SL 641.50	
20	1	TAILLAMP LOWER RH	\$	SL 548.40	
21	1	TAILLAMP UPPER RH	\$	SL 557.90	
22	1	REAR BUMPER SIDE RH	\$	n SL 232.00	✓
23	1	REAR BUMPER SIDE LH	\$	SL 232.00	} X
24	1	TAILLAMP LOWER LH	\$	SL 548.40	
25	1	TAILLAMP UPPER LH	\$	SL 557.90	
26	1	REAR RH FENDER PANEL	\$	n 836.70	
27	1	REAR LH FENDER PANEL	\$	n 836.70	
28	1	LINER, REAR WHEEL HOUSE, LH	\$	n 138.10	
29	1	LINER, REAR WHEEL HOUSE, RH	\$	n 138.10	

Trans-cab Auto Services Pte Ltd**AAD1908-113**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7591J

30	1	BOARD, BACK DOOR TRIM	\$	SH	222.00
31	1	PANEL ASSY, DECK TRIM SIDE, RH	\$	SH	351.10
32	1	PANEL ASSY, DECK TRIM SIDE, LH	\$	SH	351.10
33	1	COVER, FLOOR UNDER, NO.1	\$	SH	172.60
34	1	COVER, FLOOR UNDER, NO.2	\$	SH	238.70
35	1	COVER, REAR FLOOR	\$	SH	226.80
36	1	SPOILER SUB-ASSY, REAR	\$	SH	1,345.00
37	1	GLASS, BACK WINDOW FIX	\$	SH	737.90
38	1	STAY ASSY, BACK DOOR, RH	\$	SH	239.20
39	1	STAY ASSY, BACK DOOR, LH	\$	SH	239.20
40	1	LAMP SET, STOP CENTER	\$	SH	189.90
41	1	LAMP SUB-ASSY, LICENSE PLATE	\$	SH	284.00
42	1	BOARD, REAR FLOOR, NO.1	\$	SH	511.80
43	1	COVER, DECK TRIM, REAR	\$	SH	125.00

TOTAL \$ 15,669.37**25% \$ 3,917.34****\$ 11,752.03****Special Nett**

1	1SET	PARKING AID	\$	SH	700.00 X
2	1SET	REAR BUMPER CLIP	\$	na	55.00 ✓
3	2	REAR WINDSCREEN SEALANT	\$	na	80.00
4	1	WINDSCREEN MOULDING	\$	na	100.00
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00
6	1	REAR TAILGATE TOYOTA LOGO	\$	na	47.00
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	na	52.90
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	na	53.50
9	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	na	80.00
10	1	REAR TAILGATE STICKER '6555-3333'	\$	na	80.00
11	1	REAR BUMPER PROTECTOR	\$	na	100.00
12	1	REAR WHEEL RIM	\$	SH	1,570.55
13	1	REAR WHEEL RIM COVER	\$	SH	175.80
14	1	REAR TYRE 195/65/15	\$	SH	350.00
15	1	SPARE WHEEL RIM	\$	SH	1,570.55
16	1	SPARE WHEEL RIM COVER	\$	SH	175.80
17	1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00
18	1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00

TOTAL \$ 5,361.10

Trans-cab Auto Services Pte Ltd**AAD1908-113**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7591J**TOTAL PARTS \$ 17,113.13****LABOUR**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00 <i>2001</i>
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00 <i>X</i>
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00 <i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 <i>2801</i>
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>na</i> 170.00 <i>X</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i> 170.00 <i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>501</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>4</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i> 170.00 <i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>4</i> 380.00 <i>X</i>
To apply paint protection system (PPS) maintain and enhancement	\$	<i>4</i> 380.00 <i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>4</i> 380.00 <i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1908-113**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7591J

Labour charge to mount and dismount vehicle on jig
bench, to facilitate repair.

\$ *22* 380.00 *X*

To Check Electrical Lighting Concerned.

\$ *144.5* 170.00 *15%***TOTAL \$ 12,100.00****Over All Total \$ 29,213.13****(PART-BY-PART) Repair Days***15 Days**2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: