

INSURANCE CASE OWNER:

S.T

CC4 AXA1901

4766, R. 10/1/19

LKK:

IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

27/8/19

Date / Time:

27/8/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

572 54445

Name of Insured:

QUEK KUAN YI ELEMENT

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

27/8/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

S1M02405 / 132888

Policy No.:

G11114681

Make / Model:

SUARIN

Place of Accident:

BANGKOK OR

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SL5 2390



INSRS:

WSP:

Tel:

Liability:

RMKS:

Esteem performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SL5 2390 - X

SL6 4295K - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

18/10/19 - VIC

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice: GREAT

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

18/10/19

- OIWR

- PUE REVIEWED. OI INNOVATED IN A 3 VEH. C.C.; OI WAS 2ND CATE. SEND LETTER TO OI.

- UPLOAD IT IN EC.

04/10/2020

- TP LOD IN BY EMAIL

06/10/2020

- UPLOADED MANDATE IT IN EC

19/10/2020

- AXA APPROVED MANDATE

- SEND 1ST OFFER TO TP

- TP ACCEPTED OFFER.

- ALL DOCS IN ORDER.

- TO CLOSE.

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P

SS 1,539.53

(2 days)

Reduction:

44

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

0%

Repair Cost: (w/gov)

SS

1,647.50

Loss of Rental (LOR):

SS

216.00

(3 days)

x 472.00

(GREAT)

Loss of Use (LOU):

SS

-

(S x days)

Loss of Income (LOI):

SS

-

(S x days)

LOR only ☒LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

SS

7.48

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4500.00

Total:

SS

1,870.78

Global Sum SS:

1,870.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

1,870.00

Name 1:

ESTEEM PERFORMANCE PTE LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

COPY SENT

REF: Acm (Axb)

ASSIGNMENT

From

Date: 23-8-2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLS 2139D
at Workshop m/s Estren Performance
of 385 Sin ming Drive

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$17k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lump Sum:

1.21%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No.

PLS 2139D

Yr Regn

09 17

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Toy Pns

CC

1798

Colour:

h. Silver

N/C:

Insured / Std / NI / NA

Sp. Reading

200480

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTOKB3FU003570089

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / S/Rim / STD / ☒ Rrim or

Tyre Size:

F:

195/85R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

3

mm

L/Bal.

7

mm

L/Bal.

3

mm

D.O.A.

21/8/19

D.O.I.

23/8/19

Survey held at

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

P/R \$1,539.53

CRSD: \$1,229.24 (44%)

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) \$ + R5, \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

AXA
LKK

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom Vehicle
Inspection Centre (575718)

Insurer Reference: SJZ5444P
Repairer Reference: 014122
Date calculated: 22/08/2019 6:07 PM
Summary Information

Full Report
Registration: SLS2139D
Printed: 22/08/2019 6:09 PM

Claim

Location: Singapore (SG)
Printed by: Carmen SG
Claim Reference: SJZ5444P
Estimated Repair Time:
Actual Repair Days:

Work Provider:
Currency:
Date of Incident:
Hire Car Start:
Hire Car End:

AXA Insurance Pte Ltd
SGD
21/08/19

Vehicle Details

Vehicle

Manufacturer: TOYOTA
Model: PRIUS IV
Sub Model: BASE MODEL
Model Sheet Number: 70 P5 01
Registration: SLS2139D
VIN number:
Odometer:

Model Specs
TWO COAT METALLIC

*Not with paint
Running by paint
2 days*


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Time Base 10 WU/h

Price = 50.00 SGD/h

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom Vehicle
Inspection Centre (575718)

Insurer Reference: SJZ5444P
Repairer Reference: 014122
Date calculated: 22/08/2019 6:07 PM

Full Report
Registration: SLS2139D
Printed: 22/08/2019 6:09 PM

Code	Description	WU	Price SGD
NO NUMBER	R + R LOWER TAILGATE TRIM	2.0	10.00
NO NUMBER	R + R TAILGATE MOULDING	2.0	10.00
750171	R + R MANUFACTURER BADGE	5.0	25.00
B420	RENEW REAR BUMPER	12.0	60.00
	INCLUDES: REAR BUMPER AND REQUIRED ATTACHED PARTS R + R		
B410)	R + R REAR BUMPER REINFORCEMENT	1.0	5.00
NO NUMBER	RENEW L/R BUMPER BRACKET	1.0	5.00
NO NUMBER	RENEW R/R BUMPER BRACKET	1.0	5.00
2711	REAR PANEL REPAIR	X40.0* ?	200.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		6.40	64.0
Total of Labour			320.00

Paint

Code	Description - TWO COAT METALLIC	WU	Price SGD
	REAR BUMPER NEW PART PAINT K1R	12.0	
	REAR PANEL REPAIR PAINTING <50%	11.0	

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	55.10
2711	REAR PANEL REPAIR PAINTING <50%	12.27

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			50.00 SGD/h
Time Paint		23.0	
Preparation Main Work Metal	2.10	21.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	25.00
Total	10 WU/h	49.0	245.00

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom Vehicle
Inspection Centre (575718)

Insurer Reference: SJZ5444P
Repairer Reference: 014122
Date calculated: 22/08/2019 6:07 PM

Full Report
Registration: SLS2139D
Printed: 22/08/2019 6:09 PM

	Price SGD
Material Cost - Paint	
New Part Painting - Plastic K1R	55.10
Repair Painting	12.27
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	94.47

Spare Parts

				prices as at 2015-06-01/01	
Code	Description	Part Number	Supplier	Price SGD	
2583	REAR BUMPER	52159 47913		<i>Bu</i> 497.50	✓
2587	REAR COVER BUMPER	52453 47010		<i>Red / Bu</i> 582.60	✓
2589	REAR BUMPER COVER	52169 47020		<i>Sm</i> 31.70	X
2619	L/R BUMPER BRACKET	52576 47040		<i>gpc</i> 112.70	X
2620	R/R BUMPER BRACKET	52575 47040		<i>alc</i> 112.70	X
2640	REAR BUMPER REINF	52023 47030		<i>best</i> 398.80	✓
2979	BOOT/T-GATE	76801 47110A0		<i>h</i> 782.50	X
	MOULDING				
3013	REAR MANUFACT BADGE	75403 48010		<i>h</i> 61.70	X
1000	RR BMP CLIP	RR BMP CLIP		<i>h</i> 40.00	✓
1001	WORDING "PRIUS"	WORDING "PRIUS"		<i>h</i> 51.90	X
1002	WORDING "HYBRID"	WORDING "HYBRID"		<i>h</i> 55.47	X
				Savings	0.00
				Subtotal	2,727.57
				Subtotal Discount(+30.00%)	-818.27
				Total	1,909.30

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Extras

Code	Description	Price SGD
1003	R.SENSOR R.SENSOR	<i>Shen</i> 200.00* ✓
Total Extras		200.00

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom Vehicle
Inspection Centre (575718)

Insurer Reference: SJZ5444P
 Repairer Reference: 014122
 Date calculated: 22/08/2019 6:07 PM

Full Report
Registration: SLS2139D
Printed: 22/08/2019 6:09 PM

Final Calculation

Parts

Total Discount(+30.00%)

Total Parts

Labour Time Base 10 WU/h

Total 64.0 WU X 50.00 SGD/h

Total of Labour

Total Of Extras

Paint Work Time Base 10 WU/h

Labour Cost 49.0 WU X 50.00 SGD/h

Material Cost

Total Paint Including Material

Repair Cost Excludes GST

GST (+7.0%)

Repair Cost Included GST

the Repairer must notify the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SGD SGD

2,727.57

-818.27

1,909.30

320.00 65

320.00

200.00

245.00 105

94.47 71.30

339.47

2,768.77

193.81

2,962.58

2803.77

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Kh

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom Vehicle
Inspection Centre (575718)

Insurer Reference: SJZ5444P
Repairer Reference: 014122
Date calculated: 27/11/2019 7:19 PM

Full Report
Registration: SLS2139D
Printed: 27/11/2019 7:20 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Carmen SG	Currency:	SGD
Claim Reference:	SJZ5444P	Date of Incident:	21/08/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	PRIUS IV
Sub Model:	BASE MODEL
Model Sheet Number:	70 P5 01
Registration:	SLS2139D
VIN number:	
Odometer:	

Model Specs

TWO COAT METALLIC


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Time Base 10 WU/h

Price = 50.00 SGD/h

Code	Description	WU	Price SGD
B420	RENEW REAR BUMPER INCLUDES: REAR BUMPER AND REQUIRED ATTACHED PARTS R + R	12.0	60.00
B410)	R + R REAR BUMPER REINFORCEMENT	1.0	5.00
	Labour Cost	Hrs	WU
	Panel / Mechanical Labour	1.30	13.0
	Total of Labour		65.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	REAR BUMPER NEW PART PAINT K1R	12.0

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	55.10

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	50.00 SGD/h			
Time Paint			12.0	
Preparation Comp. Work Plastic		0.90	9.0	45.00
Total	10 WU/h	2.10	21.0	105.00

Material Cost - Paint	Price SGD
New Part Painting - Plastic K1R	55.10
Material-constant Plastic	16.20
Total	71.30

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01 Price SGD
2583	REAR BUMPER	52159 47913		497.50
2587	REAR COVER BUMPER	52453 47010		582.60
2640	REAR BUMPER REINF	52023 47030		398.80 ✓
1000	RR BMP CLIP	RR BMP CLIP		40.00
1004	R&R R.SENSOR	R&R R.SENSOR		50.00 ✓
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,568.90
u: Used parts	Subtotal Discount(+30.00%)			-470.67
	Total			1,098.23

Extras

Code	Description	Price SGD
1003	R.SENSOR R.SENSOR	200.00*
	Total Extras	200.00

Final Calculation

	SGD	SGD
Parts	1,568.90	
Total Discount(+30.00%)	-470.67	
Total Parts		1,098.23
Labour Time Base 10 WU/h		
Total 13.0 WU X 50.00 SGD/h	65.00	
Total of Labour		65.00
Total Of Extras		200.00
Paint Work Time Base 10 WU/h		
Labour Cost 21.0 WU X 50.00 SGD/h	105.00	
Material Cost	71.30	
Total Paint Including Material		176.30
Repair Cost Excludes GST		1,539.53
GST (+7.0%)		107.77
Repair Cost Included GST		1,647.30

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.



Service Request Details

Claim

S9M01Y05

Reference

None 

Loss Date

August 21, 2019

Report Date

Aug 22, 2019 1:04:52 PM

Request Date

August 22, 2019

Due Date

August 29, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P: Carman

T: 229 p.m

V: 1h

E: ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLS2139D

Model

TBC

Service Address

'''

Primary Contact/Insured

QUEK KUAN YI CLEMENT

17B CIRCUIT ROAD, #15-208, 372017, Singapore

TOLBUTAMIDEX@GMAIL.COM

Claim Handler

KHOR Saw Theng

6568804754

sawtheng.khor@axa.com.sg

Additional Instructions

NOT REPORTED

1

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

Catherine Chong (LKK Auto)

From: Carmen Lim <carmen@esteemperf.com.sg>
Sent: Thursday, 22 August, 2019 12:59 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: [EXTERNAL] REQUEST FOR PRI SURVEY SLS2139D

Categories: Raghav

Dear Sir / Madam,

Your Ref : SJZ5444P

Accident involving SLS2139D & SJZ5444P & SLG4295K on 21.08.2019

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES
(NIMA)**

We act for Grab Rentals Pte Ltd who has appointed the under-mentioned workshop to repair his motor vehicle no SLS 2139 D.

Please be informed that the said vehicle can be inspected at :

Name of workshop : Esteem Performance Pte Ltd

Address : 385, Sin Ming Drive Singapore 575718

Tel : 8799 0066

Fax : 6259 3326

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.

We are prefer LKK to survey the car.

Thank you



Freundliche Grüße / Best Regards

Carmen Lim

Accident Claim Executive | Operation Division

Esteem Performance Pte Ltd

M: 8799 0066

P: 6484 1221

E: carmen@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259
(Head Office)
385 Sin Ming Drive Vicom Inspection Centre
(Showroom)

www.esteemperformance.com



◀◀ **Re:<MANDATE IA>**

Type

🔗 Question

Message

Pls proceed with your proposed mandate.

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 04/02/2020

Survey Details:

Date of loss	21-Aug-19
Date of appointment	22-Aug-19
Date of survey	23-Aug-19
Location of survey	ESTEEM PERFORMANCE PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLS 2139D
Make and Model	TOYOTA PRIUS HYBRID 1.8 CVT
Date of registration	14-Sep-17
Excess	
Market Value (est)	\$77,000.00
Parf Rebate (est)	\$47,293.00
Nett Loss (est)	\$29,707.00

Repair details:

Initial Estimate	\$ 2,768.77
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 1,098.23
Check items (estimate)	\$ -
Labour	\$ 441.30
Total	\$ 1,539.53
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>2 DAYS</u>
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

We have not authorized repairs. It was reported that Insured was involved in a 3 vehicle chain collision and was the 2nd car and was pushed forward from behind and rear-ended TP vehicle. TP LOD in.

Mandate:

Liability(TP)	100%	
Proposed Repair Cost	\$ 1,647.30	w/gst
Loss of Use	\$ -	no. of days
Loss of Rental (GRAB RATE)	\$ 216.00	\$72 x 3 days
Loss of Income	\$ -	no. of days
LTA Search Fees	\$ 7.48	
Others (Medical Bills)	\$ -	
Proposed Total	\$ 1,870.78	
***TBC - To Be Confirmed		



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7820 Website: www.esteemperf.com.sg

Your Ref : SJZ 5444 P

Our Ref : CIV1302635 / SLS 2139 D

Date : 03-02-20

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

RE : ACCIDENT INVOLVING **SLS 2139 D & SJZ 5444 P**
ACCIDENT DATE **21.08.2019**
ACCIDENT ALONG **BUANGKOK DRIVE JUNCTION OF HOUGANG AVE 6**

We are the workshop for the owner of motor vehicle no : **SLS 2139 D** which was involved in the captioned accident. The vehicle was surveyed by an independent appraiser and the claims below are based on its recommendation sum being for the repair cost and the period of repair (Strictly on a Without Prejudice Basis)

As the accident was caused by the negligent act of your insured **SJZ 5444 P** we are submitting these claims for your consideration.

1	Cost of repair	S \$	1,647.30
2	Loss of rental <u>3</u> days @ \$ <u>72.00</u> / day	S \$	293.60
3	Surveyor Fee	S \$	0.00
4	GIA report fees (S\$ 15.00 for search fee & S\$ 14.00 for each report fee)	S \$	0.00
5	LTA Fee	S \$	7.48
		S \$	1,948.38

We enclosed herewith the following documents to support the claims:-

- a) Authorization letter
- b) Final repair bill(s)
- c) LTA search
- d) GIA report(s) / result
- e) Insurance certificate, etc.....

Kindly look into the matter and let us hear from you on the settlement of our client's claim as soon as possible. Thank you.

Yours faithfully

Carmen Lim

Claims Executive

Email : carmen@esteemperf.com.sg



ESTEEM PERFORMANCE PTE LTD

nt:1

Blk 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.

Tel : 6484 1221 Fax : 6484 7829

385 Sin Ming Drive (Inside Vicom) Singapore 575718.

Tel : 6753 2112 Fax : 6451 0394

Co. Reg No. : 200005485N GST Reg No. : 20-0005485-N

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

ATTN: Motor Claim Department

Your Ref No: SJZ5444P
Claim Type: Third Party
Accident Date: 21/08/2019
TP Veh Reg No: SJZ5444P

Claim No: CER1302020
Final No: CIV1302635
Date: 10 Dec 2019
Policy No:
Veh Reg No: SLS2139D
Make/Model: TOYOTA PRIUS
HYBRID 1.8 CVT
Chassis No: JTDKB3FU003570089
Engine No: 2ZRS085505
Reg. Date:

Tax Invoice to Vehicle No :SLS2139D

Description	Quantity	List Price S\$	Amount S\$
Others			
1 COST FOR REPAIR	1 PCS	1,539.53	1,539.53
		1,539.53	1,539.53
Total			S\$ 1,539.53
Add GST @ 7%			107.77
Total Amount Payable			S\$ 1,647.30

TOTAL: SINGAPORE DOLLAR ONE THOUSAND SIX HUNDRED FORTY SEVEN AND CENTS THIRTY ONLY

The above vehicle was surveyed by MR KENNETH on 23/08/2019

For Esteem Performance Pte Ltd

E. & O. E.

AUTHORISED SIGNATURE



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19014766/Kha3s2

8 SHENTON WAY #24-01
 AXA TOWERSINGAPORE 068811
 ATTN: SAW THENG

Date : 20-02-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJZ 5444P	Veh. Inspected	SLS 2139D
Policy No.	GA113468/1	Coverage (\$)	0.00
Claim No.	S9M01Y05	Excess (\$)	0.00
Assign From	SAW THENG	Assign Date	22/08/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU003570089	Colour	METALLIC SILVER
Odometer	200480	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	3 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	3 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	21/08/2019	Inspection Date	23/08/2019
Survey held at	ESTEEM PERFORMANCE PTE LTD 385 SIN MING DRIVE, VICOM SINGAPORE 575718		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 2139D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	BUCKLED	497.50	497.50
1	REAR COVER BUMPER (CONSISTENT)	DENTED / BUCKLED	582.60	582.60
1	REAR BUMPER COVER (CONSISTENT)	SERVICEABLE	31.70	-
1	L/R BUMPER BRACKET (CONSISTENT)	SERVICEABLE	112.70	-
1	R/R BUMPER BRACKET (CONSISTENT)	SERVICEABLE	112.70	-
1	REAR BUMPER REINF (CONSISTENT)	BENT	398.80	398.80
1	BOOT/T-GATE MOULDING (CONSISTENT)	SERVICEABLE	782.50	-
1	REAR MANUFACT BADGE (CONSISTENT)	NOT NECESSARY	61.70	-
1	RR BMP CLIP (CONSISTENT)	NECESSARY	40.00	40.00
1	WORDING "PRIUS" (CONSISTENT)	NOT NECESSARY	51.90	-
1	WORDING "HYBRID" (CONSISTENT)	NOT NECESSARY	55.47	-
1	R&R R.SENSOR (CONSISTENT)	NECESSARY	50.00	50.00
	LESS 30% DISCOUNT		-833.27	-470.67
			1,944.30	1,098.23
SPECIAL NETT ITEMS				
1	R.SENSOR R.SENSOR (SN) (CONSISTENT)	SHORTED	200.00	200.00
			200.00	200.00
LABOUR				
	TOTAL OF LABOUR.		320.00	65.00
	PAINT WORK: LABOUR COST.		245.00	105.00
	PAINT WORK: MATERIAL COST.		94.47	71.30
			659.47	241.30
GRAND TOTAL			2,803.77	1,539.53
RECOMMENDED COST OF REPAIRS				1,539.53

Report Ref No. CC4/ASM19014766/Kha3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.