

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AXA Insurance (S) Pte Ltd

Third Party

Policy No: _____

Date: 22.08.2019

Accident Date : 19.08.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Volkswagen Passat" Reg. No. SGA239R Claiming Against Your Insured Veh. No. SHNF710H			
1pc	Rear Bumper	7.11	1,699.60
10pcs	Rear Bumper Clips		71.10
1pc	Rear Bumper Sponge		125.00
1pc	Rear Bumper Reinforcement		500.33
1pc	Rear Bumper Center Moulding		288.96
2pcs	Rear Bumper Side Mouldings	233.75	467.50
1pc	Rear Bumper Tow Cover		117.60
1pc	Rear Bumper Reflector RH		139.79
2pcs	Rear Bumper Reverse Sensors	222.71	445.42
4pcs	Rear Bumper Reverse Sensor Holders	125.00	500.00
1pc	Rear Bumper Inner Cove		210.00
1pc	Rear Bumper Lower Diffuser Cover		433.96
1pc	Boot Badge Passat		100.97
1pc	Boot Badge 'CC'		98.79
1pc	Boot Badge 'TSI'		98.79
1pc	Bonnet		1,899.60
2pcs	Bonnet Hinges	133.71	267.42
1pc	Bonnet Lock		300.99
1pc	Bonnet Release Handle		99.60
10pcs	Bonnet Insulator Clips	7.11	71.10
1pc	Grille		999.79
1pc	Grille Top Rubber Seal		71.00
1pc	Grille Emblem		188.70
1pc	Grille Emblem Base Bracket		110.00
1pc	Grille Chrome Surround		125.00
1pc	Grille Chrome Moulding		245.00
2pcs	Grille Top Ganishs	110.00	220.00
2pcs	Headlamps	1,900.97	3,801.94
1pc	Front Bumper		1,688.70
10pcs	Front Bumper Clips	7.11	71.10
1pc	Front Bumper Sponge		188.69
1pc	Front Bumper Reinforcemrnt		600.71
2pcs	Front Bumper Brackets	99.79	199.58
2pcs	Front Bumper Top Retainers	180.71	361.42
2pcs	Front Bumper Sensors	211.70	423.40
2pcs	Front Bumper Sensor Holders	125.00	500.00
4pcs	Front Bumper Corner Retainer RH		89.96
1pc			17,821.51
		C/F	17,821.51

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AXA Insurance (S) Pte Ltd

Third Party
Policy No: _____

Date: 22.08.2019

Accident Date : 19.08.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Volkswagen Passat" Reg. No. SGA239R Claiming Against Your Insured Veh. No. SHNF710H			
		B/F	17,821.51
1pc	Front Bumper Cove		99.79 ?
1pc	Front Bumper Sensor Wiring Harness		488.60 2
1pc	Support Panel		1,500.71 ✓
1pc	Support Panel Top Garnish Cover		199.60 ✓
1pc	Radiator		686.76 ?
1pc	Air Con Condensor		899.70 ✓
1pc	Air Con Condensor Side Air Guide		80.19 ?
1pc	Engine Inner - Cooler		788.78 ?
	Rear Number Plate		45.00 SN ✓
	Front Number Plate		45.00 SN ✓
	To Conduct Electrical Check, Focus Headlamp		30.00 ✓
	To Remove / Refit Air Con Condenser & Refill Air Con Gas		120.00 1000
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		60.00 500
	To Replace / Refit Front & Rear Parking Sensors, Wiring Harness & Reprogram System		200.00 1200
	To Diagnose / Erase /Reprogram Engine Check Light Error Code		160.00 ?
	Labour Charge - Panel Beating, Repairing Of Front Chassis Member, Inner Panel, 2x Front Fender, Front Windscreen Pillar, Boot Lid, End Panel, and Parts Replacement		1,500.00 9000
	To Respray Affected Areas		1,400.00 10000
Total :			26,125.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: