

W

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: 1908111
Repairer Reference: 1908111
Date calculated: 07/10/2019 10:04 AM

Lefty

Full Report
Registration: SLU2053G ←
Printed: 07/10/2019 10:04 AM

Summary Information

Claim

Location: Singapore (SG)
Printed by: KK LAU
Claim Reference: 1908111
Estimated Repair Time:
Actual Repair Days:

Work Provider: AXA Insurance Pte Ltd
Currency: SGD
Date of Incident: 17/08/19
Hire Car Start:
Hire Car End:

Vehicle Details

Vehicle

Manufacturer: HYUNDAI
Model: ELANTRA (AD)
Sub Model: GLS
Model Sheet Number: 30 92 02
Registration: SLU2053G
VIN number:
Odometer:

Model Specs

FROM 07/2017	LED TAILLAMPS	REAR AXLE MULTI-LINK	REAR PARKING SYSTEM
1.6 LTR 94 KW	SPORT	PREPARE OFF VEHICLE	TWO COAT PEARL/MICA


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

		Time Base 10 WU/h	Price = 45.00 SGD/h	
Code	Description		WU	Price SGD
NO NUMBER	R + R L/R AIR GRILLE		1.0	4.50
86821R00	R + R LEFT REAR WHEELHOUSE SHELL		3.0	13.50
NO NUMBER	R + R R/R AIR GRILLE		1.0	4.50
86821R0R	R + R RIGHT REAR WHEELHOUSE SHELL		3.0	13.50
NO NUMBER	R + R REAR BUMPER PROTECTOR		1.0	4.50
86520R00	RENEW REAR BUMPER		9.0	40.50
	INCLUDES: R + R OUTER TAIL LAMPS AND NECESSARY ATTACHED PARTS			
NO NUMBER	R + R REAR NUMBER PLATE TRIM		1.0	4.50
87321R00	R + R BOOTLID SEAL		2.0	9.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		2.10	21.0	94.50
Total of Labour				94.50

Paint

Paint Work		Time Basis 10 WU/h	
Code	Description - TWO COAT PEARL/MICA	WU	Price SGD
99BDBTR0	REAR BUMPER PAINTING STAGE I	23.0	103.50
L 2640	REAR BUMPER SUPPORT PAINT	5.0	22.50
L 2681	L/R OUT PARKING SENS PAINTING STAGE II	6.0	27.00
L 2683	L/R INN PARKING SENS PAINTING STAGE II	6.0	27.00
L 2711	REAR PANEL PAINTING STAGE II	28.0	126.00
99GTXTC0	BOOTLID PAINTING STAGE II	20.0	90.00
Total Paint		Hrs	WU
		8.80	88.0
			Price SGD
			396.00

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
2583	REAR BUMPER	86610F2510		235.00
2593	REAR BUMPER SPOILER	86612F2500		115.00
2619	L/R BUMPER BRACKET	86613F2000		22.00
2650	RR BUMPER CLAMP KIT	USE SINGLE PARTS		8.00
3295	L/R REFLECTOR	92405F2400		20.00
1003	RR BMPR DIFFUSER CLP	PARTS		8.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			408.00
u: Used parts	Addition(+15.00%)			61.20
Total				469.20

Extras

Code	Description	Price SGD
1004	RR BMPR PROTECTOR LH parts	18.00*
1005	RR BMPR PROTECTOR RH PARTS	18.00*
	Total Extras	36.00

Final Calculation

	SGD	SGD
Parts	408.00	
Addition(+15.00%)	61.20	
Total Parts		469.20
Labour Time Base 10 WU/h		
Total 21.0 WU X 45.00 SGD/h	94.50	
Total of Labour		94.50
Total Of Extras		36.00
Paint Work Time Base 10 WU/h		
Labour Cost 88.0 WU X 45.00 SGD/h	396.00	
Total Paint Including Material		396.00
Repair Cost Excludes GST		995.70
GST (+7.00%)		69.70
Repair Cost Included GST		1,065.40

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.




松義汽車機件私人有限公司
SONG YI AUTO PARTS PTE LTD

Block 637 Veerasamy Road #01-119 Singapore 200637
Tel: 6297 3700 Fax: 6297 3839 Email: songyi@singnet.com.sg

SPECIALISTS MOTOR PTE LTD
BLK 3018A, UBI ROAD 1,
#01-26/24,
SINGAPORE 408711

TAX INVOICE

REG NO: 200922086G
GST NO: 200922086G

Invoice No: SAL19-091242
Date: 03/09/2019 16:17
Account No: S022
Sales person: SKM
Order By: 
Vehicle No: SLU2053G
P/O No: JU572955

Page 1 of 1

No.	Part No.	Description	Location	Qty	Price	Amount
1	86611-F2000	BUMPER COVER-REAR (UPR) *****	WH	1	235.00	235.00 ✓
2	86595-2T500	CLIP-BUMPER	C21-20	8	1.00	8.00 ✓
3	92405-F2000	REFLECTOR-RR BUMPER LH *****	S-10	1	20.00	20.00 ✓
4	86613-F2000	BRACKET-RR BUMPER SIDE LH	R-8 Box-2	1	22.00	22.00 ✓
5	86612-F2000	BUMPER COVER-REAR (LWR) *****	WH	1	115.00	115.00 ✓
6	86595-2T500	CLIP-BUMPER	C21-20	8	1.00	8.00 ✓

Sub Total: 408.00

Add GST @7%: 28.56

Grand Total: 436.56


Issued By


Received By

Goods sold returned are to be in full packaging
original condition within SEVEN working days

Received the above mentioned goods in order and good condition



Specialist Motor Pte Ltd
#01-24/25/26, Block 3018A, Ubi
Road 1
408711

Claim Reference: 1908111
Assessment number: 1908111
Version: 1810
Date calculated: 21/08/2019 3:33 PM

Full Report
Registration: SLU2053G
Printed: 21/08/2019 3:33 PM

Summary Information

Claim

Location: Singapore (SG)
Printed by: Motor Specialist
Claim Reference: 1908111
Estimated Repair Time:
Actual Repair Days:

Work Provider:
Currency:
Date of Incident:
Hire Car Start:
Hire Car End:

AXA Insurance Pte Ltd
SGD
17/08/19

Vehicle Details

Vehicle

Manufacturer: HYUNDAI
Model: ELANTRA (AD)
Sub Model: GLS
Model Sheet Number: 30 92 02
Registration: SLU2053G
VIN number:
Odometer:

Model Specs

FROM 07/2017
1.6 LTR 94 KW

LED TAILLAMPS
SPORT

REAR AXLE MULTI-LINK
PREPARE OFF VEHICLE

REAR PARKING SYSTEM
TWO COAT PEARL/MICA

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

not Allowed

the repairer

3 dy.
23/8/19

1/2# 995-70

Specialist Motor Pte Ltd
#01-24/25/26, Block 3018A, Ubi
Road 1
408711

Claim Reference: 1908111
Assessment number: 1908111
Version: 1810
Date calculated: 21/08/2019 3:33 PM

Full Report
Registration: SLU2053G
Printed: 21/08/2019 3:33 PM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
NO NUMBER	R + R L/R AIR GRILLE		1.0	4.50
86821R00	R + R LEFT REAR WHEELHOUSE SHELL		3.0	13.50
NO NUMBER	R + R R/R AIR GRILLE		1.0	4.50
86821R0R	R + R RIGHT REAR WHEELHOUSE SHELL		3.0	13.50
NO NUMBER	R + R REAR BUMPER PROTECTOR		1.0	4.50
86520R00	RENEW REAR BUMPER		9.0	40.50
	INCLUDES: R + R OUTER TAIL LAMPS AND NECESSARY ATTACHED PARTS			
NO NUMBER	R + R REAR NUMBER PLATE TRIM		1.0	4.50
87321R00	R + R BOOTLID SEAL		2.0	9.00
85770R00	R + R REAR CLOSING PANEL COVERING		2.0	9.00

Specialist Motor Pte Ltd
#01-24/25/26,Block 3018A, Ubi
Road 1
408711

Claim Reference: 1908111
 Assessment number: 1908111
 Version: 1810
 Date calculated: 21/08/2019 3:33 PM

Full Report
 Registration: SLU2053G
 Printed: 21/08/2019 3:33 PM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	2.30	23.0	103.50
Total of Labour			103.50

Paint

Paint Work		Time Basis 10WU/h	
Code	Description - TWO COAT PEARL/MICA	WU	Price SGD
99BDBTRO	REAR BUMPER PAINTING STAGE I	23.0	103.50
L 2640	REAR BUMPER SUPPORT PAINT	5.0	22.50
L 2681	L/R OUT PARKING SENS PAINTING STAGE II	6.0	27.00
L 2683	L/R INN PARKING SENS PAINTING STAGE II	6.0	27.00
L 2711	REAR PANEL PAINTING STAGE II	28.0	126.00
99GTXTCO	BOOTLID PAINTING STAGE II	20.0	90.00
99OQLTCO	L/R OUT QTR PANEL PAINTING STAGE II	23.0	103.50
99OQRTCO	R/R OUT QTR PANEL PAINTING STAGE II	23.0	103.50

Total Paint	Hrs	WU	Price SGD
	13.40	134.0	603.00

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
2583	REAR BUMPER	86610F2510	00/0e	235.00 ✓
2593	REAR BUMPER SPOILER	86612F2500	9m	115.00 ✓
2619	L/R BUMPER BRACKET	86613F2000	BOL	22.00 ✓
2621	L/R INN BUMPER BRKT	86633F2600	17 X	3.00 X
2650	RR BUMPER CLAMP KIT	USE SINGLE PARTS	nu	8.00 ✓
3295	L/R REFLECTOR	92405F2400	ene	20.00 ✓
4985	REAR PANEL TRIM	85770F2000TRY	17 X	48.00 X
1000	rr bmpr protector LH	part	nu	18.00 ✓ 5.0
1001	rr bmpr protector RH	part	nu	18.00 ✓ 5.0
1002	rr bpr protector (c)	part	nu	36.00 X
1003	rr bpr diffuser clip	part	nu	8.00 ✓
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			531.00
u: Used parts	Addition(+15.00%)			79.65

1-408
 152
 469.20

Specialist Motor Pte Ltd
#01-24/25/26,Block 3018A, Ubi
Road 1
408711

Claim Reference: 1908111
 Assessment number: 1908111
 Version: 1810
 Date calculated: 21/08/2019 3:33 PM

Full Report
 Registration: SLU2053G
 Printed: 21/08/2019 3:33 PM

Total		610.65
Final Calculation		
	SGD	SGD
Parts	531.00	
Addition(+15.00%)	79.65	
Total Parts		610.65
Labour Time Base 10 WU/h		
Total 23.0 WU X 45.00 SGD/h	103.50	
Total of Labour		103.50
Paint Work Time Base 10 WU/h		
Labour Cost 134.0 WU X 45.00 SGD/h	603.00	
Total Paint Including Material		603.00
Repair Cost Excludes GST		1,317.15
GST (+7.00%)		92.20
Repair Cost Included GST		1,409.35

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS