

Specialist Motor Pte Ltd
#01-24/25/26,Block 3018A, Ubi
Road 1
408711

Claim Reference: 1908111
Assessment number: 1908111
Version: 1810
Date calculated: 21/08/2019 3:33 PM

Full Report
Registration: SLU2053G
Printed: 21/08/2019 3:33 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Motor Specialist	Currency:	SGD
Claim Reference:	1908111	Date of Incident:	17/08/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HYUNDAI
Model:	ELANTRA (AD)
Sub Model:	GLS
Model Sheet Number:	30 92 02
Registration:	SLU2053G
VIN number:	
Odometer:	

Model Specs

FROM 07/2017	LED TAILLAMPS	REAR AXLE MULTI-LINK	REAR PARKING SYSTEM
1.6 LTR 94 KW	SPORT	PREPARE OFF VEHICLE	TWO COAT PEARL/MICA

not Allowed

Lhr

to be repaired

3 dy.

23/8/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Specialist Motor Pte Ltd
#01-24/25/26,Block 3018A, Ubi
Road 1
408711

Claim Reference: 1908111
Assessment number: 1908111
Version: 1810
Date calculated: 21/08/2019 3:33 PM

Full Report
Registration: SLU2053G
Printed: 21/08/2019 3:33 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
NO NUMBER	R + R L/R AIR GRILLE		1.0	4.50
86821R00	R + R LEFT REAR WHEELHOUSE SHELL		3.0	13.50
NO NUMBER	R + R R/R AIR GRILLE		1.0	4.50
86821R0R	R + R RIGHT REAR WHEELHOUSE SHELL		3.0	13.50
NO NUMBER	R + R REAR BUMPER PROTECTOR		1.0	4.50
86520R00	RENEW REAR BUMPER		9.0	40.50
	INCLUDES: R + R OUTER TAIL LAMPS AND NECESSARY ATTACHED PARTS			
NO NUMBER	R + R REAR NUMBER PLATE TRIM		1.0	4.50
87321R00	R + R BOOTLID SEAL		2.0	9.00
85770R00	R + R REAR CLOSING PANEL COVERING		2.0	9.00

Specialist Motor Pte Ltd
#01-24/25/26,Block 3018A, Ubi
Road 1
408711

Claim Reference: 1908111

Assessment number: 1908111

Version: 1810

Date calculated: 21/08/2019 3:33 PM

Full Report

Registration: SLU2053G

Printed: 21/08/2019 3:33 PM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	2.30	23.0	103.50
Total of Labour			103.50

Paint

Paint Work		Time Basis 10WU/h	
Code	Description - TWO COAT PEARL/MICA	WU	Price SGD
99BDBTRO	REAR BUMPER PAINTING STAGE I	23.0	103.50
L 2640	REAR BUMPER SUPPORT PAINT	5.0	22.50
L 2681	L/R OUT PARKING SENS PAINTING STAGE II	6.0	27.00
L 2683	L/R INN PARKING SENS PAINTING STAGE II	6.0	27.00
L 2711	REAR PANEL PAINTING STAGE II	28.0	126.00
99GTXTCO	BOOTLID PAINTING STAGE II	20.0	90.00
99OQLTCO	L/R OUT QTR PANEL PAINTING STAGE II	23.0	103.50
99OQRTCO	R/R OUT QTR PANEL PAINTING STAGE II	23.0	103.50

Total Paint	Hrs	WU	Price SGD
	13.40	134.0	603.00

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
2583	REAR BUMPER	86610F2510	DO/De	235.00
2593	REAR BUMPER SPOILER	86612F2500	gmd	115.00
2619	L/R BUMPER BRACKET	86613F2000	11 X	22.00
2621	L/R INN BUMPER BRKT	86633F2600	11 X	3.00
2650	RR BUMPER CLAMP KIT	USE SINGLE PARTS	11	8.00
3295	L/R REFLECTOR	92405F2400	7	20.00
4985	REAR PANEL TRIM	85770F2000TRY	11 X	48.00
1000	rr bmpr protector LH	part	11	18.00
1001	rr bmpr protector RH	part	11	18.00
1002	rr bpr protector (c)	part	11	36.00
1003	rr bpr diffuser clip	part	11 X	8.00

f: OEM Parts	Savings	0.00
n: Non-OEM Parts	Subtotal	531.00
u: Used parts	Addition(+15.00%)	79.65

Specialist Motor Pte Ltd
#01-24/25/26,Block 3018A, Ubi
Road 1
408711

Claim Reference: 1908111

Assessment number: 1908111

Version: 1810

Date calculated: 21/08/2019 3:33 PM

Full Report

Registration: SLU2053G

Printed: 21/08/2019 3:33 PM

Total	610.65
-------	--------

Final Calculation

	SGD	SGD
Parts	531.00	
Addition(+15.00%)	79.65	
Total Parts		610.65
Labour Time Base 10 WU/h		
Total 23.0 WU X 45.00 SGD/h	103.50	
Total of Labour		103.50
Paint Work Time Base 10 WU/h		
Labour Cost 134.0 WU X 45.00 SGD/h	603.00	
Total Paint Including Material		603.00
Repair Cost Excludes GST		1,317.15
GST (+7.00%)		92.20
Repair Cost Included GST		1,409.35

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS