

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : GBH6287J

Vehicle Model : TOYOTA HIACE

Chassis Number : JTFHT02PX00244122

Estimated Repair Cost

S/N	Parts Description	Qty	List Price
1	TAIL GATE / DD	1	2925.75
2	TAIL GATE LOCK / BT	1	632.55
3	TAIL GATE LOGO / MC	1	77.85
4	TAIL GATE CENTER GARNISH X	1	239.55 l
5	TAIL GATE WEATHERSTRIP / TM	1	482.55
6	TAIL GATE INNER BOARD X	1	632.55 l
7	TAIL GATE INNER BOARD CLIPS / MC	10	30.00 15
8	TAIL LAMP LH & RH X	2	964.50 l
9	TAIL LAMP LOWER CORNER PANEL LH / CRV	1	278.85
10	REAR BUMPER / CRV	1	782.25
11	REAR BUMPER CLIPS / MC	10	75.00 30
12	REAR BUMPER INNER BRACKET (Creta MC) LH / BR	1	92.25
13	END PANEL (INNER) X R	1	1082.10 l
14	END PANEL (OUTER) X R	1	1048.95 l
15	END PANEL UPPER PANEL X R	1	317.10 l
16	"TOYOTA HIACE" STICKER / MC	1	49.05 30
17	70 KM/H STICKER / MC	1	30.00 20
18	CAR STICKER / MC	1	30.00 20
			\$ 9770.85
Discount Less 25%			\$ 2442.71
List Prices Total			\$ 7,328.14

S/N	Special Nett Items:	Qty	
1	REVERSE SENSOR / BR	2	\$ 350.00 200
2	REAR NUMBER PLATE WITH HOLDER X	1	\$ 60.00 l
Special Nett Total			\$ 410.00

Spare Part's Total Price \$ 7738.14

Steve (LKK)
83228813

WHL Mr. John 30/8/19, 11.30am
4 days
L/S
Ry AL SM

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : GBH6287J

Vehicle Model : TOYOTA HIACE

Chassis Number : JTFHT02PX00244122

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO CUT & WELD WHERE NECESSARY; TO STRAIGHTEN & REPAIR REAR LUGGAGE FLOOR PANEL; TO REMOVE & REPLACE PARTS AS LISTED ABOVE.	\$ 1800.00 500
2	TO SPRAY PAINTING ON: TAIL GATE (INNER, OUTER), END PANEL, REAR LUGGAGE FLOOR PANEL, REAR BUMPER, REAR LHS CORNER PANEL.	\$ 1800.00 600
3	TO REMOVE & TRANSFER TAIL GATE SCREEN TO NEW TAIL GATE AND PERFORM WEST TEST.	\$ 150.00 50
4	TO REMOVE & TRANSFER TAIL GATE SERVICEABLE COMPONENTS & FITTINGS TO NEW TAIL GATE & CHECK FUNCTION.	\$ 100.00 X
5	TO CHECK ELECTRICAL WIRINGS & REAR LIGHTS FUNCTION.	\$ 100.00 30
6	CHECK & CLEAR FAULT CODES AFTER NECESSARY NECESSARY ACCIDENT REPAIRS.	\$ 280.00 X

Labour Total \$ 4230.00

Parts & Labour Total \$ 11968.14