

Our Job Ref No : 305326220

Date : 27/08/19

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHD6771C

20/08/2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: CHINA GBG202Z

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

\$5,350.00

3. Estimated normal period for repairs: 4 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name : KALVIN

Date : 28/8/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

[illegible]

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 6771C

DATE 20/8/2019 15:12

MAKE :

MODEL : MERCEDES BENZ

China

Chenig

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>— Dutch</i>			\$ 2,470.00
	Boot Lid Lamp (LH) <i>X on</i>			\$ 655.00
	Boot Lid Moulding <i>— on</i>			\$ 110.00
	Boot Lid Lock <i>X on</i>			\$ 275.00
	Boot Lid 'E220' Emblem <i>— on</i>			\$ 54.30
	Boot Lid Star Logo <i>— on</i>			\$ 45.00
	Boot Lid 'CDI' Emblem <i>— on</i>			\$ 54.30
	Rear Bumper <i>— Dutch</i>			\$ 1,510.00
	Rear Bumper Reinforcement <i>✓ Bad</i>			\$ 1,150.00
	Rear Bumper Bracket Lower (LH/RH) <i>✓ on</i>		\$ 135.00	\$ 270.00
	Rear Bumper Bracket Top (LH/RH) <i>X on</i>		\$ 125.00	\$ 250.00
	Rear Bumper Retainer Mounting (LH/RH) <i>X on</i>		\$ 115.00	\$ 230.00
	Taillamp (LH) <i>X on</i>			\$ 1,280.00
	Rear Panel End <i>X right</i>			\$ 1,380.00
	Rear Panel Inner Garnish <i>— on</i>			\$ 240.00
	Rear Panel Inner Garnish Clip (10pcs) <i>— on</i>			\$ 40.00
	<i>Rear Bumper under cover — on</i>			\$ 325
	SUB TOTAL			\$ 10,013.60
	LESS 20%			\$ 2,002.72
	DISCOUNTED TOTAL			\$ 8,010.88
	Boot Lid Sovereign' Sticker <i>— on</i>			\$ 25.00
	Rear Bumper Sensor <i>— still</i>			\$ 388.00
				\$ 413.00
	Labour Charge			
	Panel Beating			\$ 800.00 <i>600</i>
	Spray Painting Charge			\$ 900.00 <i>600</i>
	Wiring Charge			\$ 50.00 <i>20</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>30</i>
	TOTAL LABOUR			\$ 1,920.00
	ESTIMATE TOTAL			\$ 10,343.88
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

K. L. L. 16/8/19

20/8/19 11:00L

4 Days
4/5

Alpha Repair & Ltd