

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 6771C

DATE 20/8/2019 15:12

China

MAKE :

MODEL : MERCEDES BENZ

Chenig

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 2,470.00
	Boot Lid Lamp (LH) ✕			\$ 655.00
	Boot Lid Moulding ✓			\$ 110.00
	Boot Lid Lock ✕			\$ 275.00
	Boot Lid 'E220' Emblem ✓			\$ 54.30
	Boot Lid Star Logo ✓			\$ 45.00
	Boot Lid 'CDI' Emblem ✓			\$ 54.30
	Rear Bumper ✓			\$ 1,510.00
	Rear Bumper Reinforcement ✓			\$ 1,150.00
	Rear Bumper Bracket Lower (LH/RH) ?		\$ 135.00	\$ 270.00
	Rear Bumper Bracket Top (LH/RH) ?		\$ 125.00	\$ 250.00
	Rear Bumper Retainer Mounting (LH/RH) ?		\$ 115.00	\$ 230.00
	Taillamp (LH) ✕			\$ 1,280.00
	Rear Panel End ✕ rgn			\$ 1,380.00
	Rear Panel Inner Garnish ✓			\$ 240.00
	Rear Panel Inner Garnish Clip (10pcs) ✓			\$ 40.00
	Boot Lid Lamp (RH) ✓		\$ 655	
	SUB TOTAL			\$ 10,013.60
	LESS 20%			\$ 2,002.72
	DISCOUNTED TOTAL			\$ 8,010.88
	Boot Lid Sovereign' Sticker ✓			\$ 25.00
	Rear Bumper Sensor ✓			\$ 388.00
				\$ 413.00
	Labour Charge			
	Panel Beating			\$ 800.00
	Spray Painting Charge			\$ 900.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,920.00
	ESTIMATE TOTAL			\$ 10,343.88
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Accepted by Repairer
Signature:
Date:

K. Li (10/10/19)
20/8/19 11:00L
4 Days
4/5

Attn: Rep. & P.H.

Nett
Nett

600
600
20
20
30