

ASS. REC. BY:

REF:

CS/INC19014777/KSF302

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person):

Danel Koh

of

INC

Date/Time:

22.8.19 9.47a.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLR 6843H

Insured:

GX 7292T

at Workshop m/s

L soon Auto

Tel:

64821513

of

10 AMK Industrial park 2A #03-18

Policy No:

Claim No:

MT/1058602-002

Sum Insured:

Excess:

Make of Veh:

D.O.A

19.8.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

22.8.19 10:00a.m

Person Contacted:

ms Lee

Vehicle IN/OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	GX 7292T : X
	SLR 6843H : X
7/10	\$5299.04 email Submit
	( \$7,779.76 red - 60% )

ASS. REC. BY:

REF: INC1

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SUR 684314 Yr Regn: 08.17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Honda Civic c.c. 1498

Colour: M. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 37308 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: NR141-C166047000056

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 225/45ZR17

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 19/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/ File pass to

22/8 To get 02 damaged photos from NTUC

RECEIVED 18 DEC 2019

Date/Time, File Pass to?

18/12/19

1) Typ. 4

Date/Time, File Return to?

2) \_\_\_\_\_

☐: Prell. Report☒: Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS - SI

Fixings

Others

TOTAL

Add Fee: ☐: Site Insp (\$☐: Interview (\$☐: Tech Invs (\$☐: Weekend (\$

Report Format:

Lump Sum U.B.I: (\$ 5,299.04 p/p

250

**Catherine Chong (LKK Auto)**

**From:** Daniel Koh <daniel.koh@income.com.sg>  
**Sent:** Thursday, 22 August, 2019 10:15 AM  
**To:** 'assignments@lkkauto.com'  
**Cc:** admin-d@lkkauto.com  
**Subject:** FW: TP CASES FARMED OUT TO LKK ON 22/8/2019

Dear LKK,

Resend herewith claim ref. number & OIC

---

**From:** Daniel Koh  
**Sent:** Thursday, 22 August 2019 9:47 AM  
**To:** 'assignments@lkkauto.com' <assignments@lkkauto.com>  
**Cc:** 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>  
**Subject:** FW: TP CASES FARMED OUT TO LKK ON 22/8/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OIV	DOA	Ac Re
1	DAVID PHUA	MT/1058265-002	GBD8570Z	CARZ AUTO SERVICES PTE LTD	61 WOODLANDS INDUSTRIAL PARK E9 (E9 PREMIUM) #04-04 SINGAPORE 757047	Jeslyn Chua / 8322 7418		CB5965L	19/8/2019	
2	CHRYLLIS QUAH	MT/1058537-002	XE4126J	CHENG HOE MOTOR PTE LTD	38 WOODLANDS INDUSTRIAL PARK E1 #05-04/05 ADMIRALTY IND PARK SINGAPORE 757700	Efeeda / 67556142	10:00-16:00	XD1384E	17/8/2019	
3	SERENE LIM	MT/1057986-002	YP1799S	CHEONG CHEONG MOTOR SERVICE PTE. LTD.	BLK 5032 #01-293 ANG MO KIO INDUSTRIAL PARK 2	Angela Ng / 6481 4152		YL552P	16/8/2019	

					SINGAPORE 569535					
4	JARED LIU	MT/1058602- 002	SLR6843H	L SOON AUTO SERVICES	10 ANG MO KIO INDUSTRIAL PARK 2A #03- 18 AMK AUTOPOINT SINGAPORE 568047	/ 6482 1513		GX7292T	19/8/2019	
5	WO JESSIE	MT/1058786- 001	SHC2924K	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2- A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SGU8990X	13/8/2019	65 or 71
6	AZHARI	MT/1058175- 002	PA9030J	THE ONE HOLDINGS PTE LTD	8 WOODLANDS INDUSTRIAL PARK E3 WOODLANDS INDUSTRIAL PARK E SINGAPORE 757786	Muhd.Hilmi Deres / 97480340	10:00- 12:00	SLZ2322D	16/8/2019	

**Please contact workshops.**

Please revert to officer-in-charge after survey.

Thank you.

Daniel Koh  
Senior Admin Assistant  
Motor Insurance  
T +65 6430 7901  
[www.income.com.sg](http://www.income.com.sg)

**income**  
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at [Income.com.sg/careers](http://Income.com.sg/careers)

**in** with you

L Soon Auto Services  
No.10 Ang Mo Kio Industrial Park 2A  
#03-18 Ang Mo Kio Auto Point  
Singapore 568047

Not Notarised  
Rugby Before Paint

Kenneth  
96910663

5 days  
call on 22/8/19  
LRC Kennedy to 10-10/19  
Rugby work  
Hence.

SLR6843H Honda Civic

No.	Qty	Parts Description	Estimated Parts Price	
1	1	Front right door wing mirror complete assy	100% \$ 778.20	X ✓
2	1	Front right door panel	Ref work \$ 1,228.60	✓
3	1	Front right door lock mechanism	\$ 252.80	X
4	1	Front right door glass outer moulding	\$ 176.10	X
5	1	Front right door outer handle	Ref \$ 178.40	✓
6	2	Front right door sticker	Ref \$ 180.00	✓
7	2	Front right door hinges	\$ 88.00	X
8	1	Front right door weatherstrip	\$ 188.00	X
9	1	Front right door checker linkage	\$ 163.00	X
10	1	Front right door inner trim board	\$ 325.00	X
11	1	Front right door regulator with motor assy	\$ 478.50	X
12	1	Right side sill panel	\$ 896.00	X
13	1	Rear right door panel	Ref \$ 1,228.60	✓
14	1	Rear right door outer handle	\$ 178.40	X
15	1	Rear right door glass outer moulding	\$ 176.10	X
16	1	Rear right door lock mechanism	\$ 252.80	X
17	2	Rear right door sticker	\$ 180.00	✓
			\$ 6,948.50	
Less 20%			\$ 1,389.70	
			\$ 5,558.80	

Special Nett Items

1	8	Front right door inner trim board clips	\$ 30.00	?
2	1	Front right door transparent pearl spot sticker	② (Bill) \$ 600.00	?
3	1	Front right wing mirror pearl spot sticker	Ref \$ 200.00	X
4	1	Right side skirting	Ref \$ 1,800.00	X
5	10	Right side skirting clips	Ref \$ 50.00	X
6	1	Right side skirting sealant	\$ 80.00	X
7	1	Right side sill panel sealant	\$ 80.00	X
8	1	Rear right door transparent pearl spot sticker	① (Bill) \$ 600.00	?
9	1	Right side skirting pearl spot sticker	Ref \$ 500.00	X
			\$ 3,940.00	

Total parts

\$ 9,498.80

to Kennedy  
again on 24/9/19  
ask for final bill.

L Soon Auto Services  
No.10 Ang Mo Kio Industrial Park 2A  
#03-18 Ang Mo Kio Auto Point  
Singapore 568047

SLR6843H Honda Civic

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten front right, rear right affected area and replace front right and rear right damaged parts.	\$ 1,400.00	4001
2	To putty and spray painting front right and rear right affected portion.	\$ 1,400.00	<del>4001</del> 5801
3	To transfer front right door glass to new door.	\$ 80.00	601
4	To transfer rear right door glass to new door.	\$ 80.00	601
5	To check door central locking for function.	ms \$ 80.00	X
6	To apply anti rust proofing to front right and rear right affected area.	\$ 120.00	601
7	To remove and install front right door lock mechanism.	\$ 80.00	X
8	To remove and install rear right door lock mechanism.	\$ 80.00	X
9	To remove and install front right door visor.	\$ 80.00	<del>50</del> 301
10	To remove and install rear right door visor.	\$ 80.00	<del>50</del> 301
11	Towing service.	B.71 \$ 100.00	X
Total labour :		\$ 3,580.00	

Total parts : \$ 9,498.80  
Total labour : \$ 3,580.00  
Total repair cost : \$ 13,078.80

---

#### Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/08/2019 14:45
Date Of Accident	19/08/2019 18:50
Exact Location Of Accident	BT BATOK ENTER TO PIE TOWARDS TUAS (SLIP ROAD)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR6843H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	EDMUND CHAN GEE SENG
NRIC No	S6903781Z
Email Address	EDMUNDCHAN69@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96610873
Alternative Phone No	OTHERS-96610873

### Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC 1.5 TURBO VTIS SR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10773466
Cover Note Number	

### Driver

Name of Driver	EDMUND CHAN GEE SENG
NRIC No	S6903781Z
Date Of Birth	07/02/1969
Occupation	INDOOR
Date Of Driving Pass	23/04/1993
Driving Experience	26 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96610873
Fax Number	
Contact Number	OTHERS-96610873
EMail Address	EDMUNDCHAN69@HOTMAIL.COM



Address	BLK 679B JURONG WEST CENTRAL #10-02
Postcode	642679
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : THONG FUI LING
	GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX7292T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MR LIONG(AH LIANG)
NRIC/Passport Number	
Contact Number	96375189
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**




I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")


(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 Policyholder's Signature / Date & Time	 Driver's Signature (If driver is not the policyholder) / Date & Time	 Witnessed by Reporting Centre Personnel
---	---	--

Sketch Plan


(A) SLR 6843 H, (B) GA 7292 T




ON THE 19/8 2019 ABOUT 1850HRS, I WAS DRIVING ALONG  
 BUKIT BATOK ROAD TURNING RIGHT TO PLE ON THE MERGHAING LANE.  
 I WAS THE 1<sup>ST</sup> CAR ENTER TO PLE TOWARDS THAT. SUDDENLY  
 THERE WAS A IMPACT ON MY RIGHT! THE WHITE VAN GX7297T  
 DIRECT HIT TO MY RIGHT SIDE 2 DOORS AND MY SIDE MIRROR!!

Declaration

We declare the foregoing particulars are true in every respect

 20/08/2019

Policyholder's Signature / Date & Time

 20/08/2019

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

**L Soon Auto Services**  
**No.10 Ang Mo Kio Industrial Park 2A**  
**#03-18 Ang Mo Kio Auto Point**  
**Singapore 568047**

*Not Notified*  
*Recovery Before Paint*  
*4 days*  
*85299.04*

*Kenneth*  
*96910663*

**SLR6843H Honda Civic**

No	Qty	Parts Description	Estimated Parts Price	
1	1	Front right door wing mirror complete assy	\$ 778.20	<i>my look for</i> ✓
2	1	Front right door panel	\$ 1,228.60	<i>Red work</i> ✓
3	1	Front right door lock mechanism	\$ 252.80	<i>in</i> X
4	1	Front right door glass outer moulding	\$ 176.10	<i>in</i> X
5	1	Front right door outer handle	\$ 178.40	<i>in</i> ✓
6	2	Front right door sticker	\$ 180.00	<i>in</i> ✓
7	2	Front right door hinges	\$ 88.00	<i>in</i> X
8	1	Front right door weatherstrip	\$ 188.00	<i>in</i> X
9	1	Front right door checker linkage	\$ 163.00	<i>in</i> X
10	1	Front right door inner trim board	\$ 325.00	<i>in</i> X
11	1	Front right door regulator with motor assy	\$ 478.50	<i>in</i> X
12	1	Right side sill panel	\$ 896.00	<i>in</i> X
13	1	Rear right door panel	\$ 1,228.60	<i>in</i> ✓
14	1	Rear right door outer handle	\$ 178.40	<i>in</i> X
15	1	Rear right door glass outer moulding	\$ 176.10	<i>in</i> X
16	1	Rear right door lock mechanism	\$ 252.80	<i>in</i> X
17	2	Rear right door sticker	\$ 180.00	<i>in</i> ✓
			\$ 6,948.50	
Less 20%			\$ 1,389.70	
			<u>\$ 5,558.80</u>	

Special Nett Items

1	8	Front right door inner trim board clips	\$ 30.00	<i>in</i> X
2	1	Front right door transparent pearl spot sticker	\$ 600.00	<i>(Bill)</i> X
3	1	Front right wing mirror pearl spot sticker	\$ 200.00	<i>in</i> X
4	1	Right side skirting	\$ 1,800.00	<i>in</i> X
5	10	Right side skirting clips	\$ 50.00	<i>in</i> X
6	1	Right side skirting sealant	\$ 80.00	<i>in</i> X
7	1	Right side sill panel sealant	\$ 80.00	<i>in</i> X
8	1	Rear right door transparent pearl spot sticker	\$ 600.00	<i>(Bill)</i> X
9	1	Right side skirting pearl spot sticker	\$ 500.00	<i>in</i> X
			<u>\$ 3,940.00</u>	

*1200l*  
*Subject to*  
*NTUC*  
*Approval*

**Total parts**

**\$ 9,498.80**

**L Soon Auto Services**  
**No.10 Ang Mo Kio Industrial Park 2A**  
**#03-18 Ang Mo Kio Auto Point**  
**Singapore 568047**

**SLR6843H Honda Civic**

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten front right, rear right affected area and replace front right and rear right damaged parts.	\$ 1,400.00	4001
2	To putty and spray painting front right and rear right affected portion.	\$ 1,400.00	4401
3	To transfer front right door glass to new door.	\$ 80.00	601
4	To transfer rear right door glass to new door.	\$ 80.00	601
5	To check door central locking for function.	<del>ms</del> \$ 80.00	X
6	To apply anti rust proofing to front right and rear right affected area.	\$ 120.00	601
7	To remove and install front right door lock mechanism.	\$ 80.00	X
8	To remove and install rear right door lock mechanism.	\$ 80.00	X
9	To remove and install front right door visor.	\$ 80.00	<del>301</del> 301
10	To remove and install rear right door visor.	\$ 80.00	<del>301</del> 301
11	Towing service.	<del>nn</del> B71 \$ 100.00	X
<b>Total labour :</b>		<b>\$ 3,580.00</b>	

**Total parts : \$ 9,498.80**  
**Total labour : \$ 3,580.00**  
**Total repair cost : \$ 13,078.80**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Hi ah soon,

This is my invoice for ppf.

Regards

Edmund

Sent from my Huawei phone

----- Original Message -----

Subject: Receipt / Tax Invoice (#3157)

From: EA Detailer

To: [edmundchan69@hotmail.com](mailto:edmundchan69@hotmail.com)

CC:

***Making the REAL Difference***

*"WE ARE SINGAPORE BEST AUTODETAILER PROVIDING AMAZING CUSTOMER EXPERIENCE AT AN AFFORDABLE VALUE"*

Bukit Timah, Dunearn outlet

Served by: Michael Koh at Bukit Timah, Dunearn outlet

**Receipt #3157**

**Sun, 28 Oct 18, 10:41am**

1 PPF - 360° Full Invis-Werkz

@ \$8500.00    \$8500.00

Note: Full wrap with either Pearl or Matt PPF. Dent removal on left rear door.

Subtotal \$6000.00

Additional Discount -\$2500.00

GST 7% Tax (Inc. 7% GST, 7%) \$420.00

**TOTAL 1 item \$6420.00**



EA Detailer Pte Ltd  
130 Dunearn Road Singapore 309436

Bill To:

L Soon Auto Services  
10 Ang Mo Kio Auto Point #03-18  
Ang Mo Kio Ave 5, Industrial Park 2A  
Singapore 568047  
l\_soon@ymail.com

Contact Person:  
Mr Lee Soon Meng  
9636 6212

# INVOICE

# 300191701

Date: Aug 30, 2019

Payment Terms: COD

Due Date: Aug 30, 2019

**Balance Due: \$1,200.00**

Item	Quantity	Rate	Amount
InvisGard Paint Protection Film Enhancement Installation Service - Pearl Version : 2 Panels Door (Honda Civic SLR6843H)	1	\$1,200.00	\$1,200.00

Subtotal: \$1,200.00

Total: \$1,200.00

21/8/19  
ask for invoice  
to give before  
debit (Hilux) transfer  
already sent to  
customer  
21/8/19



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19014777/Ksf3e2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 19-12-2019



ATTN : JARED LIU

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GX 7292T	Veh. Inspected	SLR 6843H
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1058602-002	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	22/08/2019

#### 2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC (A)	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MRHFC1660HT000056	Colour	METALLIC BLUE
Odometer	37308 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45Z R17	PIRELLI	9 mm
L/H Front Tyre	225/45Z R17	PIRELLI	9 mm
R/H Rear Tyre	225/45Z R17	PIRELLI	9 mm
L/H Rear Tyre	225/45Z R17	PIRELLI	9 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  
DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	19/08/2019	Inspect Date / Time	22/08/2019 ( 01:07 PM )
Survey held at	L SOON AUTO SERVICES 10 ANG MO KIO INDUSTRIAL PARK 2A #03-18 AMK AUTO POINT SINGAPORE 568407		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 6843H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT RIGHT DOOR WING MIRROR COMPLETE ASSY	MTG LOOSE	778.20	778.20
1	FRONT RIGHT DOOR PANEL	DENTED / WARPED	1,228.60	1,228.60
1	FRONT RIGHT DOOR LOCK MECHANISM	TO REPAIR SEE LABOUR	252.80	-
1	FRONT RIGHT DOOR GLASS OUTER MOULDING	SERVICEABLE	176.10	-
1	FRONT RIGHT DOOR OUTER HANDLE	DENTED	178.40	178.40
2	FRONT RIGHT DOOR STICKER	NECESSARY	180.00	180.00
2	FRONT RIGHT DOOR HINGES	TO REPAIR SEE LABOUR	88.00	-
1	FRONT RIGHT DOOR WEATHERSTRIP	SERVICEABLE	188.00	-
1	FRONT RIGHT DOOR CHECKER LINKAGE	SERVICEABLE	163.00	-
1	FRONT RIGHT DOOR INNER TRIM BOARD	SERVICEABLE	325.00	-
1	FRONT RIGHT DOOR REGULATOR WITH MOTOR ASSY	SERVICEABLE	478.50	-
1	RIGHT SIDE SILL PANEL	TO REPAIR SEE LABOUR	896.00	-
1	REAR RIGHT DOOR PANEL	BENT	1,228.60	1,228.60
1	REAR RIGHT DOOR OUTER HANDLE	SERVICEABLE	178.40	-
1	REAR RIGHT DOOR GLASS OUTER MOULDING	SERVICEABLE	176.10	-
1	REAR RIGHT DOOR LOCK MECHANISM	TO REPAIR SEE LABOUR	252.80	-
2	REAR RIGHT DOOR STICKER	NECESSARY	180.00	180.00
	LESS 20% DISCOUNT		-1,389.70	-754.76
			5,558.80	3,019.04
<b>SPECIAL NETT ITEMS</b>				
8	FRONT RIGHT DOOR INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	30.00	-
1	FRONT RIGHT DOOR TRANSPARENT PEARL SPOT STICKER (SN) }	NECESSARY	600.00	1,200.00
1	REAR RIGHT DOOR TRANSPARENT PEARL SPOT STICKER (SN) }	NECESSARY	600.00	-
1	FRONT RIGHT WING MIRROR PEARL SPOT STICKER (SN)	NOT NECESSARY	200.00	-
1	RIGHT SIDE SKIRTING (SN)	SERVICEABLE	1,800.00	-
10	RIGHT SIDE SKIRTING CLIPS (SN)	NOT NECESSARY	50.00	-

Report Ref No. CS/INC19014777/Ksf3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RIGHT SIDE SKIRTING SEALANT (SN)	NOT NECESSARY	80.00	-
1	RIGHT SIDE SILL PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
1	RIGHT SIDE SKIRTING PEARL SPOT STICKER (SN)	NOT NECESSARY	500.00	-
			3,940.00	1,200.00
	<b>LABOUR</b>			
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT RIGHT, REAR RIGHT AFFECTED AREA AND REPLACE FRONT RIGHT AND REAR RIGHT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT RIGHT DOOR LOCK MECHANISM, FRONT RIGHT DOOR HINGES, RIGHT SIDE SILL PANEL AND REAR RIGHT DOOR LOCK MECHANISM.		1,400.00	400.00
	TO PUTTY AND SPRAY PAINTING FRONT RIGHT AND REAR RIGHT AFFECTED PORTION.		1,400.00	440.00
	TO TRANSFER FRONT RIGHT DOOR GLASS TO NEW DOOR.		80.00	60.00
	TO TRANSFER REAR RIGHT DOOR GLASS TO NEW DOOR.		80.00	60.00
	TO CHECK DOOR CENTRAL LOCKING FOR FUNCTION.	NOT NECESSARY	80.00	-
	TO APPLY ANTI RUST PROOFING TO FRONT RIGHT AND REAR RIGHT AFFECTED AREA.		120.00	60.00
	TO REMOVE AND INSTALL FRONT RIGHT DOOR LOCK MECHANISM.	NOT NECESSARY	80.00	-
	TO REMOVE AND INSTALL REAR RIGHT DOOR LOCK MECHANISM.	NOT NECESSARY	80.00	-
	TO REMOVE AND INSTALL FRONT RIGHT DOOR VISOR.		80.00	30.00
	TO REMOVE AND INSTALL REAR RIGHT DOOR VISOR.		80.00	30.00
	TOWING SERVICE.	NOT NECESSARY	100.00	-
			3,580.00	1,080.00
<b>GRAND TOTAL</b>			<b>13,078.80</b>	<b>5,299.04</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>5,299.04</b>

Report Ref No. CS/INC19014777/Ksf3e2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.