

Trans-cab Auto Services Pte Ltd

AAD1908-130

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 448B

Not Authorised

Anthony Blegain

1569.48

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer : *21 AUG 2019*
 Date of Registration:

SHD 448B
 VF1ABL15AUC283351
 RENAULT
 LATITUDE
 17.8.19
NTUC Income
 16/9/2016

	PART		LIST	
1	BUMPER COVER FRT	\$	<i>Avulcan</i> 1,259.42	✓
1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75	} X
1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68	
1	BUMPER RETAINER FRT LH	\$	<i>SL</i> 151.41	
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88	
1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83	
1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80	
1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21	
1	BUMPER BEAM FRT	\$	<i>N</i> 914.08	
1	HEADLAMP LH	\$	<i>SL</i> 1,184.43	
1	HEADLAMP PANEL FRT LH	\$	<i>N</i> 152.15	
1	FENDER PANEL FRT LH	\$	<i>N</i> 783.83	
1	WHEELARCH FRT LH	\$	<i>SL</i> 278.84	
1	FENDER BRACKET LOWER LH	\$	<i>SL</i> 15.79	
1	FENDER INSULATOR LH	\$	<i>SL</i> 130.84	
1	FRONT BRACE PANEL	\$	<i>N</i> 177.22	
1	RADIATOR GRILLE	\$	<i>SL</i> 1,707.78	
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36	
1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 1,353.75	
1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 615.90	
1	FRAME FULL SUPPORT BRACKET	\$	<i>N</i> 89.79	
1	BONNET	\$	<i>N</i> 1,941.63	
1	BONNET INSULATOR	\$	<i>SL</i> 405.73	
1	BONNET STRUT LH	\$	<i>SL</i> 88.61	
1	BONNET STRUT RH	\$	<i>SL</i> 88.61	
1	BONNET HINGE LH	\$	<i>N</i> 348.31	
1	BONNET HINGE RH	\$	<i>N</i> 348.31	

Trans-cab Auto Services Pte Ltd

AAD1908-130

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 448B

1	BONNET LOCK	\$	305.48
1	BONNET CABLE	\$	119.19
1	BONNET CABLE COVER	\$	161.03
1	BONNET SEAL OUTER	\$	92.36
1	BONNET SEAL INNER	\$	157.28
1	AIR CLEANER BOX	\$	464.20
1	AIR CLEANER HOSE	\$	175.85
1	AIR CLEANER LOWER	\$	271.26

X *See*

TOTAL	\$	15,655.58
10%	\$	1,565.56
	\$	14,090.02

Special Nett

1	BUMPER CLIP FRT	\$	<i>na</i> 66.00
1	BUMPER BRACKET CLIP FRT LH	\$	<i>na</i> 12.00
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>na</i> 10.50
1	BUMPER GRILLE LOWER CLIP	\$	<i>na</i> 69.00
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>na</i> 70.00
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>na</i> 20.00
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>na</i> 30.00
1	WHEELARCH CLIP FRT LH	\$	<i>na</i> 30.50
1	FRONT LEFT TYRE	\$	<i>sh</i> 300.00
1	FRONT LEFT TYRE RIM	\$	<i>sh</i> 380.00
1SET	Front licence plate with holder	\$	<i>sh</i> 80.00
1	WINDSCREEN SEALANT	\$	<i>na</i> 253.80
1	FRONT WINDSCREEN MOULDING	\$	<i>na</i> 120.00
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00
6	BONNET INSULATOR CLIP L70Y	\$	<i>na</i> 7.30
2	BONNET STRUT L70Y	\$	<i>na</i> 88.61
2	BONNET CABLE CLIP L70Y	\$	<i>na</i> 6.31
2	BONNET CABLE COVER SCREW L70Y	\$	<i>sh</i> 10.85
1SET	RADIATOR GRILLE FRAME CLIP	\$	<i>na</i> 52.00
1SET	RADIATOR GRILLE SCREW	\$	<i>na</i> 16.00

X

TOTAL	\$	1,722.88
--------------	-----------	-----------------

TOTAL PARTS	\$	15,812.90
--------------------	-----------	------------------

Trans-cab Auto Services Pte Ltd

AAD1908-130

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 448B

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	150d
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	L 380.00	X
To transfer of front windscreen fittings and conduct water seepage test.	\$	5 170.00	X
To check steering geometry and computer wheel alignment	\$	7 220.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	L 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	Y 170.00	X
Putty and spray painting of the affected portion.	\$	6,000.00	220d
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	nn 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	nn 170.00	X
To rust-proofing of the affected areas.	\$	nn 170.00	X

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after a job is done
- To display damaged parts, and resurvey
- Parts prices and supplier confirmation
- Third party survey is on a no liability basis
- No disputes may be raised in the future
- Scrap parts to be removed and disposed of

PART BY PART (REPAIR DAY)

Acknowledged by Repairer:

Signature:

TOTAL	\$	14,800.00
Over All Total	\$	30,612.90

20 days
2 day